

















## Recall Summary – European Toys

### EU Safety Gate Alerts (Nov 2021)

Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A11/00092/21	Denmark	<b>Sling Cradle</b>  (Country of Origin: <b>India</b> )		<b>Damage to Sight, Injury</b> The product may release metal splints which can fall on a child inside the cradle and into the eyes of the child, causing injury. The product does not comply with the requirements of the General Product Safety directive and the European standard EN 1130.	Warning consumers of the risks
A11/00098/21	Lithuania	<b>Plastic Toy Airplane</b>  (Country of Origin: <b>China</b> )		<b>Injury</b> The protective cap, cap or tip may come off the projectile. A child could be hit by the detached components, which may cause a puncture or penetration injury. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Withdrawal of the product from the market
A11/00099/21	Lithuania	<b>Swing</b>  (Country of Origin: <b>Poland</b> )		<b>Injury</b> The plastic rope suspension and rope length adjustment partition hole part may break. A child may fall and get injured. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-8.	Withdrawal of the product from the market
A11/00100/21	Lithuania	<b>Rattle Owl</b>  (Country of Origin: <b>China</b> )		<b>Injury</b> The product has a protruding part. If a child puts the toy in the mouth and falls face down, the protruding part could obstruct the airways, causing choking and injury around the pharynx or trachea area. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Withdrawal of the product from the market
A12/01485/21	Finland	<b>Toy</b>  (Country of Origin: <b>China</b> )		<b>Injury</b> The lid of the battery compartment can be easily opened without the use of a tool or two simultaneous movements. A child might ingest the batteries and suffer internal injury. The product does not comply with the requirements of the Toy Safety Directive and the European standard EN 62115.	Withdrawal of the product from the market

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.






A12/01486/21	Germany	<b>Children's Fancy Dress Costume</b>  (Country of Origin: <b>China</b> )		<b>Burn</b> The fancy dress costume's mask is easily flammable and the flame propagation is too high. If it catches fire, a child could suffer from burns. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-2.	Recall of the product from end users
A12/01487/21	France	<b>Babies' Soother</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The product contains Bisphenol A (BPA) (measured value: 0.1 mg/kg). BPA may damage fertility and has been identified as a substance affecting the hormonal systems of humans and animals. The product does not comply with the requirements of the General Product Safety Directive and the relevant European standard EN 1400.	Removal of this product listing by the online marketplace
A12/01488/21	France	<b>Babies' Soother</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The product contains Bisphenol A (BPA) (measured value: 0.14 mg/kg). BPA may damage fertility and has been identified as a substance affecting the hormonal systems of humans and animals. The product does not comply with the requirements of the General Product Safety Directive and the European standard EN 1400.	Removal of this product listing by the online marketplace
A12/01494/21	Denmark	<b>Baby Walker</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The nut fixture of the wheel is inadequately fixed and it can easily detach. A child can put it in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and European standard 71-1.	Recall of the product from end users
A12/01496/21	Denmark	<b>Doll Pram</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The nut fixture of the wheel is inadequately fixed and it may fall off. A child can put it in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and European standard 71-1.	Recall of the product from end users
A12/01497/21	Cyprus	<b>Push/ Pull-along Toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The toy can easily break releasing small parts. A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the European standard EN 71-1.	Withdrawal of the product from the market

A12/01498/21	Hungary	<b>Toy Scooter</b>  (Country of Origin: <b>China</b> )		<b>Injury</b> The front wheel is too small and could get stuck in holes on the ground, and the steering tube is not sufficiently secured. This could cause a child to lose balance and fall off, leading to injury. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Import rejected at border
A12/01499/21	Cyprus	<b>Friction Car-rattle</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The toy can easily break, releasing small parts. A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the European standard EN 71-1	Withdrawal of the product from the market
A12/01501/21	Cyprus	<b>Plastic Doll</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The head of the doll contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) (measured value: up to 20.1% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/01502/21	Cyprus	<b>Plastic Doll</b>  (Country of Origin: <b>Cyprus</b> )		<b>Chemical</b> The head of the doll contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) (measured value: up to 33.45% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/01503/21	Slovakia	<b>Water Playing Set</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The plastic material of the product contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) (measured value: up to 8.47% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Warning consumers of the risks





A12/01504/21	The Netherlands	<b>Wooden Toy</b>  (Country of Origin: <b>China</b> )		<b>Choking, Strangulation</b> A small wooden part can detach. A small child may put it in the mouth and choke. In addition, the carrying strap does not have a quick-opening system on it and it could pose a strangulation risk. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Warning consumers of the risks
A12/01509/21	Poland	<b>Plastic Doll</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The plastic material of the doll's hand contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) (measured value: up to 1.13% by weight) and di-isononyl phthalate (DINP) (measured value: up to 1.76% by weight). These phthalates may harm the health of children, causing possible damage to their reproductive system and liver. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/01511/21	Slovenia	<b>Soft Toy with LED</b>  (Country of Origin: <b>Vietnam</b> )		<b>Environment</b> The LED lamp contains an excessive amount of cadmium (measured value: up to 0.0486% by weight). Cadmium poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Withdrawal of the product from the market
A12/01514/21	Slovakia	<b>Wooden Puzzle</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> Small parts (both ears, both horns and tail) may easily detach from the toy. A small child may put it in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European Standard EN 71-1.	Stop of sales
A12/01517/21	Croatia	<b>Slime Toy</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The migration of boron from the toy slime is too high (measured value: up to 864 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3.	Ban on the marketing of the product and any accompanying measures






The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.









A12/01519/21	Slovakia	<b>Toy Slime</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The migration of boron from the toy slime is too high (measured value: up to 1401.3 mg/kg). Ingestion of boron or contact with an excessive quantity of boron may harm the health of the children by damaging the reproductive system. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3.	Stop of sales
A12/01525/21	Poland	<b>Fancy-dress Mask</b>  (Country of Origin: <b>China</b> )		<b>Burn</b> The mask is easily flammable and the flame propagation is too high. If it catches fire, a child could suffer from burns. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-2.	Withdrawal of the product from the market
A12/01526/21	Poland	<b>Toy Slime</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The migration of boron from the toy is too high (measured value: up to 500 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3.	Destruction of the product
A12/01528/21	France	<b>Children's Fancy Dress</b>  (Country of Origin: <b>China</b> )		<b>Strangulation, Suffocation</b> The functional non-detachable cords in the neck area can become trapped during various activities of a child, leading to strangulation. In addition, the non-permeable plastic bag of the product is too thin. If a child plays with the bag, the plastic can cover the mouth and nose, causing the child to suffocate. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Removal of this product listing by the online marketplace
A12/01529/21	Poland	<b>Plastic Doll</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The plastic material of the toy contains bis (2-ethylhexyl) phthalate (DEHP) (measured value: up to 16.8% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

A12/01538/21	France	<b>Plush Toy</b>  (Country of Origin: <b>China</b> )		<b>Chemical, Choking</b> The plastic material of the product contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) (measured value: up to 37% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. In addition, the suction cup can easily detach. If a child puts the product in the mouth, the suction cup can detach causing the airways obstructed by the suction cup. Finally, the stuffing material of the product is easily accessible which, if ingested, could cause choking. The product does not comply with the REACH Regulation, the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Removal of this product listing by the online marketplace
A12/01539/21	France	<b>Plush Toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The suction cup of the product can easily detach. If a child puts the product in the mouth, the suction cup can obstruct the airways. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Removal of this product listing by the online marketplace
A12/01540/21	France	<b>Plush Toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> Small parts can easily detach (key-ring). Consequently, a small child may put them in the mouth and choke on them. In addition, the stuffing material is easily accessible and, if ingested, could cause choking. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Removal of this product listing by the online marketplace
A12/01544/21	Hungary	<b>Plastic Doll</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The product contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) (measured value: 35% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Ban on the marketing of the product and any accompanying measures

A12/01548/21	Sweden	<b>Bouncing Ball</b>  (Country of Origin: <b>China</b> )		<b>Environment</b> The solders contain an excessive amount of lead (measured value: up to 14.9 % by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Withdrawal of the product from the market
A12/01554/21	Czechia	<b>Plastic Doll</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The plastic material of the head of the doll contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) (measured value: up to 43.9% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/01574/21	France	<b>Children's Fancy Dress Costume</b>  (Country of Origin: <b>China</b> )		<b>Burn</b> The fancy dress costume is easily flammable and the flame propagation is too high. If it catches fire, a child could suffer from burns. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-2.	Removal of this product listing by the online marketplace
A12/01575/21	Hungary	<b>Plastic Doll</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The product contains an excessive amount of di-2-ethylhexyl phthalate (DEHP) (measured value: 34% by weight) and dibutyl phthalate (DBP) (measured value: 0.35% by weight). These phthalates may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Recall of the product from end users
A12/01576/21	Lithuania	<b>Toy Car with Candies</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> Small parts can easily detach. A child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Withdrawal of the product from the market





A12/01577/21	Poland	<b>Toy Telephone</b>  (Country of Origin: <b>China</b> )		<b>Damage to Hearing</b> The sound level produced by the toy is too high (measured value: up to 76.3 dB), which could lead to permanent or temporary loss of hearing. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Withdrawal of the product from the market
A12/01581/21	Hungary	<b>Sandbox Toy Set</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The toy contains small elements (crab, fish, shells) that a child may put in the mouth and choke. The product does not comply with the Toy Safety Directive and the relevant European standard EN 71-1.	Withdrawal of the product from the market
A12/01582/21	Poland	<b>Soft Toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> Small parts (plastic eyes and suction cup) may easily detach from the toy. A small child may put small parts in the mouth and choke. The product does not comply with the regulations on the safety of toys and standard EN 71-1.	Withdrawal of the product from the market
A12/01584/21	Lithuania	<b>Snake Toy</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The plastic material of the product contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) and Di-n-octyl phthalate (DNOP) (measured values: up to 20% and 1.5% by weight, respectively). These phthalates may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/01585/21	Ireland	<b>Baby Carrier</b>  (Country of Origin: <b>China</b> )		<b>Injury</b> The plastic washer which secures the child seat to the adult shoulder and waist straps may fail and the buckle which holds a child in place can also break. Consequently, the baby could fall out and get injured. The product does not comply with the requirements of the General Product Safety Directive.	Recall of the product from end users
A12/01586/21	Hungary	<b>Toy Ironing Set</b>  (Country of Origin: <b>China</b> )		<b>Injury</b> The ironing board is not sufficiently secured and can tip over when using the product, which could lead to injury. Furthermore, the fingers of a child could be entrapped between moving parts, causing injury. The product does not comply with the requirements of the Toy Safety Directive and the relevant European Standard EN 71-1.	Withdrawal of the product from the market

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.






A12/01589/21	France	<b>Luminous Balloons</b>  (Country of Origin: <b>China</b> )		<b>Chemical, Choking</b> The plastic case containing the button batteries can easily open and release the button batteries. A child may put them in the mouth and ingest them, which may lead to choking if they enter the airways, or could cause damages to the gastrointestinal tract. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 62115.	Recall of the product from end users
A12/01590/21	Poland	<b>Magnetic Blocks</b>  (Country of Origin: <b>China</b> )		<b>Injury</b> If a child swallows the magnetic balls, they could attract one another causing intestinal blockage or perforation. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Withdrawal of the product from the market
A12/01600/21	Sweden	<b>Quadcopter/Drone</b>  (Country of Origin: <b>China</b> )		<b>Environment</b> A solder on the printed circuit board (PCB) in the product and two solders on the PCB in the remote control contain an excessive amount of lead (measured values: up to 52%, 86% and 59% by weight, respectively). Lead poses a risk to the environment. The product does not comply with the Commission Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Withdrawal of the product from the market
A12/01601/21	Sweden	<b>Radio-controlled Excavator</b>  (Country of Origin: <b>China</b> )		<b>Environment</b> Some solders of the printed circuit board (PCB) contain an excessive amount of lead (measured values: up to 67.7% by weight). Lead poses a risk to the environment. The product does not comply with the Commission Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Withdrawal of the product from the market
A12/01604/21	Finland	<b>Soother Holder</b>  (Country of Origin: <b>Finland</b> )		<b>Choking</b> The garment fastener of the soother holder clip breaks easily, generating small parts. A child could put the small parts in the mouth and choke. The product does not comply with the relevant European standard EN 12586.	Recall of the product from end users




The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

A12/01609/21	Croatia	<b>Slime Toy</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The migration of boron from the toy slime is too high (measured value: up to 2273 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3.	Ban on the marketing of the product and any accompanying measures
A12/01618/21	Sweden	<b>Electrical Toy Piano</b>  (Country of Origin: <b>China</b> )		<b>Environment</b> The solder in the toy contains an excessive amount of lead (measured value: up to 74% by weight) and cadmium (measured value: up to 0.12% by weight). Lead and cadmium pose a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Withdrawal of the product from the market
A12/01619/21	Sweden	<b>Plastic Ball with Spikes with Light and Sound</b>  (Country of Origin: <b>China</b> )		<b>Environment</b> The solder in the toy contains an excessive amount of lead (measured value: up to 63.4% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Withdrawal of the product from the market
A12/01621/21	Sweden	<b>Electrical Toy Wand</b>  (Country of Origin: <b>China</b> )		<b>Environment</b> The solder in the toy contains an excessive amount of lead (measured value: up to 62.9% by weight) and cadmium (measured value: up to 0.02% by weight). Lead and cadmium pose a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Withdrawal of the product from the market

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

A12/01624/21	Sweden	<b>Baby Doll</b>  (Country of Origin: <b>China</b> )		<b>Environment</b> The solder in the toy contains an excessive amount of lead and cadmium (measured value: up to 72.6% and 0.3% by weight, respectively). Lead and cadmium pose a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Withdrawal of the product from the market
A12/01628/21	Poland	<b>Plastic Doll</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The head of the doll contains an excessive amount of bis (2-ethylhexyl) phthalate (DEHP) (measured value: up to 16.4% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Destruction of the product
A12/01629/21	Sweden	<b>Plastic Doll with Accessories</b>  (Country of Origin: <b>China</b> )		<b>Chemical, Environment</b> The plastic in the head and legs of the doll contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP), di-isononyl phthalate (DINP), dibutyl phthalate (DBP), diisobutyl phthalate (DIBP) and short chain chlorinated paraffins (SCCPs) (measured values: up to 25.2%, 1.4%, 4.3%, 0.17% and 0.24% by weight, respectively). The solder in the toy contains an excessive amount of lead and cadmium (measured values: up to 66.5% and 0.4% by weight, respectively). These phthalates may harm the health of children, causing possible damage to their reproductive system and liver. SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations and bioaccumulate in wildlife and humans, posing a risk to human health and the environment. Lead and cadmium pose a risk to the environment. The product does not comply with the requirements of the REACH Regulation, the Regulation on persistent organic pollutants (POP Regulation) and the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Withdrawal of the product from the market

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

A12/01630/21	Poland	<b>Plastic Doll</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The plastic of the doll's head contains an excessive amount of bis (2-ethylhexyl) phthalate (DEHP) (measured value: up to 16.4% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Destruction of the product
A12/01632/21	Lithuania	<b>Plastic Doll</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The plastic material of the doll contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) (measured value: up to 25% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/01634/21	Sweden	<b>Plastic Ball</b>  (Country of Origin: <b>Pakistan</b> )		<b>Chemical</b> The plastic of the ball contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP), di-isononyl phthalate (DINP) and lead (measured value: up to 23%, 27% and 0.12% by weight, respectively). These phthalates may harm the health of children, causing possible damage to their reproductive system and liver. Lead is harmful to human health, accumulates in the body and can cause developmental neurotoxicity and may also affect breast-fed or unborn children. The product does not comply with the REACH Regulation.	Other : The product was already sold out, but the importer will not import it again.

## Safety Gate: the EU Rapid Alert System for Dangerous Non-food Products

“Safety Gate”, the EU rapid alert system (formerly known as ‘RAPEX’), enables the rapid exchange of information between 31 European countries and the European Commission on non- food dangerous products found on the market posing a risk to health and safety of consumers.




A weekly overview of the alerts on those products is published in English for free on <https://ec.europa.eu/safety-gate-alerts/screen/webReport#weeklyReports>. The measures taken in the notifying country in order to restrict their marketing or use can be ordered by national authorities ("compulsory measures") or be taken directly by producers and distributors ("voluntary measures").

The official contact points of the Member and EFTA-EEA States provide the information published in these weekly overviews. Under the terms of Annex II.10 of the General Product Safety Directive (2001/95/EC) responsibility for the information provided lies with the notifying party. The Commission does not take any responsibility for the accuracy of the information provided.



## Recall Summary – US Toys / Children’s Products

*CPSC Recall List (Nov 2021)*

Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
22-706	USA	<b>Turbo Racer, Cloud Racer, Captain’s Fort and Fort Highlander Outdoor Playsets</b>  (Country of Origin: <b>China</b> )		<b>Entrapment Hazard</b> The wooden parts used to reinforce and create a decorative gable design on the wooden roof pose an entrapment hazard to children. Children can become trapped in the gap between the lower part of the roof structure and the bottom of the gable decoration.	Consumers should immediately stop using the recalled playsets and contact Backyard Play Systems for a free repair kit which includes replacement wood parts, hardware and instructions.
22-709	USA	<b>Baby Long Sleeve Wiggle Sets</b>  (Country of Origin: <b>Bangladesh</b> )		<b>Choking Hazard</b> The snaps on the long sleeve top can detach, posing a choking hazard to young children.	Consumers should immediately stop using the recalled Baby Long Sleeve Wiggle Set and contact Hanna Andersson for a full refund. Hanna Andersson will be providing postage-paid labeling to consumers for the return of the product for a full refund. Hanna Andersson is contacting all known purchasers directly.
22-710	USA	<b>Baby Ruffle Rompers</b>  (Country of Origin: <b>Bangladesh</b> )		<b>Choking Hazard</b> The snaps on the romper can detach, posing a choking hazard to young children.	Consumers should immediately stop using the recalled Ruffle Romper and contact Hanna Andersson for a full refund. Hanna Andersson will be providing postage-paid labeling to consumers for the return of the product for a full refund. Hanna Andersson is contacting all known purchasers directly.

\*Source: www.recalls.gov

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

## CPSC

The United States Consumer Product Safety Commission (CPSC) is an independent agency of the United States government. To provide better service in alerting the American people to unsafe, hazardous or defective products, a “one stop shop” for U.S. Government recalls, [www.recalls.gov](http://www.recalls.gov), has been created. Publics can report unsafe products to CPSC by using the platform.



The recall list is divided into seven categories: Consumer Products, Motor Vehicles, Boats, Food, Medicine, Cosmetics and Environmental Products. Generally, the recall was conducted, voluntarily by the company, under CPSC’s Fast Track Recall program. Fast Track recalls are initiated by firms who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.

---





The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

## Recall Summary – Australia Toys / Children’s Products

*ACCC Recall List (Nov 2021)*



PRA No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
2021/19195	Australia	<b>Fisher Price Dots and Spots Puppy Deluxe Swing Plug-in Adaptor</b>		<b>Risk of Electric Shock</b> The swing was supplied with an overseas plug-in adaptor which is not designed for use in Australia. If used with an incompatible power source there is an increased risk of electric shock, which can cause serious injury or death.	Consumers should stop using the overseas plug-in adaptor immediately.
2021/19224	Australia	<b>Tender Leaf Toys Audio Sensory Tray</b>  <b>A Wooden Tray with Four Different Wooden Shapes.</b>  <b>Each Shape Features a Different Type of Sound.</b>		<b>Suffocation Hazard</b> The small internal metal bell and steel pin inside the orange bell may come off. If the metal bell and steel pin come off, it may pose a choking or suffocation hazard for young children.	Consumers should immediately stop using the product and dispose of it. Consumers will need to contact Kaleidoscope and provide evidence that the product has been disposed of and the place of purchase. Kaleidoscope will organize for a full refund from the place of purchase once this has been provided.
2021/19232	Australia	<b>A Wooden Bear Rattle</b>		<b>Suffocation Hazard</b> The product may not comply with the size and shape requirements of the mandatory safety standard for toys for children up to and including 36 months of age. The product may pose a choking or suffocation hazard for young children, which can lead to severe injury or death.	Consumers should immediately stop using the product. Consumers should dispose of or destroy the product and contact CleverLittleKoalas to arrange for a full refund.

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.





2021/19235	Australia	<p><b>The Evolved Parent Co The Chew Box</b></p> <p><b>Silicone Teether Sets</b></p>		<p><b>Suffocation Hazard</b></p> <p>The products do not comply with the size and shape requirements of the mandatory safety standard for toys for children up to and including 36 months of age. The length of the teethers may pose a choking or suffocation hazard for young children.</p>	<p>Consumers should stop using the products and return them to Mr Indeva for a refund.</p>
2021/19242	Australia	<p><b>Plastic Toy Gun with 6 Soft Bullet Projectiles</b></p>		<p><b>Missing of Warning</b></p> <p>The product does not have the warning text "WARNING: Do not aim at eyes or face." User may not be aware of the hazard if the product is not labelled.</p>	<p>Consumers should ensure that the product is not aimed at the eyes or face when used. Consumers should return the product to the place of purchase for replacement labelling or a full refund.</p>
2021/19249	Australia	<p><b>Magic Princess Tutu</b></p> <p><b>A Children's Tutu with Lights</b></p>		<p><b>Burn Injury</b></p> <p>The product's button battery compartment is not adequately secured, and the button batteries are accessible. If young children gain access to the button batteries and ingest them, they are likely to suffer severe internal burn injury, which can result in serious illness or death. Button batteries also pose a choking hazard to young children.</p>	<p>Consumers should contact customerservice@themagicprincess.com to organize to return the product for a full refund. Consumers will receive a shipping label to be used to return the product.</p>
2021/19262	Australia	<p><b>Baby Gift Set Wooden Rattle 5 pcs Montessori Teether Natural Toy Boy Girl Hamper</b></p> <p><b>A 5 Piece Wooden Rattle and Teether Set</b></p>		<p><b>Suffocation Hazard</b></p> <p>The products do not comply with the size and shape requirements of the mandatory safety standard for toys for children up to and including 36 months of age. The products may also break, releasing small parts. The products or small parts may pose a choking or suffocation hazard for young children, which can lead to severe injury or death.</p>	<p>Consumers should immediately stop using the product, dispose of it and contact INCDECK to receive a full refund. Consumers will be asked to provide evidence to INCDESK that the product has been disposed of.</p>

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.



2021/19263	Australia	<p><b>The Bunny Silicone Teether and Wooden Rattle Sold as Part of Newborn Baby Shower Care Gift Set Box Pink 6pcs Girl Toy Hamper Present Xmas</b></p>		<p><b>Suffocation Hazard</b> The bunny silicone teether and wooden rattle do not comply with the size and shape requirements of the mandatory safety standard for toys for children up to and including 36 months of age. The bunny silicone teether and wooden rattle may pose a choking or suffocation hazard for young children, which can lead to severe injury or death.</p>	<p>Consumers should immediately stop using the bunny silicone teether and wooden rattle, dispose of them and contact INCDESK to receive a refund for the value of the teether and rattle. Consumers will be asked to provide evidence to INCDESK that the products have been disposed of.</p>
2021/19264	Australia	<p><b>The Bear Rattle Sold as Part of Montessori Newborn Baby Wooden Toys Gift Car Rattle Teether Set Neutral Learning</b></p>		<p><b>Suffocation Hazard</b> The bear rattle does not comply with the size and shape requirements of the mandatory safety standard for toys for children up to and including 36 months of age. The bear rattle may pose a choking or suffocation hazard for young children, which can lead to severe injury or death.</p>	<p>Consumers should immediately stop using the bear rattle, dispose of it and contact INCDESK to receive a refund for the value of the rattle. Consumers will be asked to provide evidence to INCDESK that the bear rattle has been disposed of.</p>
2021/19271	Australia	<p><b>Hype Kids' Swim Shorts</b></p>	 <p>PRODUCT NO. YWF-360 HYPE ELECTRIC PALM KIDS SWIM SHORTS</p>	<p><b>Injury and Entrapment Hazard</b> The holes in the internal mesh of the swim shorts are too large. The swim shorts' drawstring is too long. A child's genitals may become stuck in the holes in the internal mesh of the swim shorts, causing injury. The drawstring also poses an entrapment hazard.</p>	<p>Consumers should stop using the swim shorts and return them to the place of purchase for a full refund, including postage.</p>

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

2021/19272	Australia	<b>A Set of Small Colored Magnetic Balls</b>		<p><b>Internal Injury</b> The product contains small, high-powered magnets that exceed the maximum allowable magnetic flux set by the permanent ban on small high-powered magnets. If a child swallows more than one small high-powered magnet, the magnets can stick together across the walls of the child's intestine or other digestive tissue, which can lead to internal injuries and even death.</p>	Consumers should immediately stop using the product and return the product to the place of purchase to receive a full refund.
2021/19284	Australia	<b>Sunny Denim Short Sizes 2 and 3</b>		<p><b>Choking Hazard</b> The snap button on the shorts may be faulty, causing it to snap off. If the snap button falls off it may pose a choking hazard for young children.</p>	Consumers should immediately stop using this product and return it to any Cotton On Kids or Cotton On store for a full refund.
2021/19289	Australia	<b>Baby Beechwood Rattle</b>		<p><b>Suffocation Hazard</b> The product may not comply with the size and shape requirements of the mandatory safety standard for toys for children up to and including 36 months of age. The product may pose a choking or suffocation hazard for young children, which can lead to severe injury or death.</p>	Consumers should stop using the product and return it to Kasey Pearce and Co for a full refund.
2021/19295	Australia	<b>A Wooden Seahorse Rattle with a Barbell-shaped Base and Wooden Rings</b>		<p><b>Suffocation Hazard</b> The product does not comply with the size and shape requirements of the mandatory safety standard for toys for children up to and including 36 months of age. The product may pose a choking or suffocation hazard for young children, which can lead to severe injury or death.</p>	Consumers should stop using the product and return it to Birch and Bear for a full refund.

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

## Australian Product Safety System

The Australian product safety system is to maximize the safety of good by the cooperation of consumers, businesses and agencies. This policy sets out the principles adopted by the Australian Competition and Consumer Commission (ACCC) for prioritizing and addressing product safety risks.

Under the Australian Consumer Law, a responsible Minister can order a compulsory recall when there are hazards on the products. A voluntary recall could be conducted to remove the product from the marketplace when the suppliers become aware of unsafe or defective products.

The ACCC administers a national recalls system for recalls of specific and general consumer products, and publishes all product recalls on the website <https://www.productsafety.gov.au/recalls>.

STC (Hong Kong Standards and Testing Centre) is a not-for-profit, independent testing, inspection and certification organization. With a global network of ISO/IEC 17025 accredited testing laboratories and over 50 years of experience in consumer product testing, we can meet your conformity assessment needs with highly efficient and reliable service. Our testing scope and capabilities related to toys and children's products include but not limited to:

### EU Requirements

- EN 71
- Phthalates (EC) no. 1907/2006
- Nickel Release (EC) no. 1907/2006
- Total Cadmium (EEC) no. 91/338
- Lead in Jewellery product (EC) no. 836/2012
- Azo-dye (EC) no. 1907/2006
- Bisphenol-A (2014/81/EU)
- DMF (Dimethylfumarate) (EU) no. 2011/135
- Flame retardants TCEP, TCPP, TDCP (2014/79/EU)
- Package Waste Directive (94/62/EC)

### US & Canada Requirements

- ASTM F963
- CPSIA
- California Proposition 65
- 16 CFR 1501
- ASTM F2923 (Children's jewellery)
- ASTM F2999 (Adult's jewellery)
- US Toxic in Packaging Clearinghouse (TPCH)
- CCPSA - Toys Regulations (SOR/2011-17)

### Japan Requirements

- Japan Toy Safety Standard (ST)
- Japan Food Sanitation Law (JFSL)

### Australia Requirements

- AS/NZS 8124
- Consumer Protection Notice No. 6 of 2010 - DEHP

FOR MORE DETAILS, PLEASE CONTACT US :

Hong Kong: [hktcd@stc.group](mailto:hktcd@stc.group)  
Changzhou: [czstc@stc.group](mailto:czstc@stc.group)  
U.S.A.: [usstc@stc.group](mailto:usstc@stc.group)

Dongguan: [dgtcd@stc.group](mailto:dgtcd@stc.group)  
Vietnam: [vnstc@stc.group](mailto:vnstc@stc.group)  
Germany: [grstc@stc.group](mailto:grstc@stc.group)

Shanghai: [shtcd@stc.group](mailto:shtcd@stc.group)  
Japan: [jpo@stc.group](mailto:jpo@stc.group)



The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.