

## **Recall Summary – European Toys**

EU Safety Gate Alerts (Sep				lierts (Sep 2022)	
Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A11/00100/22	Cyprus	Baby	<b>8 8</b>	Injuries	Withdrawal of the
		swing	"MINKY"	The lateral swing angle of the swing is too	product from the
				large, and there is no protection from a	market
		(Country of		restraint system. The baby can therefore	
		Origin:		fall from the swing and be injured. The	
		China)		product does not comply with the	
				requirements of the General Product Safety	
				Directive nor with the European standard	
				EN 16232.	
A11/00101/22	Cyprus	Reclined		Injuries	Withdrawal of the
		cradle	1/2	The angle between the backrest and the	product from the
				horizontal surface is too small. As a	market
		(Country of		consequence, the swing is not stable	
		Origin:		enough, it can tip over and fall, leading to	
		Unknown)		injuries to a child. The product does not	
				comply with the requirements of the	
				General Product Safety Directive nor with	
				the European standard EN 12790.	
A11/00102/22	Poland	Toy gun		Damage to sight, Injuries	Withdrawal of the
			GUN	The kinetic energy of the arrows ejected is	product from the
		(Country of		too high, exceeding the permitted levels.	market
		Origin:		This can cause injuries to a child, in	
		China)		particular to the eyes. The product does not	
			SUPER-SHOOT THIN	comply with the requirements of the Toy	
				Safety Directive nor with the European	
				standard EN 71-1.	
A11/00103/22	Hungary	Wooden		Injuries	Recall of the
		swing		The ropes of the swing seat are fixed with	product from end
				knots which may easily loosen. A child may	users
		(Country of		fall and suffer injuries. The product does not	
		Origin:		comply with the requirements of the Toy	
		Hungary)		Safety Directive nor with the European	
				standard EN 71-8.	





A11/00104/22	Hungary	Wooden		Injuries	Withdrawal of
711176016172		swing	Toler,	The ropes are fixed to the swing seat with knots	the product
			7 3 11=	that may easily loosen. A child may fall down and	from the
		(Country of		suffer injuries. The product does not comply with	market
		Origin:		the requirements of the Toy Safety Directive nor	
		Romania)		with the relevant European standard EN 71-8.	
A11/00105/22	Germany	Rattle toy	A	Choking	Removal of
				The handle of the rattle is too long and if a child	this product
		(Country of		puts it in the mouth, it can block the airways and	listing by the
		Origin:		cause choking. The product does not comply	online
		China)		with the requirements of the Toy Safety Directive	marketplace
				nor with the European standard EN 71-1.	-
A11/00106/22	Germany	Rattle toy		Choking	Removal of
				The handle of the rattle toy is too long and if a	this product
		(Country of	100	child puts it in the mouth, it can block the airways	listing by the
		Origin:		and cause choking. The product does not comply	online
		Ukraine)		with the requirements of the Toy Safety Directive	marketplace
				nor with the European standard EN 71-1.	
A11/00107/22	Germany	Rattle toy		Choking	Ban on the
				The handle of the rattle toy is too long and if a	marketing of
		(Country of		child puts it in the mouth, it can block the airways	the product
		Origin:		and cause choking. The toy does not comply with	and any
		Russian		the requirements of the Toy Safety Directive, nor	accompanyin
		Federation)		with the European standard EN 71-1.	g measures
A12/01233/22	France	Wooden	TO A PA	Choking	Recall of the
		puzzle		Small parts of the puzzle pieces can easily	product from
			AVAS	detach (white plastic knobs). As a consequence,	end users
		(Country of		a child may put them in the mouth and cause	
		Origin:		chocking The product does not comply with the	
		China)		requirements of the Toy Safety Directive nor with	
				the European standard EN 71-1.	
A12/01235/22	Austria	Plastic toy	a marine	Choking	Marking the
			37.0	The toy can easily break, generating small parts.	product with
		(Country of	Control Albert	A child may put them in the mouth and cause	appropriate
		Origin:		chocking. The product does not comply with the	warnings on
		China)		requirements of the Toy Safety Directive nor with	the risks
				the European standard EN 71-1.	





A12/01241/22	Poland	Plastic		Entrapment, Injuries, Strangulation	Import rejected
		swing	Fig. (5) Table 1	The rope of the swing has no pre-fixed	at border
			Swing	hangers. As a result, the swing can be	
		(Country of		assembled improperly and the knots may	
		Origin:		easily get loose. A child may fall down and	
		China)		suffer injuries. The product has accessible	
			AID.266619-1	openings and accessible holes, in which	
				children can be trapped or suffer injuries.	
				The product does not comply with the	
				requirements of the Toy Safety Directive	
				nor with the European standard EN 71-8.	
A12/01242/22	Poland	Plastic		Entrapment, Injuries, Strangulation	Import rejected
		swing	13	The rope of the swing has no pre-fixed	at border
			Swing   S	hangers, and the product has accessible	
		(Country of	New Control	openings and accessible holes/ As a result,	
		Origin:		the swing can be assembled improperly	
		China)		and the knots may easily get loose. A child	
			NO.28881R	may fall and suffer injuries. The product	
				does not comply with the requirements of	
				the Toy Safety Directive nor with the	
				European standard EN 71-8.	
A12/01243/22	Poland	Plastic toy		Choking	Withdrawal of
			(3 S)	The product can easily break, resulting in	the product
		(Country of		small parts. A child may put them in the	from the
		Origin:		mouth and cause chocking. The product	market
		China)		does not comply with the requirements of	
				the Toy Safety Directive nor with the	
				European standard EN 71-1.	
A12/01248/22	Cyprus	Baby swing	(a) hanoybaby	Injuries	Withdrawal of
			Share has the desired of the share of the sh	The width of the straps of the restraint	the product
		(Country of		system is too short. The crotch straps can	from the
		Origin:		therefore tear away easily, causing the	market
		China)		baby to fall and be injured. The product	
				does not comply with the requirements of	
				the General Product Safety Directive nor	
				with the European standard EN 12790.	








A12/01249/22	Cyprus	Baby swing	@2 linbs Starr 0 self-tet beren	Injuries	Withdrawal of
7 , 0	C) p. a.c	Similar to the second	The angle between the backrest and the	the product	
		(Country of	A A	horizontal surface of the swing is too small.	from the
		Origin:	own)	As a consequence, with the backrest in the	market
		Unknown)		most reclined position, the swing may tilt	
				close to the horizontal surface, causing the	
				baby to hit its head. Also, the locking	
				mechanism on the product does not	
				engage automatically. As a consequence,	
				the product may fold and loose stability,	
				causing the baby to fall down and hit its	
				head and suffer injuries. The product does	
				not comply with the requirements of the	
				General Product Safety Directive nor with	
				the European standard EN 16232.	
A12/01260/22	Austria	Wooden		Choking	Destruction of
A12/01200/22	rattle	Windel Hill	The product can easily break and generate	the product	
		V V	to small parts. A child may put them in the	the product	
		(Country of	10000	mouth and cause chocking. The product	
		Origin:	The second of	does not comply with the requirements of	
		Germany)	CONTRACTOR OF THE PARTY OF THE	the Toy Safety Directive nor with the	
		Germany)		European standard EN 71.	
A12/01261/22	Austria	Soft toy		Choking	Withdrawal of
A12/01201/22	Austria	Soft toy	B&B G G G G G G G G G G G G G G G G G G	Small parts (beads) can easily detach. A	the product
		(Country of	22097965-001	child may put them in the mouth and cause	from the
		Origin:		chocking. The product does not comply	market
		China)		with the requirements of the Toy Safety	market
		China)			
				Directive nor with the European standard	
A12/01262/22	Augtric	Dull eleme		EN 71-1.	Withdrawal of
A12/01262/22	Austria	Pull-along	2	Choking	Withdrawal of
		toy	Small parts (horns) can easily detach. A	the product	
		(Country of	9	child may put them in the mouth and cause	from the
		(Country of		chocking. The product does not comply	market
		Origin:		with the requirements of the Toy Safety	
		Czechia)		Directive nor with European standard EN	
				71-1.	





A12/01263/22	Germany	Baby	4	Injuries	Recall of the
A12/U1203/22	Germany	carrier  (Country of Origin: China)	Total control of the	The carrier does not secure a baby sufficiently from falling to the ground. The carrier bends sideways or forwards and a baby may slip out and suffer fatal injuries. The product does not comply with the requirements of General Product Safety Directive nor with the European standard EN 13209-2.	product from end users
A12/01264/22	Austria	Puffer toy  (Country of Origin: China)		Choking Small parts (eyes) can easily detach. A child may put them in the mouth and cause chocking. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Destruction of the product
A12/01267/22	Germany	Soother holder  (Country of Origin: China)	AN MAINT	Choking The wooden beads break easily and generate small parts. A child could put them in the mouth and cause chocking. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 12586.	Ban on the marketing of the product and any accompanying measures
A12/01268/22	Germany	Soother holder  (Country of Origin: China)		Choking The product can easily break, generate to small parts. A child may put them in the mouth and cause chocking. The product does not comply with the requirements of the General Product Safety Directive nor with European standard EN 12586.	Ban on the marketing of the product and any accompanying measures
A12/01270/22	Hungary	Plastic doll with accessori es  (Country of Origin: China)	THE GIRL WITH A PASSION FOR FASHION	Chemical The product contains an excessive concentration of di-2-ethylhexyl phthalate (DEHP) (measured value: 35% by weight). This phthalate may harm the health of children, possibly causing damage to their reproductive system. The product does not comply with the REACH Regulation.	Recall of the product from end users





A12/01273/22	Hungary	Plastic doll  (Country of Origin: China)		Chemical The product contains an excessive concentration of di-2-ethylhexyl phthalate (DEHP) (measured value 33% by weight). This phthalate may harm the health of children, possibly causing damage to their reproductive system. The product does not	Recall of the product from end users
A12/01274/22	Hungary	Plastic doll	Cutegal	comply with the REACH Regulation.  Chemical	Recall of the
		with accessories  (Country of Origin: China)	Helper	The doll's head contains an excessive concentration of di- (2-ethylhexyl) phthalate (DEHP) and dibutyl phthalate (DBP) (measured values up to 28% and 0,54% by weight, respectively). These phthalates may harm the health of children, possibly causing damage to their reproductive system. The product does not comply with the REACH Regulation.	product from end users
A12/01275/22	Hungary	Plastic doll set  (Country of Origin: China)		Chemical The product contains an excessive concentration of di-2-ethylhexyl phthalate (DEHP) (measured value: 25% by weight). This phthalate may harm the health of children, possibly causing damage to their reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/01276/22	Czechia	Plastic doll  (Country of Origin: China)	The state of the s	Chemical The plastic material of the head of the doll contains an excessive concentration of di-(2-ethylhexyl) phthalate (DEHP) (measured value up to 4.84 % by weight). This phthalate may harm the health of children, possibly causing damage to the reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market



A12/01281/22	Austria	Puzzle		Choking	Withdrawal of
			13 P. 13	Small parts can easily detach (plastic	the product
		(Country of	6 14.4	buttons). A child may put them in the mouth	from the
		Origin:		and cause chocking. The product does not	market
		China)		comply with the requirements of the Toy	
				Safety Directive nor with the European	
				standard EN 71-1.	
A12/01282/22	Austria	Puzzle	TRAFICO : Nespense GOULE & 101	Choking	Withdrawal of
				Small parts can easily detach (wooden	the product
		(Country of		buttons). A child may put them in the mouth	from the
		Origin:		and cause chocking. The product does not	market
		Czechia)		comply with the requirements of the Toy	
				Safety Directive nor with the European	
				standard EN 71-1.	
A12/01290/22	Belgium	Plastic doll	160	Chemical, Environment	Recall of the
			Merri	The plastic material of the product contains	product from
		(Country of		an excessive amount of organic tin (TBT)	end users
		Origin:		(measured value up to 26 mg/kg). TBT is	
		China)		potentially persistent, bioacumulative and	
				toxic for the environment. The product	
				does not comply with the REACH	
			Artista -	Regulation nor with the European standard	
				EN 71-3.	
A12/01292/22	Norway	Electric	100	Choking	Recall of the
		ride-on		The plastic cover of the charging connector	product from
		tricycle		can easily detach from the toy. A child may	end users
				put it in the mouth and cause chocking.	
		(Country of		The product does not comply with the	
		Origin:		requirements of Toy Safety Directive nor	
		China)		with the European standard EN 71-1.	
A12/01297/22	Austria	Wooden toy		Choking	Marking the
				Small parts (seahorse) can easily detach.	product with
		(Country of		As a consequence, a child may put them in	appropriate
		Origin:		the mouth and cause chocking. The	warnings on
		China)		product does not comply with the	the risks
				requirements of the Toy Safety Directive	
				nor with the European standard EN 71-1.	



A12/01301/22	France	Soft toy	~	Damage to sight, Injuries	Recall of the
				The LEDs of the toy are too powerful and	product from
		(Country of	26-22-	may cause eye damage. The seams come	end users
		Origin:	POULPE RÉVERSIBLE LED	easily apart, making the LEDs and the	
		China)	WILLIAM I	filling accessible. Sharp edges of the LEDs	
			3 664889 001458 >	may cause injury while the ingestion of the	
				filling may cause choking. The product	
				does not comply with the requirements of	
				the Toy Safety Directive, nor with the	
				European standards EN 71-1 and EN	
				62115.	
A12/01302/22	Hungary	Plastic doll	00	Chemical	Withdrawal of
		with		The product contains an excessive	the product
		accessories	STORY ST	concentration of di-2-ethylhexyl phthalate	from the
				(DEHP) (measured value: 31% by weight).	market
		(Country of		This phthalate may harm the health of	
		Origin:		children, causing possible damage to their	
		China)		reproductive system. The product does not	
		,	o co	comply with the REACH Regulation.	
A12/01318/22	The	Baby gym	Newson.	Choking	Withdrawal of
	Netherlan			Small parts can easily detach from the toy.	the product
	ds	(Country of		A child could put them in the mouth and	from the
		Origin:	PIANO HITNESS RACK	cause chocking. The product does not	market
		China)		comply with the requirements of the Toy	
		J.IIIIa)		Safety Directive and the European	
				standard EN 71-1.	
A12/01321/22	Germany	Baby carrier		Injuries	Recall of the
7112/01021/22	Connany	Baby carrier		Due to the insufficient attachment options	product from
		(Country of		on the baby carrier, the support is	end users
		Origin:		inadequate and the baby may slip out of	cha ascis
		China)		the carrier. The baby may fall and suffer	
		Gillia)		from serious injuries. The product does not	
				comply with the requirements of General	
			Entraphysical Action Control of the	Product Safety Directive nor with the	
				•	
A42/04224/22	Llungan	Dettle toward		European standard EN 13209-2	Decall of the
A12/01331/22	Hungary	Rattle toy set	Conte	Choking The rettles can easily break generating	Recall of the
		(County of		The rattles can easily break, generating	product from
		(Country of	F. Co	small parts. A child may put them in the	end users
	Origin			mouth and cause chocking. The product	
		China)		does not comply with the requirements of	
				the Toy Safety Directive nor with the	
				European standard EN 71-1.	1





8



A40/04000/00	0=====	Disease to the		Ob anning!	Mide election (
A12/01336/22	Czechia	Plastic doll		Chemical  The plantic material of the head centains	Withdrawal of
		(O		The plastic material of the head contains	the product
		(Country of		an excessive concentration of bis	from the
		Origin:		(2-ethylhexyl) phthalate (DEHP)	market
		China)		(measured value up to 42.2% by weight).	
			2 0	This phthalate may harm the health of	
				children, causing possible damage to their	
			FASHION GIRLS	reproductive system. The product does not	
			Inches Control of the	comply with the REACH Regulation.	
A12/01337/22	Hungary	Mobile		Choking	Withdrawal of
		musical toy	Charles .	Small parts can easily detach (teddy bear's	the product
			Happy Shaking Bell	eyes) and the stuffing material is easily	from the
		(Country of		accessible. A small child may put these in	market
		Origin:		the mouth and cause chocking. The	
		China)		product does not comply with the	
				requirements of the Toy Safety Directive	
				nor with the relevant European standard	
				EN 71-1.	
A12/01338/22	Hungary	Toy rattle set	@ 01000 Thomas (F)	Choking	Withdrawal of
			B. Tous & D	The rattles can easily break, generating	the product
		(Country of		small parts. A child may put them in the	from the
		Origin:		mouth and cause chocking. The product	market
		China)		does not comply with the requirements of	
		,		the Toy Safety Directive nor with the	
				European standard EN 71.	
A12/01355/22	Czechia	Plastic doll		Chemical	Withdrawal of
1.12,0.300,22	02001110		(3) E 2) (3)	The plastic material of the head of the doll	the product
		(Country of		contains an excessive concentration of	from the
		Origin:	Beauty Beauty	bis(2-ethylhexyl) phthalate (DEHP)	market
		China)		(measured value up to 13.18% by	markot
		Jillia)		weight). This phthalate may harm the health	
				of children, causing possible damage to	
				their reproductive system. The product	
				does not comply with the REACH	
				Regulation.	



Issue no.: 38/22/TCD

A12/01356/22	Czechia	Key ring  (Country of Origin: Unknown)		Chemical The plastic material of the head of the doll contains an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 22.79% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/01358/22	Hungary	(Country of Origin: China)		Choking The rattle can easily break, generating small parts. A child may put them in the mouth and cause chocking. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market
A12/01361/22	Hungary	Activity play mat  (Country of Origin: China)		Choking One of the rattles of the activity play mat can easily break, generating small parts. A child may put them in the mouth and cause chocking. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market
A12/01362/22	Czechia	Plastic doll  (Country of Origin: Unknown)	MERMAID	Chemical The plastic material of the head of the doll contains an excessive concentration of bis (2-ethylhexyl) phthalate (DEHP) (measured value up to 29.8% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market





INFO/00119/22	Germany	Baby blanket		Choking, Entrapment, Strangulation	Recall of the
				A child's fingers may be trapped in loops	product from
		(Country of		because of the threads that have become	end users
		Origin: India)		loose or unraveled from the product. The	
			In the second second second	threads can twist around parts of the body,	
				causing entrapment of the fingers and toes	
				or can get wrapped around the neck of the	
				child, causing strangulation. The child can	
				also put these in the mouth and cause	
				chocking. The product does not comply	
				with the requirements of the General	
				Product Safety Directive (GPSD).	
INFO/00121/22	Austria	Soft toy	An .	Choking	No
				Small parts can easily detach (the eyes). A	enforcement
		(Country of		child may put them in the mouth and cause	action;
		Origin:		chocking. The product does not comply	wholesalers
		China)		with the requirements of the Toy Safety	and retailers
				Directive nor with the European standard	cannot be
				EN 71-1.	found

## Safety Gate: the EU rapid alert system for dangerous non-food products

"Safety Gate", the EU rapid alert system (formerly known as 'RAPEX'), enables the rapid exchange of information between 31 European countries and the European Commission on non- food dangerous products found on the market posing a risk to health and safety of consumers.

A weekly overview of the alerts on those products is published in English for free on https://ec.europa.eu/safety-gate-alerts/screen/webReport#weeklyReports. The measures taken in the notifying country in order to restrict their marketing or use can be ordered by national authorities ("compulsory measures") or be taken directly by producers and distributors ("voluntary measures").

The official contact points of the Member and EFTA-EEA States provide the information published in these weekly overviews. Under the terms of Annex II.10 of the General Product Safety Directive (2001/95/EC) responsibility for the information provided lies with the notifying party. The Commission does not take any responsibility for the accuracy of the information provided.



## Recall Summary – US Toys / Children's Products

CPSC Recall List (Sep 2022)

				PSC Recall List (Sep 2022)
Recall No.	Notifying Country	Product Pho	Hazard/ Risk	Remedy
22-215	USA	UPPAbaby	Amputation Hazard	Consumers should
		All-Terrain	UPPAbaby Recalls RIDGE Jog	ging immediately stop using the
		RIDGE	Strollers Due to Fing	ertip recalled strollers and contact
		Jogging	Amputation Hazard; One Injur	y to UPPAbaby to receive free
		Strollers	Child Reported	replacement brake discs for
				both wheels.
		(Country of	The stroller's rear disc brakes h	nave
		Origin: <b>China</b> )	openings that can cause ampute	ation
			or laceration if a non-occu	pant
			child's fingertip gets caught in	the
			openings while the stroller is in u	use.
22-217	USA	Children's	Burn And Injury Hazards	Consumers should
		HearMuffs	Hearing Lab Technology/L	ucid immediately stop using the
		sound	Audio Recalls Children's Hearl	fluffs recalled HearMuffs and
		compression	Due to Burn and Injury Hazards	from contact Hearing Lab
		ear muffs	Rupturing Alkaline Batteries	Technology/Lucid Audio to
				receive two new replacement
		(Country of	The AAA alkaline batteries inclu	uded AAA batteries free of charge.
		Origin: <b>China</b> )	in the recalled HearMuffs	can
			rupture, posing hearing, proje	ectile
			and/or burn injury.	
22-222	USA	Model Year	Fall Hazard	Consumers should
		2022 Cervélo	Cervélo USA Recalls R5	and immediately stop using the two
		R5 and	Caledonia-5 Bicycles and Cei	vélo recalled models of Cervélo
		Caledonia-5	Replacement Stems Due to	Fall bicycles and Cervélo
		bicycles and	Hazard	replacement stems and
		Cervélo ST31		contact their authorized
		LT	The handlebars on the bicycles	can Cervélo dealer to arrange for a
		replacement	slip in the stem and cause the	rider free repair to replace the
		stems	to lose control, posing a fall haza	ard. faceplate.
		(Country of		
		Origin: <b>China</b> )		





22-226	USA	Miffy First LED		Burn Hazard	Consumers should immediately
		Lights		Mr. Maria Recalls Miffy	stop using the recalled Miffy First
		95		First Lights Due to Burn	Lights and visit
		(Country of Origin:	ABOUT 12 INCHES	Hazard	https://www.mrmaria.com/bluem
		China)	12 N		odule for instructions on how to
			CHES	The recalled lights can	determine which LED module is
				overheat during use,	being recalled. Consumers who
				posing a burn hazard.	purchased the Miffy First LED
				pooning a parit ma_arar	Light at a local store, should
					bring the light to the store to
					have the module replaced free of
					charge. Consumers who
					purchased the light online (or if
					the retailer is no longer in
					business) should take one photo
					of the blue label on the bottom of
					the light and one photo of the
					date embossed underneath the
					right foot of the light and email
					both photos together with their
					shipping address and phone
					number to
					bluemodule@mrmaria.com to
					receive an upgraded LED
					module free of charge.
22-232	USA	Toddleroo Rotating	4 DACK	Choking Hazard	Consumers should immediately
		Cabinet Latches	TODDE ROTATING CABINET	North States Industries	stop using the recalled cabinet
			northistores LATCHES	Recalls Toddleroo Rotating	latches and contact North States
		(Country of Origin:	PREVENTS CHILD FROM OPENING CABINETS	Cabinet Latches Due to	Industries for a refund.
		China)		Choking Hazard	Consumers will be asked to send
			DI DI	onoming risabars	North States Industries photos of
			AA	The latching button can	the front and back of the product,
				dislodge and detach from	and confirm that they have
				the cabinet latches, posing	destroyed or disposed of the
				a choking hazard to young	latches. Upon receipt of the
				children.	photos and confirmation,
					consumers will be issued a
					refund of \$5.50 or the purchase
					price indicated on the receipt if
					available.
	<u> </u>				available.





22 222	LICA	Children's	Violation Of Foderal Load Courters	Congumera shaul-l
22-233	USA	Children's	Violation Of Federal Lead Content	Consumers should
		Bowtie	BE Jewel Accessories Recalls Children's	immediately take
		Hairclips	Hairclips Due to Violation of Federal Lead	the recalled
		(0)	Content Ban	hairclips away from
		(Country of		children and
		Origin:	The crystals on the hairclip contain levels of	contact BE Jewel
		China)	lead that exceed the federal lead content	Accessories for
			ban. Lead is toxic if ingested by young	information on how
			children and can cause adverse health	to properly dispose
			issues.	of the hairclips and
				receive a full
				refund.
22-768	USA	Infant Bath	Drowning Hazard	Consumers should
		Seats	Yuboloo Recalls Infant Bath Seats Due to	immediately stop
			Drowning Hazard; Sold Exclusively on	using the recalled
		(Country of	Amazon.com (Recall Alert)	infant bath seats
		Origin:		and contact
		China)	The bath seats fail to meet the federal	Yuboloo to receive
			safety standard for infant bath seats,	a pre-paid label to
			including requirements for stability and leg	return the infant
			openings, and can tip over while in use,	bath seats. Upon
			posing a drowning hazard to babies.	receipt of the infant
				bath seats,
				consumers will be
				issued a full refund
				for the purchase
				price. Yuboloo is
				notifying all known
				purchasers directly.
22-769	USA	Otter MOMO	Violation Of Federal Lead Content	Consumers should
		Children's	Kolan Recalls Children's Sandals Due to	immediately stop
		Sandals	Violation of Federal Lead Content Ban;	using the recalled
			Sold Exclusively on Amazon.com (Recall	sandals and contact
		(Country of	Alert)	Kolan for
		Origin:		information on how
		China)	The inner layer of the recalled sandals	to properly dispose
			contains levels of lead that exceed the	of the shoes and
			federal lead content ban. Lead is toxic if	receive a full
			ingested by young children and can cause	refund. Kolan is
			adverse health issues.	contacting all
				known purchasers
				directly.



www.stc.group

14

Issue no.: 38/22/TCD

22-772	USA	Cityscape Travel		Fall And Injury Hazards	Consumers should
		Jogger Strollers,	The state of the s	Baby Trend Recalls	immediately stop using the
		Model TJ75B12A	1	Cityscape Travel Jogger	recalled strollers. Baby
				Strollers Due to Fall and	Trend and Amazon are
		(Country of Origin:	0	Injury Hazards (Recall Alert)	contacting all purchasers
		China)			directly with instructions for
				The parking brake on the	how to return the strollers at
				strollers can fail, posing fall	no cost in exchange for
				and injury hazards to	either a \$175 e-voucher for
				children.	use at Baby Trend's online
					store or a full refund. If you
					do not receive
					communication from either
					Baby Trend or Amazon,
					contact Baby Trend.

\* Source: www.recalls.gov

### **CPSC**

The United States Consumer Product Safety Commission (CPSC) is an independent agency of the United States government. To provide better service in alerting the American people to unsafe, hazardous or defective products, a "one stop shop" for U.S. Government recalls, www.recalls.gov, has been created. Publics can report unsafe products to CPSC by using the platform.

The recall list is divided into seven categories: Consumer Products, Motor Vehicles, Boats, Food, Medicine, Cosmetics and Environmental Products. Generally, the recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall program. Fast Track recalls are initiated by firms who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without

## Recall Summary - Australia Toys / Children's Products

ACCC Recall List (Sep 2022)

	ACCC Recall List (Sep 2)				
PRA No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
2022/19548	Australia	Yatsal		Risk of Serious Injury	Consumers should stop
		Distributors		The product does not comply with	using the product and
		Pty Ltd -		the mandatory safety standard for	store it out of the reach
		Shoot &		projectile toys that warns	of children. Consumers
		Catch Set - 4		consumers that the toy should not	should return the
		piece		be aimed at the eyes or face.	product to the place of
					purchase for a full
				What are the hazards?	refund.
				If the product is aimed at the eyes	
				or face during use, there is a risk of	
				serious injury.	
2022/195	Australia	LED Light Up	W.C.	Choking Hazard	Consumers should
52		Party Wands		The product contains button	immediately stop using
		7 different		batteries which are not adequately	the product and keep it
		flashing		secured.	out of reach of children.
		modes	-		Consumers can contact
				If young children gain access to	Lux Glow & Toy Co by
				button batteries and ingest them,	email:
				they are likely to suffer severe	luxglowtoyco@gmail.c
				internal burn injuries, which can	om to receive a
				result in serious injury or death.	replacement product to
				Button batteries also pose a	the same value or a
				choking hazard to young children.	refund.
2022/195	Australia	Mini LED light		Choking Hazard	Consumers should
53		up balloon		The product contains button	immediately stop using
		wand		batteries which are not adequately	the product and keep it
				secured.	out of reach of children.
					Consumers can contact
				If young children gain access to	Lux Glow & Toy Co by
				button batteries and ingest them,	email:
				they are likely to suffer severe	luxglowtoyco@gmail.c
				internal burn injuries, which can	om to receive a
				result in serious injury or death.	replacement product to
				Button batteries also pose a	the same value or a
				choking hazard to young children.	refund.



Headquarters - The Hong Kong Standards and Testing Centre Ltd. 👂 10 Dai Wang Street, Tai Po Industrial Estate, Tai Po, N.T., Hong Kong



2022/19554	Australia	Wearable		Choking Hazard	Consumers should
2022/10001	radirana	multi-color flower	S. Company	The product contains button	immediately stop using
		crown with LED		batteries which are not	the product and keep it
		lights		adequately secured.	out of reach of children.
		ngino		adoquatory occurred.	Consumers can contact
				If young children gain access to	Lux Glow & Toy Co by
				button batteries and ingest them,	email:
				they are likely to suffer severe	luxglowtoyco@gmail.co
				internal burn injuries, which can	m to receive a
				•	
				result in serious injury or death.	replacement product to
				Button batteries also pose a	the same value or a
				choking hazard to young	refund.
0000/40550	A			children.	
2022/19556	Australia	ELC Little Senses		Choking Hazard	Consumers should
		Lights & Sounds		The product's red sorting cube,	immediately remove the
		Shape Sorter		which has a clear top, may	red cube from the
				break, releasing a small ball.	product and safely
		Item Code 145795			dispose of this part only.
				The product may not comply with	Consumers should then
		A sensory shape		the size requirements of the	contact Modern Brands
		sorters with six		mandatory standard for toys for	to request a replacement
		different coloured		children up to and including 36	cube, free of charge. To
		and textured		months of age.	order a replacement
		shapes, for young			cube please email
		children from 6		If released the small ball may	elcshapesorter@modern
		months to 36		pose a choking hazard for young	brands.com.au
		months.		children, which can lead to	
				severe injury or death.	
2022/19577	Australia	Target Australia		Choking Hazard	Consumers should
		Pty Ltd — Early		The product's red sorting cube,	immediately remove the
		Learning Centre		which has a clear top, may	red cube from the
		Little Senses		break, releasing a small ball.	product and safely
		Lights & Sounds		The product may not comply with	dispose of this part only.
		Shape Sorter		the size requirements of the	
				mandatory standard for toys for	
				children up to and including 36	
				months of age.	
				If released the small ball may	
				pose a choking hazard for young	
				children, which can lead to	
				severe injury or death.	







## **Australian Product Safety System**

The Australian product safety system is to maximize the safety of good by the cooperation of consumers, businesses and agencies. This policy sets out the principles adopted by the Australian Competition and Consumer Commission (ACCC) for prioritizing and addressing product safety risks.

Under the Australian Consumer Law, a responsible Minister can order a compulsory recall when there are hazards on the products. A voluntary recall could be conducted to remove the product from the marketplace when the suppliers become aware of unsafe or defective products.

The ACCC administers a national recalls system for recalls of specific and general consumer products, and publishes all product recalls on the website <a href="https://www.productsafety.gov.au/recalls">https://www.productsafety.gov.au/recalls</a>.





Issue no.: 38/22/TCD

STC (Hong Kong Standards and Testing Centre) is a not-for-profit, independent testing, inspection and certification organization. With a global network of ISO/IEC 17025 accredited testing laboratories and nearly 60 years of experience in consumer product testing, we can meet your conformity assessment needs with highly efficient and reliable service. Our testing scope and capabilities related to toys and children's products include but not limited to:

## **EU Requirements**

- EN 71
- Phthalates (EC) no. 1907/2006
- Nickel Release (EC) no. 1907/2006
- Total Cadmium (EEC) no. 91/338
- Lead in Jewellery product (EC) no. 836/2012
- Azo-dye (EC) no. 1907/2006
- Bisphenol-A (2014/81/EU)
- DMF (Dimethyl fumarate) (EU) no. 2011/135
- Flame retardants TCEP, TCPP, TDCP (2014/79/EU)
- Package Waste Directive (94/62/EC)

## **US & Canada Requirements**

- ASTM F963
- **CPSIA**
- California Proposition 65
- 16 CFR 1501
- ASTM F2923 (Children's jewellery)
- ASTM F2999 (Adult's jewellery)
- US Toxic in Packaging Clearinghouse (TPCH)
- CCPSA Toys Regulations (SOR/2011-17)

## **Japan Requirements**

- Japan Toy Safety Standard (ST)
- Japan Food Sanitation Law (JFSL)

### **Australia Requirements**

- AS/NZS 8124
- Consumer Protection Notice No. 6 of 2010 DEHP

### FOR MORE DETAILS, PLEASE CONTACT US:

Hong Kong: <a href="https://ht Dongguan: dgtcd@stc.group Shanghai: shtcd@stc.group Changzhou: czstc@stc.group Vietnam: vnstc@stc.group Japan: jpo@stc.group

U.S.A.: <u>usenquiry@stc.group</u> Germany: grstc@stc.group





