












Recall Summary – European Toys





Published: 03/01/2019





RAPEX notification (Dec 2018)





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A12/1804/18	Spain	Musical toy Country of origin: China		Choking When pushing the yellow button of the guitar it may remain stuck, leaving a hole through which parts of the electronic components inside the toy are accessible. The parts may be detached, generating small parts. A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European Standard EN 71-1.	Import rejected at border
A12/1805/18	Spain	Kitchen play set Country of origin: China		Choking Various components of the set (transparent lids, lid of the teapot, jug and plates) can detach and generate small parts. A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European Standard EN 71-1.	Import rejected at border
A12/1806/18	Poland	Plastic doll Country of origin: China		Chemical The plastic material of the doll contains 2-ethylhexyl phthalate (DEHP) (measured value: 1.7% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. The product does not comply with the REACH Regulation.	Destruction of the product (By: Importer)





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A12/1808/18	Spain	Toy xylophone Country of origin: China		Choking The bars of the xylophone and the pins holding them onto the sound box easily come off. A child could put either of them in the mouth and choke on them. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Import rejected at border
A12/1809/18	Spain	Squeezable toy Country of origin: China		Choking Small parts can easily be detached from the toy. A small child may put one of them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Import rejected at border
A12/1811/18	Spain	Baby doll Country of origin: China		Choking The decorative flower on the clothing of the baby doll can detach, and parts of the sound box under the clothing can break, generating small parts. A child could put the small parts in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Import rejected at border
A12/1823/18	The Netherlands	Educational toy Country of origin: The Netherlands		Choking The wooden beads can easily break into small pieces. A child could put them in the mouth and choke on them. The product does not comply with the requirements of the Toy Safety Directive and with the relevant European standard EN 71-1.	Recall of the product from end users; Warning consumers of the risks; Withdrawal of the product from the market





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A12/1824/18	Spain	Squeezable toy Country of origin: China		Choking Small parts can easily be detached from the toy. A small child may put one of them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Import rejected at border
A12/1829/18	Lithuania	Wind-up toy Country of origin: China		Choking The toy can break and small parts may detach from it. A child may put a small part into mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European Standard 71-1.	Ban on the marketing of the product and any accompanying measures
A12/1830/18	Hungary	Plush bear in mug Country of origin: China		Choking The eyes, nose and a suction cup can detach from the toy bear and the fibrous stuffing material is accessible. A small child may put the small parts or the stuffing material in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Recall of the product from end users; Withdrawal of the product from the market
A12/1838/18	Spain	Shooting play set Country of origin: Canada		Choking The suction cups can easily detach from the projectiles. If a child puts the projectile in the mouth, the suction cup may detach and obstruct the airways. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Import rejected at border





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A12/1839/18	Lithuania	Wind-up toy Country of origin: China		Choking The operating handle, hands on the side and rear wheels of the toy can detach and the toy might break, generating small parts. A child may put the small parts into the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European Standard EN 71-1.	Ban on the marketing of the product and any accompanying measures
A11/0092/18	Hungary	Tricycle Country of origin: Poland		Entrapment, Injuries There are accessible gaps between the mudguard and the front wheel of the tricycle. A child could put the fingers in them and get trapped. The tricycle is not stable enough. When using it on uneven ground, it could easily overturn causing injuries to the child. The product does not comply with the requirements of the Toy Safety Directive and with the relevant European standard EN 71-1.	Withdrawal of the product from the market
A11/0096/18	Hungary	Ride-on toy Country of origin: Czech Republic		Entrapment There are accessible gaps between moving parts in the body and digger arm of the product. Children's fingers can become trapped between these moving elements, causing injuries. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Withdrawal of the product from the market
A12/1842/18	Spain	Flashing bracelet Country of origin: China		Choking The fasteners of the bracelet easily come loose, generating small parts. A child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Import rejected at border




Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A12/1843/18	Spain	Plastic doll with accessories Country of origin: China		Chemical The plastic material of the doll's shoes contains 2-ethylhexyl phthalate (DEHP) (measured value: 4.35% by weight) and di-butyl phthalate (DBP) (measured value: 0.58% by weight). These phthalates may harm the health of children, causing possible damage to the reproductive system. The product does not comply with the REACH Regulation.	Import rejected at border
A12/1851/18	Italy	Plastic doll Country of origin: China		Chemical The plastic material of the doll's head contains 2-ethylhexyl phthalate (DEHP) (measured value: 26.9% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. The product does not comply with the REACH Regulation.	Ban on the marketing of the product and any accompanying measures
A12/1852/18	France	Soft toy Country of origin: China		Choking The nose may detach from the soft toy, generating a small part, and the fibrous stuffing material is accessible due to the weakness of certain seams. A small child may put the small part or the fibrous stuffing material in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European Standard EN 71-1.	Recall of the product from end users
A12/1860/18	Hungary	Soft toy Country of origin: China		Choking The eyes and the suction cup on the product can easily detach. In addition, the fibrous stuffing material of the toy is easily accessible due to the weakness of certain seams. A small child may put the detached elements or the stuffing material in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Withdrawal of the product from the market




Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A12/1864/18	Hungary	Musical toy Country of origin: China		Damage to hearing The sound pressure level of the toy is too high. It could cause damage to hearing. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Recall of the product from end users; Withdrawal of the product from the market
A12/1865/18	Poland	Rattle chain Country of origin: China		Choking The toy's string breaks easily, releasing small parts. A small child may put the small parts in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Withdrawal of the product from the market (By: Importer)
A12/1867/18	France	Toy set Country of origin: China		Choking The nose of the plush toy can detach, generating a small part. A small child may put it in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European Standard EN 71-1.	Recall of the product from end users
A12/1869/18	United Kingdom	Modelling clay/slime Country of origin: China		Chemical The migration of boron from the toy slime is too high (measured value up to 1,450 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3.	Import rejected at border





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A12/1873/18	France	Fancy-dress mask Country of origin: China		Burns The fancy-dress mask is highly flammable and does not self-extinguish in the event that it is ignited by a flame. If it catches fire, the child could suffer burns. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-2.	Recall of the product from end users
A12/1877/18	Luxembourg	Squeezable toy Country of origin: Unknown		Choking Small parts can easily be detached from the toy. A small child may put one of them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Ban on the marketing of the product and any accompanying measures; Recall of the product from end users; Temporary ban on the supply, offer to supply and display of the product
A12/1881/18	Germany	Plastic bags Country of origin: China		Chemical The plastic of the product contains diisobutyl phthalate (DIBP) (measured value: 17% by weight) and dibutyl phthalate (DBP) (measured value: 1% by weight). These phthalates may harm the health of children, causing possible damage to the reproductive system. The product does not comply with the REACH Regulation.	Ban on the marketing of the product and any accompanying measures
A12/1889/18	Cyprus	Plastic electric gun Country of origin: China		Chemical The battery compartment can be easily opened by removing the cover and the button batteries are accessible. A child may put them in the mouth, causing damage to the gastrointestinal tract. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 62115.	Withdrawal of the product from the market





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A12/1891/18	Cyprus	Police set Country of origin: China		Choking The suction cups can detach from the projectiles. If a child puts the projectile in the mouth and the suction cup detaches, it could obstruct the airways. The product does not comply with the requirements of the Toy Safety Directive or the relevant European standard EN 71-1.	Withdrawal of the product from the market
A12/1895/18	Sweden	Shark biting game Country of origin: China		Environment Solder in four different places in the toy contain cadmium and lead in concentrations above the limit values. Lead and cadmium pose a risk to the environment. The product does not comply with the Commission Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Withdrawal of the product from the market
A12/1897/18	Sweden	LED Toy Country of origin: China		Environment Solder in four different places contain lead and cadmium in concentrations above the limit values. Lead and cadmium pose a risk to the environment. The product does not comply with the Commission Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Withdrawal of the product from the market
A12/1898/18	Sweden	Tamagotchi Country of origin: China		Environment Solder in three different places on the toy contain lead and cadmium in concentrations above the limit values. Lead and cadmium pose a risk to the environment. The product does not comply with the Commission Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Withdrawal of the product from the market

Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A12/1899/18	Sweden	Finger Monkey Country of origin: China		Environment Solder in four different places in the toy contain lead in concentrations above the limit value. Lead poses a risk to the environment. The product does not comply with the Commission Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Withdrawal of the product from the market (By: Importer)
A12/1902/18	United Kingdom	Modelling clay Country of origin: China		Chemical The migration of boron from the clay is too high (measured value up to 6,799 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3.	Import rejected at border
A11/0098/18	Hungary	Ride-on toy Country of origin: Hungary		Entrapment, Injuries There are accessible gaps between the folding seat and the frame of the vehicle. The fingers can be trapped between the gaps, causing injuries. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Withdrawal of the product from the market
A12/1903/18	Cyprus	Toy Tank Country of origin: China		Chemical, Damage to sight The battery compartment is easily accessible and the button batteries could be swallowed. A child might put them in the mouth and swallow them, causing damage to the gastrointestinal tract. The laser beam in the tank's turret is too powerful. Direct viewing of the laser beam could cause damage to sight. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 62115.	Withdrawal of the product from the market

Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A12/1906/18	Poland	Plastic toy guitar Country of origin: China		Chemical, Strangulation The strap attached to the toy does not have a quick release mechanism and the battery compartment can easily be opened without the use of any tools so the batteries inside are accessible. If the strap is worn around the neck, it could form a loop and become trapped. The absence of a quick release mechanism, enabling the child to detach the strap, can lead to strangulation. The child may put the batteries in the mouth and swallow them, causing damage to the gastrointestinal tract. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standards EN 62115 and EN 71-1.	Withdrawal of the product from the market (By: Importer)
A12/1915/18	Bulgaria	Key-ring Country of origin: Unknown		Choking Due to its characteristic form, colour, appearance, volume and size, it is likely that consumers will confuse the product with foodstuff and, in consequence, place it in the mouth. Parts of the keyring can easily detach. A small child might choke on the loose parts. The product does not comply with the requirements of the Food Imitating Products Directive.	Withdrawal of the product from the market
A12/1923/18	Croatia	Plastic doll with accessories Country of origin: China		Chemical The plastic material of the doll contains bis (2-ethylhexyl) phthalate (DEHP), di-isononyl phthalate (DINP) and di-butyl phthalate (DBP) (measured values: 2.8%, 0.7% and 0.3% in weight, respectively). These phthalates may harm the health of children, causing possible damage to the reproductive system and/or the liver. The product does not comply with the REACH Regulation.	Import rejected at border

Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A12/1940/18	Sweden	Baby doll Country of origin: China		Environment The PVC plastic of the packaging contains cadmium (measured value up to 0.038%). Cadmium is toxic to the environment and can also cause osteoporosis, kidney damage and cancer. The product does not comply with the requirements of the Directive on packaging and packaging waste.	Withdrawal of the product from the market
A12/1941/18	Sweden	Bouncing ball Country of origin: China		Chemical, Environment The red plastic in the bouncing ball contains short-chain chlorinated paraffins (SCCPs) (measured value up to 0.215%. In addition, the plastic contains diisobutyl phthalate (measured value up to 28%). SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations and bioaccumulate in wildlife and humans, posing a risk to human health and the environment. Diisobutyl phthalate may damage the unborn child and is suspected of damaging fertility. Also, the substance may be fatal if swallowed and enters airways, is very toxic to aquatic life with long lasting effects and is very toxic to aquatic life. The product does not comply with the Regulation on persistent organic pollutants (POP Regulation) and with the requirements of the Toy Safety Directive.	Withdrawal of the product from the market
A12/1947/18	France	Toy Slime Country of origin: China		Chemical The migration of boron from the toy slime is too high (measured value: up to 557 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3.	Recall of the product from end users; Withdrawal of the product from the market (By: Importer)

Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A12/1948/18	Slovakia	Plastic doll Country of origin: China		Chemical The plastic material of the doll's head contains bis (2-ethylhexyl) phthalate (DEHP) (measured value: 26.5% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. The product does not comply with the REACH Regulation.	Recall of the product from end users; Withdrawal of the product from the market
A12/1949/18	Slovakia	Plastic doll Country of origin: China		Chemical The plastic material of the doll's head contains bis (2-ethylhexyl) phthalate (DEHP) (measured value: 30.5% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. The product does not comply with the REACH Regulation.	Recall of the product from end users; Withdrawal of the product from the market
A12/1950/18	Slovakia	Plastic doll Country of origin: China		Chemical The plastic material of the doll's head contains bis (2-ethylhexyl) phthalate (DEHP) and di-isononyl phthalate (DINP) (measured values: 15% and 14% by weight). These phthalates may harm the health of children, causing possible damage to the reproductive system or the liver. The product does not comply with the REACH Regulation.	Recall of the product from end users; Withdrawal of the product from the market
A12/1951/18	Slovakia	Plastic doll Country of origin: China		Chemical The plastic material of the doll's head contains bis (2-ethylhexyl) phthalate (DEHP) (measured value: 32.5% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. The product does not comply with the REACH Regulation.	Recall of the product from end users; Withdrawal of the product from the market
A12/1952/18	Slovakia	Plastic doll Country of origin: China		Chemical The plastic material of the doll's head contains bis (2-ethylhexyl) phthalate (DEHP) (measured value: 19% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. The product does not comply with the REACH Regulation.	Recall of the product from end users; Withdrawal of the product from the market

Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A12/1953/18	Slovakia	Plastic doll with accessories Country of origin: China		Chemical The plastic material of the doll contains di-butyl phthalate (DBP), bis (2-ethylhexyl) phthalate (DEHP) and di-isononyl phthalate (DINP) (measured values: 0.8%, 0.6% and 0.4% in weight, respectively). These phthalates may harm the health of children, causing possible damage to the reproductive system and/or the liver. The product does not comply with the REACH Regulation.	Recall of the product from end users; Withdrawal of the product from the market
A12/1956/18	Slovakia	Soft textile doll Country of origin: China		Chemical, Choking The battery compartment can easily be opened without use of any tools leaving the contained button cell batteries accessible. A child may put these in the mouth, which could cause damage to the child's gastrointestinal tract. They may also cause choking if swallowed by a small child. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 62115.	Recall of the product from end users; Withdrawal of the product from the market
A12/1958/18	Slovakia	Soft toy Country of origin: China		Choking The eyes of the rabbit easily detach. A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Recall of the product from end users; Withdrawal of the product from the market
A12/1970/18	Estonia	Bath toy set Country of origin: Poland		Choking The small parts can easily detach from the toys. A small child could put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive or the relevant European standard EN 71-1.	Recall of the product from end users

RAPEX – Rapid Exchange of Information System




The Rapid Alert System enables the rapid exchange of information (RAPEX) between 31 European countries and the European Commission on non- food dangerous products found on the market posing a risk to health and safety of consumers.

A weekly overview of the alerts on those products is published in English for free on <http://ec.europa.eu/rapex>. The measures taken in the notifying country in order to restrict their marketing or use can be ordered by national authorities ("compulsory measures") or be taken directly by producers and distributors ("voluntary measures").

The official contact points of the Member and EFTA-EEA States provide the information published in these weekly overviews. Under the terms of Annex II.10 of the General Product Safety Directive (2001/95/EC) responsibility for the information provided lies with the notifying party. The Commission does not take any responsibility for the accuracy of the information provided.

Recall Summary – US Toys / Children’s Products

CPSC Recall List (Dec 2018)

Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
19-044	U.S.	Kids infant and toddler hoodies Country of origin: China		Choking The zipper slider can detach from the hoodie, posing a choking hazard to young children.	Consumers should immediately take the recalled hoodies away from children, stop using them and return them to the importer for a full refund.
19-053	U.S.	Infant snowsuits Country of origin: China		Choking The metal snaps on the snowsuit can detach, posing a choking hazard to young children.	Consumers should immediately take the recalled snowsuits away from children, stop using them and return them to the importer for a full refund. Online customers will receive return instructions by email from the importer on obtaining a full refund.
19-054	U.S.	Soft Books Country of origin: China		Choking A metal grommet used to attach a fabric flap to a page in the book can detach, posing a choking hazard to young children.	Consumers should immediately take the recalled books away from children, stop using them and return it to the place of purchase or contact the importer for a full refund.

*Source: www.recalls.gov

CPSC





The United States Consumer Product Safety Commission (CPSC) is an independent agency of the United States government. To provide better service in alerting the American people to unsafe, hazardous or defective products, a “one stop shop” for U.S. Government recalls, www.recalls.gov, has been created. Publics can report unsafe products to CPSC by using the platform.

The recall list is divided into seven categories: Consumer Products, Motor Vehicles, Boats, Food, Medicine, Cosmetics and Environmental Products. Generally, the recall was conducted, voluntarily by the company, under CPSC’s Fast Track Recall program. Fast Track recalls are initiated by firms who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.



The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kind and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

Recall Summary – Australia Toys / Children’s Products

ACCC Recall List (Dec 2018)

PRA No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
2018/17192	Australia	Sand and Water Table		Choking Small part on watering can nozzle may detach from the spout. Detached small part may pose a choking hazard to young children.	Stop using the product and return the product to the supplier for a full refund.
2018/17193	Australia	Toy Trucks		Choking Products do not comply with the mandatory standard 'Consumer Protection Notice No.14 - Consumer Product Safety Standard: Toys for children up to and including 36 months of age'. The products may liberate small parts. Small parts pose a potential choking or ingestion hazard for small children.	Consumers should immediately remove the toy(s) from the child and return them to the retailer where they were purchased for a full refund.
2018/17195	Australia	Tricycle		Injuries The product in its 12-month age mode has key features of a stroller, but does not have the safety features required by the mandatory safety standard for strollers. When used as a stroller to transport children in its 12-month age mode, the product may cause injury to a child if the product rolls in an uncontrolled manner or if a child falls out of the product.	Consumers should not use the product as a stroller to transport children. Consumers should remove and discard the high headrest and shoulder straps on the tricycle and follow the supplier’s updated guidance that children younger than 18 months of age should not use the modified product. If required, contact the supplier to assist with the modification.
2018/17218	Australia	Beach Ball		Choking The product contains small beads and pellets, which may be inhaled during inflation or deflation. Inhaling the beads or pellets can lead to choking, internal injuries and even death.	Consumers should return the item to the retailer where they purchased it from for a full refund.

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kind and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

PRA No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
2018/17219	Australia	Pool Noodle		Choking The product contains small beads and pellets, which may be inhaled during inflation or deflation. Inhaling the beads or pellets can lead to choking, internal injuries and even death.	Consumers should return the item to the retailer where they purchased it from for a full refund.
2018/17228	Australia	Plush toy		Choking The reindeer's plastic nose may detach from the plush toy. Small parts can be a choking hazard for infants and young children.	Consumers should dispose of the reindeer immediately.

Australian Product Safety System

The Australian product safety system is to maximize the safety of good by the cooperation of consumers, businesses and agencies. This policy sets out the principles adopted by the Australian Competition and Consumer Commission (ACCC) for prioritizing and addressing product safety risks.

Under the Australian Consumer Law, a responsible Minister can order a compulsory recall when there are hazards on the products. A voluntary recall could be conducted to remove the product from the marketplace when the suppliers become aware of unsafe or defective products.

The ACCC administers a national recalls system for recalls of specific and general consumer products, and publishes all product recalls on the website <https://www.productsafety.gov.au/recalls>.

STC (The Hong Kong Standards and Testing Centre) is a not-for-profit, independent testing, inspection and certification organization. With a global network of ISO/IEC 17025 accredited testing laboratories and over 50 years of experience in consumer product testing, we can meet your conformity assessment needs with highly efficient and reliable service. Our testing scope and capabilities related to toys and children's products include but not limited to:

EU Requirements

- EN 71
- Phthalates (EC) no. 1907/2006
- Nickel Release (EC) no. 1907/2006
- Total Cadmium (EEC) no. 91/338
- Lead in Jewellery product (EC) no. 836/2012
- Azo-dye (EC) no. 1907/2006
- Bisphenol-A (2014/81/EU)
- DMF (Dimethylfumarate) (EU) no. 2011/135
- Flame retardants TCEP, TCPP, TDCP (2014/79/EU)
- Package Waste Directive (94/62/EC)

US & Canada Requirements

- ASTM F963
- CPSIA
- California Proposition 65
- 16 CFR 1501
- ASTM F2923 (Children's jewellery)
- ASTM F2999 (Adult's jewellery)
- US Toxic in Packaging Clearinghouse (TPCH)
- CCPSA - Toys Regulations (SOR/2011-17)

Japan Requirements

- Japan Toy Safety Standard (ST)
- Japan Food Sanitation Law (JFSL)

Australia Requirements

- AS/NZS 8124
- Consumer Protection Notice No. 6 of 2010 - DEHP

For more information, please contact our Toys and Children's Products Department.

Hong Kong: hktcd@stc.group

Japan: jpo@stc.group

Dongguan: dgtcd@stc.group

USA: usstc@stc.group

Shanghai: shtcd@stc.group

Germany: info@pkm.eu.com

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kind and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.