












Recall Summary – European Toys





Published: 08/02/2019





RAPEX notification (Jan 2019)




Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A12/1973/18	France	Building blocks Country of origin: Unknown		Choking The product contains small loose parts. A small child could put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Recall of the product from end users; Withdrawal of the product from the market (By: Importer)
A12/1974/18	France	Plush pyjama bag Country of origin: China		Choking The zipper can detach easily from the toy, generating a small part. A small child may put it in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Recall of the product from end users (By: Importer)
A12/1981/18	Spain	Tea set Country of origin: China		Injuries The teapot and its lid can easily break leaving sharp edges accessible. A small child could get hurt with them. The product does not comply with the requirements of the Toy Safety Directive and the relevant European Standard EN 71-1.	Import rejected at border






Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A12/1984/18	France	Toy Slime Country of origin: China		<p>Chemical, Injuries</p> <p>The migration of barium, lead and boron from the slime is too high (measured values: 896mg/kg, 24.3 mg/kg and 589 mg/kg respectively) and it contains a small magnet with a high magnetic flux. Barium is potentially toxic if ingested. Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system and lead is harmful for human health and can cause developmental neurotoxicity. If a child swallows this small magnet and other metallic objects, they could attract one another causing intestinal blockage or perforation.</p> <p>The product does not comply with the requirements of the Toy Safety Directive and with the relevant European standards EN 71-1 and EN 71-3.</p>	Recall of the product from end users
A12/1985/18	Spain	Baby doll with accessories Country of origin: China		<p>Choking</p> <p>The soother and the bottle can break, generating small parts. A small child may put them in the mouth and choke.</p> <p>The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.</p>	Import rejected at border
A12/1988/18	Slovakia	Soft toy Country of origin: Unknown		<p>Choking</p> <p>The eyes, the nose and the suction cup can easily be detached from the toy and generate small parts. A small child may put these small parts in the mouth and choke.</p> <p>The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.</p>	Recall of the product from end users; Withdrawal of the product from the market
A12/1989/18	Slovakia	Soft toy Country of origin: China		<p>Choking</p> <p>The suction cup can easily detach. A child may put it in the mouth, which could result in an obstruction of the airways.</p> <p>The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.</p>	Recall of the product from end users; Withdrawal of the product from the market



Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A12/1991/18	Spain	Beach toy set Country of origin: China		Injuries The octopus and the boat inside the toy set can have dangerous sharp points. These elements become accessible to children and could cause injury. The product does not comply with the requirements of the Toy Safety Directive and the relevant European Standard EN 71-1.	Import rejected at border
A12/1998/18	Hungary	Soft toy Country of origin: China		Choking The nose can easily detach from the soft toys, generating small parts. A small child may put the detached element in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European Standard EN 71.	Recall of the product from end users; Withdrawal of the product from the market
A12/2003/18	Slovakia	Soft toy Country of origin: Unknown		Choking The eyes may easily be detached from the toy, generating small parts. A small child may put these small parts in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European Standard EN 71-1.	Recall of the product from end users; Withdrawal of the product from the market
A12/2004/18	France	Teething ring Country of origin: China		Choking The beads may become detached, generating small parts. A child could put a bead in the mouth and choke.	Recall of the product from end users




Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A12/2005/18	France	Outdoor toy – castle with slide Country of origin: Turkey		Chemical The paint used for the railings contains a high amount of lead (measured value: 698.2 mg/kg). Exposure to lead is harmful for human health and can cause developmental neurotoxicity. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3.	Recall of the product from end users
A12/0005/19	Poland	Push/pull – along toy Country of origin: China		Choking, Strangulation A small part (plastic handle connector) may detach from the toy and the cord attached to the toy is too long. A child may put the small part in the mouth and choke on it. The cord can wrap around child's neck without the child being able to remove it, causing strangulation. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Withdrawal of the product from the market
A12/0019/19	Slovenia	Wooden swing/ladder Country of origin: Czech Republic		Injuries, Strangulation There are openings between the rungs of the ladder. While climbing up, a child may slip through the opening and remain stuck with the head, leading to strangulation or injuries. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standards EN 71-1 and EN 71-8.	Withdrawal of the product from the market
A12/0024/19	The Netherlands	Plastic doll inside cupcake Country of origin: China		Chemical The plastic material of the toy contains di-butyl phthalate (DBP) (measured value: 24% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A12/0025/19	The Netherlands	Plastic dog Country of origin: China		Chemical The plastic material of the product contains di-(2-ethylhexyl) phthalate (DEHP) (measured value: 18% by weight) and diisobutyl phthalate (DIBP) (22% by weight). These phthalates may harm the health of children causing possible damage to the reproductive system. The product does not comply with the REACH Regulation.	Destruction of the product
A12/0032/19	Poland	Plastic toy Country of origin: China		Choking, Damage to hearing Small parts can be detached from the toy. A small child may put a small part in the mouth and choke. Furthermore, the sound level produced by the toy is too high which could lead to damage to hearing. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Withdrawal of the product from the market (By: Importer)
A12/0036/19	Poland	Set of plastic rattles Country of origin: China		Choking The toy can break easily generating small parts. A child may break the toy, swallow small parts which may cause choking. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Withdrawal of the product from the market (By: Importer)
A12/0037/19	Poland	Doctor play set Country of origin: China		Chemical The plastic material of one of the elements of the set (i.e. the stethoscope) contains 2-ethylhexyl phthalate (DEHP) (measured value: 20.2% by weight) and dibutyl phthalate (DBP) (measured value: 13.2% by weight). These phthalates may harm the health of children, causing possible damage to the reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market (By: Importer)





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A12/0040/19	Poland	Doctor play set Country of origin: China		Chemical The plastic material of one of the elements from the set (the stethoscope) contains 2-ethylhexyl phthalate (DEHP) (measured value: 24,9% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system and/or liver. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market (By: Importer)
A12/0042/19	Finland	Plastic bouncing ball Country of origin: China		Chemical, Choking, Suffocation The plastic material of the product contains di-(2-ethylhexyl) phthalate (DEHP) (measured value: 3% by weight) and diisobutyl phthalate (DIBP) (36% by weight). The valve plug can easily detach and the plastic bag of the packaging is too thin. These phthalates may harm the health of children causing possible damage to the reproductive system. The valve plug may become detached while inflating the toy and obstruct the airways. If a child plays with the packaging, the plastic can cover the mouth and nose, causing the child to suffocate. The product does not comply with the REACH Regulation, the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Import rejected at border
A12/2013/18	Spain	Plastic rattle toy Country of origin: China		Choking, Injuries The ear of the red bear protrudes. If a child puts the toy in the mouth and falls face down, the protruding ball could obstruct the airways, causing choking and injuries around the pharynx or trachea area. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Import rejected at border






Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A12/2014/18	Spain	Activity play mat Country of origin: China		Playmat The star, the lion and the giraffe attached to the arch can easily detach, generating into small parts. A small child can put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European Standard EN 71-1.	Import rejected at border
A12/2016/18	Austria	Toy Slime Country of origin: China	 	Injuries The slime contains a small magnet with a high magnetic flux. If a child swallows the small magnet and other metallic objects, they could attract one another causing intestinal blockage or perforation. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Withdrawal of the product from the market (By: Importer)
A12/2020/18	France	Fancy-dress mask Country of origin: China		Chemical The plastic material of the mask contains 2-ethylhexyl phthalate (DEHP) (measured value: 29.5% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. The product does not comply with the REACH Regulation.	Recall of the product from end users (By: Importer)
A12/2024/18	Slovakia	Soft toy Country of origin: China		Choking The suction cup can easily detach from the toy. A child may put it in the mouth and choke on it. The toy does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Recall of the product from end users; Withdrawal of the product from the market





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A11/0101/18	Slovakia	Soft toy Country of origin: China		<p>Choking The fibrous stuffing material of the toy is easily accessible due to the weakness of certain seams. Young children may put it in the mouth, which could result in an obstruction of the airways.</p> <p>The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.</p>	Recall of the product from end users; Withdrawal of the product from the market
A12/0048/19	Finland	Bouncy toy Country of origin: China		<p>Chemical, Choking, Suffocation The product contains 2-ethylhexyl phthalate (DEHP) (measured value: 3% by weight) and Dibutylphthalate (DBP) (measured value: 16% by weight). A small part (valve plug) can be easily detached from the toy with fingers or teeth. The plastic bag of the packaging is too thin. Phthalates may harm the health of children, causing possible damage to the reproductive system.</p> <p>A child could put the small part (valve plug) in the mouth and choke on it.</p> <p>If a child plays with the packaging, the plastic bag can cover the mouth and nose, causing the child to suffocate.</p> <p>The product does not comply with the REACH Regulation, with the requirements of the Toy Safety Directive and the relevant European Standard EN 71-1.</p>	Import rejected at border





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A12/0049/19	Finland	Bouncy toy Country of origin: China		<p>Chemical, Choking, Injuries, Suffocation</p> <p>The plastic material of the product contains di-(2-ethylhexyl) phthalate (DEHP) (measured value 0.29% by weight), and dibutyl phthalate (DBP) (measured value 17% by weight). These phthalates may harm the health of children, causing possible damage to the reproductive system. In addition, the valve plug can be easily detached from the toy and could be put in the mouth by a small child, causing choking. The batteries are easily accessible and could cause choking if put in the mouth or damage the organs if swallowed.</p> <p>The plastic bag, in which the toy is packed, is too thin. A child could put it over the mouth and nose, leading to suffocation.</p> <p>The product does not comply with the REACH Regulation, with the requirements of the Toy Safety Directive and the relevant European Standards EN 71-1 and EN 62115.</p>	Import rejected at border
A12/0055/19	Luxembourg	Slime toy Country of origin: Unknown		<p>Chemical</p> <p>The migration of boron from the toy slime is too high (measured value up to 1000 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system.</p> <p>The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3.</p>	Recall of the product from end users; Temporary ban on the supply, offer to supply and display of the product
A12/0058/19	Spain	Bubble gun Country of origin: China		<p>Choking</p> <p>Various pieces can detach from the toy, generating small parts. A small child may put them in the mouth and choke.</p> <p>The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.</p>	Import rejected at border





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A12/0079/19	Belgium	Squeezable toy Country of origin: China		Choking The product contains small parts that can be easily detached. A small child can put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and relevant European standard EN 71-1.	Recall of the product from end users (By: Importer)
A12/0080/19	Belgium	Plastic bus with squeezable toy Country of origin: China		Choking The product contains small parts that can be easily detached. A toddler can put them in the mouth and choke. The product does not comply with the requirements of Toy Safety Directive and the relevant European Standard EN 71-1.	Recall of the product from end users (By: Importer)
A12/0081/19	Belgium	Squeezable toy Country of origin: China		Choking Small parts can easily be detached from the toy. A small child may put one of them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Recall of the product from end users (By: Importer)
A12/0082/19	Belgium	Squeezable toy Country of origin: China		Choking Small parts can easily be detached from the toy. A small child may put one of them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Recall of the product from end users (By: Importer)




Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A12/0083/19	Belgium	Squeezable toy Country of origin: China		Choking Small parts can easily be detached from the toy. A small child may put one of them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Recall of the product from end users (By: Importer)
A12/0084/19	Belgium	Squeezable toy Country of origin: Unknown		Choking The product contains small parts that can easily be detached. A small child can put them in the mouth and choke. The product does not comply with the Toy Safety Directive and the requirements of the European Standard 71-1.	Recall of the product from end users (By: Importer)
A12/0085/19	Spain	Wall Growth chart Country of origin: Malaysia		Choking Small pieces of plastic come off easily from the toy generating small parts. Small children may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and with the relevant European standard EN 71-1.	Import rejected at border
A12/0086/19	France	Children's fancy-dress costume Country of origin: China		Burns, strangulation, suffocation The instructions for a correct assembly of the toy are lacking in a comprehensible language and the required warnings are absent. The product is highly flammable and the plastic bag of the packaging is too thin. Children may wear the costume close to an ignition source and the costume may catch fire, resulting in burns. Due to the absence of instructions for assembly, wearing the hood may lead to strangulation. If a child plays with the packaging, the plastic can cover the mouth and nose, causing the child to suffocate. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	This product listing was removed from the AliExpress marketplace; Withdrawal of the product from the market

Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A12/0090/19	France	Bath toy set Country of origin: China		Chemical The toys contain di-(2-ethylhexyl phthalate (DEHP) (measured value up to 10 % by weight) and di-butyl phthalate (DBP) (measured value up to 0.6% by weight). These phthalates may harm the health of children, causing possible damage to the reproductive system. The product does not comply with the REACH Regulation.	This product listing was removed by Amazon; Warning consumers of the risks; Withdrawal of the product from the market
A12/0092/19	France	Set of bath toys Country of origin: France		Chemical The plastic material of the toys contains 2-ethylhexyl phthalate (DEHP) (measured value up to 22.9 % by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. The product does not comply with the REACH Regulation.	Warning consumers of the risks; Withdrawal of the product from the market
A12/0097/19	France	Fancy-dress costume Country of origin: China		Chemical The plastic material of the black belt contains bis(2-ethylhexyl)phthalate (DEHP) (measured value: 4% by weight) and di-butyl phthalate (DBP) (measured value: 0.2% by weight). These phthalates may harm the health of children, causing possible damage to the reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/0098/19	France	Children's fancy-dress costume Country of origin: Unknown		Choking The zip fastener can easily detach. A small child may put it in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European Standard EN 71-1.	Withdrawal of the product from the market
A12/0099/19	France	Children's fancy-dress costume Country of origin: China		The sliders on the zip fastener may be easily detached. A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	This product listing was removed by the marketplace Amazon; Withdrawal of the product from the market




Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A12/0100/19	France	Fancy-dress costume Country of origin: Unknown		Burns The fire hazard warning is absent. Children may wear the costume close to an ignition source and the costume may catch fire, resulting in burns. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-2.	Withdrawal of the product from the market
A12/0101/19	France	Bath toy set Country of origin: Unknown		Chemical, Choking The plastic material of the toy contains di-(2-ethylhexyl phthalate (DEHP) (measured value: 23.1 % by weight) and a small plastic part (squeaking element) may easily detach from the toy. This phthalate may harm the health of children, causing possible damage to the reproductive system. A small child may put the small part in the mouth and choke. The product does not comply with the REACH Regulation, the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Consumers who have bought the product are to be contacted directly by the seller and/or the online marketplace; Withdrawal of the product from the market
A12/0102/19	Slovenia	Nail set for children Country of origin: China		Chemical The red nail polish contains too much phenoxyethanol (measured value: 1.4%). Phenoxyethanol is haematotoxic and a mild irritant, and may damage blood and liver. The product does not comply with the Cosmetics Regulation.	Recall of the product from end users
A12/0103/19	Italy	Toy Slime Country of origin: Unknown		Chemical The migration of boron from the toy slime is too high (measured value: up to 4383 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3.	Withdrawal of the product from the market

Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A12/0106/19	Slovakia	Bath toy set Country of origin: China		Chemical The plastic material of the toys contains bis(2-ethylhexyl)phthalate (DEHP) (measured value up to 1.8 % by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. The product does not comply with the REACH Regulation.	Recall of the product from end users; Withdrawal of the product from the market
A12/0108/19	Poland	Set of footwear for plastic doll Country of origin: China		Chemical The plastic material of the set contains bis(2-ethylhexyl)phthalate (DEHP) (measured value: 4.8 % by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market (By: Importer)
A12/0109/19	Luxembourg	Spinning top with slime Country of origin: China		Chemical The migration of boron from the toy slime is too high (measured value up to 1020 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3.	Ban on the marketing of the product and any accompanying measures; Recall of the product from end users; Temporary ban on the supply, offer to supply and display of the product
A12/0115/19	Luxembourg	Toy Slime Country of origin: Unknown		Chemical The migration of boron from the toy slime is too high (measured value up to 928 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3.	Ban on the marketing of the product and any accompanying measures; Recall of the product from end users; Temporary ban on the supply, offer to supply and display of the product

Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A12/0132/19	Luxembourg	Slime toy Country of origin: Unknown		Chemical The migration of boron from the toy slime is too high (measured value up to 1020 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3.	Ban on the marketing of the product and any accompanying measures; Recall of the product from end users; Temporary ban on the supply, offer to supply and display of the product
A12/0136/1	France	Electric ride-on car Country of origin: China		Burns The lugs of the battery are identical, so it's possible to connect the battery by reversing the connections which can lead to smoke and a rapid rise in battery temperature occurs. As a consequence, children can burn themselves. The product does not comply with the requirements of the Toy Safety Directive and the relevant European Standard EN 62115.	Import rejected at border
A12/0142/19	Slovakia	Soft toy with key ring Country of origin: China		Choking The eyes, the nose and the metal chain as well as the metal ring can easily detach from the toy, generating small parts. A small child may put these small parts in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the European Standard EN 71-1.	Recall of the product from end users; Withdrawal of the product from the market
A12/0143/19	Slovakia	Toy gun Country of origin: China		Choking The suction cups can easily detach from the projectiles. If a child puts the projectile in the mouth, the suction cup may detach and obstruct the airways. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.	Recall of the product from end users; Withdrawal of the product from the market

Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A12/0144/19	Belgium	Plastic doll Country of origin: China		<p>Chemical</p> <p>The product contains bis (2-ethylhexyl) phthalate (DEHP) (measured value up to 34% by weight) and dibutyl phthalate (DBP) (measured value up to 1.57% by weight). These phthalates may harm the health of children, causing possible damage to the reproductive system.</p> <p>The product contains also di-isononyl phthalate (DINP) (measured value up to 1.69% by weight). This phthalate may harm the health of children, causing possible damage to the liver.</p> <p>The product does not comply with the REACH Regulation.</p>	Recall of the product from end users (By: Importer)
A12/0145/19	Belgium	Plastic doll Country of origin: China		<p>Chemical</p> <p>The product contains di-(2-ethylhexyl) phthalate (DEHP) (measured value up to 33% by weight) and dibutyl phthalate (DBP) (measured value 0.31% by weight). These phthalates may harm the health of children, causing possible damage to the reproductive system.</p> <p>The product contains di-isononyl phthalate (DINP) (measured value 1.98% by weight). and di-isodecyl phthalate (DIDP) (measured value 0.27% by weight). These phthalates may harm the health of children, causing possible damage to the liver.</p> <p>The product does not comply with the REACH Regulation.</p>	Recall of the product from end users (By: Importer)
A12/0148/19	Belgium	Plastic doll Country of origin: China		<p>Chemical</p> <p>The product contains di-(2-ethylhexyl) phthalate (DEHP) (measured value up to 31% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system.</p> <p>The product contains di-isononyl phthalate (DINP) (measured value 3.75% by weight) and di-isodecyl phthalate (DIDP) (measured value 0.44% by weight). These phthalates may harm the health of children, causing possible damage to the liver.</p> <p>The product does not comply with the REACH Regulation.</p>	Recall of the product from end users (By: Importer)

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kind and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A12/0149/19	Sweden	Toy gun Country of origin: China		Environment Solder in four different places in the toy contain lead and cadmium in concentrations above limit values. Lead and cadmium pose a risk to the environment. The product does not comply with the Commission Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Withdrawal of the product from the market
A11/0003/19	France	Soft toy Country of origin: Unknown		Choking The fibrous stuffing material of the toy is easily accessible due to the weakness of certain seams. A small child could take out the stuffing, put it in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and with the relevant European standard EN 71-1.	Consumers having purchased the product are being contacted; This product listing was removed by the retailer.
A11/0004/19	France	Plastic doll Country of origin: China		Choking The fibrous stuffing material of the toy is easily accessible due to the weakness of certain seams. A small child could take out the stuffing, put it in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and with the relevant European standard EN 71-1.	The customers concerned are contacted by the seller and/or the Internet marketplace; Withdrawal of the product from the market

RAPEX – Rapid Exchange of Information System

The Rapid Alert System enables the rapid exchange of information (RAPEX) between **31 European countries** and the European Commission on non- food dangerous products found on the market posing a risk to health and safety of consumers.







A weekly overview of the alerts on those products is published in English for free on <http://ec.europa.eu/rapex>. The measures taken in the notifying country in order to restrict their marketing or use can be ordered by national authorities ("compulsory measures") or be taken directly by producers and distributors ("voluntary measures").

The official contact points of the Member and EFTA-EEA States provide the information published in these weekly overviews. Under the terms of Annex II.10 of the General Product Safety Directive (2001/95/EC) responsibility for the information provided lies with the notifying party. The Commission does not take any responsibility for the accuracy of the information provided.



The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kind and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

Recall Summary – Australia Toys / Children’s Products

ACCC Recall List (Jan 2019)

PRA No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
2019/17257	Australia	Remote Control ATV		Burns The USB charger supplied with the toy can overheat and melt the charger’s plastic housing	Customers should cease using their product immediately and return the product to any store of the supplier for a full refund.
2018/17238	Australia	Organic Cotton Coveralls		Choking Detached zip puller may pose a choking/ingestion risk to infants.	Consumers should stop using the garment and return it to the store of the supplier for a full refund.
2018/17245	Australia	Baby Dummies		Strangulation No warning and directions provided to customers. A torn or broken dummy may pose a choking hazard to children and a cord or ribbon attached to a dummy may pose a strangulation hazard.	Consumers should immediately contact the supplier for a copy of the correct information.
2018/17247	Australia	Plush Toy		Choking The reindeer's plastic nose may detach from the plush toy. Small parts can be a choking hazard for infants and young children.	Consumers should dispose of the reindeer immediately or return the product to the concierge desk or centre management of any supplier managed property.
2019/17276	Australia	Plush Toy		Choking The reindeer's plastic nose may detach from the plush toy. Small parts can be a choking hazard for infants and young children.	Consumers should either immediately return the Reindeer to the customer service desk at the shopping centre or safely dispose of the Reindeer.
2018/17255	Australia	Baby Stroller		Injuries The stroller does not have red brakes or a tether strap and does not display safety warnings or a warning on the harness. If the products do not have the required safety features, they may not be used correctly, posing a risk of injury to the child.	The supplier will make contact with owners of the affected product to provide a full refund including original shopping cost.

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kind and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

PRA No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
2019/17315	Australia	Swing Set		Injuries Swing seat may tilt forward and/or frame may tip during use due to a design defect. Risk of a fall that may cause a serious injury to a child.	Consumers should cease using this product and immediately return to the retail store as soon as possible for a full refund. A receipt is not required to obtain a refund.
2019/17311	Australia	Infant Girls Overall and Tee Set		Choking Detached buttons may pose a potential ingestion/choking risk to infants.	Consumers should immediately cease using the overall and tee set and return it to any retail store for a full refund.

Australian Product Safety System

The Australian product safety system is to maximize the safety of good by the cooperation of consumers, businesses and agencies. This policy sets out the principles adopted by the Australian Competition and Consumer Commission (ACCC) for prioritizing and addressing product safety risks.

Under the Australian Consumer Law, a responsible Minister can order a compulsory recall when there are hazards on the products. A voluntary recall could be conducted to remove the product from the marketplace when the suppliers become aware of unsafe or defective products.

The ACCC administers a national recalls system for recalls of specific and general consumer products, and publishes all product recalls on the website <https://www.productsafety.gov.au/recalls>.

STC (The Hong Kong Standards and Testing Centre) is a not-for-profit, independent testing, inspection and certification organization. With a global network of ISO/IEC 17025 accredited testing laboratories and over 50 years of experience in consumer product testing, we can meet your conformity assessment needs with highly efficient and reliable service. Our testing scope and capabilities related to toys and children's products include but not limited to:

EU Requirements

- EN 71
- Phthalates (EC) no. 1907/2006
- Nickel Release (EC) no. 1907/2006
- Total Cadmium (EEC) no. 91/338
- Lead in Jewellery product (EC) no. 836/2012
- Azo-dye (EC) no. 1907/2006
- Bisphenol-A (2014/81/EU)
- DMF (Dimethylfumarate) (EU) no. 2011/135
- Flame retardants TCEP, TCPP, TDCP (2014/79/EU)
- Package Waste Directive (94/62/EC)

US & Canada Requirements

- ASTM F963
- CPSIA
- California Proposition 65
- 16 CFR 1501
- ASTM F2923 (Children's jewellery)
- ASTM F2999 (Adult's jewellery)
- US Toxic in Packaging Clearinghouse (TPCH)
- CCPSA - Toys Regulations (SOR/2011-17)

Japan Requirements

- Japan Toy Safety Standard (ST)
- Japan Food Sanitation Law (JFSL)

Australia Requirements

- AS/NZS 8124
- Consumer Protection Notice No. 6 of 2010 - DEHP

For more information, please contact our Toys and Children's Products Department.

Hong Kong: hktcd@stc.group

Japan: jpo@stc.group

Dongguan: dgtcd@stc.group

USA: usstc@stc.group

Shanghai: shtcd@stc.group

Germany: info@pkm.eu.com

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kind and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.