ESTC | NEWSLETTER

Recall Summary – European Toys

EU Safety Gate Alerts (Feb 2022)

	Matthe		LO Sujety Gute Alerts (Feb 202				
Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted		
A11/00020/22	Hungary	Toy Piano (Country of Origin: China)		Chemical The battery compartment can be easily opened without the aid of a tool, leaving batteries accessible. A small child might put them in the mouth and the acid content may cause damage to the gastrointestinal tract if they are ingested. The product does not comply with the requirements of the Toy Safety Directive and the European standard EN 71-1.	Withdrawal of the product from the market		
A11/00022/22	Hungary	Balloon with LED Lights (Country of Origin: The Netherland s)		Chemical The battery compartment is easily broken, leaving the batteries accessible. A child may put the batteries in the mouth, which could cause damage to the child's gastrointestinal tract if swallowed. The product does not comply with the requirements of the Toy Safety Directive and the European standard EN 71-1.	Withdrawal of the product from the market		
A11/00024/22	Poland	Children's High Chair (Country of Origin: Unknown)		Choking, Entrapment, Injury Due to presence of the openings, the stuffing material of the sheathing is accessible. A child could detach the stuffing material and swallow it, which may cause choking. Moreover, presence of the openings poses a risk of finger or body entrapment. The product does not comply with the requirements of the General Product Safety Directive and the European standard EN 14988.	Withdrawal of the product from the market		
A11/00028/22	Hungary	Toy Panda with Battery (Country of Origin: China)		Chemical The battery compartment of the toy can be easily opened, leaving batteries accessible. A child may put them in the mouth and ingest them, which may lead to choking if they enter the airways, or could cause injuries to the gastrointestinal tract. The product does not comply with the requirements of the Toy Safety Directive and the European standard EN 62115.	Recall of the product from end users		



A11/00029/22 A11/00036/22	Malta France	Electric Swing for Babies (Country of Origin: Bulgaria) Toy Gun	Injury The swing is not stable enough. As a result, it can tip over and fall, leading injury to a child. The product does not comply with the requirements of the General Product Safety Directive and the European standard EN 1273. Damage to Sight	Withdrawal of the product from the market Recall of the
A11/00030/22	France	(Country of Origin: Hong Kong)	The LED laser sight on the top of the toy gun is too powerful (measured value: 1.23 mW). Direct viewing of the laser beam could cause damage to sight. The product does not comply with the requirements of the Toy Safety Directive and the European standard EN 62115.	product from end users
A12/00194/22	Sweden	Inflatable Beach Ball (Country of Origin: China)	Chemical According to the REACH regulation, DEHP is prohibited in articles. The product does not comply with the REACH Regulation 1907/2006 Annex XVII entry 51.3.	Removal of this product listing by the online marketplace
A12/00195/22	Sweden	Swim Ring (Country of Origin: China)	Chemical The product contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) (measured value: up to 30% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Removal of this product listing by the online marketplace
A12/00199/22	Hungary	Plastic Toy (Country of Origin: China)	Chemical, Choking The small flashing unit and the button cell batteries are easily accessible. A child could put them in the mouth, which could cause damage to the child's gastrointestinal tract or choking. The product does not comply with the requirements of the Toy Safety Directive and the European standard EN 62115.	Recall of the product from end users
A12/00211/22	Hungary	Flashing LED Toy (Country of Origin: China)	Chemical, Choking The small flashing unit and button cell batteries may become accessible. A child may put them in the mouth and ingest them, which may lead to choking if they enter the airways. The button cell batteries could cause damages to the gastrointestinal tract if they are ingested. The product does not comply with the requirements of the Toy Safety Directive and the European standard EN 62115.	Withdrawal of the product from the market





A12/00228/22	Sweden	Plastic Toy		Chemical, Environment	Removal of
				The blue and green plastic contains an	this product
		(Country of		excessive amount of bis(2-ethylhexyl)	listing by the
		Origin:		phthalate (DEHP) and di-isobutyl phthalate	online
		China)		(DIBP) (measured values: up to 15.0% and	marketplace
		,		13.7% by weight respectively). These	
				phthalates may harm the health of	
				children, causing possible damage to their	
				reproductive system. The solders in the	
				toy contain lead (measured value: up to	
				50.7% by weight). Lead poses a risk to the	
				environment. The product does not	
				comply with the REACH Regulation and the	
				requirements of the Directive on the	
				restriction of the use of certain hazardous	
				substances in electrical and electronic	
112/00220/22	<u> </u>			equipment (RoHS 2 Directive).	
A12/00230/22	Germany	Baby	in inter	Injury	Ban on the
		Walker		The baby walker does not provide	marketing of
			An in state of	protection against falls and could fall down	the product
		(Country of	C Reality of the	a flight of stairs, causing injury to a child. In	and any
		Origin:	Statement and Statement	addition, there are openings on the tray	accompanying
		Germany)	au ** ··································	edge. A small child may put the fingers	measures
			-1 Copyright Constant	inside and become trapped. The product	
				does not comply with the requirements of	
				the General Product Safety Directive and	
				the European standard EN 1273.	
A12/00233/22	Luxembourg	Set of	*	Chemical, Choking	Removal of
		Inflatable		The plastic material of the product	this product
		Beach Balls		contains an excessive amount of	listing by the
			Car Cia	bis(2-ethylhexyl) phthalate (DEHP) and	online
		(Country of		diisobutyl phthalate (DIBP) (measured	marketplace
		Origin:	and the second sec	value: up to 26% and 0.12% by weight	
		China)		respectively). These phthalates may harm	
				the health of children, causing possible	
				damage to their reproductive system.	
				Furthermore, the balls' stopper can easily	
				detach; a young child may put it into its	
				mouth and choke. The product does not	
				comply with the REACH Regulation, the	
				requirements of the Toy Safety Directive	
				and the European standard EN 71-1.	
A12/00234/22	Austria	Plastic Toy		Choking	Destruction of
, ·/ 			stores Man	The toy can easily break, generating small	the product
		(Country of	The second	parts. A child may put them in the mouth	
		Origin:		and choke. The product does not comply	
		China)		with the requirements of the Toy Safety	
		Cillia)		Directive and the European standard	
				-	
				EN 71-1.	



A12/00235/22	The	Тоу		Choking	Recall of the
A12/00233/22	Netherlands	Tambourine		The bell may get loose from the	product from
	Nethenanas	rambourne	1.501	tambourine's wooden frame and liberate	end users
		(Country of	1 3233	a small part (axe of the bell). A child may	chu users
		Origin: China)	CI SCORE	put it in the mouth and choke. The	
		ongin. china)	-	product does not comply with the	
				requirements of the Toy Safety Directive	
				and the European standard EN 71-1.	
A12/00241/22	Luxembourg	Baby	_	Choking, Injury	Removal of
A12/00241/22	Luxembourg	Maracas	<u> </u>	If a child puts the toy in the mouth and	this product
		Ivial acas		falls face down, the protruding parts	listing by the
		(Country of		could obstruct the airways, causing	online
		Origin:		choking and injury around the pharynx or	marketplace
		United		trachea area. The product does not	marketplace
		States)		comply with the requirements of the	
		otates,		General Product Safety Directive and the	
				European standard EN 71-1.	
A12/00244/22	Czechia	Plastic Doll	24531 - 1244	Chemical	Withdrawal of
, , –	-		A State of the	Some plastic parts (heads of the dolls)	the product
		(Country of	8 38 16	contain di-(2-ethylhexyl) phthalate	from the
		Origin: China)	10 a 4 . 25	(DEHP) (measured value: up to 21.48% by	market
		C ,	46	weight). This phthalate is toxic and	
				harmful for the health of children and	
				may cause damages to their reproductive	
				system. The product does not comply	
				with the REACH Regulation.	
A12/00247/22	Slovakia	Plush Toy	12	Choking	Withdrawal of
			00	Small parts (the nose, the jingle bell and	the product
		(Country of	Fol	the suction cup) may be easily detached	from the
		Origin: China)	10	from the toy. A small child may put the	market
			7	detached elements in the mouth and	
				choke. The product does not comply	
				with the requirements of the Toy Safety	
				Directive and the European standard	
				EN 71-1.	
A12/00250/22	Sweden	Toy Pool		Injury	Recall of the
				The corner pins can detach from their	product from
		(Country of		brackets and may hurt the child seriously	end users
		Origin: China)		if the pin hits the face or the eye of the	
				child. The product does not comply with	
				the requirements of the Toy Safety	
				Directive and European standard EN 71-	
A12/00252/22	Slovakia	Plush Toy		1. Choking	Warning
A12/00232/22	JIUVANIA	FIUSHIOY		Due to the weakness of the seam on the	consumers of
		(Country of	A start	bottom of the toy, the filling material and	the risks
		Origin: China)		small parts (lockable zip bag with small	110 11313
		Cingini. Cinina)		balls) may become accessible to children.	
				A child may put them in the mouth and	
				choke. The product does not comply	
				with the requirements of the Toy Safety	
			1	with the requirements of the roy safety	



			Directive and the European standard EN 71-1.	
A12/00259/22	Sweden	Toy Fire Fighter Helmet (Country of Origin: China)	Environment The solders of the product contain an excessive amount of lead and cadmium (measured value: up to 64.1% and 0.11% by weight, respectively). Lead and cadmium pose a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Withdrawal of the product from the market
A12/00263/22	Sweden	Puffer Ball with Light (Country of Origin: China)	Environment The solders of the toy contain an excessive amount of lead (measured value: up to 13.8% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Withdrawal of the product from the market
A12/00264/22	Sweden	Flying Disk Toy (Country of Origin: Unknown)	Environment The solders of the toy contain an excessive amount of lead (measured value: up to 0.19% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Withdrawal of the product from the market
A12/00266/22	Luxembourg	Stacking Cups (Country of Origin: China)	Suffocation The cups are large enough to cover a young child's mouth and nose, and some of the cups lack the necessary openings to allow an inflow of air. A young child may suffocate when placing the product on the mouth and nose. The product does not comply with the requirements of the Toy Safety Directive and the European standard EN 71-1.	Removal of this product listing by the online marketplace
A12/00267/22	Luxembourg	Toy Set (Country of Origin: China)	Choking, Suffocation The plastic foil packaging bag is too thin and poses a suffocation risk. In addition, the toy contains small parts (surprise toys). The product lacks the appropriate age warning, therefore a small child could be given the toy, put it in the mouth and choke. The product does not	Removal of this product listing by the online marketplace



				comply with the requirements of the Toy Safety Directive and the European standard EN 71-1.	
A12/00269/22	Croatia	Soft Toy (Country of Origin: China)	R	Choking Small parts may detach. In addition, the fibrous stuffing material of the toy is easily accessible due to the weakness of certain seams. A small child may put the small parts or the stuffing material in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the European standard EN 71-1.	Import rejected at border
A12/00271/22	The Netherlands	Soother Holder (Country of Origin: The Netherlands)		Strangulation The strap is too long and may lead to strangulation of a child. The product does not comply with the relevant European standard EN 12586.	Ban on the marketing of the product and any accompanying measures
A12/00273/22	The Netherlands	Soother Holder (Country of Origin: United States)		Choking The soother holder breaks easily and generates small parts. A small child could put them in the mouth and choke. In addition, the strap is too long and may lead to strangulation of the child. The product does not comply with the relevant European standard EN 12586.	Ban on the marketing of the product and any accompanying measures
A12/00277/22	Sweden	Electrical Soccer Game (Country of Origin: China)		Chemical The plastic material of the product contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) (measured value: 27%). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Removal of this product listing by the online marketplace
A12/00289/22	Slovakia	Plush Toy (Country of Origin: China)		Choking A small part (the suction cup) may be easily detached from the toy. A small child may put it in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the European standard EN 71-1.	Withdrawal of the product from the market
A12/00297/22	Poland	Toy telephone (Country of Origin: China)		Damage to Hearing The sound level pressure is too high (measured value: up to 75.0 dB). This could lead to permanent or temporary hearing loss. The product does not comply with the requirements of the Toy Safety Directive and the European standard EN 71-1.	Withdrawal of the product from the market



A12/00298/22	Poland	Plastic Toy		Choking, Cuts	Withdrawal of
		,		The product has small plastic parts	the product
		(Country of		(tentacle, wheels) that can be easily	from the
		Origin: China)		detached. A child may put them in the	market
				mouth and choke. The toy has accessible	
				sharp elements (metal axle), which could	
				cause cuts. The product does not comply	
				with the requirements of the Toy Safety	
				Directive and the European standard EN	
				71-1.	
A12/00300/22	Poland	Plastic Ball	and the second second second second	Chemical	Withdrawal of
112,00000,22	1 olullu	Thastic Dan		The toy contains an excessive amount of	the product
		(Country of	No States	diisobutyl phthalate (DIBP) (measured	from the
		Origin: China)	dini	value: up to 39.3%). This phthalate may	market
		Oligin. China)		harm the health of children, causing	market
				possible damage to their reproductive	
				system. The product does not comply with the REACH Regulation.	
A12/00301/22	Slovakia	Pull Toy		Strangulation	Recall of the
A12/00301/22	Slovakia	run roy	1.1.	The cord of the toy is too long. It may get	product from
		(Country of		wrapped around a child's neck and lead	end users
		Origin: China)	5	to strangulation. The product does not	enu users
		Origin. China)		comply with the requirements of the Toy	
				Safety Directive and the European standard EN 71-1.	
A12/00302/22	Slovakia	Toy Slime		Chemical	Recall of the
A12/00302/22	SIOVAKIA	TOy Shine	S.N.	The migration of boron from the toy	product from
		(Country of	See.L.	slime is too high (measured value: up to	end users
					enu users
		Origin: Hong		2044 mg/kg). Ingestion or contact with	
		Kong)	9	an excessive quantity of boron may harm	
			CO/	the health of children by damaging the	
			the second	reproductive system. The product does	
				not comply with the requirements of the	
				Toy Safety Directive and the European	
				standard EN 71-3.	A MALE A CONTRACT
A12/00309/22	Czechia	Swim Ring	The second	Chemical	Withdrawal of
			CA CAN	The plastic material of the product (swim	the product
		(Country of		ring and inflation valve) contains an	from the
		Origin: China)	a stand	excessive amount of bis(2-ethylhexyl)	market
				phthalate (DEHP), (measured values: up	
				to 14.62% by weight). This phthalate	
				may harm the health of children, causing	
				possible damage to their reproductive	
				system. The product does not comply	
				with the REACH Regulation.	
A12/00313/22	Latvia	Toy Slime		Chemical	Removal of
				The migration of boron from the toy	this product
		(Country of		slime is too high (measured value: up to	listing by the
	1	Onigina Ching)	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1026 mg/kg) Ingestion or contact with	online
		Origin: China)	A CAL	1026 mg/kg). Ingestion or contact with	
		Origin: China)		an excessive quantity of boron may harm the health of children by damaging the	marketplace



				reproductive system. The product does not comply with the requirements of the Toy Safety Directive and the European standard EN 71-3.	
A12/00318/22	Germany	Toy Car Set (Country of Origin: China)		Chemical The product releases an excessive amount of nickel (measured value: up to 31 μ g/cm ² /week). Nickel is a strong sensitiser and can cause allergic reactions if present in articles that come into direct and prolonged contact with the skin. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/00325/22	Latvia	Magnetic Building Set (Country of Origin: China)	MAGNEY, JOURS ST	Injury The magnetic toy is made of small parts (balls) with a high magnetic flux. If a child swallows them, they could attract one another causing intestinal blockage or perforation. The product does not comply with the requirements of the Toy Safety Directive and the European standard EN 71-1.	Removal of this product listing by the online marketplace
A12/00326/22	Sweden	Activity Toy (Country of Origin: China)	E C	Entrapment, Injury, Strangulation The distance between the rods of the climbing arch is too small. A child's head can consequently become trapped between the rods of the toy, causing risks for entrapment, injury and strangulation. The toy does not comply with the requirements of the Toy Safety Directive and the European standard EN 71-8.	Recall of the product from end users
A12/00337/22	Germany	Water Wiggler (Country of Origin: China)		Microbiological The liquid in the product is contaminated with Burkholderia cepacia (measured value: 2,080,000 CFU/g). The product can be damaged during play and fluid may leak out; if a person using the toy has skin injuries, germs may enter the body. Burkholderia cepacia may cause pneumonia, wound infections and sepsis, especially in immunocompromised people. The product does not comply with the requirements of the Toy Safety Directive and the European standard EN 71-5.	Stop of sales
A12/00343/22	Latvia	Plastic Doll with Accessories		Chemical The plastic material of the doll contains an excessive amount of bis(2-etylhexyl) phthalate (DEHP), dibutyl phthalate (DBP), butylbenzyl phthalate (BBP) and	Removal of this product listing by the online marketplace



		(Country of Origin: China)	diisobutyl phthalate (DIBP) (total measured value: up to 15.8% by weight). These phthalates may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	
A12/00344/22	Latvia	Baby Rattle (Country of Origin: China)	Choking The rattle has a small bell and a protruding part (the handle). The child can put either of them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and with the European standard EN-71.	Removal of this product listing by the online marketplace
A12/00345/22	France	Plush Toy (Country of Origin: China)	Choking Small parts (eyes) may easily detach from the toy. A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the European standard EN 71-1.	Removal of this product listing by the online marketplace
A12/00346/22	France	Plush Toy (Country of Origin: China)	Choking Small parts (eyes) can easily detach from the toy. A small child may put them in the mouth and choke on them. The product does not comply with the requirements of the Toy Safety Directive.	Removal of this product listing by the online marketplace

Safety Gate: the EU rapid alert system for dangerous non-food products

"Safety Gate", the EU rapid alert system (formerly known as 'RAPEX'), enables the rapid exchange of information between 31 European countries and the European Commission on non-food dangerous products found on the market posing a risk to health and safety of consumers.

A weekly overview of the alerts on those products is published in English for free on https://ec.europa.eu/safety-gate-alerts/screen/webReport#weeklyReports. The measures taken in the notifying country in order to restrict their marketing or use can be ordered by national authorities ("compulsory measures") or be taken directly by producers and distributors ("voluntary measures").

The official contact points of the Member and EFTA-EEA States provide the information published in these weekly overviews. Under the terms of Annex II.10 of the General Product Safety Directive (2001/95/EC) responsibility for the information provided lies with the notifying party. The Commission does not take any responsibility for the accuracy of the information provided.



ESTC NEWSLETTER

Recall Summary – US Toys / Children's Products

CPSC Recall List (Feb 2022)

Recall	Notifying	Ducdast	Due duet Dhest		Demodu
No.	Country	Product	Product Photo	Hazard/ Risk	Remedy
22-066	USA	Children's Robes (Country of Origin: China)		Burn Hazard The children's robes fail to meet the federal flammability standards for children's sleepwear, posing a risk of burn injury to children.	Consumers should immediately take the recalled robes away from children and stop using them. Consumers who purchased the robes from Amazon will be contacted through Amazon's messaging platform and provided prepaid mailers to return the robes for a full refund. Consumers can also contact BAOPTEIL to request a postage prepaid mailer to return the robes for a full refund.
22-067	USA	KOYO Bounca the Squig Limited Edition Plush Toys (Country of Origin: China)		Choking Hazard The pom-poms can detach from the toy, posing a choking hazard to young children.	Consumers should immediately take the recalled plush toy away from young children and return the toy to any Games Workshop or Warhammer store for a full refund, or destroy the product by cutting off the tail with scissors and provide photographic proof of destruction by email.
22-071	USA	Children's Nightgowns (Country of Origin: China)		Burn Hazard The children's nightgowns fail to meet federal flammability standards for children's sleepwear, posing a risk of burn injury to children.	Consumers should immediately take the recalled nightgowns away from children and stop using them. Consumers who purchased the garments from Amazon.com will be contacted through Amazon's messaging platform and provided prepaid mailers to return the products for a full refund. Consumers can also contact AllMeInGeld to request a postage prepaid mailer to return the products for a full refund.
22-073	USA	Adam the Apple™ Children's Stackable Toys (Country of Origin: India)		Poisoning Hazard Surface paint on the wooden toys contains levels of lead that exceed the federal lead paint ban. Lead is toxic if ingested by young children and can cause adverse health effects.	Consumers should immediately take the recalled toys away from children and contact Stack Em' Up Books to receive a pre-paid shipping label to return the recalled product, regardless of whether they purchased the product or received it as a free giveaway. Consumers that purchased the product at



					www.stackemupbooks.com or the Philadelphia Gift Show will receive a full refund once they return the product.
22-074	USA	Kids Reiny Szn Mid-Cushion Crew Socks (Country of Origin: China)		Choking Hazard The bells attached to the socks can detach, posing aspiration and choking hazards to young children.	Consumers should immediately stop using and return the recalled socks to a Stance store or contact Stance at info@stance.com to receive instructions for a pre-paid shipping label to return the recalled socks. Upon return of the recalled socks, consumers will receive a refund in the form of a credit of up to \$20 to use on their next purchase on Stance.com or at a Stance retail store.
22-080	USA	Children's Sleepwear Garments (Country of Origin: United States)	***	Burn Hazard The recalled children's sleepwear garments fail to meet the flammability standards for children's sleepwear, posing a risk of burn injury to children.	Consumers should immediately take the recalled sleepwear garments away from children, stop using them and contact the firm for a free replacement garment or a full refund. Esme is contacting all known purchasers and providing prepaid mailers to return the products for a full refund or replacement.
22-083	USA	Valco Baby Snap Duo Trend Strollers (Country of Origin: Taiwan)		Fall Hazard The stroller's front wheels can break off while in use, causing the strollers to fall unexpectedly, posing a fall hazard to children in the stroller.	Consumers should immediately stop using the recalled strollers and contact Valco Baby to receive a free replacement front wheel assembly and instructions for replacement. Valco Baby is contacting all known purchasers directly.
22-087	USA	Wooden Teethers (Country of Origin: China)	0.0	Choking Hazard The string that connects the beads on the teether can come untied, releasing the beads and posing a choking hazard to young children.	Consumers should immediately take the recalled teethers away from children and contact Bebe au Lait for instructions on how to receive a full refund or store credit. Consumers can also fill out a form for a store credit at www.bebeaulait.com/recall.
22-724	USA	Infant Walkers (Country of Origin: China)	3	Fall and Entrapment Hazards The infant walkers fail to meet the federal safety standard. They can fit through a standard doorway and are not designed to stop at the edge of a step as required by the	Consumers should immediately stop using the recalled infant walkers and contact Zeno via e-mail to receive a shipping label to return the infant walker free of charge. Upon receipt of the infant walker, consumers will be issued a full refund of the purchase price. Zeno is notifying all known purchasers directly.



				fodoral cofoty standard	
				federal safety standard. The walkers also have	
				leg openings that allow	
				a child to slip down until the child's head	
				can become entrapped	
				at the neck. Babies	
				using these walkers can	
				be seriously injured or	
22.720	110.4			killed.	
22-728	USA	Children's	and the second s	Burn Hazard	Consumers should immediately take
		Sleepwear Sets		The children's	the recalled sleepwear sets away
				sleepwear sets fail to	from children and stop using them.
		(Country of		meet the federal	H&M will contact all known
		Origin: Turkey)		flammability standards	purchasers directly with instructions
				for children's	on how to return the sleepwear sets
				sleepwear, posing a risk	for a full refund.
				of burn injury to	
				children.	
22-731	USA	Mama & Me	AL CONTROL	Violation of Federal	Consumers should immediately take
		MINI Children's	Tot Plank	Lead Content	the recalled handbags away from
		Handbags	ALC: NOT AND	The metal zipper slider,	children and contact Kelly Wynne for
			C- Carlo	zipper O-ring, d-ring,	a full refund if purchased at
		(Country of	CALCOLOGIC CAS	rivet and stud of the	kellywynne.com or contact
		Origin: China)		children's handbags	Nordstrom if purchased at
				contain levels of lead	Nordstrom.com. Kelly Wynne and
				that exceed the federal	Nordstrom are contacting all known
				lead content ban. Lead	purchasers directly, and will provide
				is toxic if ingested by	pre-paid shipping labels for
				young children and can	consumers to return the recalled
				cause adverse health	product for a full refund.
				issues.	

*Source: www.recalls.gov

CPSC

The United States Consumer Product Safety Commission (CPSC) is an independent agency of the United States government. To provide better service in alerting the American people to unsafe, hazardous or defective products, a "one stop shop" for U.S. Government recalls, www.recalls.gov, has been created. Publics can report unsafe products to CPSC by using the platform.

The recall list is divided into seven categories: Consumer Products, Motor Vehicles, Boats, Food, Medicine, Cosmetics and Environmental Products. Generally, the recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall program. Fast Track recalls are initiated by firms who commit to work with CPSC to guickly announce the recall and remedy to protect consumers.

ESTC NEWSLETTER

Recall Summary – Australia Toys / Children's Products

ACCC Recall List (Feb 2022)

PRA No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
2021/19298	Australia	A Wooden Bell Rattle	2-2	Choking or Suffocation Hazard The product may not comply with the size and shape requirements of the mandatory safety standard for toys for children up to and including 36 months of age. The product may pose a choking or suffocation hazard for young children, which can lead to severe injury or death.	Consumers should immediately stop using the product. Consumers should dispose of or destroy the product and contact Inspired Mumma to arrange for a full refund.
2021/19313	Australia	Grotime Essentials Birch High-Low Chair Model number: 38100 Available in Sky Blue, Desert Grey and Coral Red	ÂÂÂ	Risk of Injury to Small Children The rear chair legs may develop cracks or breaks, which may lead to the chair legs twisting and can impact the strength and stability of the chairs legs. If the chair legs become unstable, the chair may collapse, increasing the risk of injury to small children.	Consumers should immediately stop using the product. A supportive cross brace repair kit designed to strengthen the structure of the high chair and prevent twisting of the chair legs will be sent to consumers, with installation instructions, at no cost. Consumers should visit www.grotime.link/recall to register their product.
2021/19319	Australia	Voice Changer which, when spoken into, changes the tone of a voice.	Annuel Re	Choking Hazard The product's button battery compartment is not adequately secured, and the button batteries are accessible. If young children gain access to the button batteries and ingest them, they are likely to suffer severe internal burn injury, which can result in serious illness or death. Button batteries also pose a choking hazard to young children.	Consumers should stop using the product and store it out of the reach of children. Consumers should return the product to the place of purchase for a full refund.
2021/19348	Australia	EVA Foam Puzzle Mat Consisting of 26 Interlocking		Missing of Warnings The product does not comply with the labelling requirements of the mandatory standard for toys for children up to and	Consumers should immediately stop using the puzzle mat and should return them to



		Tiles each Piece Approximately 29cm x 29cm with Letters		including 36 months of age. The puzzle mat may be used incorrectly without the required safety warning label. If foam pieces break off, they could cause a choking or suffocation hazard for young children, which can lead to severe injury or death.	the place of purchase for a full refund.
2021/19350	Australia	A Set of Small, Coloured Magnetic Balls		Choking Hazard The product contains small, high-powered magnets that exceed the maximum allowable magnetic flux set by the permanent ban on small high- powered magnets. If a child swallows more than one small high powered magnet, the magnets can stick together across the walls of the child's intestine or other digestive tissue, which can lead to internal injury and even death. The magnets may pose a choking hazard to young children (small parts).	Consumers should immediately stop using the product and return the product to the place of purchase to receive a full refund.
2022/19406	Australia	Cotton On Kids Baby Swim Ring Inflatable Ring Available in Multiple Colours	HERERAL PLANA Descent and the second	Risk of Drowning The product does not comply with the mandatory safety standard for swimming and flotation aids. There is an increased risk of drowning if the product deflates during use or is not used correctly.	Consumers should immediately stop using the product and return it to any Cotton On or Cotton On Kids store for a full refund.

Australian Product Safety System

The Australian product safety system is to maximize the safety of good by the cooperation of consumers, businesses and agencies. This policy sets out the principles adopted by the Australian Competition and Consumer Commission (ACCC) for prioritizing and addressing product safety risks.

Under the Australian Consumer Law, a responsible Minister can order a compulsory recall when there are hazards on the products. A voluntary recall could be conducted to remove the product from the marketplace when the suppliers become aware of unsafe or defective products.

The ACCC administers a national recalls system for recalls of specific and general consumer products, and publishes all product recalls on the website https://www.productsafety.gov.au/recalls.



ESTC NEWSLETTER

STC (Hong Kong Standards and Testing Centre) is a not-for-profit, independent testing, inspection and certification organization. With a global network of ISO/IEC 17025 accredited testing laboratories and over 50 years of experience in consumer product testing, we can meet your conformity assessment needs with highly efficient and reliable service. Our testing scope and capabilities related to toys and children's products include but not limited to:

EU Requirements

- EN 71
- Phthalates (EC) no. 1907/2006
- Nickel Release (EC) no. 1907/2006
- Total Cadmium (EEC) no. 91/338
- Lead in Jewellery product (EC) no. 836/2012
- Azo-dye (EC) no. 1907/2006
- Bisphenol-A (2014/81/EU)
- DMF (Dimethylfumarate) (EU) no. 2011/135
- Flame retardants TCEP, TCPP, TDCP (2014/79/EU)
- Package Waste Directive (94/62/EC)

US & Canada Requirements

- ASTM F963
- CPSIA
- California Proposition 65
- 16 CFR 1501
- ASTM F2923 (Children's jewellery)
- ASTM F2999 (Adult's jewellery)
- US Toxic in Packaging Clearinghouse (TPCH)
- CCPSA Toys Regulations (SOR/2011-17)

Japan Requirements

- Japan Toy Safety Standard (ST)
- Japan Food Sanitation Law (JFSL)

Australia Requirements

- AS/NZS 8124
- Consumer Protection Notice No. 6 of 2010 DEHP

FOR MORE DETAILS, PLEASE CONTACT US :

Hong Kong: <u>hktcd@stc.group</u> Changzhou: czstc@stc.group U.S.A.: enquiry@stc.group

Dongguan: dgtcd@stc.group Vietnam: vnstc@stc.group Germany: grstc@stc.group

Shanghai: shtcd@stc.group Japan: jpo@stc.group



