Recall Summary – European Toys

ESTC NEWSLETTER

EU Safety Gate Alerts (Apr 2022) Notifying **Product Measures** Alert No. Product Hazard/ Risk Country Photo Adopted A11/00053/22 Reclined Suffocation Bulgaria Marking the Cradle The plastic of the packaging is too product with thin. If a child plays with it, the appropriate (Country of plastic can cover the mouth and warnings on Origin: nose causing the child to suffocate. the risks China) The product does not comply with the requirements of the General Product Safety Directive and the European standard EN 12790. Marking the A11/00054/22 Baby Bulgaria Injury Swing The product is not accompanied by product with all required marking and instructions appropriate (Country of for safe use in the national warnings on Origin: The language. Consumers therefore the risks Netherlands) do not have all necessary information about appropriate and safe use of the product and children may be injured. The product does not comply with the requirements of the General Product Safety Directive the European and standard EN 16232. A11/00060/22 Croatia Baby Injury Ban on the marketing of Swing The locking mechanism may disengage too easily. As a result, a the product (Country of child can fall from the baby swing and any Origin: and suffer injury. The product does accompanying China) not comply with the requirements of measures the General Product Safety Directive and the European standard EN 16232.

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

www.stc.group

1

📠 Headquarters - The Hong Kong Standards and Testing Centre Ltd. 🛛 💡 10 Dai Wang Street, Tai Po Industrial Estate, Tai Po, N.T., Hong Kong

A12/00488/22	Finland	Hobby	A star II.	Choking	Import
		Horse	B.I	Small parts can easily detach (eyes).	rejected at
			in the second se	Consequently, a child may put them in	border
		(Country of		the mouth and choke. The product	
		Origin:		does not comply with the	
		China)		requirements of the Toy Safety	
				Directive and the European standard	
				EN 71-1.	
A12/00492/22	Poland	Тоу	2	Choking, Damage to Hearing	Withdrawal
		Musical	INSTRUMENTS	The sound pressure level is too high	of the
		Instrument	OTA	(measured value: up to 119.5 dB).	product from
		Set		This could lead to permanent or	the market
			-	partial hearing loss, when the product	
		(Country of		is used. The toy maracas can easily	
		Origin:		break into small parts. A child may	
		China)		put them in the mouth and choke.	
				The product does not comply with the	
				requirements of the Toy Safety	
				Directive and the European standard	
				EN 71-1.	
A12/00493/22	Poland	Тоу		Choking, Damage to Hearing	Warning
		Trumpet		The sound pressure level is too high	consumers of
				(measured value: up to 120.4 dB).	the risks
		(Country of		This could lead to permanent or	
		Origin:		partial hearing loss, when the product	
		China)		is used. Moreover, small plastic	
				parts may easily detach from the toy.	
				A child may put them in the mouth and	
				choke. The product does not comply	
				with the requirements of the Toy	
				Safety Directive and the European	
				standard EN 71-1.	
A12/00494/22	Poland	Plastic Toy	139	Chemical	Warning
			15th	The product contains an excessive	consumers of
		(Country of		amount of bis (2-ethylhexyl) phthalate	the risks
		Origin:	Z	(DEHP) (measured value: up to	
		China)	all of	10% by weight). This phthalate may	
			SEN	harm the health of children, causing	
	1	1	and the second second	and the second sec	
			Charles and a	possible damage to the reproductive	
			and a	system. The product does not	

A12/00498/22	Bulgaria	Baby		Injury	Withdrawal
		Swing		The product has completely bounded	of the
			1/ TV	openings on each side within the	product from
		(Country of		protected volume. As a result, a	the market
		Origin:		baby's fingers can become trapped in	
		China)		the openings and cause injury. The	
			and the first first	product does not comply with the	
				requirements of the General Product	
				Safety Directive and the European	
				standard EN 16232.	
A12/00520/22	Poland	Rattle Toy		Choking	Withdrawal
			TULLO, HON SCALE	The toy has protruding parts. A child	of the
		(Country of	Grzecholka Ecoy Ratie	could put it in the mouth, which could	product from
		Origin:	ESP	block the airways and cause choking.	the market
		Czechia)	R CLAR	The product does not comply with the	
			15/22	requirements of the Toy Safety	
				Directive and the European standard	
				EN 71-1.	
A12/00522/22	Bulgaria	Reclined	evolde here boarson	Injury	Withdrawal
		Cradle	Calding Calden	The product is not accompanied by all	of the
				required marking and instructions for	product from
		(Country of	A Southern B Colline 1	safe use in the national language.	the market
		Origin:		Consumers therefore do not have the	
		United		necessary information about the	
		States)		appropriate and safe use of the	
				product and children may be injured.	
				The product does not comply with the	
				requirements of the General Product	
				Safety Directive and the European	
				standard EN 12790.	

A12/00523/22	Bulgaria	Baby Swing (Country of Origin: China)	Damage to Hearing, Injury The restraint system of the product does not have shoulder straps. Furthermore, the crotch strap of the waist belt may easily break. As a result, a child can fall from the baby swing and suffer injury. Moreover, the sound pressure level is too high (measured value: up to 81.4 dB). This could lead to permanent or partial hearing loss, when the product is used. The product does not comply with the requirements of the General Product Safety Directive and the European standard EN 16232	Withdrawal of the product from the market
A12/00524/22	Bulgaria	Reclined Cradle (Country of Origin: China)	the European standard EN 16232. Injury The locking mechanism on the product does not engage automatically. Consequently, the product may fold and loose stability, causing the baby to fall and hit its head and suffer injury. The product does not comply with the requirements of the General Product Safety Directive and the European standard EN 12790.	Withdrawal of the product from the market
A12/00526/22	Bulgaria	Baby Swing (Country of Origin: China)	Injury, Suffocation The angle between the backrest and the horizontal surface is too small. Consequently, with the backrest in the most reclined position, the swing may tilt close to the horizontal surface, causing the baby to hit its head. Furthermore, the plastic of the packaging is too thin. If a child plays with it, the plastic can cover the mouth and nose, causing the child to suffocate. The product does not comply with the requirements of the General Product Safety Directive and the European standard EN 16232.	Withdrawal of the product from the market

A12/00527/22	Finland	Plush Toy		Choking	Import
A12/00021/22	1 Intaria	r lush roy	Con and	Small parts (eyes) can easily detach	rejected at
		(Country of		from the toy. A small child may put	border
		Origin:		them in the mouth and choke. The	border
		China)		product does not comply with the	
		Omina)		requirements of the Toy Safety	
				Directive and the European standard	
				EN 71-1.	
A12/00529/22	Iceland	Reclined		Injury, Strangulation	Recall of the
1112/00020/22	Iociaria	Cradle		The restraint system of the product is	product from
		oradic		not adjustable to the size of the baby.	end users
		(Country of		As a result, the baby can slide down	
		Origin: New	No I I	and remain trapped with the strap	
		Zealand)		around the neck suffering	
		/		strangulation. Furthermore, since	
				the angle between the backrest and	
				the horizontal surface is too small, if	
				the baby kicks the legs vigorously, the	
				cradle can bounce too much and the	
				head of the baby may hit the floor.	
				The product does not comply with the	
				requirements of the General Product	
				Safety Directive and the European	
				standard EN 12790.	
A12/00535/22	Poland	Toy Mobile	Telefon Telefon	Damage to Hearing	Warning
		Phone		The sound level produced by the toy	consumers of
				is too high (measured value: up to	the risks
		(Country of	6m+ smily-play.pl	71.6 dB), which could lead to	
		Origin:		permanent or partial hearing loss.	
		China)		The product does not comply with the	
				requirements of the Toy Safety	
				Directive and the European standard	
				EN 71-1.	
A12/00544/22	Finland	Bath Toy		Choking	Import
			the los	Small parts (propellers) may easily	rejected at
		(Country of	Mar miles	detach from the toy. A child may put	border
		Origin:		them in the mouth and choke. The	
		China)		product does not comply with the	
				requirements of the Toy Safety	
				Directive and the European standard	
				EN 71-1.	

A12/00559/22	Poland	Plastic Ball (Country of Origin: China)	Chemical The toy contains an excessive amount of diisobutyl phthalate (DIBP) (measured value: up to 18.5%). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/00560/22	Poland	Plastic Doll (Country of Origin: China)	Chemical The toy contains bis (2-ethylhexyl) phthalate (DEHP) (measured value: up to 28.6% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/00576/22	Poland	Toy Slime (Country of Origin: China)	Chemical The migration of boron from the toy is too high (measured value: up to 1,177 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system. The product does not comply with the requirements of the Toy Safety Directive and the European standard EN 71-3.	Withdrawal of the product from the market
A12/00577/22	Poland	Toy Slime (Country of Origin: China)	Chemical The migration of boron from the toy is too high (measured value: up to 1,133 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system. The product does not comply with the requirements of the Toy Safety Directive and the European standard EN 71-3.	Warning consumers of the risks

A12/00581/22	Ireland	Children's		Chemical, Choking	Recall of the
		Watch		The button battery compartment of	product from
				the product may not be adequately	end users
		(Country of		secured and the button battery may	
		Origin:	P CO	be accessible by children. A child	
		China)		may put it in the mouth, which could	
			100	cause damage to the child's	
			5-4	gastrointestinal tract or a risk of	
			55	choking. The product does not	
				comply with the requirements of the	
				Toy Safety Directive.	
A12/00583/22	France	Toy Torch		Burns, Chemical, Choking	Recall of the
		with		The toy can easily break, leaving the	product from
		Sweets		button batteries accessible. A child	end users
				could put them in the mouth, which	
		(Country of		could cause damage to the child's	
		Origin:		gastrointestinal tract or choking.	
		China)		The product does not comply with the	
				requirements of the Toy Safety	
				Directive and the European standard	
				EN 62115.	
A12/00586/22	Poland	Toy Slime		Chemical	Destruction
			UNICORNU	The migration of boron from the toy is	of the
		(Country of		too high (measured value: up to	product
		Origin:		1,455 mg/kg). Ingestion or contact	
		China)		with an excessive quantity of boron	
				may harm the health of children by	
				damaging their reproductive system.	
				The product does not comply with the	
				requirements of the Toy Safety	
				Directive and the European standard	
				EN 71-3.	

A12/00587/22	Poland	Toy Slime (Country of Origin: China)		Chemical The migration of boron from the toy is too high (measured value: up to 1,099 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system. The product does not comply with the requirements of the Toy Safety Directive and the European standard EN 71-3.	Warning consumers of the risks
A12/00594/22	Austria	Referee Toy Set (Country of Origin: Austria)		Damage to Hearing The sound pressure level is too high (measured value: up to 121.7 dB). This could lead to permanent or partial hearing loss when the product is used. The product does not comply with the requirements of the Toy Safety Directive and the European standard EN 71-1.	Recall of the product from end users
A12/00634/22	France	Soft Toy (Country of Origin: Philippine s)		Choking, Strangulation The toy has a small part (metal ring) which can easily detach. A child could put it in the mouth and choke. Furthermore, there is a long cord attached to the toy, which may get wrapped around the child's neck and lead to strangulation. The product does not comply with the requirements of the Toy Safety Directive and the European standard EN 71-1.	Removal of this product listing by the online marketplace
A12/00639/22	Luxembourg	Key Ring with a Plush Toy (Country of Origin: China)	SOPHIE SOPHIE	Choking Small parts can easily detach (key ring and right arm of the plush teddy bear). Consequently, a child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the European standard EN 71-1.	Withdrawal of the product from the market

A12/00645/22	Poland	Toy Slime		Chemical	Destruction
				The migration of boron from the toy is	of the
		(Country of		too high (measured value: up to	product
		Origin:		1,225 mg/kg). Ingestion or contact	
		China)	Married Brites Brites	with an excessive quantity of boron	
				may harm the health of children by	
				damaging their reproductive system.	
				Moreover, the migration of cadmium	
				from the toy is too high (measured	
				value: up to 1.07 mg/kg) and lead	
				(measured value: up to 0.88 mg/kg).	
				Cadmium and lead are harmful to	
				human health because they	
				accumulate in the body, can damage	
				the kidneys and bones, and may	
				cause cancer. The product does not	
				comply with the requirements of the	
				Toy Safety Directive and the	
				European standard EN 71-3.	
A12/00646/22	Poland	Toy Slime		Chemical	Warning
			DAC	The migration of boron from the toy is	consumers of
		(Country of		too high (measured value: up to	the risks
		Origin:		1,278 mg/kg). Ingestion or contact	
		China)		with an excessive quantity of boron	
				may harm the health of children by	
				damaging their reproductive system.	
				The product does not comply with the	
				requirements of the Toy Safety	
				Directive and the European standard	
				EN 71-3.	

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

9

Headquarters - The Hong Kong Standards and Testing Centre Ltd. 💡 10 Dai Wang Street, Tai Po Industrial Estate, Tai Po, N.T., Hong Kong

r					1
A12/00647/22	Poland	Toy Slime		Chemical	Warning
			The lead	The migration of boron from the toy is	consumers of
		(Country of		too high (measured value: up to	the risks
		Origin:		1,440 mg/kg). Ingestion or contact	
		China)	5	with an excessive quantity of boron	
				may harm the health of children by	
				damaging their reproductive system.	
				Moreover, the migration of cadmium	
				from the toy is too high (measured	
				value: up to 3.16 mg/kg).	
				Cadmium is harmful to human health	
				because it accumulates in the body,	
				can damage the kidneys and bones,	
				and it may cause cancer. The	
				product does not comply with the	
				requirements of the Toy Safety	
				Directive and the European standard	
				EN 71-3.	
A12/00648/22	Poland	Toy Slime		Chemical	Withdrawal
				The migration of boron from the toy is	of the
		(Country of	New State	too high (measure value: up to	product from
		Origin:		1,101 mg/kg). Ingestion or contact	the market
		China)		with an excessive quantity of boron	
				may harm the health of children by	
				damaging their reproductive system.	
				The product does not comply with the	
				requirements of the Toy Safety	
				Directive and the European standard	
				EN 71-3.	
A12/00649/22	Poland	Toy Slime		Chemical	Destruction
				The migration of boron from the toy is	of the
		(Country of		too high (measured value: up to	product
		Origin:	wheth ES AMPEX 50,2 and 20 and 20 and	1,239 mg/kg). Ingestion or contact	
		China)	Windowski (Babel Poplaria) Windowski (Babel Poplaria) Wi	with an excessive quantity of boron	
				may harm the health of children by	
				damaging their reproductive system.	
				The product does not comply with the	
				requirements of the Toy Safety	
				Directive and the European standard	
				EN 71-3.	

A12/00650/22	Finland	Puffer Toy		Choking	Withdrawal
				The product can easily release small	of the
		(Country of	Contraction of the second	parts (eyes). A child may put them in	product from
		Origin:		the mouth and choke. The product	the market
		China)		does not comply with the	
				requirements of the Toy Safety	
				Directive and the European standard	
				EN 71-1.	
A12/00652/22	Austria	Toy Flute	TIMP	Choking, Damage to Hearing	Destruction
				The mouthpiece of the flute detaches	of the
		(Country of		easily, generating a small part. A	product
		Origin:		child may put it in the mouth and	
		Hong		choke. The sound pressure level is	
		Kong)	an a	too high (measured value: up to 117	
			E F	dB) which could lead to permanent or	
				temporary hearing loss. The product	
				does not comply with the	
				requirements of the Toy Safety	
				Directive and the European standard	
				EN 71-1.	
A12/00653/22	Austria	Тоу	· Ibaby	Choking	Withdrawal
		Clarinet		The keys of the instrument detach too	of the
				easily, resulting in small parts. A	product from
		(Country of		child playing with the instrument could	the market
		Origin:		put them in the mouth and choke.	
		Italy)		The product does not comply with the	
			G	requirements of the Toy Safety	
				Directive and the European standard	
			TIEM NO, TOEZO	EN 71-1.	

A12/00654/22	Belgium	Double Tip	ATHER DE LA CARA	Chemical	Recall of the
		Felt Pens		The felt pens' inks contain a mixture of	product from
			Relatives dals parts	the preservatives	end users
		(Country of		methylchloroisothiazolinone and	
		Origin:	Jesseesse sse	methylisothiazolinone (MCI/MI,	
		China)		measured values: up to 5.2 mg/kg	
				and 7.3 mg/kg, respectively).	
				Dermal contact with MCI and MI	
				containing products can provoke	
				allergic contact dermatitis to sensitive	
				persons. The product does not	
				comply with the requirements of the	
				Toy Safety Directive and the	
				European standard EN 71-10 and	
				EN 71-11.	
INFO/00088/2	Croatia	Baby		Injury	Withdrawal
2		Swing	E H	The lateral swing angle is too large,	of the
			F	and there is no protection from a	product from
		(Country of		restraining system. The baby can	the market
	Origin:	858	therefore fall from the swing and be		
		China)	injured. The product does not		
				comply with the requirements of the	
				General Product Safety Directive and	
				the European standard EN 16232.	

Safety Gate: the EU rapid alert system for dangerous non-food products

"Safety Gate", the EU rapid alert system (formerly known as 'RAPEX'), enables the rapid exchange of information between **31 European countries** and the European Commission on non- food dangerous products found on the market posing a risk to health and safety of consumers.

A weekly overview of the alerts on those products is published in English for free on <u>https://ec.europa.eu/safety-gate-alerts/screen/webReport#weeklyReports</u>. The measures taken in the notifying country in order to restrict their marketing or use can be ordered by national authorities ("compulsory measures") or be taken directly by producers and distributors ("voluntary measures").

The official contact points of the Member and EFTA-EEA States provide the information published in these weekly overviews. Under the terms of Annex II.10 of the General Product Safety Directive (2001/95/EC) responsibility for the information provided lies with the notifying party. The Commission does not take any responsibility for the accuracy of the information provided.

Recall Summary – US Toys / Children's Products

ESTC NEWSLETTER

CPSC Recall List (Apr 2022)

Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
22-113	USA	Clikk High	Y	Fall and Injury Hazards	Consumers should
		Chairs	T I	The white plastic seat can	immediately stop using
				break, posing fall and injury	the recalled white high
		(Country of		hazards to children. The	chairs and contact
		Origin: The		recalled high chair has a white	Stokke for a free
		Netherlands)		molded plastic seat and foot	replacement.
				rest with wooden legs. Only	Consumers will receive
				Clikk high chairs that are	the free replacement
				white in color, have item	Clikk high chair in white
				number 552104 and within the	after visiting Stokke's
				following serial number range	website to confirm their
				(135AA0057070 to	product is included in the
				135AA0057908) are included	recall and registering the
				in this recall.	product online.
22-116	USA	FAO Schwarz	Cherry Con	Choking Hazard	Consumers should
		Toy Wood Play	AT AB	Due to a manufacturing issue,	immediately take the
		Smart Robot		small parts from the products	recalled toys away from
		Buddy(s) and		can come loose, posing a	children, stop using
		FAO Schwarz		choking hazard to young	them and contact
		Toy Wood		children.	MerchSource to receive
		Sensory			a pre-paid label to return
		Boards			the recalled toys and
					instructions on how to
		(Country of			receive a full refund.
		Origin: China)			
22-124	USA	Children's		Risk of Burn Injury	Consumers should
		Pajamas		The children's pajamas fail to	
				meet the federal flammability	recalled pajamas away
		(Country of		standards for children's	from children and
		Origin: China)		sleepwear, posing a risk of	contact The Red League
				burn injury to children.	to receive a pre-paid
					mailer and instructions
					on how to return the
					garment(s) for a full
					refund.

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information. 13

22-126	USA	H for Happy™ Woven Bunny Baskets (Country of Origin: China)		Choking Hazard The recalled baskets are white woven baskets with bunny faces that have either pink or blue cheeks and black plastic eyes. The bunny basket's eyes can detach, posing a choking hazard to young children.	Consumers should immediately take the recalled baskets away from children and return them to any Bed Bath & Beyond location for a full refund.
22-741	USA	Monti Kids Wooden Push Toys (Country of Origin: Vietnam)	- Hereiter	Choking Hazard This recall involves Push Toys which are included with the Level 7 of the Monti Kids Program subscription box. The Push Toy consists of a wooden handle attached to a rolling cylinder, which contains wooden balls. The toy's rolling cylinder can separate, exposing the balls inside, posing a choking hazard to children.	Consumers should immediately take the recalled toy away from children, dispose of the toy by throwing it into the trash, and contact Monti Kids to receive a \$40 refund. The firm is contacting all known purchasers directly.
22-743	USA	AmazonBasics School Classroom Stack Chairs (Country of Origin: China)		Fall and Injury HazardsThisrecallinvolvesAmazonBasicsSchoolClassroom Stack Chairs. Thechairsaremade ofdurableplasticandhavechrome-platedmetallegs. Theystackableand weresold as aset of six chairs in pink, limegreen, yellow, blue, purple,and/orredcolors.The weldonthechair'sframeframecanfail,posingposing a fall hazard	Consumers should immediately stop using the recalled chairs and contact Amazon for instructions on how to dispose of the chairs for a full refund. Amazon is contacting all known purchasers directly.



ESTC

CPSC

The United States Consumer Product Safety Commission (CPSC) is an independent agency of the United States government. To provide better service in alerting the American people to unsafe, hazardous or defective products, a "one stop shop" for U.S. Government recalls, <u>www.recalls.gov</u>, has been created. Publics can report unsafe products to CPSC by using the platform.

NEWSLETTER

The recall list is divided into seven categories: Consumer Products, Motor Vehicles, Boats, Food, Medicine, Cosmetics and Environmental Products. Generally, the recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall program. Fast Track recalls are initiated by firms who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.

Recall Summary – Australia Toys / Children's Products

NEWSLETTER

ACCC Recall List (Apr 2022)

PRA No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
2022/19449	Australia	Roly Poly		Choking or Suffocation Hazard	Consumers
		Hard Plastic	roly paly conkuloo	The product does not comply with	should
		Cockatoo-	- Colar	the size and shape requirements	immediately stop
		Shaped Toy		of the mandatory safety standard	using the item
		with		for toys for children up to and	and return it to the
		Tinkling	X Y	including 36 months of age.	place of purchase
		Bell Sound		The yellow component of the	for a full refund.
				wing may detach, creating small	
		Batch		parts. Small parts may pose a	
		Number on		choking or suffocation hazard for	
		Packaging		young children, which can lead to	
		near		severe injury or death.	
		Barcode			
		#21180			

Australian Product Safety System

BESTC

The Australian product safety system is to maximize the safety of good by the cooperation of consumers, businesses and agencies. This policy sets out the principles adopted by the Australian Competition and Consumer Commission (ACCC) for prioritizing and addressing product safety risks.

Under the Australian Consumer Law, a responsible Minister can order a compulsory recall when there are hazards on the products. A voluntary recall could be conducted to remove the product from the marketplace when the suppliers become aware of unsafe or defective products.

The ACCC administers a national recalls system for recalls of specific and general consumer products, and publishes all product recalls on the website <u>https://www.productsafety.gov.au/recalls</u>.

STC (Hong Kong Standards and Testing Centre) is a not-for-profit, independent testing, inspection and certification organization. With a global network of ISO/IEC 17025 accredited testing laboratories and nearly 60 years of experience in consumer product testing, we can meet your conformity assessment needs with highly efficient and reliable service. Our testing scope and capabilities related to toys and children's products include but not limited to:

NEWSLETTER

EU Requirements

• EN 71

• Phthalates (EC) no. 1907/2006

ESTC

- Nickel Release (EC) no. 1907/2006
- Total Cadmium (EEC) no. 91/338
- Lead in Jewellery product (EC) no. 836/2012
- Azo-dye (EC) no. 1907/2006
- Bisphenol-A (2014/81/EU)
- DMF (Dimethylfumarate) (EU) no. 2011/135
- Flame retardants TCEP, TCPP, TDCP (2014/79/EU)
- Package Waste Directive (94/62/EC)

US & Canada Requirements

- ASTM F963
- CPSIA
- California Proposition 65
- 16 CFR 1501
- ASTM F2923 (Children's jewellery)
- ASTM F2999 (Adult's jewellery)
- US Toxic in Packaging Clearinghouse (TPCH)
- CCPSA Toys Regulations (SOR/2011-17)

Japan Requirements

- Japan Toy Safety Standard (ST)
- Japan Food Sanitation Law (JFSL)

Australia Requirements

- AS/NZS 8124
- Consumer Protection Notice No. 6 of 2010 DEHP

FOR MORE DETAILS, PLEASE CONTACT US:

Hong Kong: <u>hktcd@stc.group</u>	Dongguan: <u>dgtcd@stc.group</u>	Shanghai: <u>shtcd@stc.group</u>
Changzhou: <u>czstc@stc.group</u>	Vietnam: <u>vnstc@stc.group</u>	Japan: <u>jpo@stc.group</u>
U.S.A.: <u>usenquiry@stc.group</u>	Germany: <u>grstc@stc.group</u>	



