### **Recall Summary – European Toys**

JE STC NEWSLETTER

#### Notifying Product Measures Alert No. Product Hazard/ Risk Country Photo Adopted A11/00021/23 Poland Soft toy **Choking, Suffocation** Warning The foam filling material of the toy is easily consumers of (Country of accessible as some of the cover's seams may the risks Origin: break. A small child may put the filling material in the mouth and choke on it. Moreover, the China) plastic of the packaging is too thin. If a child plays with the packaging, the plastic can cover the mouth and nose, causing the child to suffocate. The product does not comply with the requirements of the Toy Safety Directive or with the European standard EN 71-1. A11/00022/23 Croatia Soft toy Choking Ban on the The fibrous stuffing material of the toy is easily marketing of (Country of accessible due to the weaknesses of certain the product Origin: seams. A small child may put the stuffing and China) material in the mouth and choke. The product accompanying does not comply with the requirements of the measures Toy Safety Directive or with the European standard EN 71-1. A11/00023/23 Latvia Stroller Informing and Iniuries The seat structure and a wheel of the stroller giving (Country of break easily so that the stroller can collapse instructions Origin: The and injure a child. The product does not comply **Netherlands** with the requirements of the General Product Safety Directive or with the European standard EN 1888-1. A11/00025/23 Destruction of Croatia Soft toy Choking Small parts may become detached. Also, the the product (Country of fibrous stuffing is accessible. A child may put Origin: any of these in the mouth and choke. The Türkiye) product does not comply with the requirements of the Toy Safety Directive or with the European standard EN 71-1.

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information

### EU Safety Gate Alerts (Feb 2023)

www.stc.group

```
📠 Headquarters - The Hong Kong Standards and Testing Centre Ltd. 🛛 💡 10 Dai Wang Street, Tai Po Industrial Estate, Tai Po, N.T., Hong Kong
```

### Issue no.: 09/23/TCD

# **ESTC** NEWSLETTER

A11/00026/23	Poland	Plastic toy		Cuts	Warning
//////0020/20	1 olaria	T lastic toy	Peppa fig	The ball surface and bottom of the cones have	consumers of
		(Country of		rough edges which can cause cuts to a user.	the risks
		Origin:	Beating Set	The product does not comply with the	
		China)		requirements of the Toy Safety Directive or with	
		Onna)		the European standard EN 71-1.	
A12/00218/23	Germany	Baby carrier		Injuries	Removal of
A12/00210/23	Germany	Baby carrier	107090	The carrier has an inadequate attachment	this product
		(Country of	AWARNING	system which means that a baby may slip out	-
		Origin:	And the second s		from the listing
		Ũ	0 100 C	of the carrier, fall and suffer injuries. The	by the online
		China)	Charles and Charles	product does not comply with the requirements	marketplace
			PP <sup>2</sup>	of the General Product Safety Directive or with	
				the European standard EN 13209-2.	
A12/00226/23	Czechia	Plastic doll		Chemical	Withdrawal of
				The plastic material of the head of the doll has	the product
		(Country of		an excessive concentration of bis (2-ethylhexyl)	from the
		Origin:		phthalate (DEHP) (measured value up to	market
		China)	COLORIDA DE LA COLORIDA	21,2% by weight). This phthalate may harm the	
				health of children, possibly causing damage to	
			Jashion Deather Con	their reproductive systems. The product does	
				not comply with the REACH Regulation.	
A12/00230/23	Italy	Plastic book	Contrari	Chemical	Ban on the
			a free and a second	The plastic material of the product has an	marketing of
		(Country of	contrari	excessive concentration of bis (2-ethylhexyl)	the product
		Origin:		phthalate (DEHP) (measured value up to 2.2%	and
		China)		by weight). This phthalate may harm the health	accompanying
			R	of children, possibly causing damage to their	measures
			© Officieline	reproductive systems. The product does not	
				comply with the REACH Regulation.	
A12/00231/23	Italy	Children's		Chemical	Ban on the
		bag	R	The plastic material of the product has an	marketing of
				excessive concentration of bis (2-ethylhexyl)	the product
		(Country of	I MACON	phthalate (DEHP) (measured value up to	and
		Origin:	- ( - mar	10.2% by weight). This phthalate may harm the	accompanying
		China)		health of children, possibly causing damage to	measures
				their reproductive systems The product does	
				not comply with the REACH Regulation.	

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

A12/00250/23	Poland	Plastic toy		Choking	Withdrawal of
				A small part (knob with metal rod) may be	the product
		(Country of	2 2 5	easily detached from the toy. A child may	from the
		Origin:		put the small part in the mouth and choke.	market
		China)		The product does not comply with the	
				requirements of the Toy Safety Directive or	
			wierzaki	with the European standard EN 71-1.	
A12/00255/23	Ireland	Inflatable	UIH. 🍸	Burns, Fire, Injuries	Recall of the
		children's		The product is flammable and may catch	product from
		costume	3. 72	fire and cause a fire if worn close to a	end users
				flame. A user and/or bystander may	
		(Country of		receive burns and injuries. The product	
		Origin:		does not comply with the requirements of	
		China)		the Toy Safety Directive.	
A12/00264/23	Poland	Pull-along		Choking	Small parts
		toy	Adar Toys	Small parts (plastic blocks) may easily	posing risk of
			Ани ADAR Алексолинато Макадализан Аникала	detach. A small child may put them in the	choking to be
		(Country of	Andrew Revenue and the or sale of the original and the or	mouth and choke. The product does not	removed from
		Origin:	ubdate update	comply with the requirements of the Toy	the toy
		China)	CIAGADLO	Safety Directive or with the European	
			5 19012711051959	standard EN 71-1.	
A12/00265/23	Poland	Toy gun set		Choking, Cuts, Damage to sight	Warning
				The suction cups of the projectiles can be	consumers of
		(Country of		easily detached. A child can put them in the	the risks
		Origin:		mouth and choke. Moreover, the protective	
		China)		glasses break easily, generating sharp	
				edges which may cause cuts or eye	
				injuries. The product does not comply with	
				the requirements of the Toy Safety	
				Directive or with the European standard EN	
				71-1.	
A12/00267/23	Poland	Rattle toy	11-23-34	Choking	Warning
				The toy has protruding parts (handles). A	consumers of
		(Country of		child could put these into the mouth, which	the risks
		Origin:		could block the airway and cause choking.	
		Belarus)		The product does not comply with the	
				requirements of the Toy Safety Directive or	
				with the European standard EN 71-1.	

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

					1
A12/00268/23	Finland	Тоу	2*	Choking	Stop of sales
		tractor		Small parts (a small wheel and the axel)	
			TRACTOR BELOW	may easily detach. A child may put them in	
		(Country of	RC INACION LTT	the mouth and choke. The product does not	
		Origin:		comply with the requirements of the Toy	
		China)		Safety Directive or with the European	
				standard EN 71-1.	
A12/00275/23	Latvia	Magnetic	Contract Vice and	Choking, Injuries	Withdrawal of
		toy		The toy is made of small parts (balls) with a	the product
				high magnetic flux. If a child swallows them,	from the
		(Country of	and the second s	they could attract one another causing	market
		Origin:		intestinal blockage or perforation. The	
		China)		product does not comply with the	
				requirements of the Toy Safety Directive or	
				with the European standard EN 71-1.	
A12/00283/23	Slovakia	Modelling	ATO	Chemical	Recall of the
		clay	MODELINA	The migration of boron from the modelling	product from
			50°	clay is too high in all available colours of the	end users
		(Country of	A Construction of the second s	product (measured values up to 2234	
		Origin:		mg/kg). Ingestion or contact with an	
		China)		excessive quantity of boron may harm the	
				health of children by damaging their	
				reproductive systems. The product does	
				not comply with the requirements of the Toy	
				Safety Directive or with the European	
				standard EN 71-3.	
A12/00286/23	France	Children's		Chemical	Recall of the
		balance		The dark leatherette of the handles	product from
		bike	No	contains DEHP and DINP (measured	end users
				values up to 14.87% and 1.23% by weight,	
		(Country of		respectively). These phthalates may harm	
		Origin:		the health of children, possibly causing	
		China)		damage to their reproductive systems and	
				livers. The product does not comply with	
				the REACH Regulation.	
A12/00288/23	Romania	Puffer toy	0 0 9 9	Choking	Withdrawal of
		,		Small parts (spikes) may easily detach from	the product
		(Country of	0 0 0	the toy. A small child may put them in the	from the
		Origin:	A BAR	mouth and choke. The product does not	market
		China)		comply with the requirements of the Toy	
				Safety Directive or with the European	
				Standard EN 71-1.	

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

110/0000 : /00	A ( )	<b>.</b>			<b>D</b>
A12/00294/23			à	Strangulation	Recall of the
		bag		The sleeping bag bears long functional cords	product from
				with free ends. These cords can become	end users
		(Country of		trapped while a child is sleeping, possibly	
		Origin:		causing strangulation. The product does not	
		Unknown)		comply with the requirements of the General	
				Product Safety Directive or with the	
				European standard EN 16781.	
A12/00295/23	Austria	Sleeping		Strangulation	Recall of the
		bag		The sleeping bag bears long functional cords	product from
			1	with free ends. These cords can become	end users
		(Country of		trapped while a child is sleeping, possibly	
		Origin:		causing strangulation. The product does not	
		Unknown)		comply with the requirements of the General	
				Product Safety Directive or with the	
				European standard EN 16781.	
A12/00303/23	The	Children's		Injuries, Suffocation	Recall of the
	Netherlands	cot		The distance between the slats on the side is	product from
			A CONTRACTOR OF A CONTRACT	too wide. A child may get stuck between two	end users
		(Country of	Martin MAATURA	slats and suffocate. Furthermore, there is a	
		Origin:		material imperfection on the cot's corner and	
		Poland)		the strength of the cot base is inadequate. A	
				child may become injured by the corner, or if	
				the cot base breaks. The product does not	
				comply with the requirements of the General	
				Product Safety Directive or with the	
				European standard EN 716-1.	
A12/00304/23	France	Electric		Chemical, Injuries	Recall of the
		balance	V 7	The plastic parts of the handles contain	product from
		bike for		DEHP, DIBP and DINP (measured values up	end users
		children		to 9.71%, 0.32% and 0.36% by weight,	
				respectively). These phthalates may harm	
		(Country of		the health of children, possibly causing	
		Origin:		damage to their reproductive systems and	
		China)		livers. Furthermore, the toy reaches a speed	
				that is too high (measured values: up to	
				10.36 km/h) and has an inadequate braking	
				capacity, which creates a risk of accident.	
				The product does not comply with the	
				REACH Regulation or with the requirements	
				of the Toy Safety Directive.	

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

A12/00313/23	Greece	Plastic doll	34	Chemical	Withdrawal of
				The plastic material of the product has an	the product
		(Country of		excessive concentration of	from the
		Origin:		bis(2-ethylhexyl) phthalate (DEHP) and	market
		China)		dibutyl phthalate (DBP) (measured	mantot
		Offina)		values up to 15.7 % and 0.48% by weight,	
				respectively). These phthalates may harm	
			AT ACCUL	the health of children, possibly causing	
			Tales of ladyburg cal weit	damage to their reproductive systems. The	
				· · · ·	
				product does not comply with the REACH	
140/00044/00	Einden d	0-44 1-44		Regulation.	Destruction of
A12/00314/23	Finland	Soft toy	66	Chemical, Choking	Destruction of
			Contract of the second s	The soft toy has a small part (suction cup)	the product
		(Country of	•	that may easily detach. A child may put it in	
		Origin:		the mouth and choke. Moreover, the plastic	
		China)	the second second	material of the suction cup contains an	
			ne	excessive concentration of dibutyl	
				phthalate (DBP) (measured value up to	
				8.9% by weight). This phthalate may harm	
				the health of children, possibly causing	
				damage to their reproductive systems. The	
				product does not comply with the REACH	
				Regulation, or with the requirements of the	
				Toy Safety Directive nor with the European	
				standard EN 71-1.	
A12/00315/23	Finland	Soft toy	Q	Choking	Import rejected
		with		The soft toy has a small part (dog's nose)	at border
		keychain	22-04689-03 KK Translate particular	that may easily detach. A child may put it in	
			litere according	the mouth and choke. The product does	
		(Country of		not comply with the requirements of the	
		Origin:		Toy Safety Directive or with the European	
		China)		standard EN 71-1.	
A12/00316/23	Finland	Soft toy		Choking	Destruction of
				The toy has small parts (eyes) and fibrous	the product
		(Country of		stuffing material which is easily accessible.	
		Origin:		A child may put this in the mouth and	
		China)		choke. The product does not comply with	
				the requirements of the Toy Safety	
				Directive or with the European standard EN	
				71-1.	

A12/00317/23	Finland	Soft toy		Chemical, Choking	Destruction
		-	1	The toy has a small part (suction cup) and	of the product
		(Country of	3	fibrous stuffing material that may easily detach.	
		Origin: China)		A child may put this in the mouth and choke.	
				The plastic material of the suction cup contains	
				an excessive concentration of	
				Di(2-ethylhexyl)phthalate (DEHP) (measured	
				value up to 40 % by weight). This phthalate	
				may harm the health of children, possibly	
				causing damage to their reproductive systems.	
				The product does not comply with the REACH	
				Regulation, or the requirements of the Toy	
				Safety Directive, or the European standard EN	
				71-1.	
A12/00318/23	Finland	Soft toy	A.	Chemical, Choking	Destruction
			·	The toy has a small part (suction cup) and	of the product
		(Country of	( ) ) /	fibrous stuffing material that can easily detach.	
		Origin: <b>China</b> )		A child may put it in the mouth and choke. The	
				plastic material of the suction cup contains an	
				excessive concentration of dibutyl phthalate	
				(DBP) (measured value up to 10 % by weight).	
				This phthalate may harm the health of children,	
				possibly causing damage to their reproductive	
				systems. The product does not comply with the	
				REACH Regulation, or the requirements of the	
				Toy Safety Directive, or the European standard	
				EN 71-1.	
A12/00319/23	Finland	Soft toy	# 18 m	Choking	Destruction
			- CALL	The toy has small parts (eyes) that may easily	of the product
		(Country of		detach. Children may put them in the mouth	
		Origin: China)		and choke. The product does not comply with	
			A A	the requirements of the Toy Safety Directive	
				nor with the European standard EN 71-1.	
A12/00320/23	Germany	Baby carrier	100	Injuries	Recall of the
				Due to the insufficient attachment options on	product from
		(Country of		the baby carrier, the support is inadequate and	end users
		Origin: <b>China</b> )		the baby may slip out of the carrier. The baby	
				may fall and suffer injuries. The product does	
				not comply with the requirements of General	
				Product Safety Directive or with the European	
				standard EN 13209-2.	

A12/00321/23	Poland	Toy bow and arrows set (Country of Origin: China)		<b>Choking, Damage to sight</b> The suction cups of the projectiles and arrows can easily detach. A child could put them in the mouth and choke. It is also possible to shoot arrows without the suction cups, and such arrows can hit the eye and cause serious injury. The product does not comply with the requirements of the Toy Safety Directive or the relevant European standard EN 71-1.	Warning consumers of the risks
A12/00330/23	France	Toy crossbow set (Country of Origin: Germany)		Injuries The product can shoot projectiles with excessive kinetic energy, which can cause injuries, especially to the eyes. The product does not comply with the requirements of the Toy Safety Directive, or with the European standard EN 71-1.	Withdrawal of the product from the market
A12/00334/23	Finland	Soft toy (Country of Origin: Unknown)	CUARE	<b>Choking</b> The toy contains small parts (plastic eyes) that may easily detach. Children may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive or with the European standard EN 71-1.	Withdrawal of the product from the market
A12/00335/23	Malta	Fancy dress (Country of Origin: Unknown)	Gaptain Gaptain	<b>Strangulation</b> The product has a long functional cord in the neck area which can become trapped during various activities of a child and possibly cause strangulation. The product does not comply with the requirements of the General Product Safety Regulation.	Recall of the product from end users
A12/00342/23	France	Toy soap (Country of Origin: United States)		<b>Choking</b> The chef's hat of the duck protrudes. A child can put it in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive or with the European standard EN 71-1.	Withdrawal of the product from the market

### Issue no.: 09/23/TCD

## **ESTC** NEWSLETTER

	1				
A12/00344/23	Belgium	Magnet		Choking, Injuries	Recall of the
		building set		The product contains small parts (metal	product from
				rods and balls). A child may put them in the	end users
		(Country of		mouth and choke. Furthermore, the	
		Origin:		magnetized metal rods exceed the	
		China)		maximum permitted magnetic flux value	
				(102.5 kG.mm <sup>2</sup> ). If various items are	
				swallowed, they could attract one another,	
				causing intestinal blockage or perforation.	
				The product does not comply with the	
				requirements of the Toy Safety Directive or	
				with the European standard EN 71-1.	
A12/00345/23	France	Тоу		Choking	Recall of the
		xylophone		Small parts (red ball from the mallet, feet	product from
				from the xylophone) are easily detached.	end users
		(Country of		Children may put them in the mouth and	
		Origin:		choke. The product does not comply with	
		China)		the requirements of the Toy Safety	
				Directive or with the European standard EN	
				71-1.	
A12/00346/23	Italy	Modelling		Chemical	Ban on the
		clay		The migration of boron from the modelling	marketing of
				clay is too high in all available colours of	the product and
		(Country of		the product (measured values up to 2250	accompanying
		Origin:		mg/kg). Ingestion or contact with an	measures
		China)		excessive quantity of boron may harm the	
				health of children by damaging their	
				reproductive systems. The product does	
				not comply with the requirements of the	
				Toy Safety Directive or with the European	
				standard EN 71-3.	
A12/00349/23	Greece	Plastic doll		Chemical	Withdrawal of
			· ·	The plastic material of the head of the doll	the product
		(Country of		has an excessive concentration of bis	from the
		Origin:	2	(2-ethylhexyl) phthalate (DEHP)	market
		China)		(measured value up to 34% by weight).	
			Rest Contractor	This phthalate may harm the health of	
				children, possibly causing damage to their	
				reproductive systems. The product does	
				not comply with the REACH Regulation.	

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

9

Kong WWW.stc.group

Germany	Baby carrier	- E WA	Injuries	Recall of the
			Due to the inadequate attachment options	product from
	(Country of		on the baby carrier, the support is	end users
	Origin:		insufficient and the baby may slip out of the	
	China)		carrier, fall and suffer serious injuries. The	
			product does not comply with the	
			requirements of General Product Safety	
			Directive.	
Luxembou	Electric		Chemical	Non-compliant
rg	balloon		The product releases an excessive amount	balloons will be
	puncher toy		of nitrosatable substances (measured	replaced by
			value up to 4.8 mg/kg) which can be	new compliant
	(Country of		converted into nitrosamines, which are	ones sent by
	Origin:		genotoxic carcinogens via inhalation,	SILVERLIT the
	China)		ingestion or dermal exposure. The	retailers in LU.
			product does not comply with the	
			requirements of the Toy Safety Directive or	
Latvia	Children`s		Entrapment, Injuries, Suffocation	Withdrawal of
co	cot		The distance between the slats is too wide.	the product
			A child may get stuck with its head or with a	from the
	(Country of	· ·		market
	-			
Latvia	Children`s			Withdrawal of
	cot			the product
				from the
	(Country of		5 , 5	market
	-			
			resistant, and may break or tip over.	
			Consequently, a user may receive injuries.	
			concequency, a door may receive injulies.	
			The product does not comply with the	
	Luxembou rg	Luxembou rgElectric balloon puncher toyLuxembou 	Luxembou rgElectric balloon puncher toy (Country of Origin: China)Image: China set of the set of	Image: Construction of the con

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

A12/00380/23	Latvia	Children`s		Entrapment, Injuries, Suffocation	Withdrawal of
A12/00300/23	Latvia	cot		The distance between the slats on the side	the product
		COL		is too large. A child may be entrapped	from the
		(Country of		between two slats and possibly suffocate.	market
					market
		Origin:		The product is not sufficiently stable or	
		Poland)		resistant and may break or tip over. A user	
				may be injured. The product does not	
				comply with the requirements of the	
				General Product Safety Directive or with	
				the European standard EN 716-1.	
A12/00387/23	France	Balloons	BALLONS	Chemical	Recall of the
			2.7. 1 44 7 350	The product releases an excessive amount	product from
		(Country of		of nitrosatable substances (measured	end users
		Origin:	ALS R	value up to 2.9 mg/kg). Nitrosatable	
		China)	RO CON	compounds can be converted into	
				nitrosamines, which are genotoxic	
				carcinogens via inhalation, ingestion or	
				dermal exposure. A child can get exposed	
				to them by putting the product in the mouth	
				The product does not comply with the	
				requirements of the Toy Safety Directive or	
				with the European standard EN 71-12.	
INFO/00006/23	France	Bath toy	Han	Chemical	No measures
				The toy releases an excessive amount of	yet taken
		(Country of	1 Contract	bisphenol A (measured value up to 0.2	
		Origin: India)	11 st	mg/I). Bisphenol A has endocrine	
		<u> </u>		disrupting properties and affects the	
				mammary glands, reproductive and	
				immune systems and may impair the	
				brain's development and create adverse	
				behavioural outcomes in children. The	
				product does not comply with the	
				requirements of the Toy Safety Directive.	
				requiremente et the rey eulog billotive.	

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

NEWSLETTER

### Safety Gate: the EU rapid alert system for dangerous non-food products

ESTC

"Safety Gate", the EU rapid alert system (formerly known as 'RAPEX'), enables the rapid exchange of information between **31 European countries** and the European Commission on non- food dangerous products found on the market posing a risk to the health and safety of consumers.

A weekly overview of the alerts on those products is published in English for free on https://ec.europa.eu/safety-gate-alerts/screen/webReport#weeklyReports. The measures taken in the notifying country in order to restrict such products' marketing or use can be ordered by national authorities ("compulsory measures") or be taken directly by producers and distributors ("voluntary measures").

The official contact points of the Member and EFTA-EEA States provide the information published in these weekly overviews. Under the terms of Annex II.10 of the General Product Safety Directive (2001/95/EC) responsibility for the information provided lies with the notifying party. The Commission does not take any responsibility for the accuracy of the information provided.

## **Recall Summary – US Toys / Children's Products**

**ESTC** NEWSLETTER

				CPS	C Recall List (Feb 2023)
Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
23-109	USA	Children's	<b>\$ \$ \$ \$ \$</b> \$ \$ \$	Burn Hazard	Consumers should immediately
		pajamas	<b></b>	Paper Cape Recalls Children's	take the recalled children's
				Pajamas Due to Violation of	pajamas away from children,
		(Country of		Federal Flammability Standards	stop using them and contact
		Origin: Peru)		and Burn Hazard	Paper Cape for a full refund or a
					refund in the form of store credit
				The recalled children's pajamas	for the original purchase price +
				fail to meet the federal	10%. Consumers should destroy
				flammability standards for	the recalled children's pajamas
				children's sleepwear, posing a risk	by cutting them in half then send
				of burn injuries to children.	Paper Cape a photo of the
					destroyed garment. Upon receipt
					of the photo, consumers will be
					issued a full refund of the
					purchase price or store credit for
					the original purchase price +
					10%. Paper Cape is contacting
					all known purchasers directly.
23-110	USA	Children's		Burn Hazard	Consumers should immediately
		robes		Children's Robes Recalled Due to	take the recalled robes away
				Violation of Federal Flammability	from children, stop using them
		(Country of		Standards and Burn Hazard;	and contact BTPEIHTD for a full
		Origin: China)	1 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Imported by BTPEIHTD; Sold	refund. Consumers who have
				Exclusively at Amazon.com	purchased the robes will be
					asked to destroy the garments
				The recalled children's robes fail	by cutting them in half and send
				to meet the federal flammability	BTPEIHTD a photo of the
				standards for children's	destroyed garment by email.
				sleepwear, posing a risk of burn	Upon receipt of the photo,
				injuries to children.	consumers will be issued a full
					refund of the purchase price.
					BTPEIHTD and Amazon are
					contacting all known purchasers
					directly.

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information. 13

Headquarters - The Hong Kong Standards and Testing Centre Ltd. 💡 10 Dai Wang Street, Tai Po Industrial Estate, Tai Po, N.T., Hong Kong

## NEWSLETTER

ESTC

00.444	110.4				
23-111	USA	Children's	Share	Burn Hazard	Consumers should immediately
		Robes		Children's Robes Recalled Due to	take the recalled robes away
				Violation of Federal Flammability	from children, stop using and
		(Country of	1 2/ 0	Standard and Burn Hazard;	destroy them by cutting them in
		Origin: China)	AT STOR	Imported by Betusline Official	half and contact Betusline
			- 4/1	Apparel; Sold Exclusively on	Official Apparel for a full refund.
			* * *	Amazon.com	Consumers who purchased the
					garments from Amazon.com will
				The recalled robes fail to meet	be contacted through Amazon's
				flammability standards for	messaging platform.
				children's sleepwear, posing a risk	
				of burn injuries to children.	
23-112	USA	Children's	the state the	Burn Hazard	Consumers should immediately
		robes	at nut	Children's Robes Recalled Due to	take the recalled robes away
				Violation of Federal Flammability	from children, stop using them
		(Country of	A A A A A A A A A A A A A A A A A A A	Standards and Burn Hazard;	and contact ChildLikeMe for a
		Origin: China)		Imported by ChildLikeMe; Sold	full refund. Consumers should
			E.	Exclusively at Amazon.com	destroy the robes by cutting
					them in half and email a photo of
				The recalled children's robes fail to	the destroyed garment to
				meet the federal flammability	ChildLikeMe at
				standards for children's	mtiinns@163.com. Upon receipt
				sleepwear, posing a risk of burn	of the photo, consumers will be
				injuries to children.	issued a full refund of the
					purchase price. ChildLikeMe and
					Amazon are contacting all
					known purchasers directly.
23-113	USA	Children's		Burn Hazard	Consumers should immediately
20 110	00/1	Robes		Children's Robes Recalled Due to	take the recalled robes away
		Robes	A PAR	Violation of Federal Flammability	from children, stop using them
		(Country of		Standards and Burn Hazard;	and contact SGMWVB for a full
		Origin: China)		Imported by SGMWVB Brand;	refund. Consumers who
		Oligin. China)	TO GATA	Sold Exclusively on Amazon.com	purchased the robes will be
				Sold Exclusively on Amazon.com	
				The recalled robes fail to meet the	asked to destroy the garments by cutting them in half and send
				federal flammability standards for	SGMWVB a photo of the
				children's sleepwear, posing a risk	destroyed robe by email.
				of burn injuries to children.	SGMWVB and Amazon are
					contacting all known purchasers
					directly.

23-117	USA	Silver Lining		Choking Hazard	Consumers should immediately
		Cloud	$\bigcirc$	Skip Hop Recalls Silver Lining	remove the raindrops on the
		Activity Gyms		Cloud Activity Gyms Due to	cloud toy by cutting them off with
				Choking Hazard	a pair of scissors, take a photo of
		(Country of			the cloud toy with the raindrops
		Origin: China)	w .	The raindrops on the cloud toy	removed, discard the raindrops
				included with the activity gym can	in the household trash, and
				detach from the ribbon, posing a	submit the photo of the cloud toy
				choking hazard if a child places it	with the raindrops cut off at
				in the mouth.	www.skiphoprecall.com.
23-121	USA	Children's		Burn Hazard	Consumers should immediately
		nightgowns		Children's Nightgowns Recalled	take the recalled nightgowns
				Due to Violation of Federal	away from children, stop using
		(Country of		Flammability Standards and Burn	them and contact Oaks Apparel
		Origin: China)		Hazard; Imported by The Oaks	for a full refund. Consumers who
				Apparel Company	purchased the nightgowns will
					be asked to destroy the
				The children's nightgowns fail to	nightgowns by cutting them in
				meet the federal flammability	half and send the recalling firm a
				standards for children's	photo of the destroyed garment
				sleepwear, posing a risk of burn	at jennifer@oaksapparel.com.
				injuries to children.	
23-122	USA	Children's		Burn Hazard	Consumers should immediately
		pajamas and		Hatley USA Recalls Children's	take the recalled products away
		headbands		Pajamas Due to Violation of	from children, stop using them
				Federal Flammability Standards	and contact Hatley USA for a full
		(Country of		and Burn Hazard and Children's	refund. Consumers should
		Origin: China)		Headbands Due to Violation of	destroy the pajamas by cutting
				Federal Lead Content Ban	them in half, break the headband
					and send Hatley USA a photo of
				The recalled children's pajamas	the destroyed recalled products
				fail to meet the federal flammability	by email at service@hatley.com.
				standards for children's	Upon receipt of the photo,
				sleepwear, posing a risk of burn	consumers will be issued a full
				injuries to children; and the	refund of the purchase price.
				children's headbands contain levels of lead that exceed the	Consumers can also return the
				federal lead content ban. Lead is	recalled products to any Hatley
					USA store. Hatley USA is
				toxic if ingested by young children and can cause adverse health	contacting all known purchasers
					directly.
				issues.	

23-123	USA	Children's		Burn Hazard	Consumers should
23-123	USA		1 main		
		nightgowns	105h	Betsy & Lace Recalls Children's	immediately take the recalled
			(MAD)	Nightgowns Due to Violation of	nightgowns away from
		(Country of	Marth	Federal Flammability Standard and	children, stop using them and
		Origin: <b>China</b> )	MATTER AND AND AND	Burn Hazard	destroy the nightgowns by
					cutting them in half. Betsy &
				The recalled children's nightgowns	Lace is contacting all known
				fail to meet the federal flammability	purchasers directly.
				standards for children's sleepwear,	
				posing a risk of burn injuries to	
				children.	
23-127	USA	"My First"		Choking Hazard	Consumers should
		Mickey		Kids Preferred Recalls "My First"	immediately take the recalled
		Mouse,		Disney-Character Figurines Due to	toys away from children and
		Minnie	-	Choking Hazard	contact Kids Preferred for
		Mouse, Buzz			instructions on receiving a full
		Lightyear,		The arms or legs on the figurines	refund. Consumers who
		and Stitch		can detach, posing a small part	register for the recall will
		Figurines		choking hazard to children.	receive a pre-paid shipping
					label to return the product to
		(Country of			the Firm for a full refund.
		Origin: China)			
23-134	USA	Lancaster		Fall Hazard	Consumers should
		Table &		Clark Associates Recalls Lancaster	immediately stop using the
		Seating brand		Table & Seating Brand High Chairs	recalled high chairs and return
		High Chairs	FEY	Due to Fall Hazard	them to any of the Restaurant
					Store locations in
		(Country of		The high chairs can break, posing a	Pennsylvania, New Jersey,
		Origin: China)		fall hazard to children.	Delaware or Maryland or
					contact Clark Associates for a
					free replacement or refund in
					the form of a store credit and
					instructions on how to properly
					discard the product.
					Consumers will be asked to
					submit a photo of the
					dismantled or destroyed
					product and dispose of it.
	1				

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

23-135	USA	Aderes	Over And Entrapment Hazards	Consumers should
		bookcases	TJX Recalls Bookcases Due to	immediately stop using the
			Tip-Over and Entrapment Hazards;	recalled bookcases and
		(Country of	Imported by Furniture Source	contact TJX for either a full
		Origin:	International; Sold at HomeGoods	refund or a refund in the form
		Mexico)		of store gift card and for
			The recalled bookcases are	instructions on how to receive
			unstable and can tip over if not	a free pick-up of the bookcase.
			anchored to the wall, posing tip-over	TJX is contacting known
			and entrapment hazards that can	purchasers directly.
			result in death or injuries to children.	
23-724	USA	Baby Sleep	Choking Hazard	Consumers should
		Sacks	WeeSprout Recalls Baby Sleep	immediately stop using, take
			Sacks Due to Choking Hazard	the recalled sleep sack and cut
		(Country of	(Recall Alert)	it in half with a pair of scissors,
		Origin: China)		take a photo of it, and discard it
		E	The zipper can detach from the	in the household
			sleep sack, posing a choking	trash. Contact WeeSprout to
			hazard.	receive a \$17 refund or credit
				in the form of a gift
				card. Email a photo
				documenting that the sleep
				sack has been destroyed along
				with your contact information to
				weecare@weesprout.com to
				receive the refund or credit.
				WeeSprout is contacting all
				known purchasers.

\* Source: www.recalls.gov

### **CPSC**

The United States Consumer Product Safety Commission (CPSC) is an independent agency of the United States government. To provide better service in alerting the American people to unsafe, hazardous or defective products, a "one stop shop" for U.S. Government recalls, <u>http://www.recalls.gov</u>, has been created. Members of the public may report unsafe products to CPSC by using the platform.

The recall list is divided into seven categories: Consumer Products, Motor Vehicles, Boats, Food, Medicine, Cosmetics and Environmental Products. Generally, the recall is conducted voluntarily by the company under CPSC's Fast Track Recall program. Fast Track recalls are initiated by firms who are committed to working with CPSC to quickly announce the recall and remedy to protect consumers.

## **Recall Summary – Australia Toys / Children's Products**

**ESTC** NEWSLETTER

	ACCC Recall List (Feb 20				
PRA No.	Notifying	Product/	Product	Hazard/ Risk	Remedy
FRA NO.	Country	Description	Photo		Kenieuy
2023/19703	Australia	Two piece		Choking Hazard	Consumers should
		clothing set with	the second s	Pom poms along the neck of the	immediately stop using
		a red wavy		top may come loose or be pulled	this outfit and return it to
		printed top with		off easily.	an Ollie's Place store to
		small pompoms			receive a full refund of
		along the neck		If a pom pom comes off, it may	the purchase price.
		and larger		pose a choking hazard for young	
		pompoms above		children leading to serious injury or	
		the front hem,		death.	
		and red leggings			
		with larger			
		pompoms above			
		the leg opening.			
		The set comes in			
		sizes from 1 to 5			
		years.			
		Style number:			
		EPJG7143			
2023/19711	Australia	Wooden baby		Choking Or Suffocation Hazard	Consumers should
		rattle	alla	The rattle set does not comply with	immediately stop using
			No.	the size and shape requirements	the rattle and place it
				of the mandatory safety standard	out of reach of
				for toys for children up to and	children. Consumers
				including 36 months of age.	should contact The
					Bomboniere Haus to
				The rattle may pose a choking or	arrange return of the
				suffocation hazard for young	rattle and receive a full
				children, which can lead to severe	refund.
				injury or death.	

ACCC Recall List (Feb 2023)

00000/10751					
2023/19714	Australia	8 sided child's	R	Choking Or Suffocation	Consumers should
		educational toy		Hazard	immediately stop using
		(including top	E	This product doesn't comply with	the product and return it
		and bottom)		the mandatory standard for toys	to the place of purchase
		with various	79 E.C.	for children up to and including	for a refund.
		activities on		36 months of age. The product	
		each side.		includes small parts.	
		Activities			
		include an		The small parts may pose a	
		abacus and		choking or suffocation hazard for	
		shape blocks.		young children.	
2023/19719	Australia	Children's		Hazard of Adverse Reaction	Consumers should stop
		Cosmetic Play		This product doesn't comply with	using the salon kits
		Set		the mandatory standard for	immediately and return
				cosmetic ingredient labelling.	them to the place of
				There is no ingredient list on the	purchase for exchange
				packaging.	or refund.
				Users may be exposed to	
				ingredients they are sensitive or	
				allergic to. If a user suffers an	
				adverse reaction, the user will	
				not be able to check the	
				ingredients list to identify the	
				possible cause and seek	
0000/10701				appropriate treatment.	
2023/19721	Australia	Mirage Junior	and a	Risk Of Drowning	Consumers should
		Swim Vest		The product does not comply	immediately stop using
		Flotation aid		with the requirements of the	the product and contact
		vest with high		mandatory standard for	Cape Byron Sports to
		visibility	-	swimming and flotation aids.	find their nearest store to
		colours blue			return the product for a
		and yellow,		• The product does not have the	full refund, credit, or
		adjustable		manufacturing batch	replacement.
		straps and		identification legibly marked on it	
		clips.		in a colour that contrasts the	
		Sizes: XS for		background colour.	
		1-3 years of		The product packaging does	
		age or 10-20		not include the required	
		kg. S for 3-6		information under the standard	
		years of age or			
		15-25 kg.			

Australia	Silicone		Choking Or Suffocation Hazard	Consumers should
raotralia		SILICOME SENSORY TRETHER	-	immediately stop using
			<b>°</b> °	the teether and return it
		30		
	on a timper ring	onscrima.		to the place of purchase
				for a full refund.
			silicone teething ring may detach.	
			, and the second s	
			infants and young children, which	
			can lead to severe injury or	
			death.	
Australia	Glow in the		Non-compliance of Cosmetic	Consumers should stop
	dark, water		Ingredient Labelling	using the paint
	washable face		This product doesn't comply with	immediately and return
	and body paint,		the mandatory standard for	it to the place of
	25ml.		cosmetic ingredient labelling. The	purchase for exchange
			ingredient list on the packaging is	or refund.
	Sold in various		not complete. The colour additive	
	colours.		is missing.	
	Item no.		Consumers may be exposed to	
	HW26307:		ingredients they are sensitive or	
	25ML		allergic to. If a consumer suffers	
			an adverse reaction the	
			consumer will not be able to	
			check the ingredients list to	
			identify the possible cause and	
			seek appropriate treatment.	
	Australia	AustraliaGlow in the dark, water washable face and body paint, 	teething ring with 6 nodules on a timber ringImage: Constant of the second	teething ring with 6 nodules on a timber ringThe silicone teething ring does not comply with the mandatory standard for toys for children up to and including 36 months of age, as small nodules from the silicone teething ring may detach.AustraliaGlow in the dark, water washable face and body paint, 25ml.Aletached nodule from the silicone teething ring may pose a choking or suffocation hazard for infants and young children, which can lead to severe injury or death.AustraliaGlow in the dark, water washable face and body paint, 25ml.Non-compliance of Cosmetic Ingredient Labelling This product doesn't comply with the mandatory standard for cosmetic ingredient labelling. The ingredient labelling. The ingredient labelling. The ingredient labelling. The ingredient labelling is not complete. The colour additive is missing.Item no. HW26307: 25MLConsumers may be exposed to ingredients they are sensitive or allergic to. If a consumer suffers an adverse reaction the consumer will not be able to check the ingredients list to identify the possible cause and

### Australian Product Safety System

The Australian product safety system is to maximize the safety of good by the cooperation of consumers, businesses and agencies. This policy sets out the principles adopted by the Australian Competition and Consumer Commission (ACCC) for prioritizing and addressing product safety risks.

Under the Australian Consumer Law, a responsible Minister can order a compulsory recall when there are hazards on the products. A voluntary recall could be conducted to remove the product from the marketplace when the suppliers become aware of unsafe or defective products.

The ACCC administers a national recalls system for recalls of specific and general consumer products, and publishes all product recalls on the website <u>https://www.productsafety.gov.au/recalls</u>.

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

STC (Hong Kong Standards and Testing Centre) is a not-for-profit, independent testing, inspection and certification organization. With a global network of ISO/IEC 17025 accredited testing laboratories and 60 years of experience in consumer product testing, we can meet your conformity assessment needs with our highly efficient and reliable service. Our testing scope and capabilities related to toys and children's products include inter alia the following:

### **EU Requirements**

- EN 71
- Phthalates (EC) no. 1907/2006
- Nickel Release (EC) no. 1907/2006
- Total Cadmium (EEC) no. 91/338
- Lead in Jewellery product (EC) no. 836/2012
- Azo-dye (EC) no. 1907/2006
- Bisphenol-A (2014/81/EU)
- DMF (Dimethyl fumarate) (EU) no. 2011/135
- Flame retardants TCEP, TCPP, TDCP (2014/79/EU)
- Package Waste Directive (94/62/EC)

### **US & Canada Requirements**

- ASTM F963
- CPSIA
- California Proposition 65
- 16 CFR 1501
- ASTM F2923 (Children's jewellery)
- ASTM F2999 (Adult's jewellery)
- US Toxic in Packaging Clearinghouse (TPCH)
- CCPSA Toys Regulations (SOR/2011-17)

### **Japan Requirements**

- Japan Toy Safety Standard (ST)
- Japan Food Sanitation Law (JFSL)

### **Australia Requirements**

- AS/NZS 8124
- Consumer Protection Notice No. 6 of 2010 DEHP

### FOR MORE DETAILS, PLEASE CONTACT US:

Hong Kong: <u>hktcd@stc.group</u>	Dongguan: <u>dgtcd@stc.group</u>	Shanghai: <u>shtcd@stc.group</u>
Changzhou: <u>czstc@stc.group</u>	Vietnam: <u>vnstc@stc.group</u>	Japan: jpo@stc.group
U.S.A.: <u>usenquiry@stc.group</u>	Germany: <u>grstc@stc.group</u>	

