










## Recall Summary – European Toys




### EU Safety Gate Alerts (May 2023)

Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A11/00047/23	Malta	<b>Pushchair</b>  (Country of Origin: <b>China</b> )		<b>Injuries</b> The handle may break, causing the user to lose control of the pushchair and a child may fall and suffer injuries. The product does not comply with the requirements of the General Product Safety Directive nor with the European Standard EN 1888-1.	Withdrawal of the product from the market
A11/00048/23	Malta	<b>Pushchair</b>  (Country of Origin: <b>Greece</b> )		<b>Injuries</b> The pushchair is not suitable for children under 6 months, even though it is advertised as such. A small child may fall out of the pushchair, leading to injuries. The product does not comply with the requirements of the General Product Safety Directive nor with the European Standard EN 1888-1.	Withdrawal of the product from the market
A11/00049/23	Poland	<b>Soft toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The fibrous stuffing material of the toy is easily accessible due to weakness of the seams. A small child may put the filling material in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Warning consumers of the risks
A11/00060/23	France	<b>Soft toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The fibrous stuffing material is easily accessible because the stitching on the back could come off. A child may put the filling material in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Recall of the product from end users

A12/00951/23	The Netherlands	<b>Sensory swing</b>  (Country of Origin: <b>China</b> )		<b>Strangulation</b> The flexible material of the swing can easily form a loop. A child can have their head entangled in the flexible material, leading to strangulation. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standards EN 71-1 and EN 71-8.	Recall of the product from end users
A12/00953/23	The Netherlands	<b>Sensory swing</b>  (Country of Origin: The Netherlands)		<b>Strangulation</b> The flexible material of the cloth swing can easily form a loop. A child may have their head entangled, leading to strangulation. The product does not comply with the requirements of the Toy Safety Directive.	Recall of the product from end users
A12/00954/23	The Netherlands	<b>Sensory swing</b>  (Country of Origin: <b>China</b> )		<b>Strangulation</b> The flexible cloth material of the swing can easily form a loop. A child can have their head entangled in the flexible material, leading to strangulation. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standards EN 71-1 and EN 71-8.	Recall of the product from end users
A12/00955/23	The Netherlands	<b>Sensory swing</b>  (Country of Origin: <b>China</b> )		<b>Strangulation</b> The flexible cloth material of the swing can easily form a loop. A child can have their head entangled in the flexible material, leading to strangulation. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standards EN 71-1 and EN 71-8.	Removal of this product listing by the online marketplace
A12/00975/23	Cyprus	<b>Plastic doll</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The plastic material of the product has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 20.8% by weight). This phthalate may harm the health of children, possibly causing damage to their reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market





A12/00976/23	Cyprus	<b>Plastic doll</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b>  The plastic material of the product has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) and dibutyl phthalate (DBP)(measured values up to 30.69% and 1.26% by weight, respectively). These phthalates may harm the health of children, possibly causing damage to their reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/00977/23	Cyprus	<b>Plastic doll</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b>  The plastic material of the product has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 28.9% by weight). This phthalate may harm the health of children, possibly causing damage to their reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/00978/23	Italy	<b>Soft toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b>  The foam filling material of the toy is easily accessible as some of the cover's seams may break. A small child may put the filling material in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Ban on the marketing of the product and any accompanying measures
A12/00982/23	Finland	<b>Toy bow and arrows set</b>  (Country of Origin: <b>Germany</b> )		<b>Chemical</b>  The material of the red grip has an excessive concentration of di-isononyl phthalate (DINP) (measured value up to 10% by weight). This phthalate may harm the health of children, possibly causing damage to their reproductive system. The product does not comply with the requirements of the Toy Safety Directive nor with the REACH Regulation.	Ban on the marketing of the product and any accompanying measures





A12/01009/23	France	<b>Toy cushion</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b>  The product has an excessive concentration of benzo[a]pyrene (measured value up to 2.21mg/kg). Benzo[a]pyrene is a polycyclic-aromatic hydrocarbon (PAH), which may cause cancer and is also mutagenic and toxic for reproduction. The product does not comply with the REACH Regulation.	Recall of the product from end users
A12/01011/23	Sweden	<b>Radio controlled car</b>  (Country of Origin: <b>China</b> )		<b>Chemical, Environment</b>  Several solders in the product have an excessive concentration of lead (measured value up to 78.3% by weight). Lead poses a risk to the environment. The USB cable plastic has an excessive concentration of short chain chlorinated paraffins (SCCPs) (measured value up to 3.08% by weight). SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations and bio-accumulate in wildlife and humans, posing a risk to human health and the environment. The plastic material of the black USB cable has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) and dibutyl phthalate (DBP) (measured values up to 0.8% and 0.9% by weight, respectively). These phthalates may harm health by possibly causing damage to the reproductive system. The product does not comply with the Persistent Organic Pollutants (POP) Regulation nor with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Withdrawal of the product from the market

A12/01016/23	Sweden	<b>Toy excavator</b>  (Country of Origin: <b>China</b> )		<b>Environment</b>  The product has an excessive concentration of lead in the solders on the USB printed circuit boards (PCBs) used in the toy (measured value up to 78% by weight). Lead poses a risk to the environment. Moreover, the solders on the engine have an excessive concentration of cadmium (measured value up to 0.15% by weight). Cadmium bio-accumulates and poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Withdrawal of the product from the market
A12/01017/23	Sweden	<b>Soap bubble toy</b>  (Country of Origin: <b>China</b> )		<b>Chemical, Environment</b>  The product has an excessive concentration of lead in the solder on the engine and on a connection to the battery (measured values up to 70% and 77% by weight, respectively). Lead poses a risk to the environment. The plastic in an internal cable has an excessive concentration of the dibutylphthalate (DBP) (measured value up to 0.25% by weight). This phthalate may harm health by possibly causing damage to the reproductive system. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Withdrawal of the product from the market
A12/01023/23	Hungary	<b>Plastic doll</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b>  The plastic material of the product has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 27% by weight). This phthalate may harm the health of children, possibly causing damage to the reproductive system. The product does not comply with the REACH Regulation.	Ban on the marketing of the product and any accompanying measures







A12/01028/23	France	<b>Key ring</b>  (Country of Origin: <b>Unknown</b> )		<b>Chemical</b> The plastic material of the dolls has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 2.85% by weight). This phthalate may harm the health of children, possibly causing damage to their reproductive system. The product does not comply with the REACH Regulation.	Recall of the product from end users
A12/01039/23	France	<b>Soft toy</b>  (Country of Origin: <b>Unknown</b> )		<b>Choking</b> Small parts (eyes) can easily detach. A small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Withdrawal of the product from the market
A12/01041/23	Belgium	<b>Fishing game</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> Small parts may easily detach. A child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Recall of the product from end users
A12/01054/23	Hungary	<b>Plastic doll with accessories</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The doll's head has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 0.17% by weight). This phthalate may harm the health of children, possibly causing damage to their reproductive system. The product does not comply with the REACH Regulation.	Destruction of the product
A12/01062/23	France	<b>Soft toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> Small parts (jacket buttons) can easily detach. A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Recall of the product from end users



A12/01067/23	Czechia	<b>Plastic doll</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The plastic material of the head of the doll has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 12.11% by weight). This phthalate may harm the health of children, possibly causing damage to their reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/01069/23	France	<b>Toy telephone</b>  (Country of Origin: <b>China</b> )		<b>Chemical, Choking</b> The battery compartment can be easily opened, leaving the batteries accessible. A child may put them in their mouth and choke on them or they can be swallowed, which could cause damage to the child's gastrointestinal tract. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 62115.	Removal of this product listing by the online marketplace
A12/01079/23	Poland	<b>Plastic swing</b>  (Country of Origin: <b>China</b> )		<b>Entrapment, Injuries</b> The product has accessible openings and accessible holes, in which children can become trapped or suffer injuries. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-8.	Withdrawal of the product from the market
A12/01096/23	Czechia	<b>Plastic doll</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The head of the doll has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 25% by weight). This phthalate may harm the health of children, possibly causing damage to their reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/01102/23	Czechia	<b>Plastic doll</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The head of the doll has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 21% by weight). This phthalate may harm the health of children, possibly causing damage to their reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market



A12/01139/23	France	<b>Soft toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b>  Small parts of the toy (suction cup) can easily detach. In addition, the fibrous stuffing material of the toy is easily accessible due to weakness of the seam on the top of the head of the toy. A small child may put the suction cup or filling material in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Recall of the product from end users
A12/01148/23	Poland	<b>Pushchair toy</b>  (Country of Origin: <b>China</b> )		<b>Strangulation</b>  The combined length of the cords attached to the toy is too long. The cords may become wrapped around a child's neck and cause strangulation. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Withdrawal of the product from the market
A12/01169/23	Czechia	<b>Electronic toy</b>  (Country of Origin: <b>China</b> )		<b>Environment</b>  The solder joint in the toy has an excessive amount of lead (measured value up to 73% by weight of lead). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Withdrawal of the product from the market
A12/01174/23	Sweden	<b>Toy with light projector</b>  (Country of Origin: <b>China</b> )		<b>Environment</b>  The solders in the product have an excessive concentration of lead (measured value up to 71.1% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Withdrawal of the product from the market





A12/01201/23	Poland	<b>Plastic doll</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b>  The toy has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 26.9% by weight). This phthalate may harm the health of children, possibly causing damage to their reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/01209/23	Hungary	<b>Fancy dress</b>  (Country of Origin: <b>China</b> )		<b>Burns</b>  The braided hair attached to the tiara is easily flammable and the flame propagation is too high. If it catches fire, a user and/or bystander could suffer burns. The product does not comply with the requirements of the Toy Safety Directive nor with European Standard EN 71-2.	Withdrawal of the product from the market
A12/01212/23	France	<b>Finger paint</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b>  The orange paint contains formaldehyde (measured value up to 958mg/kg by weight). Formaldehyde is a skin sensitizer and can trigger allergic reactions and may cause cancer. The black paint contains methylisothiazolinone (MI) (measured value up to 0.6mg/kg by weight), which is forbidden in leave-on cosmetics. Dermal contact with MI containing products can provoke allergic contact dermatitis to sensitised persons. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN-71-1, -2, -3 and -7.	Removal of this product listing by the online marketplace



A12/01219/23	Sweden	<p><b>Plastic doll</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Chemical, Environment</b></p> <p>The black plastic in the cable, solder in a connection to battery and solders on the PCB in the product have excessive concentrations of lead (measured values up to 0.27%, 60% and 53% by weight respectively). Lead poses a risk to the environment. Moreover, the solder in a connection to the battery has an excessive concentration of cadmium (measured value up to 0.24% by weight). Cadmium bio-accumulates and poses a risk to the environment. The plastic material in the cable has excessive concentrations of bis(2-ethylhexyl) phthalate (DEHP) and dibutyl phthalate (DBP) (measured values up to 2.26% and 1.43% by weight, respectively). These phthalates may harm health by possibly causing damage to the reproductive system. The plastic material in the cable has an excessive concentration of short chain chlorinated paraffins (SCCPs) (measured value up to 0.5% by weight). SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations and bio-accumulate in wildlife and humans, posing a risk to human health and the environment. Prolonged exposure to them through the skin may cause cancer. The product does not comply with Persistent Organic Pollutants (POP) Regulation nor with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).</p>	<p>Withdrawal of the product from the market</p>
--------------	--------	---	---	--	--

A12/01252/23	Ireland	<p><b>Baby self-feeding pillow</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Choking</b></p> <p>The pillow is placed around the baby's neck, the bottle is held in position by a piece of elastic or a pouch and the baby is positioned on their back to feed themselves without the assistance of a caregiver holding the bottle and controlling the feed. In this situation, the baby will not be able to control the flow of milk and the milk will continue to flow even if the baby is not swallowing. This can lead to choking. Choking can be silent and a baby will not have the dexterity or cognitive behavior to otherwise raise the alarm. The product does not comply with the requirements of the General Product Safety Directive.</p>	<p>Ban on the marketing of the product and any accompanying measures</p>
A12/01253/23	Ireland	<p><b>Baby self-feeding pillow</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Choking</b></p> <p>The pillow is placed around the baby's neck, the bottle is held in position by a piece of elastic or a pouch and the baby is positioned on their back to feed themselves without the assistance of a caregiver holding the bottle and controlling the feed. In this situation, the baby will not be able to control the flow of milk and the milk will continue to flow even if the baby is not swallowing. This can lead to choking. Choking can be silent and a baby will not have the dexterity or cognitive behavior to otherwise raise the alarm. The product does not comply with the requirements of the General Product Safety Directive.</p>	<p>Ban on the marketing of the product and any accompanying measures</p>

A12/01254/23	Ireland	<b>Baby self-feeding pillow</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The pillow is placed around the baby's neck, the bottle is held in position by a piece of elastic or a pouch and the baby is positioned on their back to feed themselves without the assistance of a caregiver holding the bottle and controlling the feed. In this situation, the baby will not be able to control the flow of milk and the milk will continue to flow even if the baby is not swallowing. This can lead to choking. Choking can be silent and a baby will not have the dexterity or cognitive behavior to otherwise raise the alarm. This product does not comply with the requirements of the General Product Safety Directive.	Ban on the marketing of the product and any accompanying measures
A12/01255/23	Ireland	<b>Baby self-feeding pillow</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The pillow is placed around the baby's neck, the bottle is held in position by a piece of elastic or a pouch and the baby is positioned on their back to feed themselves without the assistance of a caregiver holding the bottle and controlling the feed. In this situation, the baby will not be able to control the flow of milk and the milk will continue to flow even if the baby is not swallowing. This can lead to choking. Choking can be silent and a baby will not have the dexterity or cognitive behavior to otherwise raise the alarm. This product does not comply with the requirements of the General Product Safety Directive.	Ban on the marketing of the product and any accompanying measures



A12/01256/23	Ireland	<p><b>Baby self-feeding pillow</b></p> <p>(Country of Origin: China)</p>		<p><b>Choking</b></p> <p>A self-feeding pillow is designed to hold a bottle, keep it in the baby's mouth and free up the parent's hands, allowing the baby to feed themselves. The pillow is placed around the baby's neck, the bottle is held in position by a piece of elastic or a pouch and the baby is positioned on their back to feed themselves without the assistance of a caregiver holding the bottle and controlling the feed. In this situation, the baby will not be able to control the flow of milk and the milk will continue to flow even if the baby is not swallowing. This can lead to choking. Choking can be silent and a baby will not have the dexterity or cognitive behavior to otherwise raise the alarm. This product does not comply with the requirements of the General Product Safety Directive.</p>	<p>Ban on the marketing of the product and any accompanying measures</p>
A12/01258/23	Ireland	<p><b>Baby self-feeding pillow</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Choking</b></p> <p>The pillow is placed around the baby's neck, the bottle is held in position by a piece of elastic or a pouch and the baby is positioned on their back to feed themselves without the assistance of a caregiver holding the bottle and controlling the feed. In this situation, the baby will not be able to control the flow of milk and the milk will continue to flow even if the baby is not swallowing. This can lead to choking. Choking can be silent and a baby will not have the dexterity or cognitive behavior to otherwise raise the alarm. This product does not comply with the requirements of the General Product Safety Directive.</p>	<p>Ban on the marketing of the product and any accompanying measures</p>

A12/01259/23	Ireland	<b>Baby self-feeding pillow</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The pillow is placed around the baby's neck, the bottle is held in position by a piece of elastic or a pouch and the baby is positioned on their back to feed themselves without the assistance of a caregiver holding the bottle and controlling the feed. In this situation, the baby will not be able to control the flow of milk and the milk will continue to flow even if the baby is not swallowing. This can lead to choking. Choking can be silent and a baby will not have the dexterity or cognitive behavior to otherwise raise the alarm. This product does not comply with the requirements of the General Product Safety Directive.	Ban on the marketing of the product and any accompanying measures
INFO/00071/23	Malta	<b>Baby stroller</b>  (Country of Origin: <b>Bulgaria</b> )		<b>Choking</b> Small parts can detach (piece of protective material from the bumper bar). As a consequence, a small child may put the parts in their mouth and choke. The product does not comply with the requirements of the General Product Safety Directive nor with the European Standard EN 1888-1.	Withdrawal of the product from the market

## Safety Gate: the EU rapid alert system for dangerous non-food products

“Safety Gate”, the EU rapid alert system (formerly known as ‘RAPEX’), enables the rapid exchange of information between **31 European countries** and the European Commission on non- food dangerous products found on the market posing a risk to the health and safety of consumers.



A weekly overview of the alerts on those products is published in English for free on <https://ec.europa.eu/safety-gate-alerts/screen/webReport#weeklyReports>. The measures taken in the notifying country in order to restrict such products’ marketing or use can be ordered by national authorities ("compulsory measures") or be taken directly by producers and distributors ("voluntary measures").

The official contact points of the Member and EFTA-EEA States provide the information published in these weekly overviews. Under the terms of Annex II.10 of the General Product Safety Directive (**2001/95/EC**) responsibility for the information provided lies with the notifying party. The Commission does not take any responsibility for the accuracy of the information provided.


## Recall Summary – US Toys / Children’s Products

**CPSC Recall List (May 2023)**

Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
23-210	USA	<p><b>Janod Sweet Cocoon Activity Tables</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Choking Hazard</b> Juratoys Recalls Children’s Activity Tables Due to Choking Hazard</p> <p>The activity table contains a silver metal bell which can detach from its metal arch, posing a choking hazard to young children.</p>	<p>Consumers should immediately stop using the recalled activity tables and contact Juratoys for a free repair kit.</p>
23-752	USA	<p><b>L.O.L. Surprise! Trick or Treat subscription boxes sold with Metal Doll Pins</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Poisoning Hazard</b> CultureFly Recalls L.O.L. Surprise! Trick or Treat Subscription Boxes Sold with Metal Doll Pins Due to the Violation of the Federal Lead Paint Ban; Lead Poisoning Hazard (Recall Alert)</p> <p>The paint on the children’s metal doll pins contains levels of lead that exceed the federal lead paint ban, posing a lead poisoning hazard. Lead is toxic if ingested by young children and can cause adverse health effects.</p>	<p>Consumers should immediately take the recalled metal doll pins away from children, stop using them and contact CultureFly for a \$10 refund. Consumers will receive an e-mail with instructions to return or dispose of the recalled metal doll pins in accordance with local state laws. Known purchasers will be contacted directly by CultureFly.</p>

23-754	USA	<p><b>Children's white robes</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Burn Hazard</b></p> <p>The Company Store Recalls Children's White Robes Due to Violation of Federal Flammability Standards and Burn Hazard; Sold Exclusively at <a href="http://thecompanystore.com">thecompanystore.com</a> (Recall Alert)</p> <p>The recalled children's white robes fail to meet the federal flammability standards for children's sleepwear, posing a risk of burn injuries to children.</p>	<p>Consumers should immediately take the recalled robes away from children, stop using them and contact The Company Store for a full refund. Consumers should destroy the robes by cutting them both vertically and horizontally and dispose of them in accordance with local state recycling laws. The Company Store is contacting all known purchasers directly.</p>
23-761	USA	<p><b>The Preschool Electric Bicycles</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Poisoning Hazard</b></p> <p>Bunch Bikes Recalls The Preschool Electric Bicycles Due to Violation of the Federal Lead Paint Ban; Lead Poisoning Hazard (Recall Alert)</p> <p>The paint on the recalled electric bikes contains levels of lead that exceed the federal lead paint ban, posing a lead poisoning hazard. Lead is toxic if ingested by young children and can cause adverse health issues.</p>	<p>Consumers should immediately stop using the recalled Preschool electric bicycle and contact Bunch Bikes for free replacement wood panels. Bunch Bikes is contacting all known purchasers directly.</p>



23-762	USA	<p><b>The Good and the Beautiful Math 1 and Math 3 Boxes with metallic whiteboards</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Laceration Hazard</b></p> <p>The Good and the Beautiful Recalls Math 1 and Math 3 Boxes Due to Laceration Hazard (Recall Alert)</p> <p>The whiteboard attached to the boxes can become detached exposing sharp edges, posing a laceration hazard.</p>	<p>Consumers should immediately take the recalled whiteboards away from children, discard them and contact The Good and the Beautiful to receive a free non-metallic replacement. Consumers should visit <a href="http://www.goodandbeautiful.com/math-1-quality-reporting/">www.goodandbeautiful.com/math-1-quality-reporting/</a> for the Math 1 Box and <a href="http://www.goodandbeautiful.com/math-3-quality-reporting/">www.goodandbeautiful.com/math-3-quality-reporting/</a> for the Math 3 Box to complete a form with their contact information. The Good and the Beautiful is contacting known consumers directly.</p>
--------	-----	---	---	---	--

\* Source: [www.recalls.gov](http://www.recalls.gov)




## CPSC




The United States Consumer Product Safety Commission (CPSC) is an independent agency of the United States government. To provide better service in alerting the American people to unsafe, hazardous or defective products, a “one stop shop” for U.S. Government recalls, <http://www.recalls.gov>, has been created. Members of the public may report unsafe products to CPSC by using the platform.

The recall list is divided into seven categories: Consumer Products, Motor Vehicles, Boats, Food, Medicine, Cosmetics and Environmental Products. Generally, the recall is conducted voluntarily by the company under CPSC’s Fast Track Recall program. Fast Track recalls are initiated by firms who are committed to working with CPSC to quickly announce the recall and remedy to protect consumers.

## Recall Summary – Australia Toys / Children’s Products

**ACCC Recall List (May 2023)**

PRA No.	Notifying Country	Product/ Description	Product Photo	Hazard/ Risk	Remedy
2023/19765	Australia	<b>Fishing game set</b> <b>Includes: 1 dice, 2 fishing rods and 11 different figures</b>		<b>Choking or Suffocation Hazard</b> This product doesn't comply with the mandatory standard for toys for children up to and including 36 months of age. The product includes small parts.  The small parts may pose a choking or suffocation hazard for young children.	Consumers should immediately stop using the BLAVINGAD fishing game and contact IKEA for a full refund.
2023/19788	Australia	<b>ZARA branded boy's shirt, long-sleeved with brown buttons, in pale blue.</b>  <b>Sizes:</b> • 6-9 months • 9-12 months • 12-18 months • 18-24 months • 2-3 years • 3-4 years • 4-5 years		<b>Risk of Choking or Suffocation</b> The buttons on the front of the shirt are not adequately attached and may come off the shirt.  There is a risk of choking or suffocation in young children, leading to severe injury or death if a button detaches and is ingested.	Consumers should immediately stop using the shirt and return it to ZARA to receive a full refund of the purchase price.
2023/19796	Australia	<b>Pillow with padded front attachment, side loops and mesh pocket for bottle.</b>  <b>The pillow comes in various assorted colours and patterns.</b>		<b>Missing of Warnings</b> The product does not contain any warnings for consumers that it should not be used without adult supervision.  There is a risk of choking, suffocation or death if a child is left unsupervised in the pillow.	Consumers should cease using the product immediately and contact Twinkle Kids and Baby for a full refund at <a href="mailto:twinklekidsandbaby@gmail.com">twinklekidsandbaby@gmail.com</a>

2023/19797	Australia	<p><b>A wooden stick baby rattle 13cm long x 3 cm high.</b></p> <p><b>A wooden cage baby rattle 7cm long x 7 cm high.</b></p>		<p><b>Risk of Choking</b></p> <p>The rattles do not comply with size requirements of the mandatory safety standard for toys for children up to and including 36 months of age.</p> <p>There is a risk of choking, suffocation or death to young children if they continue to use these rattles.</p>	Consumers should immediately stop using the rattle.
2023/19801	Australia	<p><b>A wooden stick baby rattle with either brown or pink balls. The rattles were sold individually or in a set with a hairbrush, blanket or teether.</b></p>		<p><b>Risk of Choking</b></p> <p>The rattles do not comply with size requirements of the mandatory safety standard for toys for children up to and including 36 months of age.</p> <p>There is a risk of choking, suffocation or death to young children if they continue to use these rattles.</p>	Consumers should immediately stop using the rattle.
2023/19807	Australia	<p><b>Children's wooden jigsaw puzzles available in 3 models:</b></p> <ul style="list-style-type: none"> <li>• Elephant</li> <li>• Ship</li> <li>• Plane</li> </ul>		<p><b>Risk of Choking or Suffocation</b></p> <p>This product doesn't comply with the mandatory standard for toys for children up to and including 36 months of age. The product includes small parts.</p> <p>There is a risk of choking or suffocation to young children due to the puzzle containing small parts.</p>	Consumers should immediately stop using the product and place out of reach of children.

## Australian Product Safety System

The Australian product safety system is to maximize the safety of good by the cooperation of consumers, businesses and agencies. This policy sets out the principles adopted by the Australian Competition and Consumer Commission (ACCC) for prioritizing and addressing product safety risks.

Under the Australian Consumer Law, a responsible Minister can order a compulsory recall when there are hazards on the products. A voluntary recall could be conducted to remove the product from the marketplace when the suppliers become aware of unsafe or defective products.

The ACCC administers a national recalls system for recalls of specific and general consumer products, and publishes all product recalls on the website <https://www.productsafety.gov.au/recalls>.

STC (Hong Kong Standards and Testing Centre) is a not-for-profit, independent testing, inspection and certification organization. With a global network of ISO/IEC 17025 accredited testing laboratories and 60 years of experience in consumer product testing, we can meet your conformity assessment needs with our highly efficient and reliable service. Our testing scope and capabilities related to toys and children's products include inter alia the following:

### EU Requirements

- EN 71
- Phthalates (EC) no. 1907/2006
- Nickel Release (EC) no. 1907/2006
- Total Cadmium (EEC) no. 91/338
- Lead in Jewellery product (EC) no. 836/2012
- Azo-dye (EC) no. 1907/2006
- Bisphenol-A (2014/81/EU)
- DMF (Dimethyl fumarate) (EU) no. 2011/135
- Flame retardants TCEP, TCPP, TDCP (2014/79/EU)
- Package Waste Directive (94/62/EC)

### US & Canada Requirements

- ASTM F963
- CPSIA
- California Proposition 65
- 16 CFR 1501
- ASTM F2923 (Children's jewellery)
- ASTM F2999 (Adult's jewellery)
- US Toxic in Packaging Clearinghouse (TPCH)
- CCPSA - Toys Regulations (SOR/2011-17)

### Japan Requirements

- Japan Toy Safety Standard (ST)
- Japan Food Sanitation Law (JFSL)

### Australia Requirements

- AS/NZS 8124
- Consumer Protection Notice No. 6 of 2010 - DEHP

Hong Kong: [hktcd@stc.group](mailto:hktcd@stc.group)

Changzhou: [czstc@stc.group](mailto:czstc@stc.group)

U.S.A.: [usenquiry@stc.group](mailto:usenquiry@stc.group)

Guangdong: [gdtcd@stc.group](mailto:gdtcd@stc.group)

Vietnam: [vnstc@stc.group](mailto:vnstc@stc.group)

Germany: [grstc@stc.group](mailto:grstc@stc.group)

Shanghai: [shtcd@stc.group](mailto:shtcd@stc.group)

Japan: [jpo@stc.group](mailto:jpo@stc.group)

