

## Recall Summary – European Toys

### EU Safety Gate Alerts (June 2023)

Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
A11/00063/23	Iceland	<b>Baby swing</b>  (Country of Origin: <b>China</b> )		<b>Injuries</b> When the seat is in the most reclined position, the swing may tilt close to the horizontal surface, causing the baby to fall and suffer injuries. The locking mechanism on the product does not engage automatically, allowing the product to fold and lose stability, causing the baby to fall and suffer injuries. The product does not comply with the requirements of the General Product Safety Directive, nor with the European standard EN 16232.	Recall of the product from end users
A11/00069/23	Hungary	<b>Toy scooter</b>  (Country of Origin: <b>China</b> )		<b>Injuries</b> The fixing of the steering tube is not sufficiently stable. The steering column may slide down during use. This could cause the child to lose balance and fall off, leading to injuries. In addition, the fixing holes of the steering tube are larger than 5 mm. A child can stick their finger in it and be injured. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market
A11/00072/23	Finland	<b>Perfume kit</b>  (Country of Origin: <b>Portugal</b> )		<b>Chemical</b> The product has no appropriate labelling and lacks the required warnings, thus users are not sufficiently informed of the dangers of the product. The user may be exposed to sensitising chemicals and develop an allergic reaction. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-13.	Withdrawal of the product from the market

A11/00079/23	Croatia	<b>Soft toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The fibrous stuffing material of the toy is easily accessible due to weakness of the seams. A small child may put the filling material in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Ban on the marketing of the product and any accompanying measures
A11/00080/23	France	<b>Soft toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The fibrous stuffing material of the toy is easily accessible due to weakness of the seams. A small child may put the filling material in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Removal of this product listing by the online marketplace
A12/01283/23	Czechia	<b>Plastic doll</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The toy has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 18.8% by weight). This phthalate may harm the health of children, possibly causing damage to their reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/01285/23	Hungary	<b>Toy mask</b>  (Country of Origin: <b>China</b> )		<b>Burns</b> The mask is easily flammable. If it catches fire, a user/child could suffer burns. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-2.	Recall of the product from end users
A12/01296/23	Poland	<b>Plastic doll</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The toy has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 32.4% by weight). This phthalate may harm the health of children, possibly causing damage to their reproductive system. The product does not comply with the REACH Regulation.	Destruction of the product

A12/01310/23	Czechia	<b>Magnet building set</b>  (Country of Origin: <b>China</b> )		<b>Choking, Injuries</b> The product contains small parts (metal rods and balls). A child may put them in their mouth and choke. Furthermore, the magnetised metal rods exceed the maximum permitted magnetic flux value (109.4 kG.mm <sup>2</sup> ). If various items are swallowed, they could attract one another, causing intestinal blockage and/or perforation. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Recall of the product from end users
A12/01321/23	The Netherlands	<b>Baby walker</b>  (Country of Origin: <b>Türkiye</b> )		<b>Injuries</b> The baby walker does not provide protection against falls and could fall down a flight of stairs, causing injuries to the child. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 1273.	Recall of the product from end users
A12/01323/23	Sweden	<b>Soap bubble machine</b>  (Country of Origin: <b>China</b> )		<b>Environment</b> The solders in the product have an excessive concentration of lead and cadmium (measured values up to 80% and 0.15 by weight, respectively). Lead and cadmium pose a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Removal of this product listing by the online marketplace
A12/01339/23	Czechia	<b>Plastic doll</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The toy has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 12.52% by weight). This phthalate may harm the health of children, possibly causing damage to the reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market

A12/01345/23	France	<b>Torch</b>  (Country of Origin: <b>China</b> )		<b>Chemical, Choking</b>  The battery compartment can easily be opened, leaving the button batteries accessible. A child may put them in their mouth and choke on them or they can be swallowed, which could cause damage to the child's gastrointestinal tract. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 62115.	Removal of this product listing by the online marketplace
A12/01366/23	France	<b>Key ring with soft toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b>  Small parts (eyes) can easily detach. A small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Ban on the marketing of the product and any accompanying measures
A12/01370/23	Belgium	<b>Pushchair</b>  (Country of Origin: <b>China</b> )		<b>Injuries</b>  The parking brake of the pushchair does not work adequately. A parent / carer may lose control over the pushchair, leading to injuries to the child. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 1888-1.	Recall of the product from end users
A12/01379/23	France	<b>Soft toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b>  Small plastic parts (rabbit's eyes and nose) can easily detach from the toy. A child may swallow these small parts and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Recall of the product from end users
A12/01383/23	France	<b>Soft toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b>  Small plastic parts (rabbit's eyes and nose) can easily detach from the toy. A child may swallow these small parts and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Recall of the product from end users

A12/01387/23	The Netherlands	<b>Toy remote control</b>  (Country of Origin: <b>China</b> )		<b>Choking</b>  Small parts (silicone buttons) can easily detach. A child could put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Recall of the product from end users
A12/01389/23	The Netherlands	<b>Toy remote control</b>  (Country of Origin: <b>China</b> )		<b>Choking</b>  Small parts (buttons) can easily detach. A child could put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Recall of the product from end users
A12/01390/23	Belgium	<b>Soap bubble toy</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b>  The product has excessive concentrations of methylisothiazolinone (MI), methylchloroisothiazolinone (MCI), and formaldehyde (measured values up to 2.5 mg/kg, 7.3 mg/kg and 330 mg/kg respectively). MI, MCI, and formaldehyde are strong sensitizers and can provoke allergic contact dermatitis to sensitized persons. The product does not comply with the requirements of the Toy Safety Directive.	Recall of the product from end users
A12/01392/23	France	<b>Finger paint</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b>  The product has excessive concentrations of methylisothiazolinone (MI), methylchloroisothiazolinone (MCI), and benzisothiazolinone (measured values up to 12.1 mg/kg, 19.6 mg/kg and 13.1 mg/kg respectively). MI, MCI, and benzisothiazolinone are strong sensitizers and can provoke allergic contact dermatitis to sensitized persons. The product does not comply with the requirements of the Toy Safety Directive, nor with the European standard EN 71-7.	Removal of this product listing by the online marketplace

A12/01394/23	Poland	<b>Plastic doll</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The toy has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 11.8% by weight). This phthalate may harm the health of children, possibly causing damage to their reproductive system. The product does not comply with the REACH Regulation.	Destruction of the product
A12/01397/23	France	<b>Paint stamp</b>  (Country of Origin: <b>China</b> )		<b>Chemical, Choking</b> The product has excessive concentrations of methylisothiazolinone (MI), methylchloroisothiazolinone (MCI), and formaldehyde (measured values up to 40.3 mg/kg, 29.3 mg/kg and 509 mg/kg, respectively). MI, MCI, and formaldehyde are strong sensitizers and can provoke allergic contact dermatitis to sensitized persons. Moreover, the foam of the ink pad tears easily, a small child may put the foam in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Blocking of other advertisements using EAN barcodes and the product fiche
A12/01399/23	Croatia	<b>Toy slime</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The migration of boron from the toy slime is too high (measured value up to 1061 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-3.	Destruction of the product
A12/01403/23	Croatia	<b>Plasticine</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The product contains an excessive amount of lead (measured value up to 9.37 mg/kg). Lead is harmful to human health, accumulates in the body, can cause developmental neurotoxicity and may also affect breast-fed or unborn children. The product does not comply with the requirements of the Toy Safety Directive.	Import rejected at border

A12/01405/23	Hungary	<b>Baby walker</b>  (Country of Origin: <b>Unknown</b> )		<b>Injuries</b> The strength of the baby walker is inadequate and there is no proper protection against falls on stairs. The product can consequently collapse or fall down a flight of stairs during use, leading to injuries to a child. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 1273.	Recall of the product from end users
A12/01406/23	Hungary	<b>Plastic doll</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The doll has an excessive concentration of di-2-ethylhexyl phthalate (DEHP) (measured value up to 32% by weight). This phthalate may harm the health of children, possibly causing damage to their reproductive system. The product does not comply with the REACH Regulation.	Recall of the product from end users
A12/01411/23	The Netherlands	<b>Laser toy</b>  (Country of Origin: <b>China</b> )		<b>Damage to sight</b> The laser beam is too powerful and direct viewing of it can cause damage to sight. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 60825-1.	Withdrawal of the product from the market
A12/01420/23	Poland	<b>Plastic ball</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The toy contains an excessive concentration of dibutyl phthalate (DBP) (measured value up to 28.9% by weight). This phthalate may harm the health of children, possibly causing damage to their reproductive system. The product does not comply with the REACH Regulation.	Warning consumers of the risks
A12/01424/23	France	<b>Fancy-dress costume</b>  (Country of Origin: <b>China</b> )		<b>Injuries, Strangulation</b> The product bears long functional cords at the level of the cape of the costume which can become trapped during various activities of a child, leading to injuries or strangulation. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 14682.	Removal of this product listing by the online marketplace

A12/01427/23	France	<b>Toy traffic lights</b>  (Country of Origin: <b>China</b> )		<b>Chemical, Choking</b>  The battery compartment can easily be opened without a tool, making the button batteries accessible. A child could put the batteries into their mouth and choke. The button batteries can also cause damage to the digestive tract if swallowed. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 62115.	Recall of the product from end users
A12/01431/23	The Netherlands	<b>Toy car keys</b>  (Country of Origin: <b>China</b> )		<b>Choking</b>  Small parts (buttons) may easily detach from the toy. A child could put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Recall of the product from end users
A12/01457/23	France	<b>Toy xylophone</b>  (Country of Origin: <b>China</b> )		<b>Choking</b>  The toy has a small part (the plastic stud). A small child may put it in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Recall of the product from end users
INFO/00088/23	Sweden	<b>Whale toy</b>  (Country of Origin: <b>China</b> )		<b>Environment</b>  The solders on the PCB and the engine have excessive concentrations of lead (measured values up to 64.6% and 71.5% by weight, respectively). Lead poses a risk to the environment. The solders on the engine have an excessive concentration of cadmium (measured value: up to 0.13% by weight). Cadmium bio-accumulates and poses a risk to the environment. The product does not comply with the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Stoppage of sales

## Safety Gate: the EU rapid alert system for dangerous non-food products

“Safety Gate”, the EU rapid alert system (formerly known as ‘RAPEX’), enables the rapid exchange of information between **31 European countries** and the European Commission on non- food dangerous products found on the market posing a risk to the health and safety of consumers.

A weekly overview of the alerts on those products is published in English for free on <https://ec.europa.eu/safety-gate-alerts/screen/webReport#weeklyReports>. The measures taken in the notifying country in order to restrict such products’ marketing or use can be ordered by national authorities ("compulsory measures") or be taken directly by producers and distributors ("voluntary measures").

The official contact points of the Member and EFTA-EEA States provide the information published in these weekly overviews. Under the terms of Annex II.10 of the General Product Safety Directive (**2001/95/EC**) responsibility for the information provided lies with the notifying party. The Commission does not take any responsibility for the accuracy of the information provided.

## Recall Summary – US Toys / Children’s Products

**CPSC Recall List (June 2023)**

Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
23-211	USA	<b>Jetson Nova and Star 3-Wheel Kick Scooters</b>  (Country of Origin: <b>China</b> )		<b>Fall Hazard</b> Jetson Electric Bikes Recalls Nova and Star 3-Wheel Kick Children’s Scooters Due to Fall Hazard  The rear wheel can loosen or fall off the scooter, posing a fall hazard to children.	Consumers should immediately stop using the recalled Jetson Nova and Star 3-Wheel Kick Scooters and contact Jetson for a free repair kit. The kit includes two screws, two bolts and an Allen key, along with repair instructions and a QR code link to an installation video. Consumers will not need additional tools to install the repair kit.
23-229	USA	<b>Robo Alive Junior Baby Shark Sing &amp; Swim Bath Toys (full-size) and Robo Alive Junior Mini Baby Shark Swimming Bath Toys (mini-size)</b>  (Country of Origin: <b>China</b> )		<b>Risk of Impalement, Laceration and Puncture Injuries</b>  Zuru Recalls 7.5 Million Baby Shark and Mini Baby Shark Bath Toys With Hard Plastic Top Fins Due to Risk of Impalement, Laceration and Puncture Injuries to Children  When using the recalled bath toys, particularly in a bathtub or wading pool, a child can slip and fall or sit onto the hard plastic top fin of the shark, posing risks of impalement, lacerations and punctures.	Consumers should immediately stop using the recalled bath toys and contact Zuru for a full refund of \$14 for each full-size bath toy or \$6 for each mini-size bath toy, in the form of a prepaid virtual Mastercard. Consumers should disable the tail fin (by cutting it on the full-size bath toy or by bending it on the mini-size bath toy), mark the body of the shark bath toy with the word “recalled” and the unique code provided during registration for the recall, then upload a photo of the product, showing it is disabled and marked, at <a href="https://www.recallrtr.com/bathshark">https://www.recallrtr.com/bathshark</a> . Upon receipt of the photo, Zuru will issue a refund to purchasers.

23-230	USA	<p><b>Hurtle Multi-Purpose Helmet</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Risk of Head Injury</b></p> <p>Sound Around Recalls Children’s Multi-Purpose Helmets Due to Risk of Head Injury</p> <p>The recalled helmets do not comply with the positional stability requirements of the U.S. CPSC federal safety standard for bicycle helmets. The helmets can fail to protect in the event of a crash, posing a risk of head injury.</p>	<p>Consumers should immediately stop using the recalled helmets and contact Sound Around to receive a full refund of the purchase price. To receive a refund consumers should destroy the helmet by cutting off the straps, upload photos of the helmet with the straps cut to the recall registration website and then dispose of the recalled helmet. Consumers who received the unit as a free promotion should dispose of the unit so that children cannot use it.</p>
23-237	USA	<p><b>Canvas Baby Hammock Swings</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Suffocation Hazard</b></p> <p>CaTeam Recalls Canvas Baby Hammock Swings Due to Suffocation Hazard; Violation of Safe Sleep for Babies Act on Inclined Infant Sleep Products</p> <p>The inclined sleeper is a banned hazardous product under the Safe Sleep for Babies Act since the product was marketed for infant sleep and has an incline angle greater than 10 degrees. Infant fatalities have occurred in inclined sleepers after the infants rolled from their back to their stomach or side while unrestrained, or under other circumstances.</p>	<p>Consumers should immediately stop using the recalled baby hammock swings and contact CaTeam for instructions on how to receive a full refund and properly dispose of the product. CaTeam and Amazon are contacting all known purchasers.</p>

23-763	USA	<p><b>Narskido Infant Bath Seats</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Drowning Hazard</b></p> <p>TopGlore Recalls Narskido Infant Bath Seats Due to Drowning Hazard; Sold Exclusively on Amazon.com (Recall Alert)</p> <p>The bath seats fail to meet the federal safety standard for infant bath seats, including requirements for stability and leg openings, and can tip over while in use, posing a drowning hazard to babies.</p>	<p>Consumers should immediately stop using the recalled infant bath seats and contact TopGlore through the Amazon platform for a full refund of the purchase price. Consumers will be asked to dispose of the recalled product. TopGlore and Amazon are notifying all known purchasers directly through the Amazon platform.</p>
23-766	USA	<p><b>Deux Par Deux Children's One-Piece and Two-Piece Pajama Sets</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Burn Hazard</b></p> <p>Children's Pajamas Recalled Due to Violation of Federal Flammability Standards and Burn Hazard; Imported by Deux Par Deux (Recall Alert)</p> <p>The recalled children's pajamas fail to meet the federal flammability standards for children's sleepwear, posing a risk of burn injuries to children.</p>	<p>Consumers should immediately take the recalled children's pajamas away from children, stop using them and contact Deux Par Deux for instructions on how to dispose of the pajamas for a full refund. Deux Par Deux is directly contacting all known purchasers.</p>
23-767	USA	<p><b>Little Cotton Clothes Pajamas and Nightdresses</b></p> <p>(Country of Origin: <b>India</b>)</p>		<p><b>Burn Hazard</b></p> <p>Children's Pajamas and Nightdresses Recalled Due to Violation of Federal Flammability Standards and Burn Hazard; Imported by Little Cotton Clothes (Recall Alert)</p> <p>The recalled children's pajamas and nightdresses fail to meet the federal flammability standards for children's sleepwear, posing a risk of burn injuries to children.</p>	<p>Consumers should immediately take the recalled children's pajamas and nightdresses away from children, stop using them and contact Little Cotton Clothes for instructions on how to dispose of the pajamas for a full refund. Little Cotton Clothes is directly contacting all known purchasers.</p>

23-770	USA	<p><b>Zooby video baby monitors for cars</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Fire Hazard</b></p> <p>Infanttech Recalls Zooby Video Baby Monitors for Cars Due to Fire Hazard (Recall Alert)</p> <p>The baby monitor's battery can malfunction, overheat and burst, posing a fire hazard.</p>	<p>Consumers should immediately remove the battery from the plush camera and can continue using the Zooby plush camera and monitor plugged in. Contact Infanttech for a free replacement battery. Infanttech is contacting all known purchasers.</p>
--------	-----	---	---	---	--

\* Source: [www.recalls.gov](http://www.recalls.gov)

## CPSC

The United States Consumer Product Safety Commission (CPSC) is an independent agency of the United States government. To provide better service in alerting the American people to unsafe, hazardous or defective products, a “one stop shop” for U.S. Government recalls, <http://www.recalls.gov>, has been created. Members of the public may report unsafe products to CPSC by using the platform.

The recall list is divided into seven categories: Consumer Products, Motor Vehicles, Boats, Food, Medicine, Cosmetics and Environmental Products. Generally, the recall is conducted voluntarily by the company under CPSC’s Fast Track Recall program. Fast Track recalls are initiated by firms who are committed to working with CPSC to quickly announce the recall and remedy to protect consumers.

## Recall Summary – Australia Toys / Children’s Products

**ACCC Recall List (June 2023)**

PRA No.	Notifying Country	Product/ Description	Product Photo	Hazard/ Risk	Remedy
2023/19778	Australia	<p><b>A car booster seat sold in 2 models:</b></p> <p><b>1. Car Booster Seat Safety Chair Cushion Pad for Toddler Children Child Kids Sturdy.</b></p> <p><b>2. Car Booster Seat Safety Chair Cushion Pad for Toddler Children Child Kids Sturdy – Luxury.</b></p> <p><b>Dates sold: 1 October 2020 – 31 May 2021</b></p>		<p><b>Serious Risk Of Injury Or Death To Young Children</b></p> <p>The product does not comply with the mandatory safety standard for child restraints for use in motor vehicles.</p> <p>There is a serious risk of injury or death to young children if the vehicle abruptly stops or is in an accident.</p>	<p>Stop using the product immediately.</p> <p>Contact J-Sky to arrange return of the product and to receive a full refund.</p>
2023/19843	Australia	<p><b>Self-feeding baby spoon and teething toy. The affected spoons are the navy, dusty pink and stone coloured.</b></p>		<p><b>Risk Of Choking Or Suffocation In Young Children</b></p> <p>The choke guard may separate from the spoons due to a manufacturing fault.</p> <p>There is a risk of choking or suffocation in young children, leading to severe injury or death if the choke guard detaches and is ingested.</p>	<p>Consumers should return affected spoons to the place of purchase to exchange for a spoon in black or cherry or to get a refund.</p>

2023/19846	Australia	<b>Toddler Girls Micro Corduroy Dungarees (Overalls) Colours: Dusty Rose and Silt Green - Sizes: 1-7</b>		<b>Risk Of Choking Or Suffocation In Young Children</b> <p>The fasteners on the dungarees are not attached securely and may separate from the fabric.</p> <p>There is a risk of choking or suffocation in young children, leading to severe injury or death if the press fasteners detach and are ingested.</p>	<p>Customers should immediately stop using the dungarees and return to any BIG W store for a full refund.</p>
------------	-----------	--	---	--	---

### Australian Product Safety System

The Australian product safety system is to maximize the safety of good by the cooperation of consumers, businesses and agencies. This policy sets out the principles adopted by the Australian Competition and Consumer Commission (ACCC) for prioritizing and addressing product safety risks.

Under the Australian Consumer Law, a responsible Minister can order a compulsory recall when there are hazards on the products. A voluntary recall could be conducted to remove the product from the marketplace when the suppliers become aware of unsafe or defective products.

The ACCC administers a national recalls system for recalls of specific and general consumer products, and publishes all product recalls on the website <https://www.productsafety.gov.au/recalls>.

STC (Hong Kong Standards and Testing Centre) is a not-for-profit, independent testing, inspection and certification organization. With a global network of ISO/IEC 17025 accredited testing laboratories and 60 years of experience in consumer product testing, we can meet your conformity assessment needs with our highly efficient and reliable service. Our testing scope and capabilities related to toys and children's products include inter alia the following:

### EU Requirements

- EN 71
- Phthalates (EC) no. 1907/2006
- Nickel Release (EC) no. 1907/2006
- Total Cadmium (EEC) no. 91/338
- Lead in Jewellery product (EC) no. 836/2012
- Azo-dye (EC) no. 1907/2006
- Bisphenol-A (2014/81/EU)
- DMF (Dimethyl fumarate) (EU) no. 2011/135
- Flame retardants TCEP, TCPP, TDCP (2014/79/EU)
- Package Waste Directive (94/62/EC)

### US & Canada Requirements

- ASTM F963
- CPSIA
- California Proposition 65
- 16 CFR 1501
- ASTM F2923 (Children's jewellery)
- ASTM F2999 (Adult's jewellery)
- US Toxic in Packaging Clearinghouse (TPCH)
- CCPSA - Toys Regulations (SOR/2011-17)

### Japan Requirements

- Japan Toy Safety Standard (ST)
- Japan Food Sanitation Law (JFSL)

### Australia Requirements

- AS/NZS 8124
- Consumer Protection Notice No. 6 of 2010 - DEHP

Hong Kong: [hktcd@stc.group](mailto:hktcd@stc.group)

Changzhou: [czstc@stc.group](mailto:czstc@stc.group)

U.S.A.: [usenquiry@stc.group](mailto:usenquiry@stc.group)

Guangdong: [gdtcd@stc.group](mailto:gdtcd@stc.group)

Vietnam: [vnstc@stc.group](mailto:vnstc@stc.group)

Germany: [grstc@stc.group](mailto:grstc@stc.group)

Shanghai: [shtcd@stc.group](mailto:shtcd@stc.group)

Japan: [jpo@stc.group](mailto:jpo@stc.group)

