














## Recall Summary – European Toys

### EU Safety Gate Alerts (Nov 2023)

Alert No.	Notifying Country	Product	Product Photo	Hazard / Risk	Measures Adopted
A11/00113/23	Poland	<b>Toy scooter</b>  (Country of Origin: <b>China</b> )		<b>Injuries</b> The locking mechanisms of the steering tube are inadequate. The handlebar may slide or separate from the scooter. A child may fall from their scooter and suffer injuries. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Warning consumers of the risks
A11/00114/23	Hungary	<b>Magnetic fishing toy</b>  (Country of Origin: <b>China</b> )		<b>Choking, Injuries</b> The product contains an easily detachable small part (magnet) with a high magnetic flux. A small child may put it in their mouth and choke. In addition, if a child swallows these pieces, they could attract one another causing intestinal blockage or perforation. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Ban on the marketing of the product and any accompanying measures
A11/00115/23	Denmark	<b>Toy gun</b>  (Country of Origin: <b>China</b> )		<b>Choking, Damage to Sight</b> The gel beads can be put into the mouth and swallowed by children. As the beads expand, they can cause a fatal occlusion of the respiratory track or intestinal blockage. In addition, the kinetic energy of the projectiles fired from the toy gun is too high and can lead to eye injuries. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Stopping of sales
A11/00116/23	Poland	<b>Soft toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The fibrous stuffing material of the toy is easily accessible due to the weakness of certain seams. A small child may put the filling material in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Withdrawal of the product from the market

A11/00118/23	Poland	<b>Electric toy motorcycle</b>  (Country of Origin: <b>China</b> )		<b>Injuries</b> The space between the wheels and the motorcycle's body is too small and a child's foot may get caught between the elements, leading to bruises or injuries. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Withdrawal of the product from the market
A11/00120/23	Estonia	<b>Foaming soap</b>  (Country of Origin: <b>United Kingdom</b> )		<b>Burns</b> The product contains butane, isobutane, and propane, all of which are classified as extremely flammable gases. A child may catch fire and/or suffer burns while playing with the product or if covered with the product next to a flame. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-2.	Withdrawal of the product from the market
A11/00126/23	Poland	<b>Toy motorcycle</b>  (Country of Origin: <b>China</b> )		<b>Injuries</b> A child's foot may become trapped by the kickstand, leading to bruises or injuries. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Warning consumers of the risks
A11/00127/23	France	<b>Interactive doll</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The fibrous stuffing material of the doll is easily accessible, due to weakness of certain seams, and a small child may put it in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Withdrawal of the product from the market
A12/02603/23	The Netherlands	<b>Wooden truck with trailer</b>  (Country of Origin: <b>Unknown</b> )		<b>Choking</b> Small parts (the wheels) can be easily detached. A small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Recall of the product from end users

A12/02611/23	Denmark	<b>Toy tractor</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The small plastic figures can break, and small parts can detach. A small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Recall of the product from end users
A12/02612/23	Sweden	<b>Safety barrier</b>  (Country of Origin: <b>Unknown</b> )		<b>Choking</b> The barrier has small parts (grey elements at the ends) which can be easily detached. A small child may put them in their mouth and choke. The product does not comply with the requirements of the General Product Safety Directive nor with the European Standard EN 1930.	Recall of the product from end users
A12/02613/23	Sweden	<b>Safety barrier</b>  (Country of Origin: <b>Estonia</b> )		<b>Injuries, Strangulation</b> The opening between the vertical slats of the safety barriers is too wide. A child may fall through this opening and suffer injuries. Moreover, items around a child's neck, such as necklaces or hoodies, can get caught on protrusions which can lead to strangulation. The product does not comply with the requirements of the General Product Safety Directive nor with the European Standard EN 1930.	Recall of the product from end users
A12/02614/23	Sweden	<b>Safety barrier</b>  (Country of Origin: <b>Latvia</b> )		<b>Injuries, Strangulation</b> The locking function does not work. A child may open the barrier and fall down the stairs and suffer injuries. The screws of the gate have flaws which may cause the gate's bottom hinge to become loose and create an opening. The child's head may get stuck in the opening, leading to strangulation. The product does not comply with the requirements of the General Product Safety Directive nor with the European Standard EN 1930.	Recall of the product from end users

A12/02615/23	The Netherlands	<b>Toy camera</b>  (Country of Origin: <b>Unknown</b> )		<b>Strangulation</b>  The toy has a long strap to carry it around the neck. This strap can tangle and form a loop around the neck of a child, leading to strangulation. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Recall of the product from end users
A12/02635/23	Romania	<b>Toy slime with small balls</b>  (Country of Origin: <b>China</b> )		<b>Choking</b>  The polystyrene balls are too small. A small child can put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Ban on the marketing of the product and any accompanying measures
A12/02645/23	Poland	<b>Toy scooter</b>  (Country of Origin: <b>China</b> )		<b>Injuries</b>  The bracket connecting the steering tube to the scooter can easily break, which can cause the steering tube to detach. This could cause a child to lose balance and fall off, leading to injuries. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Withdrawal of the product from the market
A12/02651/23	France	<b>Finger paints</b>  (Country of Origin: <b>Israel</b> )		<b>Chemical</b>  The product contains formaldehyde (measured value up to 0.072% by weight), which is forbidden in finger paints. Formaldehyde is a skin sensitiser and can trigger allergic reactions and may cause cancer. It also contains methylisothiazolinone (MI) (measured value up to 0.00068%), which is also forbidden in finger paints. Dermal contact with MI containing products can provoke allergic contact dermatitis to sensitised persons. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-7.	Withdrawal of the product from the market





A12/02653/23	Lithuania	<b>Screw-on toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> Small parts can easily detach (stickers). A small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Withdrawal of the product from the market
A12/02655/23	Lithuania	<b>Toy car</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> Small parts can be easily detached (doors, wheels and steering wheel). A small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Withdrawal of the product from the market
A12/02657/23	Lithuania	<b>Toy unicorn in a plastic egg</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The product has an excessive concentration of di-isononyl phthalate (DINP), di-isodecyl phthalate (DIDP) and di-n-octyl phthalate (DNOP) (measured value up to 3.22% by weight, altogether). These phthalates may harm the health of children by causing possible damage to their reproductive system and liver. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/02659/23	Czechia	<b>Toy with sweets</b>  (Country of Origin: <b>Türkiye</b> )		<b>Chemical</b> The plastic material of the head of the doll contains di-(2-ethylhexyl) phthalate (DEHP) (measured value up to 30.32% by weight). This phthalate may harm the health of children, possibly causing damage to their reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/02660/23	Lithuania	<b>Machine toy set</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The toy has small parts (the connecting parts of the rigid plastic tipper and the moving parts of the lift) which can be easily detached. A small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Withdrawal of the product from the market

A12/02661/23	France	<b>Expandable toy</b>  (Country of Origin: <b>China</b> )		<b>Choking, Injuries</b> The dinosaur figurine can be put into the mouth and swallowed by children. As this figurine expands, it can cause fatal occlusion of the respiratory tract or intestinal blockage in small children. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Withdrawal of the product from the market
A12/02667/23	Lithuania	<b>Toy plane with sweets</b>  (Country of Origin: <b>China</b> )		<b>Choking, Injuries</b> The toy has small parts (wheels, stickers, the plastic disc film, the plastic part of the cord) that can be easily detached. A child may put them in their mouth and choke. Additionally, the toy has exposed metal axles on the discs and wheels, which may cause injuries to a child. The pull string's retraction is too strong, which could also hurt a child. The product does not comply with the requirements of the Toy Safety Directive	Withdrawal of the product from the market
A12/02671/23	France	<b>Fancy-dress costume</b>  (Country of Origin: <b>China</b> )		<b>Burns, Choking, and Strangulation</b> The product has small parts (sequins), which can easily become loose. A small child may put them in their mouth and choke. Moreover, the buckle of the witch's hat is too large, which may lead to strangulation. Also, the hat is easily flammable and the flame propagation is too high. If it catches fire, the child could suffer burns. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Withdrawal of the product from the market
A12/02672/23	The Netherlands	<b>Sex toy</b>  (Country of Origin: <b>Mexico</b> )		<b>Chemical</b> The sex toy has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 0.16% by weight). This phthalate may harm the user's health, possibly causing damage to their reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market

A12/02679/23	Ireland	<b>Baby self-feeding pillow</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> During self-feeding, the baby is not able to control the flow of fluid. The fluid will continue to flow even if the baby is not swallowing. This can/will lead to choking. The product does not comply with the requirements of the General Product Safety Directive.	Removal of this product listing by the online marketplace
A12/02681/23	Ireland	<b>Baby self-feeding pillow</b>  (Country of Origin: <b>Unknown</b> )		<b>Choking</b> During self-feeding, the baby is not able to control the flow of fluid. The fluid will continue to flow even if the baby is not swallowing. This can/will lead to choking. The product does not comply with the requirements of the General Product Safety Directive.	Removal of this product listing by the online marketplace
A12/02682/23	Ireland	<b>Baby self-feeding pillow</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> During self-feeding, the baby is not able to control the flow of fluid. The fluid will continue to flow even if the baby is not swallowing. This can/will lead to choking. The product does not comply with the requirements of the General Product Safety Directive.	Removal of this product listing by the online marketplace
A12/02684/23	The Netherlands	<b>Wooden toy</b>  (Country of Origin: <b>Sweden</b> )		<b>Strangulation</b> The product has a long cord. This cord can become trapped in the neck area during various activities of a child, leading to strangulation. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Recall of the product from end users
A12/02685/23	Ireland	<b>Baby self-feeding pillow</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> During self-feeding, the baby is not able to control the flow of fluid. The fluid will continue to flow even if the baby is not swallowing. This can/will lead to choking. The product does not comply with the requirements of the General Product Safety Directive.	Removal of this product listing by the online marketplace
A12/02686/23	Ireland	<b>Baby self-feeding pillow</b>  (Country of Origin: <b>Unknown</b> )		<b>Choking</b> During self-feeding, the baby is not able to control the flow of fluid. The fluid will continue to flow even if the baby is not swallowing. This can/will lead to choking. The product does not comply with the requirements of the General Product Safety Directive.	Removal of this product listing by the online marketplace




A12/02720/23	Lithuania	<b>Plastic toy</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b>  The plastic material of the head of the toy has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) and di-'isononyl' phthalate (DINP) (measured values up to 8.9% and 0.2% by weight, respectively). These phthalates may harm the health of children, by possibly causing damage to their reproductive system and liver. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/02724/23	The Netherlands	<b>Toy train</b>  (Country of Origin: <b>Germany</b> )		<b>Choking</b>  Small parts of the product (locomotive chimney, green block on wagon A, blue booklet of wagon B, gift of wagon D) can be easily detached. A small child can put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Recall of the product from end users
A12/02729/23	Germany	<b>Toy water pistol</b>  (Country of Origin: <b>Germany</b> )		<b>Choking</b>  The product has a small part (hose connection), which a small child could put in their mouth and choke on. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Withdrawal of the product from the market
A12/02731/23	Germany	<b>Nesting doll set</b>  (Country of Origin: <b>China</b> )		<b>Choking</b>  The smallest and second smallest figures are too small, which means that a child can put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with European Standard 71-1.	Removal of this product listing by the online marketplace



A12/02734/23	France	<b>Magnetic fishing game</b>  (Country of Origin: <b>China</b> )		<b>Chemical, Choking</b>  The product contains an easily detachable small part (the tips of the fishing rods) with a high magnetic flux. A small child may put it in their mouth and choke. In addition, if a child swallows these pieces, they could attract one another causing intestinal blockage or perforation. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Removal of this product listing by the online marketplace
A12/02737/23	Iceland	<b>Sensory swing</b>  (Country of Origin: <b>Canada</b> )		<b>Strangulation, Suffocation</b>  A child can become entrapped in the drapes and/or the rope, leading to strangulation. If a child's head is stuck inside the drapes, they will not be able to breathe, leading to asphyxiation. The product does not comply with the requirements of the Toy Safety Directive.	Withdrawal of the product from the market
A12/02738/23	Germany	<b>Baby carrier</b>  (Country of Origin: <b>China</b> )		<b>Injuries</b>  Due to insufficient attachment points on the baby carrier, the support is inadequate and the baby may slip out, fall and suffer serious injuries. The product does not comply with the requirements of General Product Safety Directive nor with European Standard EN 13209-2.	Import rejected at border
A12/02739/23	France	<b>Key ring</b>  (Country of Origin: <b>China</b> )		<b>Chemical, Choking</b>  The battery compartment is easy to open/break, resulting in the button cell batteries becoming accessible. A small child may put them into their mouth and choke, or suffer injuries in their gastrointestinal tract. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 62115.	Recall of the product from end users

A12/02745/23	Poland	<b>Plastic doll</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The product has an excessive amount of bis (2-ethylhexyl) phthalate (DEHP) (measured value up to 13.2% by weight). This phthalate may harm the health of children, possibly causing damage to their reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/02753/23	Poland	<b>Magnetic toy set</b>  (Country of Origin: <b>China</b> )		<b>Injuries</b> The toy is made of small parts (cubes) with a high magnetic flux. If a child swallows them, they could attract one another, causing intestinal blockage or perforation. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Warning consumers of the risks
A12/02754/23	Cyprus	<b>Toy bow with arrow</b>  (Country of Origin: <b>China</b> )		<b>Choking, Damage to Sight</b> The suction cup of the arrow can be easily detached. A child could put it in their mouth and choke. Shooting the arrow without the suction cup can cause injuries to the eyes. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Withdrawal of the product from the market
A12/02755/23	Lithuania	<b>Rattle toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The toy's small parts are too small to be safe. A small child could put them into their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Withdrawal of the product from the market
A12/02764/23	Germany	<b>Toy crossbow</b>  (Country of Origin: <b>Germany</b> )		<b>Choking</b> The suction cups of the bolts can be easily detached. A small child could put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with European Standard EN 71-1.	Recall of the product from end users

A12/02765/23	Germany	<b>Toy crossbow</b>  (Country of Origin: <b>Germany</b> )		<b>Choking</b> The suction cups of the bolts can be easily detached. A child could put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with European Standard EN 71-1.	Ban on the marketing of the product and any accompanying measures
A12/02775/23	Austria	<b>Battery-operated soft toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> Small parts (eyes and the nose) can be easily detached. A small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Recall of the product from end users
A12/02820/23	Czechia	<b>Plastic doll</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The plastic material of the head of the toy has an excessive concentration of bis (2-ethylhexyl) phthalate (DEHP) (measured value up to 38.6% by weight). This phthalate may harm the health of children, possibly causing damage to their reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/02828/23	Poland	<b>Plastic dolls</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The plastic material of the toy contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 13.4% by weight). This phthalate may harm the health of children, possibly causing damage to the reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/02833/23	Romania	<b>Slime</b>  (Country of Origin: <b>China</b> )		<b>Strangulation</b> When rotated over the head, the elastic cord extends and can get wrapped around the neck. This can lead to strangulation. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-1.	Ban on the marketing of the product and any accompanying measures

A12/02861/23	Italy	<b>Soft plastic toy</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The plastic material of the product has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP), dibutyl phthalate (DBP), benzyl butyl phthalate (BBP), and diisobutyl phthalate (DIBP) (measured values up to 0.1%, 0.06%, <0.01% and <0.01% by weight, respectively). These phthalates may harm the health of children, possibly causing damage to the reproductive system. This product does not comply with the REACH Regulation.	Ban on the marketing of the product and any accompanying measures
A12/02862/23	Poland	<b>Plastic toy</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The toy contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) and diisobutyl phthalate (DIBP) (measured values up to 9.8% and 2.58% by weight respectively). These phthalates may harm the health of children, possibly by causing damage to the reproductive system. The product does not comply with the REACH Regulation.	Warning consumers of the risks
A12/02863/23	Latvia	<b>Slime toy</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The migration of boron from the toy slime is too high (measured value up to 888mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system. The product does not comply with the requirements of the Toy Safety Directive nor with the European Standard EN 71-3.	Recall of the product from end users

## Safety Gate: the EU rapid alert system for dangerous non-food products



“Safety Gate”, the EU rapid alert system (formerly known as ‘RAPEX’), enables the rapid exchange of information between **31 European countries** and the European Commission on non-food dangerous products found on the market posing a risk to the health and safety of consumers.




A weekly overview of the alerts on those products is published in English for free on <https://ec.europa.eu/safety-gate-alerts/screen/webReport#weeklyReports>. The measures taken in the notifying country in order to restrict such products’ marketing or use can be ordered by national authorities (“compulsory measures”) or be taken directly by producers and distributors (“voluntary measures”).

The official contact points of the Member and EFTA-EEA States provide the information published in these weekly overviews. Under the terms of Annex II.10 of the General Product Safety Directive (**2001/95/EC**) responsibility for the information provided lies with the notifying party. The Commission does not take any responsibility for the accuracy of the information provided.

## Recall Summary – US Toys / Children’s Products

**CPSC Recall List (Nov 2023)**

Recall No.	Notifying Country	Product	Product Photo	Hazard / Risk	Remedy
24-017	USA	<b>Yoccaa baby loungers</b>  (Country of Origin: <b>China</b> )		<p><b>Fall and Entrapment Hazards</b>                      Yoccaa Baby Loungers Recalled Due to Suffocation Risk and Fall and Entrapment Hazards; Fails to Meet Safety Requirements for Infant Sleep Products; Exclusively on Amazon.com by Yoccaa Direct</p> <p>The recalled loungers fail to meet the safety requirements of CPSC’s Infant Sleep Products Rule, creating an unsafe sleeping environment for infants and posing a suffocation risk and fall and entrapment hazards to infants.</p>	<p>Consumers should immediately stop using the recalled baby loungers and contact Yoccaa Direct for instructions on how to receive a full refund and properly dispose of the product. Yoccaa Direct and Amazon are contacting all known purchasers directly.</p>
24-019	USA	<b>Creativity Street Assorted Craft Buttons</b>  (Country of Origin: <b>China</b> )		<p><b>Violation of Federal Lead Content Ban</b>                      Dixon Ticonderoga Recalls Creativity Street Children’s Assorted Craft Buttons Due to Violation of Federal Lead Content Ban</p> <p>The recalled children’s craft buttons contains levels of lead that exceed the federal lead content ban. Lead is toxic if ingested by young children and can cause adverse health effects.</p>	<p>Consumers should stop using the recalled buttons immediately and contact Dixon Ticonderoga to receive a pre-paid label to return the recalled buttons. When the buttons are received, consumers will receive a full refund.</p>

24-030	USA	<p><b>Balloon Time Mini Helium Tanks</b></p> <p>(Country of Origin: <b>United States</b>)</p>		<p><b>Injury Hazard</b></p> <p>Balloon Time Mini Helium Tanks Recalled by Worthington Industries Due to Injury Hazard</p> <p>Compressed helium from the tank can escape and cause the plastic cap to be released into the air unexpectedly, posing an injury hazard due to projectiles striking users and bystanders.</p>	<p>Consumers should immediately stop using the recalled mini helium tanks. Consumers should point the tank away from themselves and others, and carefully remove the plastic safety seal and cap. Release all helium in a well-ventilated area and then clearly write their name, "RECALLED" and destruction code on the front of the tank with a non-erasable marker.</p>
24-707	USA	<p><b>Infant Bath Seats</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Drowning Hazard</b></p> <p>UncleWu Life Recalls Infant Bath Seats Due to Drowning Hazard; Violation of Bath Seat Requirements; Sold Exclusively on Amazon.com (Recall Alert)</p> <p>The bath seats fail to meet the federal safety regulation for infant bath seats, including requirements for stability and leg openings, and can tip over while in use, posing a drowning hazard to babies.</p>	<p>Consumers should immediately stop using the recalled infant bath seats and contact UncleWu Life to receive a pre-paid label to return the infant bath seat. Upon receipt of the returned infant bath seats, consumers will be issued a full refund. UncleWu Life and Amazon are notifying all known purchasers directly.</p>
24-708	USA	<p><b>Electric bicycles</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Fall and Injury Hazards</b></p> <p>Murf Electric Bikes Recalls Electric Bicycles Due to Fall and Injury Hazards (Recall Alert)</p> <p>The bicycles do not meet the U.S. safety standard, posing fall and injury hazards to the rider.</p>	<p>Consumers should immediately stop using the recalled electric bikes and contact Murf's store for a free repair. Consumers can perform this repair themselves with the repair video available here. Murf Electric Bikes is contacting all known purchasers directly.</p>


24-712	USA	<p><b>Children’s Nightgowns</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Burn Hazard</b></p> <p>Children’s Nightgowns Recalled Due to Burn Hazard and Violation of Federal Flammability Standards; Sold by iMOONZZZ Exclusively on Amazon.com</p> <p>The children’s nightgowns fail to meet the flammability standards for children’s sleepwear, posing a risk of burn injuries to children.</p>	<p>Consumers should immediately take the recalled nightgowns away from children, stop using them and contact iMOONZZZ for a full refund. Consumers will be asked to destroy the garments by cutting them in half and disposing of them in accordance with local state recycling laws. Consumers should send the recalling firm a photo of the destroyed garment by email at <a href="mailto:imoonzzz-recall@cdream.com">imoonzzz-recall@cdream.com</a>. Upon receipt of the photo, consumers will be issued a full refund of the purchase price. iMOONZZZ is contacting all known purchasers directly.</p>
24-714	USA	<p><b>LAOION Children’s Cups</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Choking and Laceration Hazards</b></p> <p>Stainless Steel Children’s Cups Recalled Due to Violation of Federal Lead Content Ban; Sold Exclusively at Amazon.com by LAOION (Recall Alert)</p> <p>The bottom exterior of the stainless-steel cups contains an accessible solder bead with levels of lead that exceed the federal lead content ban. Lead is toxic if ingested by young children and can cause adverse health effects. In addition, the lid can crack and break during use producing sharp edges and small parts, posing choking and laceration hazards to children.</p>	<p>Consumers should immediately take the cups away from children, stop using them and contact LAOION for a full refund. LAOION and Amazon are contacting all known purchasers directly.</p>



24-715	USA	<p><b>13-Piece Toy Mushroom Peg Sorters</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Choking Hazard</b></p> <p>Target Recalls Hearth &amp; Hand™ with Magnolia Toy Mushroom Peg Sorters Due to Choking Hazard (Recall Alert)</p> <p>The stems of the toy mushrooms can detach, posing a choking hazard to young children.</p>	<p>Consumers should immediately take the recalled toys away from young children and return them to any Target store for a full refund or contact Target to receive a prepaid return label to return the toy set by mail. Target is contacting all known purchasers directly.</p>
24-716	USA	<p><b>PandaEar Stainless Steel Toddler Cups, 8 oz.</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Choking and Laceration Hazards</b></p> <p>PandaEar Recalls Stainless Steel Children's Cups Due to Violation of Federal Lead Content Ban; Sold Exclusively on Amazon.com (Recall Alert)</p> <p>The bottom exterior of the recalled stainless-steel cups contains an accessible solder bead with levels of lead that exceed the federal lead content ban. Lead is toxic if ingested by young children and can cause adverse health effects. In addition, the lid can crack and break during use producing sharp edges and small parts, posing choking and laceration hazards to children.</p>	<p>Consumers should immediately take the recalled cups away from children, stop using them and contact PandaEar for a full refund. PandaEar and Amazon are contacting all known purchasers.</p>
24-718	USA	<p><b>Supacaz Orbitron Pedals</b></p> <p>(Country of Origin: <b>Taiwan</b>)</p>		<p><b>Fall Hazard</b></p> <p>Specialized Bicycle Components Recalls Supacaz Brand Orbitron Pedals Due to Fall Hazard (Recall Alert)</p> <p>The pedal body can detach from the pedal spindle and/or the pedal spindle can break, posing a fall hazard.</p>	<p>Consumers should immediately stop using the recalled Supacaz Orbitron Pedals and contact Specialized for a full refund. All known purchasers are being contacted directly by retailers who sold this product.</p>

24-719	USA	<p><b>YPSI and Z4 Inclined Sleeper Bassinets</b></p> <p>(Country of Origin: <b>Italy</b>)</p>		<p><b>Suffocation and Fall Hazard</b></p> <p>Peg Perego Recalls Inclined Sleeper Bassinets for YPSI and Z4 Strollers Due to Risk of Suffocation and Fall Hazard; Violation of Federal Safety Standards (Recall Alert)</p> <p>The recalled bassinets violate the Safe Sleep for Babies Act because they were marketed for infant sleep and have an incline angle greater than 10 degrees. Infant fatalities have occurred in inclined sleeper products after the infants rolled from their back to their stomach or side while unrestrained, or under other circumstances. The bassinets also violate the Infant Sleep Products regulation because they do not have a stand.</p>	<p>Consumers should immediately stop using the recalled bassinets and contact Peg Perego for instructions on how to receive a full refund or repair instructions for the recalled bassinets. Consumers who purchased their bassinet for a stroller system or with a stand will be given instructions on how to disable the backrest recline adjustment feature. Peg Perego will offer a \$50 cash incentive for consumers who provide proof of backrest disengagement for bassinets part of this recall. Consumers who solely purchased the bassinet should return the product for a full refund. Peg Perego and Amazon are contacting all known purchasers directly.</p>
24-721	USA	<p><b>Vibe Bear Playyard Mattresses</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Suffocation Hazards</b></p> <p>Vibe Bear Playyard Mattresses Recalled Due to Suffocation Hazards for Infants; Violation of the Federal Safety Regulation for Crib Mattresses; Sold Exclusively on Amazon.com by Beyond Baby (Recall Alert)</p> <p>The recalled mattresses violate multiple provisions of the Safety Standard for Crib Mattresses, including the firmness and thickness tests and missing warnings and labels. The product poses a suffocation hazard to infants.</p>	<p>Consumers should immediately stop using and destroy the mattresses by cutting them in half and contact Beyond Baby at <a href="mailto:recallguof@outlook.com">recallguof@outlook.com</a> to send photos of destroyed recalled products for a full refund. Beyond Baby and Amazon are contacting all known purchasers directly.</p>

24-723	USA	<p><b>DODO Baby House Pack and Play Mattresses</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Suffocation Hazard</b></p> <p>Pack and Play Mattresses Recalled Due to Suffocation Hazard for Infants; Violations to the Federal Safety Regulation for Crib Mattresses; Sold Exclusively on Amazon.com by DODO Baby House (Recall Alert)</p> <p>The recalled mattresses violate multiple provisions of the federal safety regulation for crib mattresses, including the thickness test and missing warnings and labels. The product poses a suffocation hazard to infants.</p>	<p>Consumers should immediately stop using and destroy the pack and play mattresses by cutting them in half, then contact DODO Baby House to send photos of the destroyed recalled products for a full refund. DODO Baby House and Amazon are contacting all known purchasers directly.</p>
24-724	USA	<p><b>Tibblue 8 oz and 12 oz children's cups</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Laceration and Choking Hazards</b></p> <p>Tibblue Stainless Steel Children's Cups Recalled Due to Violation of Federal Lead Content Ban; Sold Exclusively on Amazon.com by FENGM (Recall Alert)</p> <p>The bottom exterior of the stainless-steel cups contains an accessible solder bead with levels of lead that exceed the federal lead content ban. Lead is toxic if ingested by young children and can cause adverse health effects. In addition, the lid can crack and break during use producing sharp edges and small parts, posing laceration and choking hazards to children.</p>	<p>Consumers should immediately take the cups away from children, stop using them and contact FENGM for a full refund. FENGM and Amazon are contacting all known purchasers directly.</p>

24-725	USA	<p><b>Klickpick Home Children's Cup Sets</b></p> <p>(Country of Origin: <b>China</b>)</p>		<p><b>Laceration and Choking Hazards</b></p> <p>Klickpick Home Recalls Stainless Steel Children's Cup Sets Due to Violation of Federal Lead Content Ban; Sold Exclusively at Amazon.com (Recall Alert)</p> <p>The bottom exterior of the stainless-steel cups contains an accessible solder bead with levels of lead that exceed the federal lead content ban. Lead is toxic if ingested by young children and can cause adverse health effects. In addition, the lid can crack and break during use producing sharp edges and small parts, posing laceration and choking hazards to children.</p>	<p>Consumers should immediately take the recalled cups away from children, stop using them and contact Klickpick Home for a full refund. Klickpick Home and Amazon are contacting all known purchasers directly.</p>
--------	-----	---	---	--	--

\* Source: [www.recalls.gov](http://www.recalls.gov)


## CPSC


The United States Consumer Product Safety Commission (CPSC) is an independent agency of the United States government. To provide better service in alerting the American people to unsafe, hazardous or defective products, a “one stop shop” for U.S. Government recalls, <http://www.recalls.gov>, has been created. Members of the public may report unsafe products to CPSC by using the platform.


The recall list is divided into seven categories: Consumer Products, Motor Vehicles, Boats, Food, Medicine, Cosmetics and Environmental Products. Generally, the recall is conducted voluntarily by the company under CPSC’s Fast Track Recall program. Fast Track recalls are initiated by firms who are committed to working with CPSC to quickly announce the recall and remedy to protect consumers.

## Recall Summary – Australia Toys / Children’s Products

**ACCC Recall List (Nov 2023)**

PRA No.	Notifying Country	Product / Description	Product Photo	Hazard / Risk	Remedy
2023/19963	Australia	<p><b>Thomas &amp; Friends wooden toy train cars for children aged 2 years and over. Each train car features a connector containing a high-powered magnet which allows the train car to be connected to other train cars.</b></p> <p><b>Product and date codes are printed on the underside of the cars.</b></p> <p><b>Affected product codes:</b></p> <ul style="list-style-type: none"> <li>• HBJ89</li> <li>• HBJ90</li> </ul>		<p><b>Risk of Serious Internal Injuries or Death</b></p> <p>Affected products may not comply with the mandatory standard for toys for children up to and including 36 months of age.</p> <p>The small plastic piece containing a high-powered magnet that connects one train to another can detach from the trains or become loose.</p> <p>There is a risk of young children choking on the connector that contains a magnet if it detaches.</p> <p>There is also a risk of serious internal injuries or death if a child swallows more than one small high-powered magnet as they can stick together across the walls of the child's intestine or other digestive tissue.</p>	<p>Consumers should immediately stop using the product and return the product to the place of purchase or follow the instructions found at <a href="http://www.service.mattel.com">www.service.mattel.com</a> to receive a full refund.</p>

2023/19970	Australia	<p><b>Wooden activity toy in the shape of a car dashboard.</b></p>		<p><b>Risk of Choking</b></p> <p>Affected products may not comply with the mandatory standard for toys for children up to and including 36 months of age.</p> <p>The gearstick knob on the toy can detach during play.</p> <p>There is a risk of choking, suffocation or death to young children if they put the detached gearstick part into their mouth.</p>	<p>Consumers should stop using the Little Drive toy immediately.</p> <p>Consumers can return the toy to any Adairs store for a full refund or contact Adairs for a pre-paid label to post the toy back to Adairs.</p>
2023/19971	Australia	<p><b>Infant silicone teether</b></p> <p><b>Only the 'Riff the Fox' teether is affected. The teether is shaped like a fox with an orange body and white and black colouring on the face and ears.</b></p>		<p><b>Risk of Choking</b></p> <p>The teether does not comply with the mandatory safety standard for toys for children up to and including 36 months of age.</p> <p>The tip of the ear may detach from the teether creating a small part.</p> <p>There is a risk of choking, suffocation, or death to young children if the ear detaches while in use.</p>	<p>Consumers should stop using the product immediately and place it out of reach of children.</p> <p>Consumers should contact Riff Raff Baby to arrange a refund and to return the product.</p> <p>For more information, consumers can contact Riff Raff Baby by phone on 0493 721 478, via email at <a href="mailto:productinfo@riffraffbaby.com">productinfo@riffraffbaby.com</a> or via the website.</p>

2023/19982	Australia	<p><b>Wooden activity play gym with hanging rope and threaded beads.</b></p> <p><b>SKU: T03869 can be found on the packaging of the product.</b></p>		<p><b>Risk of Choking</b></p> <p>Affected products may not comply with the mandatory standard for toys for children up to and including 36 months of age.</p> <p>The small hanging beads can become detached during play creating small parts.</p> <p>There is a risk of choking, suffocation or death to young children if they put the detached small parts into their mouth.</p>	<p>Consumers should stop using the play gym immediately.</p> <p>Consumers will be contacted by the Mocka customer service team to return the product via a pre-paid label for a full refund.</p> <p>For more information or to return the play gym, consumers can contact the Mocka customer support team via email at <a href="mailto:hello@mocka.com.au">hello@mocka.com.au</a> or by phone on 07 3184 8466 (8:00 am – 5:00 pm, Monday to Friday).</p>
------------	-----------	--	---	---	--

## Australian Product Safety System

The Australian product safety system is set up to maximize the safety of goods through the cooperation of consumers, businesses and agencies. This policy sets out the principles adopted by the Australian Competition and Consumer Commission (ACCC) for prioritizing and addressing product safety risks.

Under the Australian Consumer Law, a responsible Minister can order a compulsory recall when there are hazards on the products. A voluntary recall could be conducted to remove the product from the marketplace when the suppliers become aware of unsafe or defective products.

The ACCC administers a national recalls system for recalls of specific and general consumer products, and publishes all product recalls on the website <https://www.productsafety.gov.au/recalls>.

Hong Kong Standards and Testing Centre (STC) is a not-for-profit, independent testing, inspection and certification organisation. With a global network of ISO/IEC 17025 accredited testing laboratories and 60 years of experience in consumer product testing, we can meet your conformity assessment needs with our highly efficient and reliable service. Our testing scope and capabilities related to toys and children's products include inter alia the following:

### EU Requirements

- EN 71
- Phthalates (EC) no. 1907/2006
- Nickel Release (EC) no. 1907/2006
- Total Cadmium (EEC) no. 91/338
- Lead in Jewellery product (EC) no. 836/2012
- Azo-dye (EC) no. 1907/2006
- Bisphenol-A (2014/81/EU)
- DMF (Dimethyl fumarate) (EU) no. 2011/135
- Flame retardants TCEP, TCPP, TDCP (2014/79/EU)
- Package Waste Directive (94/62/EC)

### US & Canada Requirements

- ASTM F963
- CPSIA
- California Proposition 65
- 16 CFR 1501
- ASTM F2923 (Children's jewellery)
- ASTM F2999 (Adult's jewellery)
- US Toxic in Packaging Clearinghouse (TPCH)
- CCPSA - Toys Regulations (SOR/2011-17)

### Japan Requirements

- Japan Toy Safety Standard (ST)
- Japan Food Sanitation Law (JFSL)

### Australia Requirements

- AS/NZS 8124
- Consumer Protection Notice No. 6 of 2010 - DEHP

Hong Kong: [hktcd@stc.group](mailto:hktcd@stc.group)

Changzhou: [czstc@stc.group](mailto:czstc@stc.group)

U.S.A.: [usenquiry@stc.group](mailto:usenquiry@stc.group)

Guangdong: [gdtcd@stc.group](mailto:gdtcd@stc.group)

Vietnam: [vnstc@stc.group](mailto:vnstc@stc.group)

Germany: [grstc@stc.group](mailto:grstc@stc.group)

Shanghai: [shtcd@stc.group](mailto:shtcd@stc.group)

Japan: [jpo@stc.group](mailto:jpo@stc.group)

