
















Recall Summary – European Toys





EU Safety Gate Alerts (Jul 2024)





Alert No.	Notifying Country	Product	Product Photo	Hazard / Risk	Measures Adopted
A11/00070/24	The Netherlands	Baby travel cot (Country of Origin: Germany)		Injuries The bed base can easily break, making sharp edges or protruding parts accessible, which could cause injuries to the baby or bystanders. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 716-2.	Stopping of sales
A11/00079/24	Poland	Toy telephone (Country of Origin: China)		Damage to hearing The sound pressure level produced by the toy is too high (measured value up to 77.9 dB). This could lead to permanent or partial hearing loss. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market
A11/00083/24	Poland	Soft toy (Country of Origin: China)		Choking The fibrous stuffing material of the toy is easily accessible due to the zipper. A small child may put the filling material in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market
A12/01693/24	France	Soft toy (Country of Origin: China)		Choking Small parts (the buttons) can be easily detached. A small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive, nor with the European standard EN 71-1.	Recall of the product from end users
A12/01696/24	France	Fancy dress costume (Country of Origin: China)		Chemical The product contains chromium VI (measured value up to 0.05 mg/kg). Chromium VI is sensitising, can trigger allergic reactions and can cause cancer. The product does not comply with the requirements of the Toy Safety Directive nor with the REACH Regulation.	Recall of the product from end users

A12/01712/24	France	Toy bow (Country of Origin: China)		Choking The product has small parts (balls). A small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Recall of the product from end users
A12/01713/24	Slovakia	Puzzle mat (Country of Origin: China)		Choking The toy has small parts that can be easily detached (window of the plane with propeller, rear part of horizontal tail surface and front part of the plane). A small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market
A12/01714/24	Slovakia	Children's scooter (Country of Origin: China)		Injuries The diameter of the front wheels of the scooter is too small (measured value up to 110 mm). When a child rides the scooter on an uneven surface, the wheel can get stuck in a hole and the child may fall, suffering injuries. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Stopping of sales
A12/01716/24	France	Fancy dress costume (Country of Origin: China)		Choking The zipper puller easily detaches from the zipper on the product. A child may put it in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market
A12/01717/24	Czechia	Plastic doll (Country of Origin: China)		Chemical The plastic material of the toy has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 59.2% by weight). This phthalate may harm the health of children by causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market






A12/01793/24	Lithuania	Doll (Country of Origin: China)		Chemical The doll contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) and dibutyl phthalate (DBP) (measured values up to 3.4% and 0.7% by weight, respectively). These phthalates may harm the health of children by causing possible damage to their reproductive system. The product does not comply with the requirements of the Toy Safety Directive.	Withdrawal of the product from the market
A12/01794/24	Lithuania	Rattle toy set (Country of Origin: China)		Choking The rattle toy set has small parts. A small child could put them into their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market
A12/01800/24	Latvia	Modelling clay (Country of Origin: China)		Chemical The migration of boron from the modelling clay is too high (measured value up to 1793 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-3.	Recall of the product from end users
A12/01813/24	Romania	Plastic toy set (Country of Origin: China)		Choking Due to their characteristic appearance, form, colour, and size, the product may be mistaken for foodstuff. This may lead children to put them in their mouth and ingest them. The product does not comply with the requirements of the Food Imitating Directive and the Toy Safety Directive, nor with the European standard EN 71-1.	Ban on the marketing of the product and any accompanying measures
A12/01828/24	Germany	Toy rattle (Country of Origin: China)		Choking The small wooden balls of the rattle can be easily detached. A child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Removal of this product listing by the online marketplace




A12/01837/24	Croatia	Plastic toys (Country of Origin: China)		Chemical The toy contains an excessive amount of di-2-ethylhexyl phthalate (DEHP) (measured value up to 2.3% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Destruction of the product
A12/01843/24	Poland	Children's car seat base (Country of Origin: Poland)		Injuries Due to an installation error, the child car seat may separate from the base, which in case of an accident, increases the risk of injuries. The product does not comply with Regulation UN/ECE No 44-04.	Recall of the product from end users
A12/01845/24	Slovakia	Luminous mask (Country of Origin: China)		Environment The solders have an excessive concentration of lead (measured value up to 33.71% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Stopping of sales
A12/01849/24	Poland	Magnetic puzzle set (Country of Origin: China)		Injuries Small parts with high magnetic flux may be easily detached from the toy. If a child swallows them, they could attract one another, causing intestinal blockage or perforation. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Destruction of the product
A12/01879/24	Poland	Children's car seat (Country of Origin: China)		Injuries One of the handle attachment components may become loose. The seat may detach from the handle while carrying a child, which may cause the child to fall and suffer injuries. The product does not comply with Regulation UN/ECE No 44-04.	Recall of the product from end users

A12/01902/24	Poland	Electric toy (Country of Origin: China)		Environment The electronic components of the product have an excessive concentration of lead (measured value up to 84.5% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Warning consumers of the risks
A12/01903/24	Czechia	Fishing game (Country of Origin: China)		Environment The solders in the product have an excessive concentration of lead and cadmium (measured values up to 72.6% and 0.11% by weight, respectively). Lead and cadmium pose a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Recall of the product from end users
A12/01904/24	Czechia	Toy kitchen set (Country of Origin: China)		Environment The solders in the product have an excessive concentration of lead and cadmium (measured values up to 78.8% and 0.14% by weight, respectively). Lead and cadmium pose a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Recall of the product from end users
A12/01909/24	Lithuania	Soft toy (Country of Origin: China)		Choking, Cuts The toy can easily break, resulting in small parts (parts of the glasses). A small child may put them in their mouth and choke. Moreover, the glasses have sharp edges, which may cause cuts or injuries to a child. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market

A12/01912/24	Germany	Toy slime (Country of Origin: China)		Chemical The migration of boron from the toy slime is too high (measured value up to 610 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-3.	Import rejected at border
A12/01929/24	France	Soft toy (Country of Origin: China)		Choking, Suffocation The toy contains small parts (nose and paws) which can be easily detached. A small child may put them in their mouth and choke. Moreover, the plastic bag of the packaging is too thin. If a child plays with the packaging, the plastic can cover their mouth and nose, causing the child to suffocate. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Removal of this product listing by the online marketplace
A12/01943/24	Germany	Toy slime (Country of Origin: China)		Chemical The migration of boron from the toy slime is too high (measured value up to 1710 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-3.	Import rejected at border
A12/01944/24	Germany	Toy slime (Country of Origin: China)		Chemical The migration of boron from the toy slime is too high (measured value up to 960 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-3.	Import rejected at border

A12/01945/24	Germany	Toy slime (Country of Origin: China)		Chemical The migration of boron from the toy slime is too high (measured value up to 1000 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-3.	Import rejected at border
A12/01946/24	Germany	Toy slime (Country of Origin: China)		Chemical The migration of boron from the toy slime is too high (measured value up to 997 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-3.	Import rejected at border
A12/01947/24	Germany	Toy slime (Country of Origin: China)		Chemical The migration of boron from the toy slime is too high (measured value up to 1450 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-3.	Import rejected at border
A12/01949/24	France	Magnetic fishing game (Country of Origin: China)		Choking Small parts in the toy can be easily detached (metal part of the dolphin). As a consequence, a small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Recall of the product from end users

A12/01951/24	France	Bath toy (Country of Origin: China)		Chemical The toy releases an excessive amount of bisphenol A (measured value up to 0.051 mg/l). Bisphenol A has endocrine disrupting properties and affects the mammary glands, reproductive and immune systems, and may impair the brain's development and behaviour. The product does not comply with the requirements of the Toy Safety Directive.	Removal of this product listing by the online marketplace
A12/01953/24	France	Plastic toy set (Country of Origin: China)		Choking Very young children might put the duck in their mouth. The size of the duck creates a risk of choking by regurgitation. The product does not comply with the requirements of the Toy Safety Directive nor with the standard EN 71-1.	Removal of this product listing by the online marketplace
A12/01954/24	Spain	Soother (Country of Origin: China)		Choking The clip attaching the item to clothing can break easily, generating small parts. A small child may put them in their mouth and choke. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 12586.	Ban on the marketing of the product and any accompanying measures
A12/01955/24	Spain	Fancy-dress costume (Country of Origin: China)		Burns, Choking, Fire The bells can be easily detached. A small child may put them in their mouth and choke. Moreover, the headband is easily flammable, creating a risk of fire and burns. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Ban on the marketing of the product and any accompanying measures
A12/01956/24	Spain	Pull-along toy (Country of Origin: China)		Asphyxiation Small parts (tips of the antennas) may be easily detached. A small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Ban on the marketing of the product and any accompanying measures

A12/01958/24	France	Soft toy (Country of Origin: China)		Chemical The eyes of the toy pig have an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 20.6% by weight). These phthalates may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Removal of this product listing by the online marketplace
A12/01959/24	France	Finger painting kit (Country of Origin: China)		Chemical, Choking, Suffocation The painting kit has small parts (foam parts of the inkers) that can be easily detached. Small children may put them in their mouth and choke. Moreover, the product has an excessive concentration of a mixture of the preservatives methylchloroisothiazolinone and methylisothiazolinone (MCI/MI) (measured values up to 0.00008% and 0.00011%). MCI and MI cause severe skin burns. Additionally, the plastic bag of the packaging is too thin. If a child plays with it, the plastic can cover their mouth and nose, causing the child to suffocate. The product does not comply with the requirements of the Toy Safety Directive nor with the European standards EN 71-1 and EN 71-7.	Removal of this product listing by the online marketplace
A12/01967/24	Czechia	Toy chainsaw (Country of Origin: China)		Environment The solders in the product have an excessive concentration of lead and cadmium (measured values up to 71.3% and 0.14% by weight, respectively). Lead and cadmium pose a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Ban on the marketing of the product and any accompanying measures

A12/01968/24	Finland	Toy kitchen set (Country of Origin: China)		Chemical, Choking The battery compartment is easily opened, leaving the button batteries accessible. A child could put them in their mouth, which could cause damage to the child's gastrointestinal tract or choking. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 62115.	Recall of the product from end users
INFO/00092/24	France	Baby changing cot (Country of Origin: China)		Injuries The sides of the basket cannot stop a baby from getting out of the basket. This creates a risk of falling for the baby when the changing basket is used on a high surface. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 12221-1.	Marking the product with appropriate warnings on the risks

Safety Gate: the EU rapid alert system for dangerous non-food products



“Safety Gate”, the EU rapid alert system (formerly known as “RAPEX”), enables the rapid exchange of information between **31 European countries** and the European Commission on non-food dangerous products found on the market posing a risk to the health and safety of consumers.



A weekly overview of the alerts on those products is published in English for free on <https://ec.europa.eu/safety-gate-alerts/screen/webReport#weeklyReports>. The measures taken in the notifying country in order to restrict such products’ marketing or use can be ordered by national authorities (“compulsory measures”) or be taken directly by producers and distributors (“voluntary measures”).

The official contact points of the Member and EFTA-EEA States provide the information published in these weekly overviews. Under the terms of Annex II.10 of the General Product Safety Directive (**2001/95/EC**) responsibility for the information provided lies with the notifying party. The Commission does not take any responsibility for the accuracy of the information provided.


Recall Summary – US Toys / Children’s Products



CPSC Recall List (Jul 2024)


Recall No.	Notifying Country	Product	Product Photo	Hazard / Risk	Remedy
24-289	USA	<p>SWOMOG Children’s Two-Piece Pajama Sets</p> <p>(Country of Origin: China)</p>		<p>Burn Hazard</p> <p>SWOMOG Children’s Pajamas Recalled Due to Burn Hazard; Violation of Federal Flammability Regulations; Sold Exclusively on Amazon.com by SWOMOG</p> <p>The children’s pajama sets violate the federal flammability standards for children’s sleepwear, posing a burn hazard to children.</p>	<p>Consumers should immediately take the recalled pajamas away from children, stop using them and contact SWOMOG to receive a full refund. Consumers should destroy the garments by cutting the top and bottom in half, and disposing of them in accordance with local and state recycling laws. Consumers should email the recalling firm a photo of the destroyed garment at swomogservice@163.com to receive a refund. SWOMOG is contacting all known purchasers directly.</p>
24-296	USA	<p>Children’s Long-Sleeve / Pants Two-Piece Pajama Sets</p> <p>(Country of Origin: China)</p>		<p>Burn Hazard</p> <p>Children’s Pajama Sets Recalled Due to Burn Hazard and Violation of Federal Flammability Standards; Sold Exclusively on Temu.com by Fashion Online</p> <p>The recalled children’s pajama sets violate the flammability standards for children’s sleepwear, posing a risk of burn injuries to children.</p>	<p>Consumers should immediately take the recalled pajamas away from children, stop using them, and contact Fashion Online to receive a full refund. Consumers should destroy the garments by cutting the top and bottom in half and disposing of them in accordance with local and state recycling laws. Consumers should email the recalling firm a photo of the destroyed garments at 327937323@qq.com, or send via the “messages” button on the seller’s page to Fashion Online on Temu.com to receive a refund. Fashion Online is contacting all known purchasers directly.</p>

24-299	USA	<p>Halloween Witch Hats</p> <p>(Country of Origin: China)</p>		<p>Burn Hazard</p> <p>Claire's and Icing Stores Recalls Halloween Witch Hats Due to Burn Hazard and Violation of Federal Flammability Requirement</p> <p>The hats violate federal flammability requirements, posing a risk of burn injuries to consumers.</p>	<p>Consumers should immediately stop using the recalled hats and return the product to any Claire's or Icing Store for a full refund.</p>
24-300	USA	<p>Lovely Angel Children's Lace Nightgowns</p> <p>(Country of Origin: China)</p>		<p>Burn Hazard</p> <p>Children's Nightgowns Recalled Due to Burn Hazard; Violation of Federal Flammability Standards; Sold Exclusively on Temu.com by Lovely Angel</p> <p>The children's nightgowns violate the federal flammability standards for children's sleepwear, posing a risk of burn injuries to children.</p>	<p>Consumers should immediately take the recalled nightgowns away from children, stop using them, and contact Lovely Angel to receive a full refund. Consumers should destroy the garments by cutting them in half and disposing of them in accordance with local and state recycling laws. Consumers should send the recalling firm a photo of the destroyed garment at wangmaxime@163.com or via Lovely Angel's online store to receive a refund. Lovely Angel is contacting all known purchasers directly.</p>

24-301	USA	<p>Children’s Button-Up Short-Sleeve / Shorts Two-Piece Pajama Sets</p> <p>(Country of Origin: China)</p>		<p>Burn Hazard</p> <p>Children’s Pajama Sets Recalled Due to Burn Hazard and Violation of Federal Flammability Standards; Sold Exclusively on Temu.com by JUVENNO KIDS</p> <p>The recalled children’s pajama sets violate the flammability standards for children’s sleepwear, posing a risk of burn injuries to children.</p>	<p>Consumers should immediately take the recalled pajamas away from children, stop using them, and contact JUVENNO KIDS to receive a full refund. Consumers should destroy the garments by cutting the top and bottom in half and dispose of them in accordance with local and state recycling laws.</p> <p>Consumers should send the recalling firm a photo of the destroyed garments by email at 603262718@qq.com or via onsite messaging to JUVENNO KIDS on Temu.com to receive a refund. JUVENNO KIDS is contacting all known purchasers directly.</p>
24-308	USA	<p>Brilliant Bee Rattles</p> <p>(Country of Origin: China)</p>		<p>Choking Hazard</p> <p>Sassy Baby Recalls Manhattan Toy Brilliant Bee Rattles Due to Choking Hazard</p> <p>The wooden base can detach from the wooden rod and release the three plastic rings, posing a choking hazard to young children.</p>	<p>Consumers should immediately stop using the recalled rattles, take them away from children, and return the product to the place of purchase to receive a full refund, or contact Manhattan Toy for instructions on how to return the product to receive a full refund. Proof of purchase is not required to receive a full refund.</p>
24-311	USA	<p>Lancaster Table & Seating Standard Height Plastic Restaurant High Chairs</p> <p>(Country of Origin: China)</p>		<p>Fall Hazard</p> <p>Clark Associates Recalls Lancaster Table & Seating Plastic Restaurant High Chairs Due to Fall Hazard</p> <p>The T-bar located at the front middle of the chair can become loose and fall or break off while the high chair is in use, posing a fall hazard to children.</p>	<p>Consumers should immediately stop using the recalled high chairs and contact Clark Associates for a full refund. Consumers should register their product online at https://www.lancastertableandseating.com/recalls/plastic-high-chairs-recall and dispose of the product in accordance with local and state recycling laws.</p>

24-313	USA	<p>Razor Icon electric scooters</p> <p>(Country of Origin: China)</p>		<p>Fall Hazard</p> <p>Razor Recalls Icon Electric Scooters Due to Fall Hazard</p> <p>The downtube of the recalled electric scooter can separate from the floorboard during use, posing a fall hazard.</p>	<p>Consumers should immediately stop using the recalled scooters and contact Razor to receive a refund or coupon. Consumers with proof of purchase for recalled scooters bought on or after March 11, 2023, can receive a full refund. All other consumers can request a \$700 coupon for a future purchase on razor.com or a \$300 refund. Consumers will be asked to remove the handlebar, and return only the handlebar to Razor. Razor will send consumers a prepaid shipping label and pouch for the return. The scooter's lithium-ion batteries must be disposed of in accordance with any local and state laws, and not in the trash. The rest of the scooter should be disposed of separately in accordance with any local and state laws.</p>
--------	-----	---	---	--	--

24-316	USA	<p>Besrey Twins Strollers</p> <p>(Country of Origin: China)</p>		<p>Fall and Choking Hazards</p> <p>Stiger Recalls Besrey Twins Strollers Due to Entrapment, Fall and Choking Hazards; Violation of Federal Regulation for Strollers; Sold Exclusively on Amazon.com</p> <p>The twin stroller violates multiple safety regulations for strollers. The front seat in the forward-facing configuration poses an entrapment hazard to children. In addition, failures with the restraint system and rear seat enclosure pose a fall hazard to children. In products with a black grab bar, the foam padding on the grab bar can pose a choking hazard if the child bites it.</p>	<p>Consumers should stop using the stroller immediately and contact Stiger for information on how to dispose of the product to obtain a full refund. Stiger and Amazon are contacting all known purchasers directly.</p>
24-318	USA	<p>Victor Electric Folding Soft Bullet Toy Guns</p> <p>(Country of Origin: China)</p>	 <p>GREEN</p> <p>The accessories are random color.</p>	<p>Eye Injury Hazard</p> <p>Toy Guns Recalled Due to Eye Injury Hazard; Failure to Meet Federal Safety Regulations for Projectile Toys; Sold Exclusively on Temu.com by Youjiu</p> <p>The recalled toy guns fail to meet federal safety standards, as they do not have a blaze orange tip that is required by the mandatory toy standard to differentiate toy guns from real guns, and the projectiles pose an eye injury hazard to children because they do not meet the requirements in the mandatory toy standard for projectile toys.</p>	<p>Consumers should stop using the recalled toy guns immediately and contact Youjiu for a full refund. To receive a refund, consumers should remove the magazine and the battery, cut the black and red wires linked to the battery, take a photo of the destroyed toy gun, and send the photo to Youjiu's store through Temu's onsite messaging system on the Youjiu store page.</p>

24-321	USA	<p>Hover-1 Dynamo E-Scooters</p> <p>(Country of Origin: China)</p>		<p>Risk of Injury and Crash Hazard</p> <p>DGL Group Recalls Hover-1 Dynamo E-Scooters Due to Risk of Serious Injury and Crash Hazard; Sold Exclusively at Walmart.com</p> <p>The e-scooter's brakes can fail, posing a risk of serious injury and crash hazard.</p>	<p>Consumers should stop using the recalled e-scooters immediately and contact DGL Group for instructions on how to receive a full refund. To receive a refund, consumers will be required to provide photographs of their e-scooter's serial number and severed motor cable.</p>
--------	-----	--	---	--	---

* Source: www.recalls.gov


CPSC

The United States Consumer Product Safety Commission (CPSC) is an independent agency of the United States Government. To provide better service in alerting the American people to unsafe, hazardous or defective products, a “one stop shop” for U.S. Government recalls, <http://www.recalls.gov>, has been created. Members of the public may report unsafe products to CPSC by using the platform.


The recall list is divided into seven categories: Consumer Products, Motor Vehicles, Boats, Food, Medicine, Cosmetics and Environmental Products. Generally, the recall is conducted voluntarily by the company under CPSC's Fast Track Recall program. Fast Track recalls are initiated by firms who are committed to working with CPSC to quickly announce the recall and remedy to protect consumers.

Recall Summary – Australia Toys / Children’s Products

ACCC Recall List (Jul 2024)

PRA No.	Notifying Country	Product / Description	Product Photo	Hazard / Risk	Remedy
2024/20221	Australia	<p>Stroller was available in Standard and Deluxe Editions and four colours – brown, green, pink and red.</p>		<p>Missing Red Parking Brake Actuator and Warnings</p> <p>The product does not comply with the Consumer Product Safety Standard for Prams and Strollers - Consumer Protection Notice No. 8 of 2007 (the mandatory Standard for prams and strollers).</p> <p>The stroller does not have a red parking brake actuator and the safety warnings and manufacturer labels are missing or insufficient.</p> <p>Risk of severe injury or death to young children due to the missing safety features and lack of warning information.</p>	<p>Consumers should stop using the product immediately.</p> <p>Consumers should contact Chi Er Le Buggy Franchise for instructions to render the stroller unusable and receive a full refund including original shipping cost.</p> <p>For more information contact Temu Support Centre at: https://www temu.com/support-center.html or email Chi Er Le Buggy Franchise at 514951258@qq.com</p> <p>Supplier:</p> <ul style="list-style-type: none"> • Chi Er Le buggy franchise • Traders who sold this product

2024/20234	Australia	<p>Polar Bear / Koala Blanket Hoodie – 60 cm 4-7 yrs</p> <p>Item no.: K174183</p> <p>Barcode: 6921866174183</p> <p>Panther / Polar Bear Blanket Hoodie – 75 cm 8-12 yrs</p> <p>Item no.: K174220</p> <p>Barcode: 6921866174220</p> <p>Sloth / Koala / Alpaca / Tie Dye Blanket Hoodie – 75 cm 8-12 yrs</p> <p>Item no.: K174206</p> <p>Barcode: 6921866174206</p>		<p>Fire Hazard</p> <p>The products do not comply with the requirements of the mandatory safety standard for nightwear for children.</p> <p>The products do not have the required fire hazard labelling.</p> <p>There is a risk of serious burn injuries if exposed to a heat or flame source.</p>	<p>Consumers should stop using the product immediately and return the product to place of purchase for a refund or replacement.</p>
------------	-----------	--	---	--	---

<p>2024/20236</p>	<p>Australia</p>	<p>Magnetic building tiles.</p> <p>Sold in 110 or 142 piece sets.</p> <p>Multi-coloured.</p>		<p>Risk of Choking and Missing Warnings</p> <p>The product does not comply with the mandatory standard for toys containing magnets.</p> <p>The product has not been tested and does not include the required warning information.</p> <p>Risk of serious internal injuries or death if more than one small high-powered magnet is swallowed as they can stick together across the walls of the intestine or other digestive tissue.</p> <p>There is also a risk of young children choking on the magnets if the tiles break and the magnets come free.</p>	<p>Consumers should stop using the product and dispose of it.</p>
-------------------	------------------	---	---	---	---

<p>2024/20237</p>	<p>Australia</p>	<p>Bamboo fork for children.</p> <p>Sold as part of a set including:</p> <p>1 x bowl = D150 mm*H50 mm 600 ml</p> <p>1 x plate = D200 mm*H15 mm</p> <p>1 x cup = D80 mm*H90 mm 300 ml</p> <p>1 x spoon + fork = L135 mm / L135 mm</p> <p>Sold in the following colours:</p> <p>Pebble Mint Blossom Lilac Sunshine Pacific Monochrome</p> <p>Affected forks were supplied between October 2022 and July 2024.</p>		<p>Risk of Death or Serious Injury from Choking or Laceration</p> <p>A tine on the fork may break while in use.</p> <p>There is a risk of death or serious injury from choking or injury from laceration if the fork breaks during use.</p>	<p>Consumers should stop using affected forks immediately.</p> <p>Dispose of the forks.</p> <p>Contact bobo&boo by e-mail on hello@boboandboo.com.au to arrange for a refund for the fork; consumers will need an order number.</p> <p>For more information contact bobo&boo on hello@boboandboo.com.au</p> <p>Supplier:</p> <ul style="list-style-type: none"> • Bobo&boo • Traders who sold this product
-------------------	------------------	--	---	--	--

2024/20244	Australia	<p>Children's pyjama all-in one fleece body suit.</p> <p>Available in pink and blue</p> <p>Embossed pattern</p>		<p>Fire Hazard</p> <p>The products do not comply with the requirements of the mandatory safety standard for nightwear for children.</p> <p>The products do not have the required fire hazard labelling.</p> <p>There is a risk of serious burn injuries if exposed to a heat or flame source. Consumers may not be aware of this hazard.</p>	<p>Consumers should stop using these products immediately. Return to the nearest H&M store for a full refund. No receipt is required.</p>
------------	-----------	--	---	---	---

Australian Product Safety System

The Australian product safety system is set up to maximize the safety of goods through the cooperation of consumers, businesses and agencies. This policy sets out the principles adopted by the Australian Competition and Consumer Commission (ACCC) for prioritizing and addressing product safety risks.

Under the Australian Consumer Law, a responsible Minister can order a compulsory recall when there are hazards on the products. A voluntary recall could be conducted to remove the product from the marketplace when the suppliers become aware of unsafe or defective products.

The ACCC administers a national recalls system for recalls of specific and general consumer products, and publishes all product recalls on the website <https://www.productsafety.gov.au/recalls>.

STC (Hong Kong Standards and Testing Centre) is a not-for-profit, independent testing, inspection and certification organization. With a global network of ISO/IEC 17025 accredited testing laboratories and over 60 years of experience in consumer product testing, we can meet your conformity assessment needs with highly efficient and reliable service. Our testing scope and capabilities related to toys and children's products include but are not limited to:

EU Requirements

- EN 71
- Phthalates (EC) no. 1907/2006
- Nickel Release (EC) no. 1907/2006
- Total Cadmium (EEC) no. 91/338
- Lead in Jewellery product (EC) no. 836/2012
- Azo-dye (EC) no. 1907/2006
- Bisphenol-A (2014/81/EU)
- DMF (Dimethyl fumarate) (EU) no. 2011/135
- Flame retardants TCEP, TCPP, TDCP (2014/79/EU)
- Package Waste Directive (94/62/EC)

US & Canada Requirements

- ASTM F963
- CPSIA
- California Proposition 65
- 16 CFR 1501
- ASTM F2923 (Children's jewellery)
- ASTM F2999 (Adult's jewellery)
- US Toxic in Packaging Clearinghouse (TPCH)
- CCPSA - Toys Regulations (SOR/2011-17)

Japan Requirements

- Japan Toy Safety Standard (ST)
- Japan Food Sanitation Law (JFSL)

Australia Requirements

- AS/NZS 8124
- Consumer Protection Notice No. 6 of 2010 - DEHP

FOR MORE DETAILS, PLEASE CONTACT US:

Hong Kong: hktcd@stc.group
Changzhou: czstc@stc.group
U.S.A.: usenquiry@stc.group

Guangdong: gdtcd@stc.group
Vietnam: vnstc@stc.group
Germany: grstc@stc.group

Shanghai: shtcd@stc.group
Japan: jpo@stc.group

