














Recall Summary – European Toys






EU Safety Gate Alerts (Nov 2024)




Alert No.	Notifying Country	Product	Product Photo	Hazard / Risk	Measures Adopted
A11/00136/24	Poland	Toy scooter (Country of Origin: China)		Injuries The diameter of wheels and handlebar grips are inadequate. The steering tubes are not resistant to load and may collapse during a ride. A child may fall off the scooter and suffer injuries. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Warning consumers of the risks
A11/00139/24	Ireland	Toy torch (Country of Origin: China)		Burns Due to a short circuit, the product can overheat, causing the bottom of the product to melt. As a consequence, users can touch hot parts and suffer burns. The product does not comply with the requirements of the Toy Safety Directive.	Withdrawal of the product from the market
A11/00141/24	Croatia	Plush toy (Country of Origin: China)		Choking The fibrous stuffing material of the toy is easily accessible due to the weakness of the seams. A small child may put the filling material in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive, nor with European standard EN 71-1.	Import rejected at border
A11/00143/24	France	Plush toy (Country of Origin: China)		Choking The fibrous stuffing material of the toy is easily accessible due to weakness of certain seams. A small child may put the filling material in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive, nor with European standard EN 71-1.	Withdrawal of the product from the market
A11/00144/24	Bulgaria	Chair (Country of Origin: Türkiye)		Cuts, Injuries The chair has sharp edges and corners on the back, seat and legs. These can cause cuts or injuries to the user or bystanders. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 17191.	Import rejected at border

A11/00145/24	Croatia	Plush toy (Country of Origin: China)		Choking The fibrous stuffing material of the toy is easily accessible due to weakness of certain seams. A small child may put the filling material in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Import rejected at border
A11/00146/24	Croatia	Soft toy (Country of Origin: China)		Choking The fibrous stuffing material of the toy is easily accessible. A small child may put the filling material in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Import rejected at border
A12/02998/24	Germany	Soft toy (Country of Origin: China)		Choking Small parts can easily detach (eyes). A small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Recall of the product from end users
A12/03001/24	Poland	Bath toy set (Country of Origin: China)		Chemical The plastic material of the product has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 16.9% by weight). This phthalate may harm the children's health by causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Warning consumers of the risks
A12/03008/24	Germany	Baby book (Country of Origin: China)		Choking The product has small parts (googly eyes and clock's press-on fastener) that can be easily detached. A small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Recall of the product from end users





A12/03010/24	Sweden	Toy helicopter (Country of Origin: China)		Chemical, Environment The plastic in the USB cable has excessive concentrations of short chain chlorinated paraffins (SCCPs) and lead (measured values up to 0.67% and 0.36% by weight, respectively). The solders in the product have an excessive concentration of lead (measured value up to 84% by weight). SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations and bio-accumulate in wildlife and humans, posing a risk to human health and the environment. Prolonged exposure to them through the skin may cause cancer. Lead is harmful to human health, accumulates in the body and may affect breast-fed or unborn children. Lead poses a risk to the environment. The product does not comply with the Persistent Organic Pollutants (POP) Regulation nor with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS Directive).	Withdrawal of the product from the market
A12/03018/24	Slovenia	Magnetic toy (Country of Origin: China)		Injuries The toy contains small magnets with a high magnetic flux (measured value up to 1565 kG2mm2). If a child swallows the small magnets, they could attract one another causing intestinal blockage or perforation. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Recall of the product from end users
A12/03020/24	France	Teething bracelet (Country of Origin: Lithuania)		Choking The product can easily break, resulting in small parts (beads). A small child may put them in their mouth and choke. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 71-1.	Removal of this product listing by the online marketplace





A12/03021/24	France	Teething necklace (Country of Origin: China)		Choking, Strangulation The necklace does not open easily and children may be strangled by the cord. Moreover, the product can easily break, resulting in small parts (beads). A small child may put them in their mouth and choke. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 71-1.	Removal of this product listing by the online marketplace
A12/03022/24	France	Teething necklace (Country of Origin: Lithuania)		Choking, Strangulation The necklace does not open easily and children may be strangled by the cord. Moreover, the product can easily break, resulting in small parts (beads). A small child may put them in their mouth and choke. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 71-1.	Warning consumers of the risks
A12/03023/24	France	Teething necklace (Country of Origin: Lithuania)		Choking The product can easily break, resulting in small parts (beads). A small child may put them in their mouth and choke. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 71-1.	Removal of this product listing by the online marketplace
A12/03024/24	France	Teething necklace (Country of Origin: China)		Choking, Strangulation The necklace does not open easily and children may be strangled by the cord. Moreover, the product can easily break, resulting in small parts (beads). A small child may put them in their mouth and choke. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 71-1.	Removal of this product listing by the online marketplace

A12/03026/24	Sweden	Soft toy (Country of Origin: Unknown)		Environment The solders in the product have an excessive concentration of lead (measured value up to 71% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Withdrawal of the product from the market
A12/03032/24	Sweden	Toy snail (Country of Origin: China)		Environment The solders in the toy have an excessive concentration of lead (measured value up to 90% by weight). Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Withdrawal of the product from the market
A12/03036/24	Croatia	Toy slime (Country of Origin: United Kingdom)		Chemical The toy slime has an excessive concentration of lead (measured value up to 0.92 mg/kg). Lead is harmful to human health, accumulates in the body, can cause developmental neurotoxicity and may affect breast-fed or unborn children. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-3.	Withdrawal of the product from the market
A12/03037/24	Slovenia	Magnetic toy (Country of Origin: China)		Injuries The toy contains small magnets with a high magnetic flux (measured value up to 176 kG2mm2). If a child swallows the small magnets, they could attract one another causing intestinal blockage or perforation. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Recall of the product from end users
A12/02800/24	Germany	Soother holder (Country of Origin: China)		Strangulation The soother holder is too long, which may lead to strangulation of a child. The product does not comply with the requirements of the General Product Safety Directive, nor with the European standard EN 12586.	Recall of the product from end users

A12/03038/24	Croatia	Toy slime (Country of Origin: Germany)		Chemical The migration of boron from the toy slime is too high (measured value up to 670 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-3.	Withdrawal of the product from the market
A12/03043/24	Sweden	Battery-operated toy (Country of Origin: China)		Environment The solders in the product have an excessive concentration of lead and cadmium (measured values up to 52% and 0.2% by weight, respectively). Cadmium bio-accumulates and poses a risk to the environment. Lead poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Withdrawal of the product from the market
A12/03046/24	Slovenia	Fishing toy set (Country of Origin: China)		Injuries The toy contains small magnets with an excessive high magnetic flux (measured value up to 110 kG2mm2). If a child swallows the small magnets, they could attract one another causing intestinal blockage or perforation. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Recall of the product from end users


A12/03047/24	Poland	Toy scooter (Country of Origin: China)		Injuries, Suffocation The diameter of the front wheels of the scooter is too small (measured value up to 116 mm). When a child rides a scooter on an uneven surface, the wheel can get stuck in a shallow depression and the child may fall, suffering injuries. Moreover, the plastic bag of the packaging is too thin. If a child plays with the packaging, the plastic can cover their mouth and nose, causing the child to suffocate. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market
A12/03065/24	France	Baby cot (Country of Origin: Belgium)		Injuries The product is not stable, which creates a risk of the child falling. This can lead to various injuries. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 1466.	Withdrawal of the product from the market
A12/03068/24	Croatia	Swing (Country of Origin: China)		Choking, Strangulation The swing can easily break and release small parts (tie rod, stickers). A small child may put them in their mouth and choke. Moreover, a small child's head or neck can get trapped in the holes/openings of the swing. This creates a risk of strangulation. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Ban on the marketing of the product and any accompanying measures
A12/03069/24	Cyprus	Plastic doll set (Country of Origin: China)		Chemical The plastic material of the product (head of the doll, arms and legs of the doll, pony) has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 38.84% by weight). This phthalate may harm the health by causing possible damage to the reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market


A12/03072/24	Sweden	Balloons (Country of Origin: China)		Chemical The latex of the balloons releases an excessive amount of nitrosamines (measured total value up to 1.9 mg/kg). Nitrosamines may cause cancer through ingestion or dermal exposure. A child could be exposed to them when touching or putting the product in their mouth. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-12.	Withdrawal of the product from the market
A12/03082/24	Poland	Jumping toy (Country of Origin: China)		Chemical The plastic material of the product has an excessive concentration of dibutyl phthalate (DBP) (measured value up to 11.6% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/03083/24	Cyprus	Doll (Country of Origin: China)		Chemical The plastic material of the doll's arms and legs has an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) and dibutyl phthalate (DBP) (measured values up to 0.96% and 0.35% by weight, respectively). These phthalates may harm the health of children, causing possible damage to their reproductive system or liver. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/03105/24	France	Teething necklace (Country of Origin: Lithuania)		Choking, Strangulation The necklace does not open and can therefore wind around the neck of the child, leading to strangulation. Furthermore, the necklace can easily break, resulting in small parts (beads). A small child may put them in their mouth and choke. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 71-1.	Removal of this product listing by the online marketplace





A12/03108/24	Sweden	Basketball set for trampoline (Country of Origin: Unknown)		Injuries Anyone who jumps on the trampoline risks head injury if they collide with the basketball hoop. If any textile parts of the hoop break, the jumper could become entangled, leading to injury or strangulation. Using a ball on the trampoline may increase the risk of injuries. The toy consists of two hoops – one inside and one outside the trampoline. Using both hoops simultaneously on inground or flatground trampolines could increase the risk of user collisions. For non-buried trampolines, there is also an increased risk that a user might crawl under the trampoline while it's in use to retrieve a lost ball. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-14.	Recall of the product from end users
A12/03119/24	Germany	Balloons (Country of Origin: China)		Chemical The balloons release an excessive amount of nitrosatable substances (NDMA and NDEA) (measured value up to 25.4 mg/kg). These nitrosamines may cause cancer through ingestion or dermal exposure. A child could be exposed to it when touching or putting the product in their mouth. The product does not comply with the requirements of the Toy Safety Directive.	Removal of this product listing by the online marketplace
A12/03125/24	France	Teething necklace (Country of Origin: Lithuania)		Choking, Strangulation The necklace does not open and can therefore wind around the neck of the child, leading to strangulation. Furthermore, the necklace can easily break, releasing small parts (beads). A small child may put them in their mouth and choke. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 71-1.	Removal of this product listing by the online marketplace
A12/03127/24	Estonia	Soother (Country of Origin: Poland)		Choking The handle of the product, which is a small part, can easily break. A small child may put it in their mouth and choke. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 1400.	Recall of the product from end users





A12/03128/24	Hungary	Doll (Country of Origin: China)		Chemical The product has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) and dibutyl phthalate (DBP) (measured values up to 29% and 0.34% by weight, respectively). These phthalates may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/03129/24	Hungary	Doll (Country of Origin: China)		Chemical The product has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 3.1% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Ban on the marketing of the product and any accompanying measures
A12/03135/24	Germany	Soft toy (Country of Origin: China)		Choking The stuffing material of the toy is easily accessible due to the weakness of certain seams. A small child may put the stuffing material in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Stopping of sales
A12/03139/24	Hungary	Plastic doll (Country of Origin: China)		Chemical The doll has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) and dibutyl phthalate (DBP) (measured values up to 14% and 0.31% by weight, respectively). These phthalates may harm the health of children by causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Recall of the product from end users
A12/03140/24	Hungary	Toy rattle (Country of Origin: China)		Choking The rattle can easily break, generating small parts. A child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71.	Withdrawal of the product from the market

A12/03147/24	Estonia	Soother (Country of Origin: Malta)		Choking The product's knob can easily detach. As a consequence, a small child may put it in their mouth and choke. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 1400.	Recall of the product from end users
A12/03148/24	France	Baby changing cot (Country of Origin: Spain)		Injuries The sides of the cot cannot stop a moving baby rolling out of the cot. A child may fall out of the basket and suffer injuries. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 12221.	Withdrawal of the product from the market
A12/03152/24	Lithuania	Children's high chair (Country of Origin: China)		Choking, Injuries The product breaks easily by falling onto the floor. It can therefore cause injuries to the child and bystanders. Moreover, the fall can generate small parts. A small child can put them in their mouth and choke. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 14988.	Withdrawal of the product from the market
A12/03154/24	Sweden	Plastic toy (Country of Origin: China)		Chemical The plastic material of the product has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 22.2% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
A12/03155/24	Estonia	Soother clips (Country of Origin: United Kingdom)		Choking Small parts (garment fastener) can easily detach from the product. A small child may put them in their mouth and choke. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 12586.	Recall of the product from end users


A12/03157/24	Bulgaria	Stroller (Country of Origin: Norway)		Injuries The product's parking brake does not work correctly. This can lead to an accident causing injuries. The product does not comply with the requirements of the General Product Safety Directive.	Recall of the product from end users
A12/03158/24	Austria	Soother (Country of Origin: China)		Choking The ring on the shield can easily detach from the product, releasing small parts. A small child may put it in their mouth and choke. The product does comply with the requirements of the General Product Safety Directive nor with the European standard EN 1400.	Removal of this product listing by the online marketplace
A12/03160/24	Estonia	Soother holder (Country of Origin: Denmark)		Choking The garment fastener of the soother holder can easily break. A small child may put it in their mouth and choke. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 1400.	Recall of the product from end users
A12/03163/24	Poland	Plastic toy (Country of Origin: China)		Choking The toy has small parts (figurine's ear) which can easily detach. Small children may put it in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market
A12/03164/24	Denmark	Spinner toy (Country of Origin: Unknown)		Choking The spinner toy has protruding parts. A small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Recall of the product from end users
A12/03167/24	France	Bath toy (Country of Origin: China)		Choking Small parts (suction cup) can easily detach from the toy. A small child may put it in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive, nor with European standard EN 71-1.	Withdrawal of the product from the market

A12/03168/24	France	Teething necklace (Country of Origin: Lithuania)		Choking, Strangulation The necklace does not open and can therefore wind around the neck of the child, leading to strangulation. Moreover, the product can easily break, resulting in small parts (beads). A small child may put them in their mouth and choke. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 71-1.	Warning consumers of the risks
A12/03169/24	Denmark	Ribbon toy (Country of Origin: Unknown)		Choking The wooden part of the product has a protruding part that can get stuck in the mouth of a small child, causing choking. The product does not comply with the requirements of the Toy Safety Directive, nor with the European standard EN 71-1.	Recall of the product from end users
A12/03170/24	Croatia	Swing (Country of Origin: Croatia)		Injuries The swing is not sufficiently resistant to load. As a consequence, under load the seat may separate from the rope and the child may fall off the swing and suffer injuries. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-8.	Destruction of the product
A12/03172/24	Slovakia	Children's cot (Country of Origin: Poland)		Entrapment, Injuries, Suffocation The distance between the slats of the cot base is too big. The limbs, head or neck of the child may get stuck and cause subsequent injuries, e.g., suffocation when the neck is stuck between the holes that are located between the slats of the cot bed. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 716-1.	Warning consumers of the risks


A12/03191/24	France	Soother holder (Country of Origin: China)		Choking, Strangulation The soother holder is too long, which may lead to strangulation of a child. Moreover, the chain can easily break, resulting in small parts. Small children may put them in their mouth and choke. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 12586.	Warning consumers of the risks
A12/03192/24	France	Soother holder (Country of Origin: China)		Choking, Entrapment The garment fastener of the soother holder can easily break, resulting in small parts. Small children may put them in their mouth and choke. In addition, the product has holes that may lead to finger entrapment. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 12586.	Warning consumers of the risks
A12/03193/24	France	Children's fancy dress (Country of Origin: China)		Strangulation The product has long functional cords in the neck area. These cords can become trapped during various activities of a child, leading to strangulation. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 14682.	Warning consumers of the risks
A12/03195/24	Bulgaria	Soother holder (Country of Origin: Türkiye)		Choking, Strangulation The soother holder is too long, which may lead to strangulation of a child. Moreover, the chain can easily break, resulting in small parts. Small children may put them in their mouth and choke. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 12586.	Withdrawal of the product from the market

A12/03196/24	Bulgaria	Soother holder (Country of Origin: France)		Strangulation The soother holder is too long, which may lead to strangulation of a child. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 12586.	Withdrawal of the product from the market
A12/03201/24	France	Teething necklace (Country of Origin: Lithuania)		Choking The necklace can easily break, resulting in small parts (beads). A small child may put them in their mouth and choke. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 71-1.	Removal of this product listing by the online marketplace
A12/03204/24	France	Teething necklace (Country of Origin: Lithuania)		Choking The necklace can easily break, releasing small parts (beads). A small child may put them in their mouth and choke. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 71-1.	Removal of this product listing by the online marketplace
A12/03207/24	France	Soother holder (Country of Origin: China)		Choking, Strangulation The clothing fastener device of the soother can easily break, resulting in small parts. Small children may put them in their mouth and choke. Moreover, the soother holder and its double-strand part is too long which can lead to strangulation. The product does not comply with the requirements of the General Product Safety Directive nor with the European standards EN 12586.	Removal of this product listing by the online marketplace


A12/03208/24	France	Toy torch light (Country of Origin: China)		Chemical, Choking, Damage to sight The battery compartment can be easily opened, leaving the button batteries accessible. A child may put them in their mouth, which could cause them to choke or they can be swallowed, which could cause damage to the child's gastrointestinal tract. The beam intensity of the white LED is too powerful. Direct viewing of the beam could cause damage to sight. The product does not comply with the requirements of the Toy Safety Directive nor with the European standards EN 71-1, EN 71-2, EN 71-3 and EN 62115.	Warning consumers of the risks
A12/03210/24	Bulgaria	Children's high chair (Country of Origin: China)		Injuries The high chair is not sufficiently stable and can easily tip over. A child may fall and suffer injuries. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 14988.	Withdrawal of the product from the market
A12/03211/24	Bulgaria	Children's high chair (Country of Origin: China)		Injuries The high chair lacks an active restraint system and is not sufficiently stable and can easily tip over. The child may fall and suffer injuries. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 14988.	Withdrawal of the product from the market
A12/03213/24	Croatia	Toy slime (Country of Origin: China)		Chemical The migration of boron from the toy slime is too high (measured value up to 670 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-3.	Ban on the marketing of the product and any accompanying measures

A12/03219/24	Romania	Children's hat (Country of Origin: China)		Strangulation The product bears cords with free ends in the neck area. These drawstrings can become trapped during various activities of a child, leading to injuries or strangulation. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 14682.	Ban on the marketing of the product and any accompanying measures
A12/03231/24	Germany	Doll (Country of Origin: China)		Chemical The plastic arms of the doll have an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) and diisobutyl phthalate (DIBP) (measured values up to 14% and 0.31% by weight, respectively). These phthalates may harm the health of children by causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Recall of the product from end users
A12/03233/24	France	Fancy dress costume (Country of Origin: China)		Strangulation The product has non-detachable functional cords in the neck area, in which a child can become trapped during various activities, leading to strangulation. The product does not comply with the requirements of the Toy Safety Directive nor of the European standard EN 71-1.	Removal of this product listing by the online marketplace
A12/03243/24	Iceland	Sensory swing (Country of Origin: China)		Strangulation, Suffocation The flexible cloth of the swing can easily form a loop. A child can have their head entangled in the flexible material, leading to strangulation. If a child's head is stuck inside the swing, they might not be able to breathe, leading to suffocation. The product does not comply with the requirements of the Toy Safety Directive nor with the European standards EN 71-1 and EN 71-8.	Recall of the product from end users

A12/03253/24	Romania	Kitchen toy set (Country of Origin: China)		Choking The product contains small parts. Small children may put them in their mouth and choke. The product does not comply with the Toy Safety Directive nor with the European standard 71-1.	Ban on the marketing of the product and any accompanying measures
A12/03255/24	Denmark	Swing (Country of Origin: Denmark)		Strangulation The swing has openings that can cause the child to fall and their head can be trapped in them, leading to strangulation. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-8.	Recall of the product from end users
A12/03257/24	Slovakia	Children's cot (Country of Origin: Poland)		Entrapment, Injuries, Strangulation The slats may become detached and create an opening. The limbs, head or neck of the child may get trapped and the child may consequently suffer injuries, or strangulation. The product does not comply with the requirements of the General Product Safety Directive nor with European standard EN 716-1.	Warning consumers of the risks
A12/03258/24	Slovakia	Children's cot (Country of Origin: Germany)		Injuries The distance between the footholds and the top of the cot sides and ends is too small. The child may fall out of the cot and suffer injuries. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 716-1.	Recall of the product from end users
A12/03259/24	Slovakia	Children's wooden cot (Country of Origin: Unknown)		Injuries, Strangulation The slats may become detached and create an opening. The limbs, head or neck of the child may get stuck and the child may consequently suffer injuries. Moreover, the cords can get entangled around snag points, leading to strangulation. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 716-1.	Warning consumers of the risks

A12/03274/24	Croatia	Swing (Country of Origin: Türkiye)		Choking, Injuries The rope is too thin and can break, causing a child to fall. Fragments of the female closures of the safety harnesses can become detached, releasing small parts. A small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-8.	Destruction of the product
A12/03287/24	Bulgaria	Children's table and chair set (Country of Origin: Türkiye)		Injuries The chair in the product can easily break, causing the user to fall, which could lead to injuries. Moreover, the chair has sharp edges and corners on the back, seat, and legs. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 17191.	Import rejected at border
A12/03288/24	France	Keyring with soft toy (Country of Origin: China)		Chemical, Choking The toy has small parts (ring, carabiner clasp and bell). The seam allows access to the stuffing material. A small child may put them in their mouth and choke. Furthermore, the migration of lead from the metal bell in the product is too high (measured value up to 70mg/kg). Lead is harmful to human health, accumulates in the body, can cause developmental neurotoxicity and may affect breast-fed or unborn children. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Removal of this product listing by the online marketplace
A12/03290/24	France	Play mat (Country of Origin: China)		Choking The toy has small parts (inner parts of the numbers and letters) which can easily detach. Small children may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Warning consumers of the risks

A12/03310/24	Bulgaria	Children's high chair (Country of Origin: China)		Injuries The high chair lacks an active restraint system. A child may fall and suffer injuries. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 14988.	Withdrawal of the product from the market
A12/03322/24	France	Finger paint (Country of Origin: China)		Chemical The migration of aluminum from the toy is too high (measured value up to 3502 mg/kg). Aluminum is toxic for children if ingested. Moreover, the product releases an excessive amount of formaldehyde (measured values up to 532 mg/kg). Formaldehyde is a skin sensitizer and can trigger allergic reactions and may cause cancer. The product does not comply with the requirements of the Toy Safety Directive nor with the European standards EN 71-3 and EN 71-7.	Warning consumers of the risks
A12/03353/24	Croatia	Swing (Country of Origin: Germany)		Choking, Injuries Small plastic sheets can easily detach from the ends of the ropes. A small child may put these in their mouth and choke. Moreover, the swing is not stable due to the distance between the lowest part and the upper part of the sitting area. This can cause the child to fall, causing serious injuries. The product does not comply with the requirements of the Toy Safety Directive nor with the European standards EN 71-1 and EN 71-8.	Destruction of the product
INFO/00125/24	Estonia	Soother holder (Country of Origin: Estonia)		Choking The garment fastener of the soother holder can easily break, resulting in small parts. A small child may put them in their mouth and choke. The product does not comply with the requirements of the General Product Safety Directive nor with the European standard EN 71-1.	Recall of the product from end users

INFO/00126/24	Sweden	Electric toy (Country of Origin: China)		Environment The solders in the product have excessive concentrations of lead and cadmium (measured values up to 79% and 0.7% by weight, respectively). Lead poses a risk to the environment. Cadmium bio-accumulates and poses a risk to the environment. The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive).	Withdrawal of the product from the market
---------------	--------	---	---	---	---

Safety Gate: the EU rapid alert system for dangerous non-food products




“Safety Gate”, the EU rapid alert system (formerly known as “RAPEX”), enables the rapid exchange of information between **31 European countries** and the European Commission on non-food dangerous products found on the market posing a risk to the health and safety of consumers.



A weekly overview of the alerts on those products is published in English for free on <https://ec.europa.eu/safety-gate-alerts/screen/webReport#weeklyReports>. The measures taken in the notifying country in order to restrict such products’ marketing or use can be ordered by national authorities (“compulsory measures”) or be taken directly by producers and distributors (“voluntary measures”).

The official contact points of the Member and EFTA-EEA States provide the information published in these weekly overviews. Under the terms of Annex II.10 of the General Product Safety Directive (**2001/95/EC**) responsibility for the information provided lies with the notifying party. The Commission does not take any responsibility for the accuracy of the information provided.




Recall Summary – US Toys / Children’s Products


CPSC Recall List (Nov 2024)

Recall No.	Notifying Country	Product	Product Photo	Hazard / Risk	Remedy
25-030	USA	Dreamgro Lullaby mermaid travel soothers (Country of Origin: China)		Choking Hazard Dreamgro Recalls Lullaby Travel Soothers Due to Choking Hazard The recalled toy’s gold-colored soft star can detach, posing a choking hazard to young children.	Consumers should immediately stop using the recalled soothers and take them away from children. Return the soother to the store where purchased for a full refund.
25-031	USA	Kyte Baby Slumber Suits (Country of Origin: China)		Burn Hazard Kyte Baby Recalls Slumber Suits Due to Burn Hazard; Violation of Federal Flammability Regulations; Sold Exclusively on Kytebaby.com The recalled slumber suits violate federal flammability regulations for children’s sleepwear, posing a risk of burn injuries to children.	Consumers should stop using the recalled slumber suits immediately and contact Kyte Baby for instructions on how to destroy or return the garments for a full refund or store credit for the original purchase price plus free shipping and handling. Kyte Baby is contacting all known purchasers directly.
25-032	USA	Guava Roam Strollers (Country of Origin: China)		Fall and Injury Hazards Guava Family Recalls Roam Strollers Due to Fall and Injury Hazards The stroller’s brakes can fail to engage or unexpectedly disengage, posing fall and injury hazards to children.	Consumers should immediately stop using the recalled strollers and contact Guava Family for instructions on how to register for a free repair kit and new installation instructions.

25-033	USA	<p>Baofali 4-in-1 Microfiber Crib Safety Bumpers</p> <p>(Country of Origin: China)</p>		<p>Suffocation Hazard</p> <p>Baofali Crib Bumpers Recalled Due to Suffocation Hazard; Violation of Federal Ban on Crib Bumpers; Sold Exclusively on Temu.com by Unique Person Home Goods</p> <p>The recalled crib bumpers violate the federal crib bumper ban, posing a suffocation hazard to infants. Padded crib bumpers are banned by the federal Safe Sleep for Babies Act.</p>	<p>Consumers should immediately stop using and remove the recalled crib bumpers from the crib. To receive a full refund, take a photo of the crib bumper cut in half and email the photo to 2540535966@qq.com or message to Baofali Trading on Temu.com. Dispose of the destroyed crib bumper in accordance with local and state laws. Baofali Trading is contacting all known purchasers directly.</p>
25-040	USA	<p>Celebration Girl's Summer Pajama Sets</p> <p>(Country of Origin: Peru)</p>		<p>Burn Hazard</p> <p>Petidoux Recalls Children's Pajamas Due to Burn Hazard; Violation of Federal Flammability Regulations for Children's Sleepwear</p> <p>The recalled children's pajamas violate the flammability regulations for children's sleepwear, posing a risk of burn injuries to children.</p>	<p>Consumers should immediately take the recalled pajamas away from children, stop using them, and contact Petidoux for a full refund. Consumers will be asked to destroy the garments by cutting the top and bottom in half and disposing of them in accordance with local and state recycling procedures. Consumers must send a photo of the destroyed garment to customerservice@petidoux.com. Upon receipt of the photo, consumers will have the option of receiving a full refund or store credit worth 1.25 times the purchase price.</p>

25-041	USA	<p>Hallmark Keepsake Christmas Tree Ornaments featuring the Cad Bane Character from Star Wars: The Book of Boba Fett</p> <p>(Country of Origin: Sri Lanka)</p>		<p>Risk of Mold Exposure</p> <p>Hallmark Recalls Cad Bane Christmas Tree Ornaments Due to Risk of Mold Exposure</p> <p>The brown paint on the exterior of the recalled Christmas tree ornaments did not fully dry before packaging, causing mold to grow on the exterior surface of the ornament, posing risk of respiratory issues to consumers due to mold exposure.</p>	<p>Consumers should immediately stop using the recalled ornament and return it to their Hallmark Gold Crown store or follow the return instructions online at www.hallmark.com to receive a postage paid shipping label for a full refund. Consumers will receive a full refund in the form of original payment. No purchase receipt is required to receive the refund.</p>
25-043	USA	<p>Woom Bicycles OFF 5, OFF AIR 5, OFF 6, OFF AIR 6, and ORIGINAL 6</p> <p>(Country of Origin: Cambodia)</p>		<p>Fall and Crash Hazards</p> <p>Woom Bikes USA Recalls Children's OFF, OFF AIR and ORIGINAL 6 Bicycles Due to Fall and Crash Hazards</p> <p>The crank can break, due to fatigue fractures, causing the rider to lose control, posing fall and crash hazards.</p>	<p>Consumers should immediately stop using the recalled bicycles and contact Woom Bikes USA for instructions on how to get a free replacement crankset. Consumers can use the online crank checker tool found at woom.com to determine if their bicycle is affected by the recall. Consumers with affected cranksets will be sent a free replacement that must be installed by a bike repair technician at their preferred bike shop. Reimbursement in the way of a check will be issued for the consumer's crank replacement expense upon submission of the repair receipt. All known purchasers are being contacted directly by Woom.</p>

25-044	USA	YOYO³ strollers (Country of Origin: China)		Injury Hazard Stokke Recalls YOYO ³ Strollers Due to Injury Hazard The parking brake on the recalled strollers can disengage, posing an injury hazard.	Consumers should immediately stop using the recalled strollers and go to https://recall.stokke.com/oyo3 to register their product to receive a full refund in the form of a refund check.
25-051	USA	Nerf Barrage Youth Bike Helmets (Country of Origin: China)		Risk of Head Injury Todson Recalls Nerf Barrage Bicycle Helmets Due to Risk of Head Injury; Violation of Federal Regulations for Bicycle Helmets; Sold Exclusively at Walmart The recalled helmets do not comply with the retention system requirements of the mandatory federal safety regulations for bicycle helmets. The helmets can fail to protect the wearer in the event of a crash, posing a risk of head injury.	Consumers should stop using the recalled Nerf Barrage helmets immediately and contact Todson Inc. for a full refund. To receive a refund, consumers should destroy the helmet by cutting off the straps, then take a photo, and send the photo to the recalling firm by email at NerfHelmetRecall@Todson.com . After submitting proof of destruction, consumers should dispose of the recalled helmet. Todson is contacting all known purchasers directly.
25-052	USA	Segway Ninebot P100 KickScooters (Country of Origin: China)		Fall and Injury Hazards Segway Recalls Segway Ninebot P100 KickScooters Due to Fall and Injury Hazards The front fork of the recalled KickScooters can break, posing fall and injury hazards to the rider.	Consumers should immediately stop using the recalled KickScooters and contact Segway for a free repair. Segway will direct consumers to a local store for the repair (where available) or provide a pre-paid shipping label to ship the product to a national service center for repair. Segway is contacting all known purchasers directly.

25-054	USA	<p>South Shore Cribs</p> <p>(Country of Origin: Malaysia)</p>		<p>Entrapment Hazard</p> <p>South Shore Cribs Recalled Due to Entrapment Hazard; Violation of Federal Regulation for Full Sized Cribs; Imported by South Shore Industries</p> <p>The spacing between some of the crib's slats is wider than allowed under the federal safety standard, posing an entrapment hazard to children.</p>	<p>Consumers should immediately stop using the recalled cribs and contact South Shore for information on how to disassemble the product. To receive a full refund, take a photo of the disassembled crib in an outdoor waste container and email the photo to service@southshorefurniture.com. South Shore, Amazon.com and Walmart.com are contacting all known purchasers directly.</p>
--------	-----	---	---	--	---

* Source: www.recalls.gov


CPSC


The United States Consumer Product Safety Commission (CPSC) is an independent agency of the United States Government. To provide better service in alerting the American people to unsafe, hazardous or defective products, a “one stop shop” for U.S. Government recalls, <http://www.recalls.gov>, has been created. Members of the public may report unsafe products to CPSC by using the platform.



The recall list is divided into seven categories: Consumer Products, Motor Vehicles, Boats, Food, Medicine, Cosmetics and Environmental Products. Generally, the recall is conducted voluntarily by the company under CPSC’s Fast Track Recall program. Fast Track recalls are initiated by firms who are committed to working with CPSC to quickly announce the recall and remedy to protect consumers.



Recall Summary – Australia Toys / Children’s Products

ACCC Recall List (Nov 2024)


PRA No.	Notifying Country	Product / Description	Product Photo	Hazard / Risk	Remedy
2024/20339	Australia	Blue plastic novelty sunglasses with flashing lights.		<p>Risk of choking or serious injury</p> <p>This product doesn’t comply with the mandatory standards for products containing button/coin batteries.</p> <p>The button/coin batteries are not adequately secured and are accessible to young children.</p> <p>The product does not include the required warning information.</p> <p>There is a risk of choking or serious injury if young children gain access to the button/coin batteries and swallow or place them inside their body.</p>	<p>Return the products to Toybox on Wheels for a full refund.</p> <p>Contact:</p> <p>Toybox on Wheels Phone: 0419 376 880</p>

<p>2024/20341</p>	<p>Australia</p>	<p>Frame for a pram/stroller for babies and toddlers, available in black or black and white.</p> <p>The seat and canopy of the pram/stroller is available in 9 colours.</p> <p>Recalled Australian models:</p> <p>YOYO 3 frame in black and white Product code: 647101</p> <p>Affected serial number: 142AA0044415 to 142AA0044564</p> <p>YOYO 3 frame in black</p> <p>Product code: 647102</p> <p>Affected serial number: 142AA0044565 to 142AA0045564</p>		<p>Risk of Serious Injury to Babies or Young Children</p> <p>The affected pram/stroller's brakes can fail when in use.</p> <p>Risk of serious injury to babies or young children if the pram/stroller's parking brakes fail.</p>	<p>Stop using this product immediately.</p> <p>Check the serial number on your stroller frame and/or visit Stokke's recall page to check if your stroller is affected and arrange for a replacement free of charge.</p> <p>Contact Stokke Australia henzo@henzoll.com.au (02) 8863 2886 9:00 am to 5:00 pm, Monday to Friday.</p>
-------------------	------------------	---	---	---	---

2024/20342	Australia	<p>The glow in the dark hooded jumper was sold in four colours and styles:</p> <p>Pink Rainbow Unicorn</p> <p>Purple Rainbow Unicorn</p> <p>Blue Dinosaur Space Planet</p>		<p>Risk of Serious Burn Injuries if Exposed</p> <p>The product does not comply with the mandatory standard for nightwear for children.</p> <p>It doesn't include the required warning label.</p> <p>There is a risk of serious burn injuries if exposed to a heat or flame source. Consumers may not be aware of this risk.</p> <p>An incident has occurred resulting in serious injuries to a child.</p>	<p>Stop using the product immediately and keep out of reach of children.</p> <p>Destroy and dispose of the product.</p> <p>Consumers will receive a full refund from Temu on behalf of the trader Sunshine Towels.</p> <p>For more information contact Temu Support Centre at: https://www temu.com/support-center.html</p>
2024/20348	Australia	<p>A 3 pack of Toddler Silicone Spoons with an animal design at the top branded as Melii Luxe.</p>		<p>Risk of Serious Injury or Death to Children</p> <p>The spoons may break apart while in use.</p> <p>There is a risk of serious injury or death to children from choking if the spoons break while in use.</p> <p>4 incidents have occurred overseas with no injuries reported.</p>	<p>Stop using the spoons immediately and dispose of them safely.</p> <p>Contact Melii Baby via email for a replacement set of spoons. Proof of disposal will be required.</p> <p>Contact: Email: care@meliibabay.com</p>

2024/20353	Australia	<p>Canyon Speedmax CF triathlon bikes.</p> <p>Affected models:</p> <p>R073 R41</p> <p>Model years: 2016 – 2024.</p>		<p>Risk of Injury from a Fall</p> <p>The stem and handlebar may crack, leading to breaking or detachment. This may occur after impacts such as striking a pothole or kerb.</p> <p>There is a risk of injury from a fall if the stem and handlebar break or detach while the bike is being ridden.</p>	<p>Stop using the bicycle immediately.</p> <p>Check Canyon’s website to arrange for a free inspection and, if necessary, repair by a professional bike mechanic.</p> <p>Contact:</p> <p>Canyon Bicycles GmbH Phone: 1800 959 071 (between 9:00 am – 5:00 pm (AEDT) Monday – Friday) or visit Canyon’s website.</p>
2024/20357	Australia	<p>Toy playhouse set, contains Kuromi themed characters and building blocks to assemble the house.</p> <p>The product contains 3 x LR44 batteries.</p>		<p>Risk of Choking or Serious Injury</p> <p>The affected product does not comply with the mandatory standards for products containing button/coin batteries.</p> <p>The button/coin batteries are not adequately secured and are accessible to young children.</p> <p>The product does not include the required warning information.</p> <p>There is a risk of choking or serious injury if young children gain access to the button/coin batteries and swallow or place them inside their body.</p>	<p>Stop using this product immediately and keep the batteries out of reach of children.</p> <p>Return product to the place of purchase for a full refund.</p> <p>Contact</p> <p>David Michael Trading Company Pty Ltd Call: 03 9553 6350 (between 9:00 am to 5:00 pm, Monday – Friday)</p>

2024/20362	Australia	<p>Foldable swimming pool for dogs in various sizes.</p> <p>In blue:</p> <p>80x20cm (SKU:170825)</p> <p>120x30cm (SKU:170826)</p> <p>160x30cm (SKU:170827)</p> <p>200x30cm (SKU:92602)</p> <p>300x40cm (SKU:92603)</p> <p>In red:</p> <p>80x20cm (SKU:170822)</p> <p>120x30cm (SKU:170823)</p> <p>160x30cm (SKU:170824)</p> <p>200x30cm (SKU:92600)</p> <p>300x40cm (SKU:92601)</p>		<p>Missing Warnings</p> <p>The products do not comply with the mandatory standard for portable swimming pools. The products do not have the required warning signs and messages.</p> <p>Risk of drowning and death if a child enters the pool unsupervised.</p>	<p>Stop using the pool immediately and contact HB Commerce Pty Ltd to arrange to return the pool for a full refund.</p> <p>For more information or to arrange the refund, consumers can:</p> <p>Contact:</p> <p>HB Commerce Pty Ltd Call toll free: 02 7908 3316</p> <p>Email: recall@vidaxl.com.au</p> <p>Visit: www.ivdaxl.com.au/product-recalls.html</p>
------------	-----------	--	---	--	--

2024/20363	Australia	Electric long tail cargo bike.		<p>Risk of Serious Injury or Accident</p> <p>The affected kickstand mounting plate welds may be faulty on some bicycles and the kickstand may fail if it overloaded.</p> <p>Consumers may not be aware of the risks associated with the kickstand use or carrying a passenger on the rear section of the bicycle.</p> <p>Risk of serious injury or accident if a passenger on the rear seat section of the bicycle comes into contact with the bicycle's moving parts.</p> <p>Risk of injury and property damage if the kickstand fails while in use.</p>	<p>Stop using affected bicycles and contact 99 Bikes to arrange for a frame inspection of your bicycle.</p> <p>99 Bikes will repair and attach warning labels to affected bicycles. Some bikes may require replacement of the entire frame.</p> <p>Contact:</p> <p>99 Bikes Pty Ltd Call: 1800 990 523 (7:30 AM to 4:00 PM Monday – Friday)</p> <p>Email: help@99bikes.com.au</p>
------------	-----------	---------------------------------------	---	--	---

Australian Product Safety System


The Australian product safety system is set up to maximize the safety of goods through the cooperation of consumers, businesses and agencies. This policy sets out the principles adopted by the Australian Competition and Consumer Commission (ACCC) for prioritizing and addressing product safety risks.

Under the Australian Consumer Law, a responsible Minister can order a compulsory recall when there are hazards on the products. A voluntary recall could be conducted to remove the product from the marketplace when the suppliers become aware of unsafe or defective products.

The ACCC administers a national recalls system for recalls of specific and general consumer products, and publishes all product recalls on the website <https://www.productsafety.gov.au/recalls>.

Recall Summary – Japan’s Toys / Children’s Products

CPSC Recall List (Nov 2024)

Date	Notifying Country	Product	Product Photo	Hazard / Risk	Remedy
2024年11月7日 7 November 2024	Japan	ライト付きカチューシャ (キッズ用) Lighted headband (for kids)		電池ボックスのフタがしっかり固定されず、外れた電池を誤飲するおそれがあるため。 The lid of the battery box is not firmly fixed and there is a risk of accidental ingestion of the battery cover that has come off, or of the battery itself.	回収・返金 Refunds

Japan’s Product Recall System (経済産業省リコール情報)

The METI (経済産業省 Ministry of Economy, Trade and Industry) administers a national recalls system for recalls of specific and general consumer products according to the Consumer Product Safety Act, and publishes all product recalls on the website: https://www.meti.go.jp/product_safety/recall/index.html and posting at <https://x.com/kochijiko>.

STC (Hong Kong Standards and Testing Centre) is a not-for-profit, independent testing, inspection and certification organization. With a global network of ISO/IEC 17025 accredited testing laboratories and over 60 years of experience in consumer product testing, we can meet your conformity assessment needs with highly efficient and reliable service. Our testing scope and capabilities related to toys and children's products include but are not limited to:

EU Requirements

- EN 71
- Phthalates (EC) no. 1907/2006
- Nickel Release (EC) no. 1907/2006
- Total Cadmium (EEC) no. 91/338
- Lead in Jewellery product (EC) no. 836/2012
- Azo-dye (EC) no. 1907/2006
- Bisphenol-A (2014/81/EU)
- DMF (Dimethyl fumarate) (EU) no. 2011/135
- Flame retardants TCEP, TCPP, TDCP (2014/79/EU)
- Package Waste Directive (94/62/EC)

US & Canada Requirements

- ASTM F963
- CPSIA
- California Proposition 65
- 16 CFR 1501
- ASTM F2923 (Children's jewellery)
- ASTM F2999 (Adult's jewellery)
- US Toxic in Packaging Clearinghouse (TPCH)
- CCPSA - Toys Regulations (SOR/2011-17)

Japan Requirements

- Japan Toy Safety Standard (ST)
- Japan Food Sanitation Law (JFSL)

Australia Requirements

- AS/NZS 8124
- Consumer Protection Notice No. 6 of 2010 - DEHP

FOR MORE DETAILS, PLEASE CONTACT US:

Hong Kong: hktcd@stc.group
Changzhou: czstc@stc.group
U.S.A.: usenquiry@stc.group

Guangdong: gdtcd@stc.group
Vietnam: vnstc@stc.group
Germany: grstc@stc.group

Shanghai: shtcd@stc.group
Japan: jpo@stc.group

