

Recall Summary – European Toys

EU Safety Gate Alerts (
Alert No.	Notifying Country	Product	Product Photo	Hazard / Risk	Measures Adopted
INFO/00007/25	UK	Soft toy		Chemical, Choking	Stopping of
			· (0 (0)	The product has an excessive concentration of	sales
		(Country of		bis(2-ethylhexyl) phthalate (DEHP) and dibutyl	
		Origin:		phthalate (DBP) (measured values up to 4.6%	
		Unknown)		and 15.6% by weight, respectively). These	
				phthalates may harm the health of children,	
				possibly causing damage to their reproductive	
				system. Additionally, the toy contains small parts	
				(suction cup) which can easily detach. A small	
				child may put them in their mouth and choke.	
				Moreover, the fibrous stuffing material of the toy	
				is easily accessible due to the weakness of	
				certain seams. A small child may put the filling	
				material in their mouth and choke. The product	
				does not comply with the requirements of the Toy	
				Safety Directive nor the REACH Regulation.	
OR/00011/25	Denmark	Toy gun		Damage to Sight, Injuries	Withdrawal of
				The gel beads can be put into a child's mouth	the product
		(Country of	- AGENIKEY	and swallowed. As the beads expand, they can	from the
		Origin:		cause fatal occlusion of the respiratory track or	market
		United		intestinal blockage. In addition, the kinetic energy	
		States)		of the projectiles fired from the toy gun is too high	
				and can lead to eye injuries. The product does	
				not comply with the requirements of the Toy	
				Safety Directive nor with the European standard	
				EN 71.	
OR/00013/25	Croatia	Soft toy	man and a	Choking	Ban on the
				The fibrous stuffing material of the toy is easily	marketing of
		(Country of	1	accessible due to the weakness of certain	the product
		Origin:		seams. A small child may put the filling material	and any
		China)		in their mouth and choke. The product does not	accompanying
				comply with the requirements of the Toy Safety	measures
				Directive nor with the European standard EN	
				71-1.	
	i .		l		l





OR/00016/25	Estonia	Soother		Suffocation	Withdrawal of
			baboo (The teat protector does not have sufficient	the product
		(Country of		ventilation holes, leading to suffocation. The	from the
		Origin:		product does not comply with the	market
		Thailand)		requirements of the General Product Safety	
				Directive nor with the European standard	
				EN 1400.	
OR/00018/25	France	Soft toy		Choking	Withdrawal of
				The fibrous stuffing material of the toy is	the product
		(Country of	6.00	easily accessible due to the weakness of	from the
		Origin: China)	73	certain seams. A small child may put the	market
				filling material in their mouth and choke. The	
				product does not comply with the	
				requirements of the Toy Safety Directive nor	
				with the European standard EN 71-1.	
OR/00022/25	Hungary	Toy scooter	4	Injuries	Withdrawal of
				The handlebar locking mechanism of the	the product
		(Country of		scooter may release under load and the	from the
		Origin: China)	-	steering column may slip down. This can	market
				cause the child to lose balance and fall off,	
				leading to injuries. The product does not	
				comply with the requirements of the Toy	
				Safety Directive nor with the European	
				standard EN 71-1.	
SR/00001/25	Germany	Anti-stress		Choking	Removal of
		ball		The toy has small parts (eyes) that can be	this product
				easily detach. A small child may put these	listing by the
		(Country of		parts in their mouth and choke. The product	online
		Origin: China)		does not comply with the requirements of	marketplace
				the Toy Safety Directive and the relevant	
				European standard EN 71-1.	
SR/00003/25	Sweden	Electric toy		Environment	Import
			Fishing Game	The solders in the product have an	rejected at
		(Country of		excessive concentration of lead (measured	border
		Origin: China)		value up to 79% by weight). Lead poses a	
			SIL OF EUR	risk to the environment. The product does	
				not comply with the requirements of the	
				Directive on the restriction of the use of	
				certain hazardous substances in electrical	
				and electronic equipment (RoHS 2	
				Directive).	







CD/00000/05	Dolond	Diestis	1.5	Chaking	Dood!! of the
SR/00023/25	Poland	Plastic toy		Choking The toy fork may breek easily generating	Recall of the
		set		The toy fork may break easily, generating	product from
		(0)		small plastic parts. A child may put them into	end users
		(Country of		their mouth and choke. The product does not	
		Origin:		comply with the requirements of the Toy	
		China)		Safety Directive nor with the European	
		+_		standard EN 71-1.	
SR/00025/25	Poland	Toy scooter	T	Injuries, Suffocation	Withdrawal
				The steering tubes are not resistant to load	of the
		(Country of		and can easily collapse during use, causing a	product from
		Origin:		child to fall off the scooter and suffer injuries.	the market
		China)		Moreover, the scooter is not equipped with a	
				braking system, causing speed reduction	
				problems, which may lead to accidents.	
				Furthermore, the diameter of the front wheels	
				of the scooter is too small (measured value	
				up to 110 mm), which can lead to the	
				scooter's wheel getting stuck on an uneven	
				surface and the child falling, suffering injuries.	
				Additionally, the plastic of the packaging is	
				too thin. If a child plays with the packaging,	
				the plastic can cover their mouth and nose,	
				causing the child to suffocate. The product	
				does not comply with the requirements of the	
				Toy Safety Directive and the relevant	
				European standard EN 71-1.	
SR/00039/25	Czechia	Toy slime		Chemical	Withdrawal
				The migration of boron from the toy slime is	of the
		(Country of	CRYCIAL	too high (measured value up to 700 mg/kg).	product from
		Origin: China)		Ingestion or contact with an excessive	the market
				quantity of boron may harm the health of	
				children by damaging their reproductive	
				system. The product does not comply with the	
				requirements of the Toy Safety Directive nor	
				with the European standard 71-3.	
SR/00046/25	France	Soft toy		Choking	Recall of the
			THE RESERVE OF THE PARTY OF THE	Small parts (eyes and nose) can easily	product from
		(Country of		detach. A small child may put them in their	end users
		Origin: Spain)		mouth and choke. The product does not	
		3 []		comply with the requirements of the Toy	
				Safety Directive nor with the European	
				standard EN 71-1.	
				Standard EN / 1-1.	







SR/00062/25	Spain	Children's		Choking, Entrapment	Ban on the
		travel cot		The corners of the cot protrude. A small	marketing of the
				child can put their mouth around them and	product and any
		(Country of	According at	choke. Additionally, the gaps in the corners	accompanying
		Origin:		of the cot are too large, the limbs of a small	measures
		Bulgaria)		child can get trapped in them. The product	
				does not comply with the requirements of	
				the General Product Safety Directive.	
SR/00074/25	Romania	Plastic doll	CONCERNATION OF THE PERSON OF	Choking	Ban on the
		Mary de Mary	999	Small parts (artificial nails) can easily detach	marketing of the
		(Country of		from the toy. A small child may put them in	product and any
		Origin:		their mouth and choke. The product does	accompanying
		China)		not comply with the requirements of the Toy	measures
				Safety Directive nor with the European	
				standard EN 71-1.	
SR/00091/25	Sweden	Toy lie		Environment	Import rejected at
		detector	MAN	The solders in the product have an	border
			VOO.	excessive concentration of lead (measured	
		(Country of		value up to 29.57% by weight). Lead poses	
		Origin:		a risk to the environment. The product does	
		China)		not comply with the requirements of the	
				Directive on the restriction of the use of	
				certain hazardous substances in electrical	
				and electronic equipment (RoHS 2	
				Directive).	
SR/00114/25	UK	Bed rail		Entrapment, Strangulation	Import rejected at
		bumpers	SAVE SEED	The distance between the bumpers and the	border
			A Fall Burgers	cot side or the mattress is too large. A small	
		(Country of		child's limbs or head can get trapped in the	
		Origin:		gaps. Moreover, the attachment straps	
		China)		between the bumpers and mattress are too	
				long and can cause strangulation. The	
				product does not comply with the General	
				Product Safety Regulation.	





SR/00123/25	UK	Magnetic toy		Choking, Injuries	Removal of
				The product can easily break, making the small	this product
		(Country of		magnets easily accessible. A child may put them in	listing by the
		Origin: China)		their mouth and choke. Moreover, as the small	online
				magnets have a high magnetic flux (measured	marketplace
				value up to 402 kG2mm2). If a child swallows the	
				small magnets, they could attract one another	
				causing serious injuries such as intestinal blockage	
				or perforation. The product does not comply with	
				the requirements of the Toy Safety Directive nor	
				with the European standard EN 71-1.	
SR/00126/25	Spain	Squeezable		Choking	Ban on the
		toy	0.0	The product has small parts (feet and the part used	marketing of
				to hang the toy) that can easily break. A small child	the product
		(Country of		may put them in their mouth and choke. The	and any
		Origin: China)		product does not comply with the requirements of	accompanying
				the Toy Safety Directive nor with the European	measures
				standard 71-1.	
SR/00148/25	Croatia	Plastic toys		Chemical	Ban on the
				The product has an excessive concentration of	marketing of
		(Country of	COS CHIP/S4	bis(2-ethylhexyl) phthalate (DEHP) and dibutyl	the product
		Origin: China)		phthalate (DBP) (measured values up to 35% and	and any
				0.54% by weight, respectively). These phthalates	accompanying
				may harm the health of children, possibly causing	measures
				damage to their reproductive system. The product	
				does not comply with the REACH Regulation.	
SR/00181/25	Croatia	Children's		Strangulation	Ban on the
		high chair		The crotch restraint system of the high chair is	marketing of
				weak which may cause the child to slip off the seat	the product
		(Country of		if they move. This may cause the child's head to	and any
		Origin:		get stuck between the tray and the seat of the high	accompanying
		Poland)		chair and result in strangulation. The product does	measures
				not comply with the requirements of the General	
				Product Safety Directive nor with the European	
				standard EN 14988.	



SR/00188/25	Hungary	Soft toy		Choking	Destruction of
				The product has small parts (eyes) that can	the product
		(Country of		easily detach. Additionally, the fibrous	
		Origin: China)	200	stuffing material of the toy is easily	
				accessible due to the weakness of the	
				seams. A small child may put the small parts	
				or the filling material in their mouth and	
				choke. The product does not comply with the	
				requirements of the Toy Safety Directive nor	
				with the relevant European standard EN	
				71-1.	
SR/00192/25	Germany	Plastic doll		Chemical	Recall of the
				The doll's head contains an excessive	product from
		(Country of		amount of di-2-ethylhexyl phthalate (DEHP)	end users
		Origin: China)		(measured value up to 12.1% by weight).	
				This phthalate may harm the health of	
				children, causing possible damage to their	
				reproductive system. The product does not	
				comply with the REACH Regulation.	
SR/00193/25	Estonia	Plastic toy	(actylers A	Choking	Stopping of
			000000	The product has small parts	sales
		(Country of		(sound-producing elements) that can be	
		Origin: China)	J. Dona	easily detach from the toy. A small child may	
			And the second second	put them in their mouth and choke. The	
				product does not comply with the	
				requirements of the Toy Safety Directive nor	
				with the European standard EN 71-1.	
SR/00194/25	Italy	Toy slime		Chemical	Ban on the
			(Soly	The migration of boron from the toy slime is	marketing of the
		(Country of	SLIME	too high (measured value up to 2100 mg/kg).	product and any
		Origin: China)	94.0	Ingestion or contact with an excessive	accompanying
				quantity of boron may harm the health of	measures
				children by damaging their reproductive	
				system. The product does not comply with	
				the requirements of the Toy Safety Directive	
				nor with the European standard EN 71-3.	







SR/00199/25	Sweden	Plastic doll		Chemical	Withdrawal of
				The plastic material of the product has an	the product from
		(Country of		excessive concentration of bis(2-ethylhexyl)	the market
		Origin: China)		phthalate (DEHP) (measured value up to	
			A Maria	11% by weight). This phthalate may harm	
				the health by causing possible damage to	
				their reproductive system. The product does	
				not comply with the REACH Regulation.	
SR/00200/25	Germany	Plastic doll		Chemical	Removal of this
			CONTRACTOR CONTRACTOR	The charging cable plug cover and the	product listing
		(Country of	COCK NAME OF AN AN ADMITTANCE OF A STATE OF	charging cable cover have an excessive	by the online
		Origin: China)		concentration of bis(2-ethylhexyl) phthalate	marketplace
				(DEHP) and di-'isononyl' phthalate (DINP)	
				(measured values up to 11.1% and 2.9% by	
				weight, respectively). DEHP may harm the	
				health of children, causing possible damage	
				to their reproductive system. DINP may	
				harm the health of children, causing	
				possible damage to their reproductive	
				system and liver. The product does not	
				comply with the REACH Regulation.	
SR/00201/25	Italy	Plastic toy	EXECUTION	Chemical	Ban on the
				The product contains an excessive amount	marketing of the
		(Country of	To.	of di-2-ethylhexyl phthalate (DEHP)	product and any
		Origin: China)		(measured value up to 0.48% by weight).	accompanying
				This phthalate may harm the health of	measures
				children, causing possible damage to their	
				reproductive system. The product does not	
				comply with the REACH Regulation.	
SR/00205/25	Italy	Bath toy	Total to demonstrate the control of controls.	Chemical	Ban on the
				The product contains an excessive amount	marketing of the
		(Country of	1300	of di-2-ethylhexyl phthalate (DEHP)	product and any
		Origin: China)		(measured value up to 0.89% by weight).	accompanying
			-	This phthalate may harm the health of	measures
				children, causing possible damage to their	
				reproductive system. The product does not	
				comply with the REACH Regulation.	



SR/00216/25	Austria	Climbing		Strangulation	Removal of this
		frame	A	The distance between the rungs poses a risk	product listing
				of hanging or strangulation, as children could	by the online
		(Country of		fall through, get their head stuck, and be	marketplace
		Origin: China)	3000000 W	unable to free themselves. The product does	
				not comply with the requirements of the Toy	
				Safety Directive or with European standard	
				EN 71-1.	
SR/00218/25	Germany	Plastic doll	WOOTS SAME	Chemical	Removal of this
				The charging cable plug sheathing and the	product listing
		(Country of		charging cable jacket of the product have an	by the online
		Origin: China)	Clenowith	excessive concentration of bis(2-ethylhexyl)	marketplace
				phthalate (DEHP) and di-'isononyl' phthalate	
				(DINP) (measured values up to 8.6% and	
				2.1% by weight, respectively). DEHP may	
				harm the health of children, causing possible	
				damage to their reproductive system. DINP	
				may harm the health of children, causing	
				possible damage to their reproductive system	
				and liver. The product does not comply with	
				the REACH Regulation.	
SR/00220/25	Austria	Bath toy		Choking	Removal of this
				The toy has small parts (flippers of the turtle)	product listing
		(Country of	The second secon	that can easily detach. A small child may put	by the online
		Origin: China)		them in their mouth and choke. The product	marketplace
				does not comply with the requirements of the	
				Toy Safety Directive nor with the European	
				standard EN 71-1.	
SR/00235/25	Sweden	Puffer ball		Environment	Import rejected
				The solders in the product have an excessive	at border
		(Country of		concentration of lead (measured value up to	
		Origin: China)		80% by weight). Lead poses a risk to the	
				environment. The product does not comply	
				with the requirements of the Directive on the	
				restriction of the use of certain hazardous	
				substances in electrical and electronic	
				equipment (RoHS 2 Directive).	





OD/00000/05	11	Disaria Lui		Observiced	Decell of the
SR/00239/25	Hungary	Plastic doll	S STORES	Chemical	Recall of the
		(O		The toy duck has an excessive concentration	product from
		(Country of		of bis(2-ethylhexyl) phthalate (DEHP) and	end users
		Origin:	(C) a	dibutyl phthalate (DBP) (measured values up	
		China)		to 9.9% and 0.13% by weight, respectively).	
				These phthalates may harm the health of	
				children, causing possible damage to their	
				reproductive system. The product does not	
				comply with the REACH Regulation.	
SR/00243/25	Estonia	Jumping toy		Chemical	Stopping of
				The product has an excessive concentration of	sales
		(Country of		bis(2-ethylhexyl) phthalate (DEHP), dibutyl	
		Origin:	23/10/2004	phthalate (DBP) and diisobutyl phthalate	
		Unknown)		(DIBP) (measured values up to 0.23%, 1.12%	
				and 0.11% by weight, respectively). These	
				phthalates may harm the health of children,	
				possibly causing damage to their reproductive	
				system. The product does not comply with the	
				REACH Regulation.	
SR/00244/25	France	Heat		Burns	Recall of the
		massaging	Mini bouillotte de massage	The product lacks the necessary warnings and	product from
		pack	60 (6)	user instructions and can therefore overheat	end users
			Agency gover Allers of vertical and an artist of vertical and an artist of vertical and an artist of vertical and artist of vertical and artist of vertical and artist of vertical and vert	when heated in a microwave oven. This can	
		(Country of		result in any child that uses the product	
		Origin:		suffering burns. The product does not comply	
		Tunisia)		with the requirements of the General Product	
				Safety Directive.	
SR/00245/25	Italy	Toy slime	-	Chemical	Ban on the
			Land Street Contract	The migration of boron from the toy slime is too	marketing of the
		(Country of	The state of the s	high (measured value up to 780 mg/kg).	product and any
		Origin:	Charles of the last of the las	Ingestion or contact with an excessive quantity	accompanying
		China)	medi (GESS) black	of boron may harm the health of children by	measures
				damaging their reproductive system. The	
				product does not comply with the requirements	
				of the Toy Safety Directive nor with the	
				European standard EN 71-3.	
SR/00246/25	Hungary	Soft toy		Choking	Destruction of
	, , , ,			The eyes of the toy can easily detach. A small	the product
		(Country of		child may put them in their mouth and choke.	
		Origin:		The product does not comply with the	
		China)		requirements of the Toy Safety Directive nor	
		Jima)		with the European standard EN 71-1.	
	1			with the European standard EN / 1-1.	







SR/00247/25	Hungary	Soft toy	A	Choking	Import
				The eyes of the toy can easily detach. A small child	rejected at
		(Country of		may put them in their mouth and choke.	border
		Origin: China)		Furthermore, the fibrous stuffing material of the toy	
				is easily accessible when the zipper of the toy is	
				opened. A small child may put the filling material in	
				their mouth and choke. The product does not	
				comply with the requirements of the Toy Safety	
				Directive nor with the European standard EN 71-1.	
SR/00248/25	France	Toy whistle	The same of the sa	Damage to Hearing	Withdrawal of
		set	3 sittlets superior Franz.	The sound pressure level of the whistles is too high	the product
				(measured value up to 101.9 dB). This could lead	from the
		(Country of		to temporary / permanent loss of hearing, when the	market
		Origin: China)		product is used. The product does not comply with	
				the requirements of the Toy Safety Directive nor	
				with the European standard EN 71-1.	
SR/00255/25	Hungary	Soft toy	400	Choking	Import
			della	The toy has small parts (eyes) that can easily be	rejected at
		(Country of	Jack V	detached. In addition, the fibrous stuffing material	border
		Origin: China)		of the toy is easily accessible due to the weakness	
				of certain seams. A small child may put them in	
				their mouth and choke on them. The product does	
				not comply with the requirements of the Toy Safety	
				Directive nor with the relevant European standard	
				EN 71-1.	
SR/00258/25	Hungary	Soft toy		Choking	Destruction of
			A	The toy has small parts (eyes) that can be easily	the product
		(Country of		detach. A small child may put them in their mouth	
		Origin: China)		and choke. The product does not comply with the	
				requirements of the Toy Safety Directive nor with	
				the relevant European standard EN 71-1.	
SR/00260/25	Italy	Toy slime		Chemical	Ban on the
			Beel	The migration of boron from the toy slime is too	marketing of
		(Country of		high (measured value up to 980 mg/kg). Ingestion	the product
		Origin: China)		or contact with an excessive quantity of boron may	and any
				harm the health of children by damaging their	accompanying
				reproductive system. The product does not comply	measures
				with the requirements of the Toy Safety Directive	
				nor with the European standard EN 71-3.	



SR/00281/25	France	Spinning toy	-	Chemical	Removal of this
				The battery compartment can be easily	product listing
		(Country of		opened, leaving the button batteries	by the online
		Origin: China)		accessible. A child may put them in their	marketplace
				mouth and swallow them, which could cause	
				damage to the child's gastrointestinal tract.	
				The product does not comply with the	
				requirements of Toy Safety Directive nor with	
				the European standard EN 62115.	
SR/00311/25	Spain	Fancy dress		Suffocation	Withdrawal of
		mask	Halloween	The plastic of the packaging is too thin. If a	the product
				child plays with the packaging, it can cover	from the
		(Country of	(Carlo	their mouth and nose, causing the child to	market
		Origin: China)		suffocate. The product does not comply with	
				the requirements of the Toy Safety Directive.	
SR/00314/25	Czechia	Toy slime		Chemical	Withdrawal of
				The migration of boron from the toy slime is	the product
		(Country of		too high (measured value up to 1.500 mg/kg).	from the
		Origin: China)		Ingestion or contact with an excessive	market
				quantity of boron may harm the health of	
				children by damaging their reproductive	
				system. The product does not comply with	
				the requirements of the Toy Safety Directive	
				nor with the European standard EN 71-3.	
SR/00319/25	Czechia	Toy slime		Chemical	Withdrawal of
				The migration of boron from the toy slime is	the product
		(Country of	THE RESERVE	too high (measured value up to 840 mg/kg).	from the
		Origin: China)		Ingestion or contact with an excessive	market
				quantity of boron may harm the health of	
				children by damaging their reproductive	
				system. The product does not comply with	
				the requirements of the Toy Safety Directive	
				nor with the European standard EN 71-3.	
SR/00331/25	Spain	Fancy dress		Chemical	Withdrawal of
		costume		The transparent plastic fastener on the	the product
				costume has an excessive concentration of	from the
		(Country of		dibutyl phthalate (DBP) (measured value up	market
		Origin: China)		to 4.6% weight). This phthalate may harm the	
				health of children, causing possible damage	
				to their reproductive system. The product	
				does not comply with the REACH Regulation.	







SR/00359/25	Poland	Plastic toy set		Chemical	Warning
			6	The toy has an excessive concentration of	consumers of the
		(Country of		bis(2-ethylhexyl) phthalate (DEHP)	risks
		Origin: China)	MANA	(measured value up to 28.2% by weight).	
			OF SCHOOL OF S	This phthalate may harm the health of	
				children, causing possibly damage to their	
				reproductive system. The product does not	
				comply with the REACH Regulation.	
SR/00360/25	Italy	Toy slime		Chemical	Removal of this
			- 6000	The migration of boron from the toy slime is	product listing by
		(Country of	O O O O O O O O O O O O O O O O O O O	too high (measured value up to 1800 mg/kg).	the online
		Origin: China)	And the desired of the second	Ingestion or contact with an excessive	marketplace
				quantity of boron may harm the health of	
				children by damaging their reproductive	
				system. The product does not comply with	
				the requirements of the Toy Safety Directive	
				nor with European standard EN 71-3.	
SR/00376/25	France	Teething		Choking, Strangulation	Warning
		necklace	Charles Annual Market Annual M	The necklace does not open and could	consumers of the
			The second secon	therefore wind around the neck of the child,	risks
		(Country of	Descriptions of the second of	leading to strangulation. Moreover, the	
		Origin:		necklace can easily break, resulting in small	
		Lithuania)		parts (beads). A small child may put them in	
				their mouth and choke. The product does not	
				comply with the General Product Safety	
				Regulation nor with the European standard	
				EN 71-1.	
SR/00379/25	Czechia	Toy slime		Chemical	Withdrawal of
				The migration of boron from the toy slime is	the product from
		(Country of		too high (measured value up to 630 mg/kg).	the market
		Origin: China)		Ingestion or contact with an excessive	
				quantity of boron may harm the health of	
				children by damaging their reproductive	
				system. The product does not comply with	
				the requirements of the Toy Safety Directive	
				nor with the European standard EN 71-3.	





SR/00387/25	Hungary	Soft toy		Chemical, Choking	Import rejected
				The plastic material of the suction cup	at border
		(Country of		contains an excessive concentration of	
		Origin: China)		bis(2-ethylhexyl) phthalate (DEHP)	
			if the state of th	(measured value up to 44% by weight). This	
				phthalate may harm the health of children,	
				possibly causing damage to their	
				reproductive system. Moreover, the fibrous	
				stuffing material of the toy is easily accessible	
				due to the weakness of certain seams. A	
				small child may put the filling material in their	
				mouth and choke. The product does not	
				comply with the REACH Regulation nor with	
				the requirements of the Toy Safety Directive	
				and the European standard EN 71-1.	
SR/00388/25	Hungary	Soft toy	8	Choking	Import rejected
				The toy has small parts (beads) which can	at border
		(Country of	6 4 6	easily detach. A small child may put them in	
		Origin: China)		their mouth and choke. Moreover, the fibrous	
				stuffing material of the toy is easily accessible	
				due to the weakness of certain seams. A	
				small child may put them in their mouth and	
				choke. The product does not comply with the	
				requirements of the Toy Safety Directive nor	
				with the European standard EN 71-1.	
SR/00395/25	Bulgaria	Children's		Injuries	Withdrawal of
		armchair		The armchair is not sufficiently stable and	the product from
			1 : 00	may tip over while the child is seated. This	the market
		(Country of	W. W.	can lead to falls and injuries. The product	
		Origin:		does not comply with the General Product	
		Bulgaria)		Safety Regulation.	
SR/00408/25	Poland	Plastic toy		Choking	Warning
				The toy has small parts (wheel) which may be	consumers of
		(Country of	G G	easily detached from the toy. A child may put	the risks
		Origin: China)		it into their mouth and choke. The product	
				does not comply with the requirements of the	
				Toy Safety Directive nor with the European	
				standard EN 71-1.	





SR/00416/25	Belgium	Soother		Choking	Stopping of
		holder		The beads of the soother holder do not have	sales
				the required ventilation holes. Furthermore,	
		(Country of		they can be loosened. Small children can	
		Origin:	put them in their mouth and choke. The		
		Belgium)		product does not comply with the	
				requirements of the General Product Safety	
				Directive nor with the European standards	
				EN 12586.	
SR/00438/25	Sweden	Soft toy		Environment	Withdrawal of
				The solders in the product have excessive	the product from
		(Country of		concentrations of lead and cadmium	the market
		Origin: China)		(measured values up to 84.6% and 0.46%	
				by weight, respectively). Lead poses a risk	
				to the environment. Cadmium	
				bio-accumulates and poses a risk to the	
				environment. The product does not comply	
				with the requirements of the Directive on the	
				restriction of the use of certain hazardous	
				substances in electrical and electronic	
				equipment (RoHS 2 Directive).	
SR/00440/25	France	Plastic toy		Choking	Withdrawal of
		set		The product contains a small plastic lettuce.	the product from
				A small child may put it in their mouth and	the market
		(Country of		choke. The product does not comply with	
		Origin: China)		the requirements of the Toy Safety	
				Directive, nor with the European standard	
				EN 71-1.	
SR/00459/25	Hungary	Toy scooter		Injuries	Withdrawal of
				The front wheel is too small and could get	the product from
		(Country of	SeasTer	stuck in holes in the ground. This could	the market
		Origin: China)		cause the child to lose balance and fall off,	
				leading to injuries. The product does not	
				comply with the requirements of the Toy	
				Safety Directive nor with the European	
				standard EN 71-1.	





			1	<u></u>	
SR/00460/25	Ireland	Foldable		Entrapment, Strangulation	Recall of the
		climbing		The product's gaps between the rungs are	product from end
		frame		too big. The limbs or head of a small child	users
			7	may become trapped, leading to	
		(Country of		strangulation. Moreover, the frame is not	
		Origin: China)		stable and can easily tip over causing the	
				child to fall and suffer injuries. The product	
				does not comply with the requirements of	
				the Toy Safety Directive nor with the	
				European standards EN 71-1 and EN71-8.	
SR/00462/25	Austria	Plastic	_	Chemical	Removal of this
		orgasm balls	Oca	The plastic material of the product has an	product listing by
			and and	excessive concentration of dibutyl phthalate	the online
		(Country of		(DBP) (measured value up to 11.62% by	marketplace
		Origin: China)		weight). This phthalate may harm the health	
				by causing possible damage to their	
				reproductive system. The product does not	
				comply with the REACH Regulation.	
SR/00465/25	UK	Activity play	Activity Gym & Foldable Play Mat	Choking	Import rejected at
		mat	Plaging Justis, Leave With 1979	The toy has small parts (blue plastic ring)	border
				which can easily detach. Moreover, the	
		(Country of	(107)	filling of the arch part of the toy can be easily	
		Origin: China)		accessed. A small child may put them in	
				their mouth and choke. The product does	
				not comply with the requirements of the Toy	
				Safety Directive nor with the European	
				standard EN 71.	
SR/00466/25	Sweden	Plastic toy		Chemical	Withdrawal of the
				The plastic material of the product has an	product from the
		(Country of	(B) (B) (B)	excessive concentration of di-'isononyl'	market
		Origin: China)		phthalate (DINP) (measured value up to	
				36.95% by weight), whereas the plastic	
				packaging has an excessive concentration	
				of bis(2-ethylhexyl) phthalate (DEHP)	
				(measured value up to 19.54% by weight).	
				DINP and DEHP may harm the health of	
				children, causing possible damage to their	
				reproductive system, while DINP can also	
				cause possible damage to their liver. The	
				product does not comply with the REACH	
1		1	I	Regulation.	

warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.





15



				T	
SR/00468/25	Sweden	Plastic doll	_ 🙈	Chemical	Withdrawal of
				The plastic material of the product has an	the product
		(Country of		excessive concentration of bis(2-ethylhexyl)	from the market
		Origin: China)		phthalate (DEHP) (measured value up to	
				13.68% by weight). This phthalate may harm	
				the health of children, causing possible	
				damage to their reproductive system. The	
				product does not comply with the REACH	
				Regulation.	
SR/00469/25	Lithuania	Toy soother	Cheeky Chompers	Choking	Withdrawal of
		holder	Hand general State of the Control of	The soother holder has small parts. Small	the product
				children may put them in their mouth and	from the market
		(Country of	in a nection	choke. The product does not comply with the	
		Origin: China)		requirements of the Toy Safety Directive nor	
				with the European standard EN 71-1.	
SR/00480/25	Lithuania	Soft toy		Choking	Withdrawal of
				The toy has small parts (nose and eyes) which	the product
		(Country of		can be easily detached. Small children may put	from the market
		Origin:		them in their mouth and choke. The product	
		Unknown)	The state of the s	does not comply with the requirements of the	
				Toy Safety Directive nor with the European	
				standard EN 71-1.	
SR/03773/24	Sweden	Electric toy		Environment	Import rejected
			CENTER OF THE PARTY OF THE PART	The solders in the product have an excessive	at border
		(Country of	323	concentration of lead (measured value up to	
		Origin: China)	program rate truck totals	61% by weight). Lead poses a risk to the	
				environment. The product does not comply with	
				the requirements of the Directive on the	
				restriction of the use of certain hazardous	
				substances in electrical and electronic	
				equipment (RoHS 2 Directive).	
SR/03781/24	Italy	Toy slime		Chemical	Ban on the
				The migration of boron from the toy slime is too	marketing of
		(Country of	1/3	high (measured value up to 1600 mg/kg).	the product and
		Origin: China)		Ingestion or contact with an excessive quantity	any
				of boron may harm the health of children by	accompanying
				damaging their reproductive system. The	measures
				product does not comply with the requirements	
				of the Toy Safety Directive nor with the	
				European standard 71-3.	





SR/03782/24	Lithuania	Toy gun set	THE STATE OF THE S	Choking	Withdrawal of
				The toy gun set has small parts. Small	the product from
		(Country of		children may put them in their mouth and	the market
		Origin: China)	HOLIS	choke. The product does not comply with the	
				requirements of the Toy Safety Directive nor	
				with the European standard EN 71-1.	
SR/03808/24	Slovenia	Puzzle		Choking	Recall of the
				The product base can easily break, resulting	product from
		(Country of		in small parts. A small child may put them in	end users
		Origin:		their mouth and choke. The product does not	
		Unknown)	Bankstone per lagra de francisco de destado como de accionidade de como de la	comply with the requirements of the Toy	
				Safety Directive nor with the European	
				standard EN 71-1.	
SR/03812/24	Slovenia	Toy train		Choking	Withdrawal of
				The product can easily break, resulting in	the product from
		(Country of		small parts (train roof). A small child may put	the market
		Origin: China)		them in their mouth and choke. The product	
				does not comply with the requirements of the	
				Toy Safety Directive nor with the European	
				standard EN 71-1.	
SR/03827/24	Slovenia	Doll		Chemical	Destruction of
				The plastic material of the doll contains an	the product
		(Country of		excessive amount of bis(2-ethylhexyl)	
		Origin: China)	Mode	phthalate (DEHP) (measured value up to	
				27% by weight). This phthalate may harm	
				the health of children by causing possible	
				damage to their reproductive system. The	
				product does not comply with the REACH	
				Regulation.	
SR/03828/24	Slovenia	Doll	(SOL	Chemical	Recall of the
				The plastic material of the doll contains an	product from
		(Country of		excessive amount of bis(2-ethylhexyl)	end users
		Origin: China)		phthalate (DEHP) (measured value up to	
				22% by weight). This phthalate may harm	
				the health of children by causing possible	
				damage to their reproductive system. The	
				product does not comply with the	
				requirements of the Toy Safety Directive and	
				REACH Regulation.	







Issue no.: 03/25/TCD

SR/03830/24	Czechia	Plastic doll		Chemical	Destruction of
				The product contains an excessive amount	the product
		(Country of	逐渐缓	of di-2-ethylhexyl phthalate (DEHP)	
		Origin: China)		(measured value up to 24% by weight) and	
				Dibutyl phthalate (DBP) (measured value up	
				to 0.22% by weight). These phthalates may	
				harm the health of children, causing possible	
				damage to their reproductive system. The	
				product does not comply with the REACH	
				Regulation.	

Safety Gate: the EU rapid alert system for dangerous non-food products

"Safety Gate", the EU rapid alert system (formerly known as "RAPEX"), enables the rapid exchange of information between 31 European countries and the European Commission on non-food dangerous products found on the market posing a risk to the health and safety of consumers.

weekly overview of the alerts on those products is published in English for https://ec.europa.eu/safety-gate-alerts/screen/webReport#weeklyReports. The measures taken in the notifying country in order to restrict such products' marketing or use can be ordered by national authorities ("compulsory measures") or be taken directly by producers and distributors ("voluntary measures").

The official contact points of the Member and EFTA-EEA States provide the information published in these weekly overviews. Under the terms of Annex II.10 of the General Product Safety Directive (2001/95/EC) responsibility for the information provided lies with the notifying party. The Commission does not take any responsibility for the accuracy of the information provided.







Recall Summary – US Toys / Children's Products

CPSC Recall List (Jan 2025)

				0/3	C Recall List (Jan 2025)
Recall No.	Notifying Country	Product	Product Photo	Hazard / Risk	Remedy
25-082	USA	Yaomiao	\ /	Risk of Lead and Cadmium	Consumers should immediately
		Children's	1	Poisoning	stop using the recalled jewelry
		Jewelry Sets	1	Yaomiao Children's Jewelry Sets	sets, take them away from
			COLLAN	Recalled Due to Risk of Lead and	children and contact LordRoads
		(Country of		Cadmium Poisoning; Violations of	for a full refund. Consumers will
		Origin: China)		the Federal Lead Content Ban and	be asked to dispose of the
				Federal Hazardous Substances	recalled jewelry sets and send a
				Act; Sold Exclusively on Amazon	photo of the disposed sets
				by LordRoads	to simlordroadple@163.com.
					LordRoads and Amazon are
				The recalled jewelry sets contain	contacting all known purchasers
				levels of lead that exceed the	directly.
				federal lead content ban and levels	
				of cadmium that are prohibited in	
				children's products by the Federal	
				Hazardous Substances Act. Lead	
				and cadmium are toxic if ingested	
				by young children and can cause	
				adverse health effects.	
25-094	USA	HallyBee		Tip-Over and Entrapment	Consumers should immediately
		Farmhouse		Hazards	stop using the recalled
		5-Drawer		HallyBee Farmhouse Dressers	HallyBee Farmhouse 5-Drawer
		Dressers		Recalled Due to Tip-Over and	Dressers, if they are not
				Entrapment Hazards; Violation of	properly anchored to a wall, and
		(Country of		Federal Regulation for Clothing	place them in an area that
		Origin: China)		Storage Units; Sold Exclusively on	children cannot access. With a
				Amazon.com by YKHallyBee	permanent marker, write the
					word "recalled" on the top and
				The recalled dressers are unstable	all sides of the dresser. Contact
				if they are not anchored to the wall,	YKHallyBee for instructions to
				posing serious tip-over and	receive a full refund and submit
				entrapment hazards that can result	a photo of disposing of the
				in injuries or death to children. The	product to the firm at
				dressers do not comply with the	yueke113@163.com.
				performance requirements of the	
				STURDY Act.	







25-096	USA	Mini Bella Bunny		Burn Hazard	Consumers should
		Pajamas, Mini	17 436	Ivy City Recalls Children's	immediately take the
		Camille Pajamas	rent & street	Pajamas Due to Burn Hazard;	recalled pajamas away from
		and Mini Petra	1	Violation of Federal	children, stop using them,
		Nightgown		Flammability Regulations; Sold	and contact Ivy City for a full
				Exclusively by Ivy City	refund. Consumers should
		(Country of Origin:			destroy the garments by
		China)		The recalled children's pajamas	cutting them in half and
				violate the flammability	disposing of them.
				standards for children's	Consumers should email Ivy
				sleepwear, posing a risk of burn	City a photo of the
				injuries to children.	destroyed garment at
					hello@ivycityco.com to
					receive a refund. Ivy City is
					contacting all known
					purchasers directly.
25-102	USA	USA Children's Holiday		Burn Hazard	Consumers should
		Pajama Sets		Duluth Trading Company	immediately take the
				Recalls Children's Holiday	recalled pajamas away from
		(Country of Origin:		Pajama Sets Due to Burn	children, stop using them,
		Cambodia)		Hazard; Violation of Federal	and contact Duluth Trading
				Flammability Regulations for	for a full refund of the full
				Children's Sleepwear; Sold	price in the original form of
				Exclusively by Duluth Trading	payment or as store credit.
				Company.	Consumers will be asked to
					destroy the garments by
				The recalled children's	cutting the top and bottom in
				pajamas violate the	half and disposing of them.
				flammability regulations for	Consumers must send a
				children's sleepwear, posing a	photo of the destroyed
				risk of burn injuries to children.	garment to
					ProductRecallK0040@dulut
					htrading.com. Duluth
					Trading is contacting all
					known purchasers directly.





25-110	USA	Cabinet Health 4 oz.		Risk of Child Poisoning	Consumers should
		Refillable Medicine	(BAST)	Cabinet Health Recalls 4 oz.	immediately secure the
		Bottles	Relation	Refillable Medicine Bottles	recalled bottles out of the
			5	Due to Failure to Retain	sight and reach of children
		(Country of Origin:		Child-Resistance; Risk of	and contact Cabinet Health
		China)		Child Poisoning	for a free replacement lid.
					Consumers will be asked to
				The plastic lid's closure can	submit a photo
				degrade after repeated	demonstrating the
				openings, causing the lid's	destruction of the recalled lid.
				child-resistance to diminish,	Cabinet Health and Amazon
				posing a risk of poisoning, if	are contacting all known
				the contents are swallowed	purchasers directly. This
				by young children.	recall does not affect the
					medication within the bottles.
25-113	USA	Cozchique, Tebbis		Burn Hazard	Consumers should
		and Beeziac Girls	25	Cozchique Tebbis, and	immediately take the recalled
		Pajamas	land the second	Beeziac Girls Pajamas	pajamas away from children,
			189	Recalled Due to Burn	stop using them, and contact
		(Country of Origin:	6 6 6	Hazard; Violation of Federal	Tupop to receive a full
		China)		Flammability Regulations;	refund. Consumers should
				Sold Exclusively on Amazon	destroy the garments by
				by Tupop	cutting the top and bottom in
					half and dispose of them.
				The recalled pajama sets	Consumers should send the
				violate federal flammability	recalling firm a photo of the
				regulations for children's	destroyed garments by email
				sleepwear, posing a risk of	at bzzservice@hotmail.com
				burn injuries to children.	to receive a full refund.
					Tupop and Amazon are
					contacting all known
					purchasers directly.





25-115	USA	Pearhead Infant		Choking Hazard	Consumers should stop
		Learning Toy Sets	CARDON CO	Pearhead Recalls Infant	using the egg shaker
			ESA	Learning Toy Sets Due to	immediately and contact
		(Country of Origin:	Sparret Cartino	Choking Hazard; Violation of	Pearhead for information on
		China)		Federal Regulations for	how to return the product to
				Rattles	obtain a free replacement
					and refund. Pearhead is
				Due to its size and shape, the	contacting all known
				wooden egg-shaped rattle in	purchasers directly.
				the recalled learning sets can	
				get lodged in a child's throat,	
				posing a choking hazard.	
				This violates the federal	
				regulations for infant rattles.	

^{*} Source: www.recalls.gov

CPSC

The United States Consumer Product Safety Commission (CPSC) is an independent agency of the United States Government. To provide better service in alerting the American people to unsafe, hazardous or defective products, a "one stop shop" for U.S. Government recalls, http://www.recalls.gov, has been created. Members of the public may report unsafe products to CPSC by using the platform.

The recall list is divided into seven categories: Consumer Products, Motor Vehicles, Boats, Food, Medicine, Cosmetics and Environmental Products. Generally, the recall is conducted voluntarily by the company under CPSC's Fast Track Recall program. Fast Track recalls are initiated by firms who are committed to working with CPSC to quickly announce the recall and remedy to protect consumers.



Recall Summary – Australia Toys / Children's Products

ACCC Recall List (Jan 2025)

	Notifying	Product /	Product	ACC	C Recall List (Jan 2025)
PRA No.	Notifying Country	Description	Photo	Hazard / Risk	Remedy
2024/20410	Australia	Pop up beach		Risk of Serious Injury,	Stop using the product
		tent with small		Drowning	immediately.
		built in pool:		The products do not comply	
				with the mandatory standard	Contact TEMU seller
		Includes ground		for portable swimming pools.	YIQISHENG OUTDOOR to
		spikes and		The products do not have	request a refund.
		storage bag		the required warning signs.	
					Contact:
		Sold on TEMU		Risk of serious injury or	
				death from drowning if	YIQISHENG OUTDOOR
				consumers are not aware of	
				these hazards.	Email: 1113658985@qq.com
2025/20413	Australia	LCD writing	00	Risk of Choking	Stop using the product
		tablets		The product does not	immediately and dispose of it.
				comply with the mandatory	
		Prodigy Kids		standard for products	Contact Prodigy Kids Shop for
		Shop		containing button/coin	a full refund.
				batteries. The batteries are	
				not adequately secured and	Contact:
				are accessible to young	
				children. The product has	Prodigy Kids Shop
				not been tested and does	
				not include the required	Email:
				warning information.	info@prodigykidsshop.com.au
				Risk of choking, severe	
				internal burn injuries or	
				death to young children if	
				they gain access to the	
				button/coin batteries and	
				swallow them or place them	
				inside their body. Severe or	
				fatal injuries can happen in 2	
				hours or less.	







2025/20420	Australia	Christmas-themed		Risk of Choking	Consumers should stop
		light-up novelty	8	The products do not comply	using the product
		rings containing a	e "	with the mandatory	immediately and place it
		button battery, in		information standard for	out of reach of children.
		four styles:		products containing	
				button/coin batteries.	Consumers should
		Santa			contact the store of
		Snowman		The products do not include	purchase to arrange for a
		Reindeer		the required warning	full refund.
		Tree		information.	
					Contact:
				There is a risk of choking or	Ask our staff to find out
				serious injury if young children	more about the recall:
				gain access to the button/coin	
				batteries and swallow or place	Email:
				them inside their body.	sales@igDesignGroup.co
					<u>m.au</u>
				Consumers may be unaware	
				that the product contains a	Call: 03 9541 0500
				button/coin battery.	8:30am to 4:30pm
					Monday to Friday
2025/20422	Australia	10-inch drawing		Risk of Choking	Stop using the product
		board for making	34.0	The product may not comply	immediately and place it
		notes and drawings		with the mandatory safety	out of reach of children.
		using the included		standard for products	
		stylus pen.		containing button/coin	Return the product to the
				batteries.	place of purchase for a full
		Colours:			refund.
		Pink, Blue		The button/coin batteries may	
				not be adequately secured	Contact:
		Model:		and may be accessible to	
		RX-YST-DB24		young children.	IFI Australia Pty Ltd
				There is a risk of choking,	Email:
				severe internal burn injuries or	support@ifisource.com
				death to young children if they	Call. 4200 500 500
				gain access to the button/coin	Call: 1300 522 523,
				batteries and swallow or place	9:00 am - 5:00 pm
				them inside their body.	(AEST), Monday to Friday
				Severe or fatal injuries can	
				happen in 2 hours or less.	





24



2025/20423	Australia	Wooden activity		Risk of Serious Injury or Death	Stop using the product
		teapot with		The affected products may not	immediately and place
		removeable lid	V (4)	comply with the mandatory	out of reach of children.
		and 6 built-in		standard for toys for children up	
		activities:		to and including 36 months of	Check the bottom of the
				age.	teapot to see if the teapot
		Shape sorter with			is from the affected batch,
		3 separate		There is a risk that the ball on top	and contact Play Imports
		shapes		of the teapot lid and/or the	to arrange to return the
				rotating mirror may become	product and receive a full
		Abacus with 3		detached from the teapot,	refund. Play Imports will
		beads		creating small parts.	also pay costs associated
					with returning the
		Cog wheels to		Risk of serious injury or death by	product.
		turn		choking if a child places the small	
				parts inside their mouth.	Contact:
		Xylophone			
					Play Imports
		Separate mallet			
					Call: 02 6494 3323
		Rotating faux			
		mirror			
		Shape slider			
		Affected batches:			
		0427/23			
		0152/23			

Australian Product Safety System

The Australian product safety system is set up to maximize the safety of goods through the cooperation of consumers, businesses and agencies. This policy sets out the principles adopted by the Australian Competition and Consumer Commission (ACCC) for prioritizing and addressing product safety risks.

Under the Australian Consumer Law, a responsible Minister can order a compulsory recall when there are hazards on the products. A voluntary recall could be conducted to remove the product from the marketplace when the suppliers become aware of unsafe or defective products.

The ACCC administers a national recalls system for recalls of specific and general consumer products, and publishes all product recalls on the website https://www.productsafety.gov.au/recalls.





25



STC (Hong Kong Standards and Testing Centre) is a not-for-profit, independent testing, inspection and certification organization. With a global network of ISO/IEC 17025 accredited testing laboratories and over 60 years of experience in consumer product testing, we can meet your conformity assessment needs with highly efficient and reliable service. Our testing scope and capabilities related to toys and children's products include but are not limited to:

EU Requirements

- EN 71
- Phthalates (EC) no. 1907/2006
- Nickel Release (EC) no. 1907/2006
- Total Cadmium (EEC) no. 91/338
- Lead in Jewellery product (EC) no. 836/2012
- Azo-dye (EC) no. 1907/2006
- Bisphenol-A (2014/81/EU)
- DMF (Dimethyl fumarate) (EU) no. 2011/135
- Flame retardants TCEP, TCPP, TDCP (2014/79/EU)
- Package Waste Directive (94/62/EC)

US & Canada Requirements

- ASTM F963
- **CPSIA**
- California Proposition 65
- 16 CFR 1501
- ASTM F2923 (Children's jewellery)
- ASTM F2999 (Adult's jewellery)
- US Toxic in Packaging Clearinghouse (TPCH)
- CCPSA Toys Regulations (SOR/2011-17)

Japan Requirements

- Japan Toy Safety Standard (ST)
- Japan Food Sanitation Law (JFSL)

Australia Requirements

- AS/NZS 8124
- Consumer Protection Notice No. 6 of 2010 DEHP

FOR MORE DETAILS, PLEASE CONTACT US:

Hong Kong: hktcd@stc.group Guangdong: gdtcd@stc.group Shanghai: shtcd@stc.group Changzhou: czstc@stc.group Vietnam: vnstc@stc.group Japan: ipo@stc.group

U.S.A.: usenquiry@stc.group Germanv: arstc@stc.aroup



