












## Recall Summary – European Toys

### EU Safety Gate Alerts (Apr 2025)

Alert No.	Notifying Country	Product	Product Photo	Hazard / Risk	Measures Adopted
OR/00046/25	France	<b>Plush toy</b>  (Country of Origin: <b>Philippines</b> )		<b>Choking</b> The fibrous stuffing material of the toy is easily accessible due to the weakness of the seams on the front legs. A small child may put the filling material in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Recall of the product from end users
OR/00049/25	Spain	<b>Soft toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The fibrous stuffing material of the toy is easily accessible due to the weakness of certain seams. A small child may put the filling material in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Ban on the marketing of the product and any accompanying measures
OR/00051/25	Slovakia	<b>Children's bicycle</b>  (Country of Origin: <b>Spain</b> )		<b>Injuries</b> The braking force of the bicycle's brakes is inadequate. The user could therefore have an accident and suffer injuries. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Warning consumers of the risks
OR/00057/25	Belgium	<b>Magnetic toy</b>  (Country of Origin: <b>Poland</b> )		<b>Injuries</b> The toy contains small magnets with a high magnetic flux (measured value up to 107.9 kG <sup>2</sup> mm <sup>2</sup> ). If a child swallows the small magnets, they could attract one another causing intestinal blockage or perforation. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market





SR/01153/25	Poland	<b>Plastic toy</b>  (Country of Origin: <b>China</b> )		<b>Damage to sight, Injuries</b> The toy can fire an unfolded projectile which has protruding parts. A projectile can hit a child's eye causing injuries and damage to sight. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Warning consumers of the risks
SR/01169/25	Poland	<b>Music toy set</b>  (Country of Origin: <b>China</b> )		<b>Choking, Cuts, Strangulation</b> The various instruments can break easily and release small parts. A child may put small plastic parts into their mouth and choke on them. Additionally, there are sharp edges at the toy's surface which may cause cuts. Furthermore, one of the instruments (toy drum) has a long cord that should be placed around the neck; this cord can become trapped during various activities of a child, leading to strangulation. The product does not comply with the requirements of the Toy Safety Directive and the European standard EN 71-1.	Warning consumers of the risks
SR/01174/25	Poland	<b>Toy scooter</b>  (Country of Origin: <b>China</b> )		<b>Injuries</b> The diameter of the wheels of the scooter is too small, which can lead the scooter's wheel to become stuck on an uneven surface and the child falling, suffering injuries. Moreover, the steering tubes are not resistant to load and may collapse during a ride. A child may fall off the scooter and suffer injuries. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Warning consumers of the risks
SR/01208/25	France	<b>Baby pillow</b>  (Country of Origin: <b>China</b> )		<b>Suffocation</b> The pillow is not firm enough, leading to a risk of suffocation for the baby if their face is turned towards or leaning against the cushion for a long period. The product does not comply with the General Product Safety Regulation nor with the European standards EN 16890 and EN 1466.	Recall of the product from end users

SR/01220/25	Poland	<b>Toy rattle set</b>  (Country of Origin: <b>China</b> )		<b>Choking, Suffocation</b> The rattles can break easily and release small parts. A child may put small plastic parts into their mouth and choke on them. Moreover, the green rattle has protruding parts. A child could put it into the mouth, which could block the airways and cause choking. In addition, the plastic of the packaging is too thin. If a child plays with it, the plastic can cover their mouth and nose, causing the child to suffocate. The product does not comply with the requirements of the Toy Safety Directive nor with the relevant European standard EN 71-1.	Withdrawal of the product from the market
SR/01221/25	Poland	<b>Musical toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> They toy has small parts (the metal pegs securing the cymbals) which may easily detach. A child may put them into their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market
SR/01222/25	UK	<b>Soft toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The toy has small parts (the eyes and keychain) which may easily detach. A child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive.	Import rejected at border
SR/01225/25	UK	<b>Soft toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The product has small parts (eyes, nose and key chain) which may easily detach. A child may put them into their mouth and choke. This product does not comply with the requirements of the Toy Safety Directive.	Import rejected at border
SR/01229/25	Italy	<b>Soap bubble toy</b>  (Country of Origin: <b>China</b> )		<b>Microbiological</b> The soap-bubble solution of the toy is microbiologically contaminated (measured value up to 72.000 CFU/ml). There is a risk of contracting infection as the solution may come in contact with the mouth, hands and eyes. The product does not comply with the requirements of the Toy Safety Directive.	Ban on the marketing of the product and any accompanying measures

SR/01230/25	Poland	<b>Jumping rope</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The toy contains an excessive amount of bis (2-ethylhexyl) phthalate (DEHP) (measured value up to 28.1% by weight). DEHP may harm the health of children, possibly by causing damage to the reproductive system. The product does not comply with the REACH Regulation.	Warning consumers of the risks
SR/01235/25	France	<b>Toy chicken</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The toy has small parts (wings) that can easily detach. A small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market
SR/01237/25	Poland	<b>Magnetic toy set</b>  (Country of Origin: <b>China</b> )		<b>Injuries</b> The toy contains small magnets with a high magnetic flux. If a child swallows the small magnets, they could attract one another causing intestinal blockage or perforation. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market
SR/01241/25	France	<b>Fancy-dress costume</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The migration of chromium VI from the toy is too high (measured value up to 0.57 mg/kg). Chromium (VI) is sensitising, can trigger allergic reactions and can cause cancer. Moreover, the migration of lead from the surface material is too high (measured value up to 116 mg/kg). Lead is harmful to human health, accumulates in the body, and can cause developmental neurotoxicity and may affect breast-fed children. The product does not comply with the requirements of the Toy Safety Directive nor with the REACH Regulation.	Withdrawal of the product from the market

SR/01245/25	France	<b>Flying ball toy</b>  (Country of Origin: <b>China</b> )		<b>Chemical, Choking</b> The battery compartment can be easily opened, leaving the button batteries accessible. A child may put them in their mouth and swallow them, which could cause damage to the child's gastrointestinal tract and/or choking. The product does not comply with the requirements of the Toy Safety Directive nor with European standard EN 62115.	Recall of the product from end users
SR/01250/25	France	<b>Children's rake</b>  (Country of Origin: <b>China</b> )		<b>Injuries</b> The toy has unprotected protruding parts (teeth of the rake). A child could be injured by falling onto the teeth of the metal rake. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market
SR/01258/25	France	<b>Key rings</b>  (Country of Origin: <b>Philippines</b> )		<b>Choking</b> The small parts of the product may easily become detached (key ring, left leg and right leg). As a result, a small child could put them in their mouth and choke on them. The product does not comply with the requirements of the Toy Safety Directive nor with European standard EN 71-1.	Recall of the product from end users
SR/01263/25	Germany	<b>Balloons</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The rubber of the balloons releases nitrosamines (measured total value up to 1.61 mg/kg). Nitrosamines may cause cancer through ingestion or dermal exposure. A child could be exposed to them when touching or putting the product in the mouth. Moreover, the product releases an excessive amount of nitrosatable substances (measured total value up to 9.13 mg/kg), which generate nitrosamines. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-12.	Recall of the product from end users






SR/01271/25	Finland	<b>Soft toy</b>  (Country of Origin: <b>China</b> )		<b>Choking, Strangulation, Suffocation</b> The plastic of the packaging is too thin. If a child plays with it, the plastic can cover their mouth and nose, causing the child to suffocate. Furthermore, the toy's electrical wires are too long and can become trapped during various activities of a child, leading to strangulation. Furthermore, the fibrous stuffing material of the toy is easily accessible due to the weakness of certain seams. A small child may put the filling material in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Recall of the product from end users
SR/01272/25	Cyprus	<b>Soother holder</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The beads of the soother holder do not have the required ventilation holes and can be loosened. Furthermore, the garment fastener of the soother holder is protruding. A small child can put those elements in the mouth and choke. The product does not comply with the General Product Safety Regulation nor with the European standards EN 12586 and 71-1.	Withdrawal of the product from the market
SR/01284/25	Cyprus	<b>Soother holder</b>  (Country of Origin: <b>China</b> )		<b>Strangulation</b> The cord of the soother holder is too long. It can become trapped during various activities of a child, leading to strangulation. The product does not comply with the General Product Safety Regulation nor with the European standard EN 12586.	Withdrawal of the product from the market
SR/01287/25	France	<b>Puzzle mat</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The toy has small parts (pieces of foam on the edges of tiles) which can easily detach. Small children may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Removal of this product listing by the online marketplace

SR/01298/25	Italy	<b>Soap bubble toy</b>  (Country of Origin: <b>China</b> )		<b>Microbiological</b> The soap-bubble solution of the toy is microbiologically contaminated (measured value up to 290,000 CFU/ml). There is a risk of contracting infection as the solution may come in contact with the mouth, hands and eyes. The product does not comply with the requirements of the Toy Safety Directive.	Ban on the marketing of the product and any accompanying measures
SR/01301/25	France	<b>Toy telephone</b>  (Country of Origin: <b>China</b> )		<b>Chemical, Choking</b> The product has small parts which may easily detach (left rear wheel). Moreover, the battery compartment can be easily opened, leaving the button batteries accessible. A child may put them in the mouth and swallow them, which could cause damage to the child's gastrointestinal tract and/or choking. The product does not comply with the requirements of the Toy Safety Directive nor with European standard EN 62115.	Removal of this product listing by the online marketplace
SR/01315/25	France	<b>Set of toy musical instruments</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The maracas have a protruding part. A child could put it into the mouth, which could block the airways and cause choking. The product does not comply with the requirements of the Toy Safety Directive nor with the relevant European standard EN 71-1.	Removal of this product listing by the online marketplace
SR/01324/25	Germany	<b>Bath toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The bath toy set has small parts which can detach (the cap of the water gun, the loop of the storage bag) and toys that can break (the blue whale), releasing small parts. A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Destruction of the product


SR/01334/25	UK	<b>Remote-controlled toy car</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The plastic material of the USB cable has excessive concentrations of bis(2-ethylhexyl) phthalate (DEHP) and dibutyl phthalate (DBP) (measured values up to 11% and 0.12% by weight, respectively). These phthalates may harm the health of children by causing possible damage to the reproductive system. The product does not comply with the REACH Regulation nor with the requirements of the Toy Safety Directive	Destruction of the product
SR/01335/25	Italy	<b>Toy slime</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The migration of boron from the toy slime is too high (measured value up to 1047 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-3.	Ban on the marketing of the product and any accompanying measures
SR/01354/25	France	<b>Keyring with soft toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> Small parts can easily detach (white plastic ring with metal fastener; plastic eyes and nose). As a result, a small child may put them in their mouth and choke on them. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Removal of this product listing by the online marketplace
SR/01358/25	France	<b>Toy tattoo kit</b>  (Country of Origin: <b>Italy</b> )		<b>Chemical</b> The tattoo transfers contain diethylene glycol monobutyl ether (DEGBE), which is prohibited in these types of products. DEGBE may cause damage to the reproductive system. Moreover, the body paints contain benzophenone (measured value up to 0.08% by weight). Benzophenone might cause cancer. The product does not comply with the Cosmetic Products Regulation nor with the requirements of the Toy Safety Directive.	Recall of the product from end users





SR/01421/25	France	<b>Fancy-dress costume</b>  (Country of Origin: <b>China</b> )		<b>Strangulation</b> The product has functional cords close to the neck area. The cords may become trapped during various activities of a child, leading to strangulation. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Removal of this product listing by the online marketplace
SR/01431/25	Norway	<b>Jumping rope</b>  (Country of Origin: <b>China</b> )		<b>Chemical</b> The plastic material of the product has an excessive concentration of diisobutyl phthalate (DIBP) and dibutyl phthalate (DBP) (measured values up to 1.03% and 14.69% by weight, respectively). These phthalates may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Removal of this product listing by the online marketplace
SR/01436/25	France	<b>Fancy-dress costume</b>  (Country of Origin: <b>China</b> )		<b>Burns, Chemical, Choking</b> The battery compartment can be easily opened, leaving the button batteries accessible. A child may put them in the mouth and swallow them, which could cause damage to the child's gastrointestinal tract and/or choking. Moreover, the tulle skirt is highly flammable and the flame propagation too high. The costume may catch fire if worn close to an ignition source, resulting in burns. The product does not comply with the requirements of the Toy Safety Directive nor with European standards EN 62115 and EN 71-2.	Warning consumers of the risks


SR/01472/25	France	<b>Fancy-dress costume</b>  (Country of Origin: <b>Hong Kong</b> )		<b>Burns, Chemical</b> The costume is highly flammable and the flame propagation too high on the white textile of the dress. The costume may catch fire if worn close to an ignition source, resulting in burns. The migration of chromium VI from the toy's plastic eye is too high (measured value up to 0.053 mg/kg). Chromium (VI) is sensitising, can trigger allergic reactions and can cause cancer. Moreover, the migration of lead from the surface material is too high (measured value up to 23 mg/kg). Lead is harmful to children as it can lead to developmental neurotoxicity. It accumulates in the body and may also affect their future progeny when breast-fed or unborn. The product does not comply with the requirements of the Toy Safety Directive nor with the European standards EN 71-2 and 71-3.	Removal of this product listing by the online marketplace
SR/01482/25	France	<b>Toy torch</b>  (Country of Origin: <b>China</b> )		<b>Damage to sight</b> The LED light is too strong and not properly labelled. Direct viewing could cause damage to sight. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 62115.	Removal of this product listing by the online marketplace
SR/01516/25	Austria	<b>Wooden puzzle</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The puzzle has small parts (the squirrel and bird pieces) that can easily detach from the toy. Small children may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Recall of the product from end users
SR/01518/25	France	<b>Children's fancy dress costume</b>  (Country of Origin: <b>China</b> )		<b>Strangulation</b> The product has long functional cords with free ends in the neck area. The cords may become trapped during various activities of a child, leading to strangulation. The product does not comply with the requirements of the Toy Safety Directive nor with the European standards EN 71-1 and EN 14682.	Recall of the product from end users

SR/01519/25	France	<b>Pen</b>  (Country of Origin: <b>China</b> )		<b>Chemical, Choking</b> The battery compartment can be easily opened, leaving the button batteries accessible. A child may put them in the mouth and swallow them, which could cause damage to the child's gastrointestinal tract and/or choking. The product does not comply with the requirements of the Toy Safety Directive nor with European standard EN 62115.	Removal of this product listing by the online marketplace
SR/01520/25	UK	<b>Toy car</b>  (Country of Origin: <b>China</b> )		<b>Chemical, Environment</b> According to the product markings, the product has batteries containing cadmium. Cadmium bio-accumulates and poses a risk to the environment. The product does not comply with the requirements of the Batteries and Accumulators Directive.	Import rejected at border
SR/01525/25	France	<b>Magnetic toy</b>  (Country of Origin: <b>China</b> )		<b>Chemical, Choking</b> The toy contains small magnets with a high magnetic flux. A small child may put it in the mouth and choke. Moreover, if a child swallows the small magnets, they could attract one another causing intestinal blockage or perforation. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market
SR/01545/25	Poland	<b>Magnetic toy</b>  (Country of Origin: <b>China</b> )		<b>Injuries</b> The toy contains small magnets with a high magnetic flux (measured value more than 50 kG <sup>2</sup> mm <sup>2</sup> ). If a child swallows the small magnets, they could attract one another causing intestinal blockage or perforation. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Warning consumers of the risks
SR/01546/25	France	<b>Toy rattle</b>  (Country of Origin: <b>Unknown</b> )		<b>Suffocation</b> The toy rattle has a protruding part (pink ring). A child could put it into the mouth, and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market

SR/01548/25	Poland	<b>Toy rattle</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> The rattle can break easily and release small plastic parts. A child may put the small plastic parts into the mouth and choke on them. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Warning consumers of the risks
SR/01550/25	France	<b>Soft toy</b>  (Country of Origin: <b>China</b> )		<b>Choking</b> Small parts can easily detach (eyes). As a result, small children could put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Recall of the product from end users
SR/01551/25	Poland	<b>Toy trumpet</b>  (Country of Origin: <b>China</b> )		<b>Damage to hearing</b> The sound pressure level produced by the toy is too high (measured value up to 112.3 dB). This could lead to permanent or partial hearing loss. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Warning consumers of the risks
SR/01553/25	France	<b>Toy snail</b>  (Country of Origin: <b>China</b> )		<b>Burns, Chemical, Choking</b> The toy has a small part which can easily detach (left eye). As a result, a small child may put it in the mouth and choke. Moreover, the battery compartment can be easily opened, leaving the button batteries accessible. A child may put them in the mouth and swallow them, which could cause damage to the child's gastrointestinal tract and/or choking. In addition, the toy may overheat and cause burns. The product does not comply with the requirements of the Toy Safety Directive nor with the European standards EN 62115 and 71-1.	Removal of this product listing by the online marketplace

SR/01569/25	France	<b>Children's toy watch</b>  (Country of Origin: <b>China</b> )		<b>Chemical, Choking</b>  The battery compartment can be easily opened/broken, leaving the button batteries accessible. A child may put them in the mouth and swallow them, which could cause damage to the child's gastrointestinal tract and/or choking. Moreover, the plastic material of the product has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP), dibutyl phthalate (DBP) and diisobutyl phthalate (DIBP) (measured values up to 0.03%, 2.28% and 11.69% by weight, respectively). These phthalates may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the requirements of the Toy Safety Directive and with the REACH Regulation nor with the European standard EN 62115.	Removal of this product listing by the online marketplace
SR/01578/25	France	<b>Activity ball</b>  (Country of Origin: <b>China</b> )		<b>Choking</b>  The activity ball has small parts (blue and orange silicone parts and plastic rings) which may easily detach. A child may put them into the mouth and choke. Moreover, the toy has protruding parts. A child may put them into the mouth, which could block the airways and cause choking. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Recall of the product from end users



SR/01585/25	Norway	<b>Pencil case</b>  (Country of Origin: <b>China</b> )		<b>Chemical, Environment</b>  The plastic material of the product has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 14.66% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. Additionally, the product contains cadmium (measured value up to 0.034% by weight). Exposure to cadmium is harmful for human health, because it accumulates in the body and can damage organs and/or cause cancer. Moreover, the product has an excessive concentration of short chain chlorinated paraffins (SCCPs) (measured value up to 0.27% by weight). SCCPs persist in the environment, are toxic to aquatic organisms at low concentrations and bioaccumulate in wildlife and humans, posing a risk to human health and the environment. The product does not comply with the REACH Regulation nor with the Regulation on persistent organic pollutants (POP Regulation).	Withdrawal of the product from the market
SR/01586/25	Poland	<b>Plastic swing</b>  (Country of Origin: <b>China</b> )		<b>Entrapment, Injuries</b>  The product has accessible openings and holes, in which children can become trapped and suffer injuries. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-8.	Removal of this product listing by the online marketplace
SR/01611/25	France	<b>Soft toy</b>  (Country of Origin: <b>Indonesia</b> )		<b>Chemical</b>  The migration of lead from the toy is too high (measured value up to 23 mg/kg). Lead is harmful to children as it can lead to developmental neurotoxicity. It accumulates in the body and may also affect their future progeny when breast-fed or unborn. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-3.	Withdrawal of the product from the market

## Safety Gate: the EU rapid alert system for dangerous non-food products

“Safety Gate”, the EU rapid alert system (formerly known as “RAPEX”), enables the rapid exchange of information between **31 European countries** and the European Commission on non-food dangerous products found on the market posing a risk to the health and safety of consumers.



A weekly overview of the alerts on those products is published in English for free on <https://ec.europa.eu/safety-gate-alerts/screen/webReport#weeklyReports>. The measures taken in the notifying country in order to restrict such products’ marketing or use can be ordered by national authorities (“compulsory measures”) or be taken directly by producers and distributors (“voluntary measures”).

The official contact points of the Member and EFTA-EEA States provide the information published in these weekly overviews. Under the terms of Annex II.10 of the General Product Safety Directive **(2001/95/EC)** responsibility for the information provided lies with the notifying party. The Commission does not take any responsibility for the accuracy of the information provided.

## Recall Summary – US Toys / Children’s Products

### CPSC Recall List (Apr 2025)


Recall No.	Notifying Country	Product	Product Photo	Hazard / Risk	Remedy
25-204	USA	<b>Room2Room LED Iridescent Bear Lights</b>  (Country of Origin: <b>China</b> )		<b>Fire and Burn Hazards</b> Five Below Recalls Room2Room LED Iridescent Bear Lights Due to Fire and Burn Hazards  The power switch on the USB cord can overheat and melt, posing fire and burn hazards.	Consumers should immediately stop using the recalled lights and either return them to any Five Below store or contact Five Below customer service for a full refund. Consumers can receive a refund to the original credit card used for purchase, cash, or store credit when they return the lights to the store where purchased, or a check or store credit from Five Below customer service when they submit a photo of the light with the cord cut. Consumers should then dispose of the light in their household trash. Proof of purchase (receipt) is not required to receive a full refund.
25-205	USA	<b>Superb Sports Baby Bath Seats</b>  (Country of Origin: <b>China</b> )		<b>Drowning Hazard</b> Superb Sports Baby Bath Seats Recalled Due to Risk of Serious Injury or Death to Babies from Drowning Hazard; Violation of Federal Regulation for Infant Bath Seats; Sold on Amazon.com by DualOranges Store  The recalled bath seats violate the federal safety regulation for infant bath seats, including requirements for stability and leg openings, and can tip over while in use, posing a risk of serious injury or death to babies due to drowning hazard.	Consumers should stop using the recalled bath seats immediately, and contact DualOranges Store via email at <a href="mailto:info@dualoranges.com">info@dualoranges.com</a> for information on how to dispose of the product and submit a photograph to obtain a full refund. DualOranges Store and Amazon are contacting all known purchasers directly.

25-206	USA	<b>HONEYJOY Convertible and Foldable High Chairs</b>  (Country of Origin: <b>China</b> )		<b>Risk of Suffocation</b> HONEYJOY Recalls Multiple Convertible and Foldable High Chairs Due to Risk of Suffocation; Violation of Federal Regulation for Infant Sleep Products and Inclined Sleepers Ban; Sold Exclusively on Amazon.com  The recalled high chairs pose a suffocation risk because they were marketed for infant sleep and have an incline angle greater than 10 degrees, in violation of the CPSC's Infant Sleep Products Rule and the Safe Sleep for Babies Act.	Consumers should immediately stop using the recalled high chairs and contact HONEYJOY to register for a full refund. Consumers should remove the seat, write "RECALLED" in large letters on the front and rear of the seatback using a marker, and email a photograph of the defaced product to honeyjoyrecall@hotmail.com to obtain a full refund. Consumers will need to follow disposal instructions provided by HONEYJOY. HONEYJOY and Amazon are contacting all known purchasers directly.
25-215	USA	<b>Brunch &amp; Go Stroller Toys</b>  (Country of Origin: <b>China</b> )		<b>Choking Hazard</b> Fisher-Price Recalls Brunch & Go Stroller Toys Due to Choking Hazard  The yolk of the toy egg can crack and create small parts, posing a choking hazard to young children.	Consumers should immediately stop using the recalled stroller toys, keep them away from children, and contact Fisher-Price to receive a free replacement stroller toy. Consumers will be asked to permanently mark the egg component of the stroller toy with the word "Recall" and the unique identifier, and upload a photo of the marked toy at <a href="https://service.mattel.com/us/recall.aspx">https://service.mattel.com/us/recall.aspx</a> . Upon receipt of the replacement confirmation email, consumers should dispose of the recalled product in the trash. For specific instructions on how to mark the stroller toy and upload the photo, consumers should go to <a href="https://service.mattel.com/us/recall.aspx">https://service.mattel.com/us/recall.aspx</a> . Fisher-Price is contacting all known purchasers directly.


25-216	USA	<b>Tissue Box Toy sold with Fisher-Price 3-in-1 SnugaPuppy Activity Centers</b>  (Country of Origin: <b>China</b> )		<b>Choking Hazard</b> Fisher-Price Recalls Tissue Box Toy Sold with SnugaPuppy Activity Centers Due to Choking Hazard  The detachable tissue box toy can come apart, exposing the small support brackets, posing a choking hazard to young children.	Consumers should immediately stop using the recalled tissue box toy, remove it from the activity center, keep it away from children and contact Fisher-Price to receive a free replacement toy for the activity center. Consumers will be asked to mark the tissue box toy permanently with the word "Recall" and the unique identifier, mark "X" on the sensory cloth tissues, and upload a photo of the marked toy at <a href="https://service.mattel.com/us/recall.aspx">https://service.mattel.com/us/recall.aspx</a> . Upon receipt of the replacement confirmation email, consumers should dispose of the recalled product in the trash. For specific instructions on how to mark the box and upload the photo, consumers should go to <a href="https://service.mattel.com/us/recall.aspx">https://service.mattel.com/us/recall.aspx</a> . Fisher-Price is contacting all known purchasers directly.
25-218	USA	<b>E-Bully Youth All-Terrain Vehicles (ATVs)</b>  (Country of Origin: <b>China</b> )		<b>Laceration Hazard</b> The recalled youth ATVs fail to comply with the requirements of the federal mandatory ATV safety standard. The handlebars pose a laceration hazard if the child rider's body or head impacts the handlebars at a high rate of speed. Additionally, the parking brakes fail to hold, posing a collision hazard. ATVs that fail to meet the mandatory safety requirements pose a risk of serious injury or death.	Consumers should stop using the recalled ATVs immediately and contact Lil Pick Up for a free repair from an authorized repair shop.



25-220	USA	<b>Bebamour Baby Bath Seats</b>  (Country of Origin: <b>China</b> )		<b>Drowning Hazard</b> Baby Bath Seats Recalled Due to Risk of Serious Injury or Death to Babies from Drowning Hazard; Violation of Federal Regulation for Infant Bath Seats; Sold on Bebamour.com and Amazon.com by Bebamour  The recalled bath seats violate the federal safety regulation for infant bath seats because the bath seat is unstable and can tip over while in use, and the leg openings are too wide, allowing a baby to slip out of the seat, posing a risk of serious injury or death to babies from drowning.	Consumers should stop using the recalled bath seats immediately and contact Bebamour by email at <a href="mailto:amanda@babyleading.com">amanda@babyleading.com</a> for information on how to dispose of the product and submit a photograph to obtain a full refund. Bebamour and Amazon are contacting all known purchasers directly.
25-221	USA	<b>Multifunctional Puzzle Crab Toys</b>  (Country of Origin: <b>China</b> )		<b>Ingestion Hazard</b> Multifunctional Puzzle Crab Toys Recalled Due to Risk of Serious Injury or Death from Ingestion Hazard; Violation of Federal Regulations for Toy Magnets; Sold Exclusively on Walmart.com by JinJiang Baimei  The recalled magnetic Multifunctional Puzzle Crab Toy set violates the mandatory federal regulation for magnet toys, posing an ingestion hazard. When high-powered magnets are swallowed, the ingested magnets can attract each other, or another metal object, and become lodged in the digestive system. This can result in perforations, twisting and/or blockage of the intestines, infection, blood poisoning and death.	Consumers should stop using the recalled Multifunctional Puzzle Crab Toy immediately, keep it away from children and contact JinJiang Baimei to receive a pre-paid label to return the recalled magnetic pieces for a full refund. JinJiang Baimei and Walmart.com are notifying all known purchasers directly.

25-222	USA	<b>Babyjoy Convertible 6-in-1 High Chair Activity Centers</b>  (Country of Origin: <b>China</b> )		<b>Injury Hazards</b> Costway Recalls Babyjoy Convertible High Chair Activity Centers Due to Entrapment and Serious Injury Hazards; Violation of Federal Regulations for High Chairs and Stationary Activity Centers  The recalled high chair activity centers violate the federal regulations for high chairs and stationary activity centers. The high chair activity centers pose a deadly entrapment hazard because the leg openings in the seat of the stationary activity center are too wide and a child can become entrapped in it, which is a violation of the federal regulation for stationary activity centers. In addition, the tray can disengage and a child can fall, which is a violation of the federal regulation for high chairs, posing a serious injury hazard.	Consumers should immediately stop using the recalled high chair activity centers and contact Costway for a full refund and instructions on how to return or dispose of the product. Consumers can return the product by receiving a prepaid shipping label or provide photos of the destroyed product to <a href="mailto:recall@costway.com">recall@costway.com</a> . Upon receipt of the returned product or photos of the destroyed product, Costway will issue the refund. Costway and Amazon are contacting all known purchasers directly.
--------	-----	---	---	---	---

25-228	USA	<b>COMEONROA Infant Swings</b>  (Country of Origin: <b>China</b> )		<b>Risk of Suffocation</b> COMEONROA Infant Swings Recalled Due to Risk of Serious Injury or Death from Suffocation Hazard; Violation of the Inclined Sleeper Ban; Sold on Walmart.com by Eonroacoo  The swings pose a suffocation risk because they were marketed for infant sleep, and they have an incline angle greater than 10 degrees, in violation of the Safe Sleep for Babies Act. In addition, the swings fail to meet mandatory warning requirements under the swing standard and are missing the required warnings and instructions for consumer products containing button cell and coin batteries under Reese's Law.	Consumers should stop using the recalled infant swings immediately and contact Eonroacoo for a full refund. Consumers should send a photo of the swing cover cut in half, and of the swing with "Recalled" written with permanent marker on its base, to <a href="mailto:eonroacoorecall@126.com">eonroacoorecall@126.com</a> and then dispose the swing in accordance with local and state laws. Eonroacoo and Walmart are contacting all known purchasers directly.  Note: Button cell batteries are hazardous. Batteries should be disposed of or recycled by following local hazardous waste procedures.
--------	-----	--	---	---	--

25-229	USA	<b>Glow Sticks and Glasses Party Pack Toys</b>  (Country of Origin: <b>China</b> )		<b>Ingestion Hazard</b> Leetous Recalls Glow Sticks and Glasses Party Pack Toys Due to Serious Injury or Death from Ingestion Hazard; Violation of Federal Regulations for Battery-Operated Toys; Sold Exclusively on Amazon.com  The glow sticks and glasses violate the mandatory federal battery-operated toy regulation because the button cell batteries are in a compartment that can be opened easily without requiring the use of a common household tool. When button cell and coin batteries are swallowed, the ingested batteries can cause serious injuries, internal chemical burns or death, posing an ingestion hazard to children.	Consumers should immediately stop using the recalled glow sticks and glasses and take them away from children. Consumers should remove the batteries in the glow sticks and party glasses immediately and contact Leetous for information on how to dispose of the product for a full refund. Leetous and Amazon are contacting all known purchasers directly.  Note: Button cell and coin batteries are hazardous. Batteries should be disposed of or recycled by following local hazardous waste procedures.
25-231	USA	<b>Tip-over Restraint Kits</b>  (Country of Origin: <b>China</b> )		<b>Over and Entrapment Hazards</b> American Bolt and Screw Recalls Tip-Over Restraint Kits Distributed with Clothing Storage Units Manufactured by Canyon Furniture Due to Tip-Over and Entrapment Hazards and Risk of Serious Injury or Death; Sold Exclusively at Rooms To Go  The plastic zip tie used with the recalled furniture tip kits can become brittle or break, which can allow a clothing storage unit that is anchored to the wall to detach during a furniture tip-over event, posing a tip-over and entrapment hazard that can result in death or serious injuries to children.	Consumers should contact American Bolt and Screw to get a free replacement tip-over restraint kit. All known purchasers are being contacted directly by American Bolt and Screw. Consumers can contact Rooms to Go for assistance in determining whether their chest or dresser came with the affected tip-over restraint kit. Keep children away from the unit while waiting for a replacement tip kit. Consumers should dispose of the recalled tip-over restraint in their household trash once they have installed the replacement tip-over restraint.

25-235	USA	<b>Huffy 12-Volt Children's Ride-On Tonka Dump Trucks</b>  (Country of Origin: <b>China</b> )		<b>Fire and Burn Hazards</b> Huffy Recalls Children's Ride-On Tonka Dump Trucks Due to Fire and Burn Hazards  The controller on the recalled ride-on dump trucks can overheat, posing fire and burn hazards.	Consumers should immediately stop using the recalled children's dump trucks and contact Huffy for a free replacement controller. Huffy is contacting all known purchasers directly.
25-237	USA	<b>Kids Thrill Shape Sorter Car Toys</b>  (Country of Origin: <b>China</b> )		<b>Choking Hazard</b> Deals Oasis Recalls Shape Sorter Car Toys Due to Choking Hazard; Violation of Small Parts Requirements; Risk of Serious Injury or Death  The recalled shape sorter car toys contain balls that violate regulations banning small parts in toys intended for children under three years of age because they are a choking hazard, and can cause serious injury or death.	Consumers should stop using the recalled shape sorter car toys immediately and contact Deals Oasis for information on how to return the product for a full refund. Amazon is contacting all known purchasers directly.
25-239	USA	<b>Huffy Torex 24V Utility Terrain Vehicle (UTV) Ride-on Toys</b>  (Country of Origin: <b>China</b> )		<b>Fire Hazard</b> Huffy Recalls Torex UTV Ride-On Toys Due to Fire Hazard; Sold Exclusively at Walmart  The recalled ride-on toys can overheat due to improper wiring, posing a fire hazard.	Consumers should immediately stop using the recalled UTVs and contact Huffy Corporation to schedule a free repair. Consumers can have the repair done by a third party. Huffy Corporation will reimburse consumers up to \$50 for charges incurred in the third-party repair.

\* Source: [www.recalls.gov](http://www.recalls.gov)




## CPSC


The United States Consumer Product Safety Commission (CPSC) is an independent agency of the United States Government. To provide better service in alerting the American people to unsafe, hazardous or defective products, a “one stop shop” for U.S. Government recalls, <http://www.recalls.gov>, has been created. Members of the public may report unsafe products to CPSC by using the platform.


The recall list is divided into seven categories: Consumer Products, Motor Vehicles, Boats, Food, Medicine, Cosmetics and Environmental Products. Generally, the recall is conducted voluntarily by the company under CPSC’s Fast Track Recall program. Fast Track recalls are initiated by firms who are committed to working with CPSC to quickly announce the recall and remedy to protect consumers.

## Recall Summary – Australia Toys / Children’s Products

**ACCC Recall List (Apr 2025)**

PRA No.	Notifying Country	Product / Description	Product Photo	Hazard / Risk	Remedy
2025/20480	Australia	<p><b>Wooden fire truck push toy.</b></p> <p><b>SKU: 43450916</b></p> <p><b>Batch code: 32/24 (stamped on bottom of product)</b></p>		<p><b>Risk of Serious Injury or Death</b></p> <p>If the wheels are attached back-to-front, the bolt and nut may loosen over time and fall off.</p> <p>Risk of serious injury or death by choking if a child places the bolt or nut in their mouth.</p>	<p>Check and make sure that the wheels are correctly positioned on the product.</p> <p>Contact Kmart to obtain the updated instructions for assembly or view on the Kmart website (here).</p> <p>Refer to the updated instruction manual for assembly instructions.</p> <p>Contact:</p> <p>Kmart Australia Ltd. call: 1800 124 125 Monday to Friday 7:00am to 6:00pm</p> <p>website: <a href="https://www.kmart.com.au/contact-us/">https://www.kmart.com.au/contact-us/</a></p>

2025/20483	Australia	<p><b>Robot fidget toy with extendable arms &amp; legs, light up head.</b></p> <p><b>Contains button batteries.</b></p> <p><b>Approx. 13cm in height.</b></p>		<p><b>Missing of Warnings</b></p> <p>The product does not comply with the mandatory standards for products containing button/coin batteries.</p> <p>The button/coin batteries are not adequately secured and are accessible by young children.</p> <p>The product does not include the required warning information.</p> <p>Risk of choking, severe internal burn injuries or death to young children if they gain access to the button/coin batteries and swallow them or place them inside their body.</p> <p>Severe or fatal injuries can happen in 2 hours or less.</p> <p>Consumers may be unaware that the product contains button batteries.</p>	<p>Consumers should stop using the fidget toys immediately and place them out of reach of children.</p> <p>Return the fidget toy to a Kidstuff store for a full refund of the purchase price.</p> <p>Contact:</p> <p>Kidstuff Pty Ltd Email: <a href="mailto:online@kidstuff.com.au">online@kidstuff.com.au</a> Ph: 1300 578 833</p>
------------	-----------	---	---	---	--

2025/20495	Australia	<b>Multiple children's two-piece or all-in-one nightwear sets.</b>		<b>Burn Injury Hazard</b> The product does not comply with the mandatory standard for nightwear for children.  It does not include the required warning label.  There is a risk of serious burn injuries if exposed to a heat or flame source.  Consumers may not be aware of this risk.	Stop using these products immediately.  Return to the nearest H&M store for a full refund. No receipt is required.  Contact:  email: <a href="mailto:customerservice.au@hm.com">customerservice.au@hm.com</a> call: 1300 401 300
------------	-----------	--	---	---	---

## Australian Product Safety System

The Australian product safety system is set up to maximize the safety of goods through the cooperation of consumers, businesses and agencies. This policy sets out the principles adopted by the Australian Competition and Consumer Commission (ACCC) for prioritizing and addressing product safety risks.

Under the Australian Consumer Law, a responsible Minister can order a compulsory recall when there are hazards on the products. A voluntary recall could be conducted to remove the product from the marketplace when the suppliers become aware of unsafe or defective products.

The ACCC administers a national recalls system for recalls of specific and general consumer products, and publishes all product recalls on the website <https://www.productsafety.gov.au/recalls>.

## Recall Summary – Japan’s Toys / Children’s Products

### METI Recall List (Apr 2025)

PRA No.	Notifying Country	Product / Description	Product Photo	Hazard / Risk	Remedy
2025-4-25	Japan	玩具 チアBoo !  toy “Cheer Boo!”		当該品のパーツの接着不備で内部ビーズパーツが外に出て、誤飲のおそれがあるため。  The internal bead parts may come out due to inadequate adhesion of the parts of the product, and there is a risk of accidental ingestion.	回収・交換 ※交換対象パーツ「くるしゃらボール」を回収して、交換用パーツを送付  Collection & Exchange * Collect the replacement parts "Kurushara Ball" and send the replacement parts

### Japan’s Product Recall System ( 経済産業省リコール情報 )

The METI (経済産業省 Ministry of Economy, Trade and Industry) administers a national recalls system for recalls of specific and general consumer products according to the Consumer Product Safety Act, and publishes all product recalls on the website: [https://www.meti.go.jp/product\\_safety/recall/index.html](https://www.meti.go.jp/product_safety/recall/index.html) and posting at <https://x.com/kochijiko>



STC (Hong Kong Standards and Testing Centre) is a not-for-profit, independent testing, inspection and certification organization. With a global network of ISO/IEC 17025 accredited testing laboratories and over 60 years of experience in consumer product testing, we can meet your conformity assessment needs with highly efficient and reliable service. Our testing scope and capabilities related to toys and children's products include but are not limited to:

### EU Requirements

- EN 71
- Phthalates (EC) no. 1907/2006
- Nickel Release (EC) no. 1907/2006
- Total Cadmium (EEC) no. 91/338
- Lead in Jewellery product (EC) no. 836/2012
- Azo-dye (EC) no. 1907/2006
- Bisphenol-A (2014/81/EU)
- DMF (Dimethyl fumarate) (EU) no. 2011/135
- Flame retardants TCEP, TCPP, TDCP (2014/79/EU)
- Package Waste Directive (94/62/EC)

### US & Canada Requirements

- ASTM F963
- CPSIA
- California Proposition 65
- 16 CFR 1501
- ASTM F2923 (Children's jewellery)
- ASTM F2999 (Adult's jewellery)
- US Toxic in Packaging Clearinghouse (TPCH)
- CCPSA - Toys Regulations (SOR/2011-17)

### Japan Requirements

- Japan Toy Safety Standard (ST)
- Japan Food Sanitation Law (JFSL)

### Australia Requirements

- AS/NZS 8124
- Consumer Protection Notice No. 6 of 2010 - DEHP

#### FOR MORE DETAILS, PLEASE CONTACT US:

Hong Kong: [hktcd@stc.group](mailto:hktcd@stc.group)  
Changzhou: [czstc@stc.group](mailto:czstc@stc.group)  
U.S.A.: [usenquiry@stc.group](mailto:usenquiry@stc.group)

Guangdong: [gdtcd@stc.group](mailto:gdtcd@stc.group)  
Vietnam: [vnstc@stc.group](mailto:vnstc@stc.group)  
Germany: [grstc@stc.group](mailto:grstc@stc.group)

Shanghai: [shtcd@stc.group](mailto:shtcd@stc.group)  
Japan: [jpo@stc.group](mailto:jpo@stc.group)

