### **Recall Summary – European Toys**

JE STC NEWSLETTER

#### EU Safety Gate Alerts (Jun 2025) Notifying Product **Measures** Alert No. Product Hazard / Risk Country Photo Adopted OR/00081/25 Poland Soft toy Import Choking The fibrous stuffing material is easily accessible rejected at (Country of due to the weakness of certain seams. A child border may put the filling material in their mouth and Origin: China) choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1. OR/00085/25 France Soft toy Removal of Choking The fibrous stuffing material of the toy is easily this product (Country of accessible due to the weakness of the seams on listing by the Origin: the back. A small child may put the filling material online China) in their mouth and choke. The product does not marketplace comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1. OR/00087/25 Toy scooter Poland Injuries Warning The diameter of the front wheels of the scooter is consumers of (Country of too small, which can lead the scooter's wheel to the risks Origin: become stuck on an uneven surface and the child falling, suffering injuries. The product does not China) comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1. OR/00095/25 Latvia **Plush toy** Choking Import The fibrous stuffing material of the toy is easily rejected at (Country of accessible due to the weakness of certain seams. border Origin: A small child may put the filling material in their China) mouth and choke. The product does not comply with the requirements of the Toy Safety Directive.

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

Headquarters - The Hong Kong Standards and Testing Centre Ltd. 🛛 💡 10 Dai Wang Street, Tai Po Industrial Estate, Tai Po, N.T., Hong Kong

www.stc.group



OR/00102/25	Ireland	Balloon		Cuts	Recall of the
		pumper	à-à-	The bottle can be overfilled with water and	product from
				over pressured. There was no	end users
		(Country of	Balloan Pumper	recommendation on the amount of water or	
		Origin: China)		pumps which could lead to the bottle	
				exploding. This can create a risk of cuts for	
				the consumer. The product does not comply	
				with the requirements of the Toy Safety	
				Directive.	
OR/00104/25	Ireland	Bath toy	Bath	Health Risk / Other	Recall of the
			Time	Once the bath book is placed in bath water,	product from
		(Country of		the colour coating of the product can begin	end users
		Origin: China)	Sector Sector	to come away from the surface, causing	
			Changes colour in water	flaking. These soft ink flakes could be	
				ingested and cause a stomach upset,	
				nausea or vomiting to the child. The product	
				does not comply with the requirements of	
				the Toy Safety Directive.	
SR/02038/25	Austria	Toothbrush		Choking	Removal of
		learning set		The toy has small parts (tooth crowns). A	this product
				small child may put them in their mouth and	listing by the
		(Country of		choke. The product does not comply with	online
		Origin: China)		the requirements of the Toy Safety Directive	marketplace
				nor with the European standard EN 71-1.	
SR/02041/25	UK	Radio-	March 1	Chemical, Environment	Import
		controlled		According to the product markings, the	rejected at
		toy car		product has batteries containing cadmium.	border
			Xg illiant	Cadmium bio-accumulates and poses a risk	
		(Country of		to the environment. The product does not	
		Origin: China)		comply with the requirements of the	
				Batteries and Accumulators Directive.	
SR/02044/25	Sweden	Battery-		Environment	Import
		operated toy	19	The solders in the product have an	rejected at
		dog	CAP.	excessive concentration of lead (measured	border
			- Sec	value up to 65% by weight). Lead poses a	
		(Country of		risk to the environment. The product does	
		Origin: China)		not comply with the requirements of the	
				Directive on the restriction of the use of	
				certain hazardous substances in electrical	
				and electronic equipment (RoHS 2	
				Directive).	

#### Issue no.: 26/25/TCD

### **ESTC** NEWSLETTER

SR/02053/25	Czechia	Plastic doll		Chemical	Withdrawal of
				The plastic material of the product has an	the product
		(Country of		excessive concentration of bis(2-ethylhexyl)	from the
		Origin:	2 the First	phthalate (DEHP) (measured value up to	market
		China)		20.71% by weight). This phthalate may harm	
				the health by causing possible damage to the	
				reproductive system. The product does not	
				comply with the REACH Regulation.	
SR/02060/25	France	Soft toy		Choking, Suffocation	Withdrawal of
				The toy's plastic button can easily detach. A	the product
		(Country of	- Carl	small child may put it in their mouth and	from the
		Origin:		choke. The plastic of the packaging is too	market
		China)	1	thin. If a child plays with it, the plastic can	
				cover their mouth and nose, causing the	
				child to suffocate. The product does not	
				comply with the requirements of the Toy	
				Safety Directive or with those of European	
				standard EN 71-1.	
SR/02066/25	Lithuania	Plastic doll		Chemical	Withdrawal of
				The plastic material of the product has an	the product
		(Country of		excessive concentration of bis(2-ethylhexyl)	from the
		Origin: China)		phthalate (DEHP) and dibutyl phthalate	market
			Bearty	(DBP) (measured values up to 3.9% and	
				0.23% by weight, respectively). These	
				phthalates may harm health by causing	
				possible damage to the reproductive system.	
				The product does not comply with the	
				REACH Regulation.	
SR/02074/25	France	Kazoo toy		Choking	Withdrawal of
			State	Small parts can detach easily (kazoo blue	the product
		(Country of		disc). A small child may put them in their	from the
		Origin: China)		mouth and choke. The product does not	market
				comply with the requirements of the Toy	
				Safety Directive nor the European standard	
				EN 71-1.	

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

SR/02079/25	Poland	Plastic doll		Chemical	Withdrawal of the
		set	The Tot	The plastic material of the product has an	product from the
				excessive concentration of bis(2-	market
		(Country of		ethylhexyl) phthalate (DEHP) (measured	
		Origin:		value up to 27.7% by weight). This	
		China)		phthalate may harm health by causing	
				possible damage to the reproductive	
				system. The product does not comply with	
				the REACH Regulation.	
SR/02089/25	Poland	Crib toy		Choking	Import rejected at
				Small parts (metal bell and its elements)	border
		(Country of	-	may easily detach from the toy. Moreover,	
		Origin:		the fibrous stuffing material is accessible	
		China)		due to weakness of certain seams. A child	
				may put small parts or the stuffing material	
				into their mouth and choke. The product	
				does not comply with the requirements of	
				the Toy Safety Directive nor with the	
				European standard EN 71-1.	
SR/02094/25	France	Fancy-	A Comment B A	Chemical, Choking, Injuries	Withdrawal of the
		dress		The masks have small parts (metallic bars)	product from the
		mask		that can easily detach. A small child may	market
				put them in their mouth and choke.	
		(Country of		Moreover, the migration of chromium from	
		Origin:		the masks is too high (measured value up	
		France)		to 3960 mg/kg). Chromium is sensitising,	
				can trigger allergic reactions and can	
				cause cancer. Additionally, the metal bars	
				in the mask can cause eye injuries to the	
				child. The product does not comply with the	
				requirements of the Toy Safety Directive	
				nor with the European standard EN 71-3	
				and EN 71-1.	

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

SR/02100/25	Iceland	Children's		Chemical, Injuries	Recall of the
		bicycle	- 11	The brake blocks of the bicycle contain	product from
			a b	asbestos fibres. Asbestos causes cancer.	end users
		(Country of		Moreover, the handlebar is too wide, not	
		Origin:	0	resistant enough and can misalign from	
		China)		the fork too easily, leading to a loss of the	
				bicycle's control and increasing the risk of	
				a fall and injuries to the rider. Additionally,	
				the bicycle lacks all required reflectors -	
				including front, rear, side, and pedal	
				reflectors - which are crucial for visibility in	
				low-light conditions. This increases the risk	
				of an accident and injuries for the rider.	
				The product does not comply with the	
				REACH Regulation nor with the European	
				standard EN 8098.	
SR/02102/25	Poland	Toy rattle	Q 4	Choking	Import rejected
				The toy has a small part (plastic ball with	at border
		(Country of		attached cord) that can easily detach. A	
		Origin:		small child may put it in their mouth and	
		China)		choke. The product does not comply with	
				the requirements of the Toy Safety	
				Directive nor with the European standard	
				EN 71-1.	
SR/02134/25	Poland	Magnetic toy	S1	Injuries	Destruction of
			MAGNETIC	The toy contains small magnets with a	the product
		(Country of		high magnetic flux (measured value more	
		Origin:		than 50 kG <sup>2</sup> mm <sup>2</sup> ). If a child swallows the	
		China)		small magnets, they could attract one	
				another causing intestinal blockage or	
				perforation. The product does not comply	
				with the requirements of the Toy Safety	
				Directive nor with the European standard	
				EN 71-1.	

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

Headquarters - The Hong Kong Standards and Testing Centre Ltd. 🛛 💙 10 Dai Wang Street, Tai Po Industrial Estate, Tai Po, N.T., Hong Kong

### NEWSLETTER

**BESTC** 

SR/02141/25	Sweden	Baby	8	Injuries, Strangulation, Suffocation	Recall of the
		hammock	June	The baby hammock's excessive tilt angle	product from
			$\square$	and curved lying surface may cause the	end users
		(Country of		child to roll over, become stuck, and	
		Origin:	=//	suffocate or have their airways obstructed.	
		Denmark)		The product also lacks a safe design, with	
				inadequate side walls that may allow the	
				child to roll out and fall, as well as	
				potentially accessible cords that could lead	
				to strangulation due to imprecise assembly	
				instructions. The product does not comply	
				with the General Safety Product	
				Regulation nor with the European	
				Standard EN 1130.	
SR/02145/25	Latvia	Plush toy		Choking	Import rejected
				The metal chain of the toy can easily	at border
		(Country of		detach. As a result, a small child may put it	
		Origin:	2 - Star	in their mouth and choke on it. The product	
		Unknown)	and the second sec	does not comply with the requirements of	
				the Toy Safety Directive.	
SR/02150/25	UK	Plush toy	62	Choking	Withdrawal of
			1	The product has small parts (the toggles	the product
		(Country of	Perie	on the removable backpack) which may	from the
		Origin:		easily detach. A small child may put them	market
		United	Car -	into their mouth and choke. The product	
		Kingdom)		does not comply with the requirements of	
				the Toy Safety Directive.	
SR/02193/25	Poland	Jumping		Chemical	Warning
		rope	- Tay	The plastic material of the product has an	consumers of
			DA-LA	excessive concentration of bis(2-	the risks
		(Country of	and the	ethylhexyl) phthalate (DEHP) and	
		Origin:		diisobutyl phthalate (DIBP) (measured	
		China)		values up to 14.3% and 9.0% by weight,	
				respectively). These phthalates may harm	
				the health of children, causing possible	
				damage to their reproductive system. The	
				product does not comply with the REACH	
				Regulation.	

SR/02199/25	France	Toy make-up		Chemical	Withdrawal of
01002100/20	Trance	set	Agus Kinder-Schmink-Ser	The toy has an excessive amount of aluminium	the product
		001	Contraction of the second	(measured value up to 18717 mg/kg) and	from the
		(Country of		chromium (measured value up to 7056 mg/kg).	market
		Origin:		Aluminium is toxic for children if ingested.	manket
		Germany)		Chromium (VI) can cause cancer, is sensitising	
		Cermany)		and can trigger allergic reactions. The product	
				does not comply with the requirements of the Toy	
				Safety Directive, the REACH Regulation nor with	
				the European standard EN 71-3.	
SR/02203/25	France	Soft toy		Choking	Withdrawal of
010/02203/23	Trance	Controy		The product has small parts (the eyes) that can	the product
		(Country of		easily detach. A small child may put them in their	from the
		Origin: China)		mouth and choke. The product does not comply	market
		ongin. onina)		with the requirements of the Toy Safety Directive	mantet
				nor with the European standard EN 71-1.	
SR/02204/25	France	Plastic toy		Damage to sight	Warning
010/02204/20	Trance	Thashe toy	63	The radiation from the LED located in the eye of	consumers of
		(Country of		the toy is too powerful and can cause damage to	the risks
		Origin: <b>China</b> )	A REAL PROPERTY AND A REAL	sight. The product does not comply with the	
		() (g (c		requirements of the Toy Safety Directive nor with	
				the European standard EN 62115.	
SR/02207/25	Malta	Bath toy set	and the second	Choking	Import
		,	To and the second	The product contains small parts that are easily	rejected at
		(Country of	and the second	accessible. A small child might put the small parts	border
		Origin: <b>China</b> )	Mar California and	in their mouth and choke. The product does not	
		, j		comply with the requirements of the Toy Safety	
				Directive nor with the European standard EN 71-1.	
SR/02208/25	Malta	Fidget rings	and the second s	Choking	Import
			TO	The ring is very small. A child may put it in their	rejected at
		(Country of	Sectors Sectors	mouth and choke. The product does not comply	border
		Origin: <b>China</b> )		with the requirements of the Toy Safety Directive	
		<b>C</b> <i>i</i>		nor with the European Standard EN 71-1.	
SR/02209/25	France	Soft toy		Chemical	Withdrawal of
		-		The migration of chromium VI from the textile label	the product
		(Country of		of the toy is too high (measured value up to 0.48	from the
		Origin: India)	and the second sec	mg/kg). Chromium (VI) is a sensitiser that can	market
				trigger allergic reactions and can cause cancer.	
				The product does not comply with the	
				requirements of the Toy Safety Directive nor with	
				the European standard EN 71-3.	

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

SR/02211/25	Germany	Inflatable		Chemical	Ban on the
		swim seat	- A Contraction	The handholds of the swim seat have an	marketing of the
			Rec Sec	excessive concentration of bis(2-ethylhexyl)	product and any
		(Country of	A State	phthalate (DEHP) and diisobutyl phthalate	accompanying
		Origin:		(DIBP) (measured values up to 20.3% and	measures
		China)		0.8% by weight, respectively). These	
				phthalates may harm the health by causing	
				possible damage to the reproductive system.	
				The product does not comply with the	
				REACH Regulation.	
SR/02214/25	Malta	Sticky hand		Choking	Import rejected
		toy		The toy can easily generate small parts. A	at border
				child may put them in their mouth and choke.	
		(Country of		The product does not comply with the	
		Origin:		requirements of the Toy Safety Directive nor	
		China)		with the European standard EN 71-1.	
SR/02215/25	Malta	Acrylic		Choking	Import rejected
		gemstone	170000	The toy contains small parts. A small child	at border
		toy set		may put them in their mouth and choke. The	
			Children Barrison	product does not comply with the	
		(Country of		requirements of the Toy Safety Directive nor	
		Origin:		with the European standard EN 71-1.	
		China)			
SR/02223/25	France	Wooden toy		Choking	Recall of the
010,02220,20	1 Tanoo		and the second se	Small parts (Velcro fastenings on the corn	product from
		(Country of	JOUET BOIS	cob) may easily detach from the toy. A child	end users
		Origin:		may put them into their mouth and choke.	
		China)		The product does not comply with the	
		China)		requirements of the Toy Safety Directive nor	
SR/02231/25	UK	Pushchair		with the European standard EN 71-1.	Import rejected
SR/02231/25	UN	Pushchair		Asphyxiation	
		(O		The product is not supplied with relevant	at border
		(Country of		safety warnings. Without these warnings, the	
		Origin:		child can be placed in the stroller to sleep in	
		China)		an upright position. This can cause the	
				child's head to drop down, restricting the	
				necessary airflow to their lungs and leading	
				to asphyxiation. This product does not	
				comply with the General Product Safety	
				Regulation.	

#### Issue no.: 26/25/TCD

### NEWSLETTER

**BESTC** 

SR/02234/25	Malta	Toy slime		Choking	Import rejected
		-	California California III - California	The toy has small parts (the beads and	at border
		(Country of		figurines) which may easily detach. A small	
		Origin: <b>China</b> )	Mark-	child may put them in their mouth and	
		3		choke. The product does not comply with	
				the requirements of the Toy Safety Directive	
				nor with the European standard EN 71-3.	
SR/02276/25	France	Fancy dress		Fire	Withdrawal of
		costume	and the second s	The costume has inflammable solid material	the product from
				(pink plush on the wings). The costume may	the market
		(Country of		catch fire if worn close to an ignition source.	
		Origin: <b>China</b> )		The product does not comply with the	
		engin enna)		requirements of the Toy Safety Directive nor	
				with the European standard EN 71-2.	
SR/02284/25	Germany	Toy furniture		Choking	Import rejected
0100220 1/20	Connaily	set	AN SEAL	The toy set contains small parts. Small	at border
			and a state of the	children may put them in their mouth and	
		(Country of		choke. The product does not comply with	
		Origin: <b>China</b> )		the requirements of the Toy Safety Directive	
		engin enna)		nor with the European standard EN 71-1.	
SR/02288/25	Malta	Soft toy		Choking	Import rejected
0.00100,10			SA.	The product has small parts (small chain)	at border
		(Country of	Chillen Banker Will All	which may easily detach. A small child may	
		Origin: <b>China</b> )		put them into their mouth and choke. The	
		engin enna)	E E	product does not comply with requirements	
			PERMIT	with the Toy Safety Directive nor with the	
				European standard EN 71-1	
SR/02289/25	France	Playpen		Choking	Recall of the
51002200120	1 ranoo			The product has small parts (the top tips of	product from end
		(Country of		the plastic rods). A small child may put it in	users
		Origin: <b>China</b> )		their mouth and choke. The product does	00010
				not comply with the requirements of the Toy	
				Safety Directive nor with the European	
				standard EN 71-1.	
SR/02293/25	Germany	Squeeze toy		Choking	Import rejected
01102230/20	Cerniany	Squeeze ivy	PINC P	The toy contains small parts (beads). Small	at border
		(Country of	Second of P	children may put them in their mouth and	
		Origin: <b>China</b> )		choke. The product does not comply with	
		Origin. Cilina)	1 Marine Con	the requirements of the Toy Safety Directive	
				nor with the European standard EN 71-1.	
l				nor with the European Standard EN / 1-1.	

#### Issue no.: 26/25/TCD

SR/02296/25	France	Soft toy		Choking	Warning
31/02290/23	FIGILLE	Soft toy		The eyes of the toy can easily detach,	consumers of
		(Country of		generating small parts. A small child could	the risks
		Origin:		put them in their mouth and choke on it.	
		China)			
		China)		The product does not comply with the	
				requirements of the Toy Safety Directive	
00/00007/05		Distantia India		nor with the European standard EN 71-1.	
SR/02297/25	Poland	Plastic doll		Chemical	Warning
			1	The plastic material of the toy has an	consumers of
		(Country of		excessive concentration of bis(2-ethylhexyl)	the risks
		Origin:	Der	phthalate (DEHP) and dibutyl phthalate	
		China)		(DBP) (measured values up to 0.374% and	
				0.577% by weight, respectively). These	
				phthalates may harm the health of children,	
				causing possibly damage to the	
				reproductive system. The product does not	
				comply with the REACH Regulation.	
SR/02301/25	UK	LED balloon		Choking, Injuries	Import rejected
		lights		The button batteries are easily accessible.	at border
				A child may put them in their mouth and	
		(Country of		swallow them, which could cause damage	
		Origin:		to the child's gastrointestinal tract and/or	
		China)		choking. The product does not comply with	
				the requirements of the Toy Safety	
				Directive.	
SR/02318/25	Croatia	Soft toy	<b>A</b>	Choking	Import rejected
			* *	The fibrous stuffing material of the toy is	at border
		(Country of		easily accessible due to the weakness of	
		Origin:	(P	the seams on the back. A small child may	
		China)		put the filling material in their mouth and	
		<b>.</b> ,		choke. The product does not comply with	
				the requirements of the Toy Safety	
				Directive and the European standard EN	
				71-1.	
SR/02320/25	Germany	Soft toy		Choking	Import rejected
UIX/UZ32U/23	Germany	Soft toy	- Contraction	•	
		(Country of		Small parts (eyes) can easily detach from	at border
		(Country of		the toy. Small children may put them in	
		Origin:		their mouth and choke. The product does	
		China)		not comply with the requirements of the Toy	
				Safety Directive nor with the European	
				standard EN 71-1.	

Issue no.: 26	/25/TCD
---------------	---------

SR/02321/25	France	Тоу		Injuries	Withdrawal of
		excavator		The toy has an accessible sharp tip, caused	the product
				by screw tips at the level of the scraper at the	from the
		(Country of		front, which poses a risk of injury to the child.	market
		Origin: China)		The product does not comply with the	
				requirements of the Toy Safety Directive nor	
				the European standard EN 71-1.	
SR/02323/25	Latvia	Plastic brick		Choking	Import rejected
		toy set	Real	This product consists of small parts and lacks	at border
			0 - 24	required labelling. Therefore the user is not	
		(Country of	B-P-	adequately informed about the risks involved	
		Origin: China)		in using the product. A child may put the small	
				parts in their mouth and choke. The product	
				does not comply with the requirements of the	
				Toy Safety Directive.	
SR/02324/25	Latvia	Plastic brick		Choking	Import rejected
		toy set		This product consists of small parts and lacks	at border
				required labelling. Therefore, the user is not	
		(Country of		adequately informed about the risks involved	
		Origin: China)		in using the product. A child may put the small	
				parts in their mouth and choke. The product	
				does not comply with the requirements of the	
				Toy Safety Directive.	
SR/02330/25	UK	Children's		Suffocation	Import rejected
		nail set	Million Studio	The plastic of the packaging is too thin. If a	at border
				child plays with it, the plastic can cover their	
		(Country of	3 Barris Caller	mouth and nose, causing the child to	
		Origin: China)		suffocate. The product does not comply with	
				the requirements of the Toy Safety Directive.	
SR/02333/25	UK	Toy pillow		Entrapment, Suffocation	Removal of
			(3 ) A A	The pillow, pillowcase and detachable moon	this product
		(Country of	Real of the second	toy include fabric loops sewn into the side of	listing by the
		Origin: China)		one of the seams. These loops are large	online
				enough for a small child to have a finger	marketplace
				entrapped in it. Moreover, the plastic of the	
				packaging is too thin. If a child plays with it,	
				the plastic can cover their mouth and nose,	
				causing the child to suffocate. This product	
				does not comply with the requirements of the	
				Toy Safety Directive.	

SR/02339/25	Ireland	Balloons		Chemical	Recall of the
0102000/20	noidhu	Balloons	22 Vatentinës Day	The rubber of the balloons releases an excessive	product from
		(Country of		amount of nitrosatable substances(measured total	end users
		Origin:		value up to 2.63 mg/kg), which generate	
		China)		nitrosamines, including N-nitrosodiethanolamine	
		cillia)		(NDELA) and N-nitrosodimethylamine (NDMA).	
				Nitrosamines may cause cancer through ingestion	
				or dermal exposure. A child could be exposed to	
				them when touching or putting the product in their	
				mouth. The product does not comply with the	
				requirements of the Toy Safety Directive nor with	
				the European standard EN 71-12.	
SR/02348/25	Czechia	Plastic doll		Chemical	Destruction of
010/02010/20	OLOGINA		888	The plastic material of the product has an	the product
		(Country of		excessive concentration of bis(2-ethylhexyl)	
		Origin:	Arthen Nicker Nicker	phthalate (DEHP) (measured value up to 55.86%	
		China)		by weight). This phthalate may harm the health by	
		,		causing possible damage to the reproductive	
				system. The product does not comply with the	
				REACH Regulation.	
SR/02355/25	Czechia	Plastic doll		Chemical	Destruction of
				The plastic material of the toy has an excessive	the product
		(Country of		concentration of bis(2-ethylhexyl) phthalate	-
		Origin:		(DEHP) (measured value up to up to 32.9% by	
		China)		weight). This phthalate may harm the health by	
				causing possible damage to the reproductive	
				system. The product does not comply with the	
				REACH Regulation.	
SR/02375/25	Poland	Plastic toy		Choking, Cuts	Warning
				There are burrs on the toy's surface, which may	consumers of
		(Country of	W ANA	cause cuts. Additionally, the product has small	the risks
		Origin:	Carlos St.	parts (green balls) that can be easily detached. A	
		China)		small child may put them in their mouth and	
				choke. The product does not comply with the	
				requirements of the Toy Safety Directive nor with	
				the European standard EN 71-1.	

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

NEWSLETTER

#### Safety Gate: the EU rapid alert system for dangerous non-food products

BSTC

"Safety Gate", the EU rapid alert system (formerly known as "RAPEX"), enables the rapid exchange of information between **31 European countries** and the European Commission on non-food dangerous products found on the market posing a risk to the health and safety of consumers.

A weekly overview of the alerts on those products is published in English for free on <u>https://ec.europa.eu/safety-gate-alerts/screen/search?resetSearch=true</u>. The measures taken in the notifying country in order to restrict such products' marketing or use can be ordered by national authorities ("compulsory measures") or be taken directly by producers and distributors ("voluntary measures").

The official contact points of the Member and EFTA-EEA States provide the information published in these weekly overviews. Under the terms of Annex II.10 of the General Product Safety Directive (2001/95/EC) responsibility for the information provided lies with the notifying party. The Commission does not take any responsibility for the accuracy of the information provided.

### **Recall Summary – US Toys / Children's Products**

**ESTC** NEWSLETTER

				CPSC	Recall List (May 2025)
Recall No.	Notifying Country	Product	Product Photo	Hazard / Risk	Remedy
25-312	USA	ZRWD Infant		Missing of Warnings	Consumers should immediately
		Swings		ZRWD Infant Swings Recalled Due	stop using the recalled infant
				to Risk of Serious Injury or Death	swings and contact ZRWD for a
		(Country of		from Suffocation Hazard; Multiple	full refund. Consumers should
		Origin: China)		Federal Safety Violations; Sold	send a photo of the swing cover
				Exclusively on Amazon.com by	cut in half and of the swing with
				ZRWD	"Recalled" written with
					permanent marker on its base
				The swings pose a deadly	to zrwdrecall@163.com and
				suffocation risk because they were	then dispose of the swing.
				marketed for infant sleep and they	ZRWD and Amazon are
				have an incline angle greater than	contacting all known purchasers
				10 degrees, in violation of	directly.
				the CPSC's Infant Sleep Products	
				Standard and Safe Sleep for	Note: Button cell and coin
				Babies Act. The swings also fail to	batteries are hazardous.
				meet mandatory warning	Batteries should be disposed of
				requirements under the swing	or recycled by following local
				standard. In addition, the remote	procedures for hazardous
				control for the swing contains a	household waste, not in the
				lithium coin battery and the	trash.
				products are missing the required	
				warnings and instructions for	
				consumer products containing	
				button cell and coin batteries	
				under Reese's Law. When button	
				cell or coin batteries are	
				swallowed, the ingested batteries	
				can cause serious injuries, internal	
				chemical burns and death.	

25-314	USA	Hobby Toy	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Choking Hazard	Consumers should stop using
		Hammer Ball		Hobby Toy Hammer Ball Sets	the recalled toys immediately
		Sets		Recalled Due to Risk of Serious	and contact Shantou
			- AND	Injury or Death from Choking	Haochengheng Technology for
		(Country of	6-	Hazard; Violation of Federal	information on how to destroy
		Origin: China)		Regulation for Toys with Small Balls;	the product and obtain a full
				Sold Exclusively on Amazon.com by	refund. Shantou Haochengheng
				Shantou Haochengheng Technology	Technology and Amazon are
					also contacting all known
				The toy sets contain small balls that	purchasers directly.
				violate regulations for toys intended	
				for children under three years of age	
				because they are a choking hazard	
				and can cause serious injury or	
				death.	
25-315	USA	ZHORANGE	$\wedge$	Fall Hazard	Consumers should immediately
		Portable		ZHORANGE Portable Bassinets	stop using the recalled portable
		Bassinets		Recalled Due to Risk of Serious	bassinets and contact DFD
				Injury or Death from Fall Hazard;	Trading for a full refund.
		(Country of		Violation of Federal Standard for	Consumers should remove the
		Origin: China)		Infant Sleep Products; Sold on	sleeping pad, cut the sides of the
				Amazon.com by DFD Trading	portable bassinets and the
					sleeping pad, and email a photo
				The recalled portable bassinets	of the destroyed bassinet
				violate the federal safety standard	to zhorange8695@gmail.com to
				for Infant Sleep Products because	obtain a full refund. DFD Trading
				the sides are too low to contain the	and Amazon are contacting all
				infant and the portable bassinets do	known purchasers directly.
				not have a stand, posing a fall	
				hazard. These violations create an	
				unsafe sleeping environment for	
				infants.	

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

25-316	USA	Portable Hook-On		Fall Hazard	Consumers should stop
		Chairs		Portable Hook-On Chairs	using the hook-on chair
				Recalled Due to Risk of	immediately and contact
		(Country of Origin:		Serious Injury or Death from	Ravmix for information on
		China)	00	Fall Hazard; Violation of the	how to receive a refund.
			1 - march	Federal Standard for	Consumers will be instructed
				Portable Hook-On Chairs;	on how to disassemble the
				Sold Exclusively on	product, cut the restraint
				Amazon.com by Ravmix	straps and cloth seat, and
					email photos of the
				The recalled portable hook-	disassembled product and
				on chair poses a deadly fall	parts to Ravmix. Upon
				hazard because the crotch	receipt of the photos, Ravmix
				restraint can be removed	will issue a full refund.
				without the use of a tool and	Ravmix is contacting all
				infants can fall through an	known purchasers directly.
				opening, which is a violation	
				of the federal standard for	
				portable hook-on chairs.	
25-318	USA	2-in-1 Funlio	-	Fall and Entrapment	Consumers should stop
		Convertible Baby		Hazards	using the recalled high chair
		High Chairs		Funlio Convertible High	immediately, disassemble it
				Chairs Recalled Due to Risk	and contact Ecogoods for
		(Country of Origin:		of Serious Injury or Death	information on how to receive
		China)		from Fall and Entrapment	a full refund. Consumers will
				Hazards; Violation of Federal	be instructed to cut the
				Standards for High Chairs;	restraint straps and email
				Sold by Ecogoods	photos of the disassembled
					and destroyed components
				The recalled high chairs	to
				pose a deadly entrapment	funlioproductrecall@outlook.
				hazard because the opening	com. Ecogoods is contacting
				between the seat and tray is	all known purchasers
				large enough that a child can	directly.
				become entrapped in it. In	
				addition, the child restraint	
				system can fail, posing a fall	
				hazard. These are violations	
				of the federal standards for	
				high chairs.	



25-335	USA	Skywalker Pro Via		Fall Hazard	Consumers should
		Ferrata Sets,	<b>N</b> N	Mammut Sports Group Recalls	immediately stop using
		Skywalker Pro		Skywalker Pro Via Ferrata Sets	the Via Ferrata Sets
		Turn Via Ferrata		Due to Risk of Serious Injury or	and contact Mammut
		Sets and		Death from Fall Hazard	Sports Group for a full
		Skywalker Pro Via			refund. Mammut Sports
		Ferrata Packages		The carabiner can be opened	Group will provide
				without engaging the safety latch,	return labels for
		(Country of Origin:		posing a risk of serious injury or	consumers to return
		Switzerland)		death due to fall hazard.	their recalled products
					to receive their refund.
					Consumers should
					email
					warranty.usa@mammut
					.com to request the
					prepaid return labels.
25-336	USA	Giraffe Highchairs		Fall Hazard	Consumers should
				Bugaboo North America Recalls	immediately stop using
		(Country of Origin:		Giraffe High Chairs Due to Risk of	the recalled highchairs
		Czech Republic)		Serious Injury or Death from Fall	and contact Bugaboo to
			F	Hazard	receive a free repair kit
					including an Allen key
				The highchairs pose a fall hazard	and new screws to
				and risk of serious injury or death	install into the product's
				to babies because the legs of the	legs. Bugaboo is
				chair can detach from the frame if	contacting all known
				the screws connecting the legs	purchasers directly.
				are not properly tightened during	
				assembly.	

			[		
25-339	USA	Manual Retractable		Drowning and Entrapment	Pool owners and operators
		Security Pool Covers		Hazards	should immediately contact
				Endless Pools Recalls	Endless Pools for a free
		(Country of Origin:	The F	Manual Retractable Pool	inspection and a free repair
		United States)		Covers Due to Drowning and	by an Endless Pools support
				Entrapment Hazards; Risk of	services representative.
				Serious Injury and Death	Endless Pools will inspect
					the pool covers and send out
				The recalled pool covers can	a service representative to
				leave a gap of more than 4.5	remedy any entrapment and
				inches between the cover	drowning risks posed by
				roller and the pool surface,	improper installation. Pool
				when installed incorrectly by	owners and operators should
				the installer. An improper	not allow children to use or
				installation can result in the	access the pool or pool cover
				covers not conforming to the	unsupervised. Until the repair
				voluntary industry standard,	for the pool cover is
				ASTM F-1346, posing	completed, keep children
				drowning and entrapment	away from the pool cover
				hazards to children that	when closed. To prevent
				could result in serious injury	serious injury or death due to
				or death.	entrapment under the pool
					cover, do not allow anyone
					- especially children - to
					sit, stand, or jump on the
					pool cover at any time.
					Endless Pools is contacting
					all known purchasers
					directly.

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

25-345	USA	TADAKAZU		Fall and Entrapment Hazards	Consumers should immediately
20-040	USA	Baby Loungers	TADAKAZU	TADAKAZU Baby Loungers	stop using the recalled baby
		Baby Loungers	FABRIC: COTTON FILLER: POLYESTER	Recalled Due to Risk of	loungers and contact
		(Country of	GRADE: QUALIFIED PRODUCTS EXECUTIVE STANDARD: ASTM F3118/F2194		
		(Country of	(Direct contact with skin)	Serious Injury or Death from	TADAKAZU for a full refund.
		Origin: <b>China</b> )		Suffocation, Fall and	Consumers should remove the
			HIGH IT CHING	Entrapment Hazards;	sleeping pad, cut up the sides
				Violations of Federal Standard	of the baby loungers and the
				for Infant Sleep Products; Sold	sleeping pad, and email a
				on Amazon	photo of the destroyed lounger
					to tadakazurecall@yeah.net to
				The recalled portable baby	obtain a full refund.
				loungers violate the federal	TADAKAZU and Amazon are
				safety standards for Infant	contacting all known
				Sleep Products because the	purchasers directly.
				sides are shorter than the	
				minimum side height limit to	
				secure the infant; the sleeping	
				pad's thickness exceeds the	
				maximum limit, posing a	
				suffocation hazard; and an	
				infant could fall out of an	
				enclosed opening at the foot of	
				the lounger or become	
				entrapped. The portable	
				loungers do not have a stand,	
				posing a fall hazard. These	
				violations create an unsafe	
				sleeping environment for	
				infants, posing a risk of serious	
				injury or death.	
	I			injury of doath.	

25-354	USA	California Gold		Risk of Serious Injury or Death	Consumers should
		Nutrition Iron	Cicroinas COL Nerveros'	iHerb Recalls Bottles and Blister	immediately secure the
		Supplements:	Daily Prenatal Multi- bulger and a failed	Packs of California Gold Nutrition	recalled supplement bottles
		Daily Prenatal	Hex.Alpha CJPC & Chenger II	Iron Supplements Due to Risk of	out of sight and reach of
		Multi, Ultamins		Serious Injury or Death from	children and contact iHerb for
		Women's		Child Poisoning; Violation of	a refund and information on
		Multivitamin,		Federal Standard for Child	how to safely discard the
		and Ultamins		Resistant Packaging	packaging and product. To
		Women's 50+			receive a refund, consumers
		Multivitamin		The recalled dietary supplements	should email
				contain iron, which must be in	ProductRecall@iherb.com
		(Country of		child-resistant packaging, as	with the subject line: "Iron
		Origin: United		required by the Poison	Supplement Refund" and
		States)		Prevention Packaging Act. The	provide the following
				iron-containing dietary	information:
				supplement packages violate the	
				federal standard for child-	Name
				resistant packaging because the	Product(s) name & quantity
				bottles and blister packs are not	ordered
				child-resistant, posing a risk of	Evidence of destruction
				deadly poisoning, if the contents	(initials and date for each
				are swallowed by young children.	product package; include a
					photo with your initials and
					the date visible)
					Optional (provide the order
					number associated with the
					purchase(s), which can be
					found by logging into
					consumer's account and
					viewing the "Order History")
					iHerb is contacting all known
					purchasers directly.

25-359	USA	Bell Sports		Risk of Head Injury	Consumers should stop
		Bicycle		Bell Sports Recalls Bicycle Helmets Due	using the recalled helmets
		Helmets	1000	to Risk of Head Injury; Violation of	immediately and contact Bell
				Federal Standard for Bicycle Helmets	Sports for a full refund.
		(Country of			Consumers should destroy
		Origin:		The recalled helmets do not comply with	the recalled helmet by cutting
		United		the impact requirements of the	the straps off the helmet.
		States)		Consumer Product Safety Commission's	Consumers can upload
				(CPSC) mandatory federal safety	photos of the helmet with the
				standard for bicycle helmets. The	straps cut off to
				helmets can fail to protect the user in	consumersupport-
				the event of a crash, posing a risk of	bell@bellhelmets.com to
				head injury.	obtain a refund. Bell Sports is
					contacting all known
					purchasers directly.
25-706	USA	Peg Perego		Risk of Suffocation	Consumers should
		Tatamia 3-	II	Peg Perego Recalls Tatamia 3-in-1	immediately stop using the
		in-1	- Ingel	Recliners, Swings and High Chairs Due	recalled products and contact
		Recliner,	1	to Risk of Suffocation; Violations of	Peg Perego for a full refund.
		Swings and	B. I	Multiple Federal Standards (Recall	Consumers should contact
		High Chairs	20	Alert)	Peg Perego for a prepaid
			0		shipping label and packaging
		(Country of		The 3-in-1 products pose a suffocation	to send the products back to
		Origin: Italy)		risk because they were marketed for	Peg Perego. Peg Perego and
				infant sleep, and they have an incline	Amazon are contacting all
				angle greater than 10 degrees, in	known purchasers directly.
				violation of the Infant Sleep Products	
				Rule and Safe Sleep for Babies Act. In	
				addition, the products fail to meet	
				mandatory warning requirements under	
				the high chair standard.	
L	I			*	Source: www.recalls.gov

\* Source: www.recalls.gov

### CPSC

The United States Consumer Product Safety Commission (CPSC) is an independent agency of the United States Government. To provide better service in alerting the American people to unsafe, hazardous or defective products, a "one stop shop" for U.S. Government recalls, <u>http://www.recalls.gov</u>, has been created. Members of the public may report unsafe products to CPSC by using the platform.

The recall list is divided into seven categories: Consumer Products, Motor Vehicles, Boats, Food, Medicine, Cosmetics and Environmental Products. Generally, the recall is conducted voluntarily by the company under CPSC's Fast Track Recall programme. Fast Track recalls are initiated by firms who are committed to working with CPSC to quickly announce the recall and remedy to protect consumers.

### **Recall Summary – Australian Toys / Children's Products**

NEWSLETTER

ESTC

				ACCO	C Recall List (Jun 2025)
PRA No.	Notifying Country	Product / Description	Product Photo	Hazard / Risk	Remedy
2025/20522	Australia	Little Tikes pink		Missing of Warnings	Stop using these products
		swim vest		These products do not	immediately.
				comply with the mandatory	Return the products to a TK
				standard for swimming and	Maxx store for a full refund.
			5	flotation aids.	
				Contact:	
			The warnings on the one-	TJX Australia	
				piece vests are not visible	
				to supervising adult.	Email:
					info@tjxaustralia.com.au
				The 3-piece float does not	
				bear the complete	Call:
				mandatory warning.	1300 768 913 from 9:00 am to
					5:00 pm Monday to Friday
				There is an increased risk	
				of drowning if the product	
				is not used as intended.	
				Users may not be aware of	
				important safety	
				information about the use	
				of the product, including	
				use under constant,	
				competent supervision.	



					1
2025/20539	Australia	Baby rattle set		Risk of Serious Injury or Death	Stop using the toys
		containing 4		These products do not comply	immediately and keep
		types of rattles		with the mandatory standard for	out of reach of children.
			400	toys for children up to and	Contact eBay store
				including 36 months of age.	im_j5409a to arrange a
					full refund.
				Risk of serious injury or death	
				from choking if a child swallows	Contact
				a small part.	eBay store im_j5409a
					Email:
					810698298@qq.com
					Visit:
					https://www.ebay.com.au /str/imj5409a
2025/20541	Australia	Best&Less -		Risk of Choking	-
2023/20341	Australia	Light up clog	1 + + +	This product may not comply	Stop using the product immediately and keep
		shoes	0.: **	with the mandatory standards for	out of reach of children.
		511065	200	-	out of reach of children.
				products containing button/coin batteries.	Return to any Best &
				ballenes.	Less store for a refund.
				The light component can	
				separate from the shoe and	
				liberate small parts including the	
				button battery.	
				button battery.	
				Risk of choking, severe internal	
				burn injuries or death to young	
				children if they gain access to	
				the button/coin batteries and	
				swallow or place them inside	
				their body. Severe or fatal	
				injuries can happen in 2 hours or	
				less. Risk of serious injury or	
				death from choking if small	
				children swallow small parts.	
				An incident has occurred.	

2025/20545	Australia	First Baby	Bath	Risk of Injury and Illness	Stop using the product
		Days: Bath	Time 😜	The colour coating of the	immediately.
		Time Bath		affected batch of product can	Return it to the place
		Book		separate from the surface of	of purchase for a full
			Oragin infere in solar .	the book in water, causing	refund.
				flaking. These soft flakes may	
				be ingested by a child.	
				Risk of injury including illness	
				if the soft flakes are ingested	
				by a child.	
				by a crina.	
2025/20563	Australia	Poncho	S. A. H. S. M.	Missing of Warnings	Immediately stop
		animal towel		The products do not comply	using the product and
				with the mandatory standard	place away from any
				for children's nightwear.	heat sources.
					Return the product to
				The products do not include	your nearest H&M
				the required warning label.	store for a full refund,
					no receipt required.
				There is a risk of serious burn	
				injuries if the product is	Contact:
				exposed to a heat or flame	H&M
				source.	
					Email:
				Consumers may not be	customerservice.au@
				aware of this risk.	<u>hm.com</u>
					Call:
					1300 401 300



NEWSLETTER

2025/20564	Australia	Children's		Missing of Warnings	s Immediately stop	
		hooded dressing gowns in		The products do not	using the product and	
				comply with the	place away from any	
		assorted colours		mandatory standard for	heat sources.	
		and styles		children's nightwear.	Return the products to	
					your nearest H&M	
				The products do not	store for a full refund,	
				include the required	no receipt required.	
				warning label.		
					Contact:	
				There is a risk of serious	H&M	
				burn injuries if exposed to		
				a heat or flame source.	Email:	
					customerservice.au@	
				Consumers may not be	hm.com	
				aware of this risk.		
					Call:	
					1300 401 300	

#### Australian Product Safety System

The Australian product safety system is set up to maximise the safety of goods through the cooperation of consumers, businesses and agencies. This policy sets out the principles adopted by the Australian Competition and Consumer Commission (ACCC) for prioritising and addressing product safety risks.

Under the Australian Consumer Law, a responsible Minister can order a compulsory recall when there are hazards on the products. A voluntary recall could be conducted to remove the product from the marketplace when the suppliers become aware of unsafe or defective products.

The ACCC administers a national recalls system for recalls of specific and general consumer products, and publishes all product recalls on <u>https://www.productsafety.gov.au/recalls</u>.

### **Recall Summary – Japanese Toys / Children's Products**

NEWSLETTER

				METI Recall List (Jun 2025)			
PRA No.	Notifying Country	Product / Description	Product Photo	Hazard / Risk	Remedy		
25 June 2025	Japan	ハンディファン	SWZ	使用中に羽根が折れる場合 があることが確認されたた	回収・返金		
		Handy Fan	•	め。また、充電中に異常発 熱・発煙する事例が確認さ れたため。	Return & refund		
				It has been confirmed that the blades may break during use. In addition,			
				cases of abnormal heat generation and smoke generation during charging have been confirmed.			

### Japan's Product Recall System (経済産業省リコール情報)

ESTC

The METI (経済産業省 Ministry of Economy, Trade and Industry) administers a national recall system for recalls of specific and general consumer products according to the Consumer Product Safety Act, and publishes all product recalls on <u>https://www.meti.go.jp/product\_safety/recall/index.html</u> and posts on <u>https://x.com/kochijiko</u>.

STC (Hong Kong Standards and Testing Centre) is a not-for-profit, independent testing, inspection and certification organization. With a global network of ISO/IEC 17025 accredited testing laboratories and over 60 years of experience in consumer product testing, we can meet your conformity assessment needs with highly efficient and reliable service. Our testing scope and capabilities related to toys and children's products include but are not limited to:

NEWSLETTER

#### **EU Requirements**

- EN 71
- Phthalates (EC) no. 1907/2006

HSTC

- Nickel Release (EC) no. 1907/2006
- Total Cadmium (EEC) no. 91/338
- Lead in Jewellery product (EC) no. 836/2012
- Azo-dye (EC) no. 1907/2006
- Bisphenol-A (2014/81/EU)
- DMF (Dimethyl fumarate) (EU) no. 2011/135
- Flame retardants TCEP, TCPP, TDCP (2014/79/EU)
- Package Waste Directive (94/62/EC)

#### **US & Canada Requirements**

- ASTM F963
- CPSIA
- California Proposition 65
- 16 CFR 1501
- ASTM F2923 (Children's jewellery)
- ASTM F2999 (Adult's jewellery)
- US Toxic in Packaging Clearinghouse (TPCH)
- CCPSA Toys Regulations (SOR/2011-17)

#### **Japan Requirements**

- Japan Toy Safety Standard (ST)
- Japan Food Sanitation Law (JFSL)

#### **Australia Requirements**

- AS/NZS 8124
- Consumer Protection Notice No. 6 of 2010 DEHP

#### FOR MORE DETAILS, PLEASE CONTACT US:

Hong Kong:	<u>hktcd@stc.group</u>	Guangdong:	gdtcd@stc.group	Shanghai:	shtcd@stc.group
Changzhou:	czstc@stc.group	Vietnam:	vnstc@stc.group	Japan:	jpo@stc.group
U.S.A.:	<u>usenquiry@stc.group</u>	Germany:	<u>grstc@stc.group</u>		

