

Recall Summary – European Toys

EU Safety Gate Alerts (Aug 2025)





| Alert No. | Notifying Country | Product | Product Photo | Hazard / Risk | Measures Adopted |
|-------------|-------------------|--|---|--|---|
| OR/00114/25 | Poland | Toy scooter (Country of Origin: China) |  | Injuries The diameter of the front wheels of the scooter is too small (measured value up to 116.59 mm), which can lead the scooter's wheel to become stuck on an uneven surface and the child falling, suffering injuries. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1. | Withdrawal of the product from the market |
| OR/00118/25 | Poland | Pushchair (Country of Origin: China) |  | Injuries The product's restraint system can be easily released. As a result, the child might not be properly secured, which might lead them to slip and injure themselves. The product does not comply with the General Product Safety Regulation nor with the European standard EN 1888. | Recall of the product from end users |
| OR/00123/25 | Ireland | Toy rabbit (Country of Origin: China) |  | Choking The product has a small part (protective film covering the mirror on the toy rabbit's back foot). If this is not removed, a small child may put it into their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive. | Warning consumers of the risks |
| OR/00127/25 | France | Soft toy (Country of Origin: China) |  | Choking The fibrous stuffing material of the toy is easily accessible due to the weakness of the seams around the battery. A small child may put the filling material in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1. | Recall of the product from end users |

| | | | | | |
|-------------|----------|---|---|---|---|
| OR/00132/25 | Ireland | Activity tower (Country of Origin: China) |  | Entrapment, Injuries, Strangulation, Suffocation There is a risk of entrapment and potential strangulation if a child climbs through a gap in the "roof" area of the playtower and becomes stuck. Additionally, the toy may tip over during use, causing injuries. Moreover, the plastic of the packaging is too thin. If a child plays with the packaging, the plastic can cover their mouth and nose, causing the child to suffocate. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1 and EN 71-8. | Making the marketing of the product subject to prior conditions |
| SR/02768/25 | Austria | Stress ball toy (Country of Origin: China) |  | Choking The product has small parts that can easily detach (bobbles and cheese). A small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive or with European standard EN 71-1. | Removal of this product listing by the online marketplace |
| SR/02769/25 | Austria | Stress ball toy (Country of Origin: China) |  | Choking The product has small parts that can easily detach. A small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1. | Recall of the product from end users |
| SR/02771/25 | Slovakia | Children's swing (Country of Origin: Hungary) |  | Injuries, Strangulation The knots may come untied and the child may fall from the swing. Moreover, due to the insufficient technical design and incomplete assembly instructions, the child's neck, head and fingers can be caught in openings. This can cause the child to suffer injuries or strangulation. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-8. | Recall of the product from end users |


| | | | | | |
|-------------|-----------|---|---|---|---|
| SR/02775/25 | Slovakia | Children's swing (Country of Origin: Czechia) |  | Injuries, Strangulation The knots may come untied and the child may fall from the swing. Moreover, due to the insufficient technical design and incomplete assembly instructions, the child's neck, head and fingers can be caught in openings. This can cause the child to suffer injuries or strangulation. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-8. | Withdrawal of the product from the market |
| SR/02797/25 | Lithuania | Toy rattle (Country of Origin: China) |  | Choking The toy has small detachable parts. A small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1. | Withdrawal of the product from the market |
| SR/02801/25 | Germany | Toy slime kit (Country of Origin: China) |  | Chemical The migration of boron from the toy slime is too high (measured value up to 1090 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system. The product does not comply with the requirements of the Toy Safety Directive nor with European standard EN 71-3 | Removal of this product listing by the online marketplace |
| SR/02802/25 | Germany | Toy slime (Country of Origin: Belarus) |  | Chemical The migration of boron from the toy slime is too high (measured value up to 846 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system. The product does not comply with the requirements of the Toy Safety Directive nor with European standard EN 71-3. | Destruction of the product |




| | | | | | |
|-------------|----------------|--|---|---|---|
| SR/02811/25 | United Kingdom | Playmat (Country of Origin: China) |  | Entrapment The detachable toys include fabric loops sewn into the side of one of the seams. The loops are large enough that a young child can easily insert their finger into them and twist, causing him to get trapped. The product does not comply with the requirements of the Toy Safety Directive. | Removal of this product listing by the online marketplace |
| SR/02812/25 | Germany | Toy slime set (Country of Origin: China) |  | Chemical The migration of boron from the toy slime is too high (measured value up to 2870 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-3. | Removal of this product listing by the online marketplace |
| SR/02814/25 | Slovakia | Toy rattle (Country of Origin: Vietnam) |  | Choking The rattle has a protruding part. A child could put it into the mouth, which could block the airways and cause choking. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1. | Warning consumers of the risks |
| SR/02831/25 | Slovakia | Playmat (Country of Origin: Vietnam) |  | Choking The toy has small parts that can easily detach (bear's nose, dragon's left leg, car's front light). A small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1. | Withdrawal of the product from the market |
| SR/02832/25 | Austria | Toy bear (Country of Origin: China) |  | Choking The product has small parts (the bear's head, legs and arms) that can easily detach. Small children may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1. | Removal of this product listing by the online marketplace |

| | | | | | |
|-------------|-----------|--|---|---|--|
| SR/02836/25 | Cyprus | <p>Toy slime</p> <p>(Country of Origin: Unknown)</p> |  | <p>Chemical</p> <p>The migration of boron from the toy slime is too high (measured value up to 354 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-3.</p> | <p>Withdrawal of the product from the market</p> |
| SR/02846/25 | France | <p>Fancy-dress costume</p> <p>(Country of Origin: China)</p> |  | <p>Chemical</p> <p>The migration of chromium VI from the toy is too high (measured value up to 0.32 mg/kg). Chromium (VI) is sensitising, can trigger allergic reactions and can cause cancer. The product does not comply with the requirements of the Toy Safety Directive nor with the European standards EN 71-1 and EN 71-3.</p> | <p>Recall of the product from end users</p> |
| SR/02849/25 | France | <p>Gardening toy set</p> <p>(Country of Origin: The Netherlands)</p> |  | <p>Injuries</p> <p>The toy has unprotected protruding parts (teeth of the rake). A child could be injured by falling onto the teeth of the metal rake. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.</p> | <p>Recall of the product from end users</p> |
| SR/02853/25 | Lithuania | <p>Plastic doll</p> <p>(Country of Origin: China)</p> |  | <p>Chemical</p> <p>The plastic material of the product has an excessive concentration of phthalates (measured value for bis(2-ethylhexyl) phthalate (DEHP) is 6.8% by weight). DEHP may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.</p> | <p>Withdrawal of the product from the market</p> |






| | | | | | |
|-------------|----------------|---|---|---|---|
| SR/02857/25 | France | Fancy-dress costume (Country of Origin: China) |  | Chemical The migration of chromium VI from the toy is too high (measured value up to 0.44 mg/kg). Chromium (VI) is sensitising, can trigger allergic reactions and can cause cancer. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-3. | Withdrawal of the product from the market |
| SR/02881/25 | Spain | Fancy-dress hairband (Country of Origin: China) |  | Chemical, Choking The battery compartment can be easily opened, leaving the button batteries accessible. A child may put them in their mouth and swallow them, which could cause damage to the child's gastrointestinal tract and/or choking. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 62115. | Ban on the marketing of the product and any accompanying measures |
| SR/02882/25 | United Kingdom | Climbing frame (Country of Origin: China) |  | Choking, Entrapment The product has fabric loops large enough for a small child to have a finger entrapped into them. Moreover, the product's legs are too prominent. A child to put them in their mouth and choke. This product does not comply with the requirements of the Toy Safety Directive. | Removal of this product listing by the online marketplace |
| SR/02888/25 | United Kingdom | Plastic toy (Country of Origin: China) |  | Choking, Injuries, Suffocation The battery compartment can be easily opened, leaving the button batteries accessible. A child may put them in their mouth and swallow them, which could cause damage to the child's gastrointestinal tract and/or choking. Additionally, the transparent plastic packaging is not thick enough, and if a child puts the head inside, it can suffocate. The product does not comply with the requirements of the Toy Safety Directive. | Import rejected at border |





| | | | | | |
|-------------|----------------|---|---|--|---|
| SR/02902/25 | Spain | Plastic toy (Country of Origin: China) |  | Chemical, Choking, Injuries The battery compartment can be easily opened, leaving the button batteries accessible. A child may put them in their mouth and swallow them, which could cause damage to the child's gastrointestinal tract and/or choking. The product does not comply with the requirements of the Toy Safety Directive. | Ban on the marketing of the product and any accompanying measures |
| SR/02903/25 | Poland | Plastic toy (Country of Origin: China) |  | Chemical The plastic material of the product has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 14.1% by weight). This phthalate may harm the health by causing possibly damage to the reproductive system. The product does not comply with the REACH Regulation. | Withdrawal of the product from the market |
| SR/02910/25 | France | Toy ladder (Country of Origin: Hong Kong) |  | Entrapment, Strangulation The knots between the rungs are not sufficiently tightened. This may cause, that when using the ladder, the knots tighten further, changing the size of the openings. A child's head or limbs may therefore become trapped inside these, causing also the risk of strangulation. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-8. | Recall of the product from end users |
| SR/02914/25 | United Kingdom | Toy bus (Country of Origin: China) |  | Choking The product has small parts that can easily detach (red ring, green square, blue triangle). A small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive. | Destruction of the product |
| SR/02916/25 | Poland | Plastic toy (Country of Origin: China) |  | Choking The toy has small parts (the pony's mane and tail, a piece of the housing and a round rubber piece) that can be easily detached. A child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1. | Warning consumers of the risks |



| | | | | | |
|-------------|----------------|--|---|--|---|
| SR/02918/25 | United Kingdom | Remote controlled toy car (Country of Origin: China) |  | Environment According to the product markings, the product has batteries containing cadmium. Cadmium bio-accumulates and poses a risk to the environment. The product does not comply with the requirements of the Batteries and Accumulators Directive. | Destruction of the product |
| SR/02922/25 | Hungary | Plastic doll (Country of Origin: China) |  | Chemical The toy has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 29% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation. | Recall of the product from end users |
| SR/02923/25 | Hungary | Plastic doll (Country of Origin: China) |  | Chemical The toy has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) and dibutyl phthalate (DBP) (measured values up to 30% and 0.3% by weight, respectively). These phthalates may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation. | Withdrawal of the product from the market |
| SR/02946/25 | United Kingdom | Toy tree (Country of Origin: Germany) |  | Choking The product has small parts (plastic balls). A small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive. | Warning consumers of the risks |
| SR/02947/25 | Czechia | Toy rings (Country of Origin: China) |  | Chemical The product has an excessive concentration of lead (measured value up to 4.99% by weight). Lead is harmful to human health, accumulates in the body, can cause developmental neurotoxicity and may affect breast-fed or unborn children. The product does not comply with the REACH Regulation. | Withdrawal of the product from the market |

| | | | | | |
|-------------|----------------|---|---|--|---|
| SR/02949/25 | France | Soft toy (Country of Origin: China) |  | Chemical The migration of chromium VI from the toy is too high (measured value up to 0.34 mg/kg). Chromium (VI) is sensitising, can trigger allergic reactions and can cause cancer. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-3. | Destruction of the product |
| SR/02951/25 | United Kingdom | Baby sleeping bag (Country of Origin: Unknown) |  | Suffocation The sleeping bag has a hood, which may cover their mouth and/or nose area of the baby. This could lead the child to suffocate. The product does not comply with the General Product Safety Regulation. | Withdrawal of the product from the market |
| SR/02952/25 | Poland | Musical toy (Country of Origin: China) |  | Suffocation The plastic of the packaging is too thin. If a child plays with the packaging, the plastic can cover their mouth and nose, causing the child to suffocate. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1. | Warning consumers of the risks |
| SR/02955/25 | Hungary | Key ring with doll (Country of Origin: China) |  | Chemical The plastic material of the doll has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 0.21% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation. | Recall of the product from end users |
| SR/02963/25 | Cyprus | Toy slime (Country of Origin: Unknown) |  | Chemical The migration of boron from the toy slime is too high (measured value up to 983 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-3. | Withdrawal of the product from the market |





| | | | | | |
|-------------|----------------|---|---|---|---|
| SR/02988/25 | Cyprus | Toy slime (Country of Origin: Unknown) |  | Chemical The migration of boron from the toy slime is too high (measured value up to 838 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-3. | Withdrawal of the product from the market |
| SR/02989/25 | France | Soft toy (Country of Origin: China) |  | Choking Small parts can easily detach (eyes of the toy). A child could put it in its mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-3. | Recall of the product from end users |
| SR/02998/25 | Hungary | Plastic doll set (Country of Origin: China) |  | Chemical The product has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) and dibutyl phthalate (DBP) (measured values up to 0.95% and 3.5% by weight, respectively). These phthalates may harm the health by causing possible damage to the reproductive system. The product does not comply with the REACH Regulation. | Ban on the marketing of the product and any accompanying measures |
| SR/03002/25 | United Kingdom | Activity toy board (Country of Origin: China) |  | Chemical, Choking, Strangulation The product has small pieces that can easily detach (the keys). A small child may put it in their mouth and choke. Moreover, the steering wheel and light battery compartment can be easily opened, leaving the button batteries accessible. A child may put them in their mouth and swallow them, which could cause damage to the child's gastrointestinal tract and/or choking. Additionally, the rope at the top and cord used to secure the phone toy to the board is too long and could tangle around the child's neck causing strangulation. This product does not comply with the requirements of the Toy Safety Directive. | Destruction of the product |




| | | | | | |
|-------------|---------|---|---|---|--------------------------------------|
| SR/03006/25 | Hungary | Easter egg toy set (Country of Origin: China) |  | Choking The toy has small parts (toy silicone figures). A small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1. | Import rejected at border |
| SR/03010/25 | Hungary | Soft toy (Country of Origin: China) |  | Choking Small parts can easily detach (the eyes of the toy). As a consequence, a small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1. | Recall of the product from end users |
| SR/03014/25 | Hungary | Soft toy (Country of Origin: China) |  | Choking Small parts can easily detach (the eyes of the toy). As a consequence, a small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1. | Recall of the product from end users |
| SR/03025/25 | Hungary | Rotating toy (Country of Origin: China) |  | Choking Small plastic parts may easily detach from the toy. A small child may put them in their mouth and choke on them. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1. | Import rejected at border |
| SR/03027/25 | Hungary | Bath toy (Country of Origin: China) |  | Chemical, Choking The product has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) and dibutyl phthalate (DBP) (measured values up to 8.4% and 0.13% by weight, respectively). These phthalates may harm the health of children, causing possible damage to their reproductive system. In addition, small plastic parts (squeaking element) may easily detach from the toy. A small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor the REACH Regulation nor with the European standard EN 71-1. | Destruction of the product |





| | | | | | |
|-------------|---------|--|---|--|---|
| SR/03028/25 | Hungary | Bath toy (Country of Origin: China) |  | Chemical, Choking The product has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 8.2% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. In addition, small plastic parts (squeaking element) may easily detach from the toy. A small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor the REACH Regulation nor with the European standard EN 71-1. | Recall of the product from end users |
| SR/03029/25 | Hungary | Bath toy (Country of Origin: China) |  | Choking The product has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) and dibutyl phthalate (DBP) (measured values up to 31% and 0.69% by weight, respectively). These phthalates may harm the health of children, causing possible damage to their reproductive system. In addition, small plastic parts (squeaking element) may easily detach from the toy. A small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive and the REACH Regulation nor with the European standard EN 71-1. | Withdrawal of the product from the market |
| SR/03030/25 | Czechia | Plastic doll (Country of Origin: China) |  | Chemical The toy has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 21% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation. | Destruction of the product |
| SR/03036/25 | Hungary | Plastic doll (Country of Origin: China) |  | Chemical The product has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 5.4% by weight). DEHP may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation. | Recall of the product from end users |






| | | | | | |
|-------------|-----------|--|---|--|---|
| SR/03038/25 | Hungary | Plastic doll (Country of Origin: China) |  | Chemical The product has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 37% by weight). DEHP may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation. | Withdrawal of the product from the market |
| SR/03040/25 | Lithuania | Plastic doll (Country of Origin: China) |  | Chemical The plastic material of the doll contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) and dibutyl phthalate (DBP) (measured value up to 4.93% by weight). These phthalates may harm the health of children by causing possible damage to their reproductive system. The product does not comply with the requirements of the Toy Safety Directive. | Withdrawal of the product from the market |
| SR/03047/25 | Germany | Baby doll (Country of Origin: China) |  | Chemical, Choking The battery compartment in the integrated soundbox of the toy can be easily opened, leaving the button batteries accessible. A child may put them in their mouth and swallow them, which could cause damage to the child's gastrointestinal tract and/or choking. Additionally, the fibrous stuffing material of the toy is easily accessible due to the weakness of the seams. The product has also small parts that can easily detach from the clothing (the buttons and pompoms). A small child may put the filling material or the small parts in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standards EN 71-1 and EN 62115. | Recall of the product from end users |

| | | | | | |
|-------------|---------|--|---|---|--------------------------------------|
| SR/03048/25 | Germany | Baby doll (Country of Origin: China) |  | Chemical, Choking The soother chain on the product can easily break, releasing small parts. The button eyes on the doll's shirt can also easily detach. A small child could put either of these in their mouth and choke. Moreover, the button batteries compartment in the integrated loudspeaker can easily break, leaving the button batteries inside easily accessible. A child may put them in their mouth and swallow them, which could cause damage to the child's gastrointestinal tract and/or choking. Additionally, the fibrous stuffing material of the toy is easily accessible due to the weakness of the seams. A small child may put the filling material in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standards EN 71-1 and EN 62115. | Recall of the product from end users |
| SR/03050/25 | Hungary | Plastic toy (Country of Origin: China) |  | Choking Small parts (squeaking element) can easily detach from the toy. A small child may put them in their mouth and choke on them. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1. | Import rejected at border |
| SR/03051/25 | Czechia | Plastic doll (Country of Origin: Czechia) |  | Chemical The plastic material of the doll contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) and dibutyl phthalate (DBP) (measured values up to 30.38% and 0.5% by weight, respectively). These phthalates may harm the health of children by causing possible damage to their reproductive system. The product does not comply with the REACH Regulation. | Destruction of the product |

| | | | | | |
|-------------|---------|---|---|--|---|
| SR/03053/25 | Hungary | Plush toy (Country of Origin: China) |  | Choking Small parts (eyes and nose) can easily detach from the toy. A small child may put them in their mouth and choke on them. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1. | Import rejected at border |
| SR/03059/25 | Norway | Soother holder (Country of Origin: Unknown) |  | Choking The beads of the soother holder do not have the required ventilation holes and can be loosened. Furthermore, the garment fastener of the soother holder is protruding. A small child can put those elements in their mouth and choke. The product does not comply with the General Product Safety Regulation nor with the European standards EN 12586 and EN 71-1. | Withdrawal of the product from the market |
| SR/03060/25 | Norway | Soother holder (Country of Origin: Norway) |  | Choking The clips of the soother holder do not have the required ventilation holes and can be loosened. Furthermore, the garment fastener of the soother holder is protruding. A small child can put those elements in their mouth and choke. The product does not comply with the General Product Safety Regulation nor with the European standards EN 12586 and 71-1. | Withdrawal of the product from the market |
| SR/03061/25 | Norway | Soother (Country of Origin: Unknown) |  | Choking The plastic parts of the product may easily break, creating small parts. A child may put them into their mouth and choke. The product does not comply with the General Product Safety Regulation nor with the European standard EN 1400. | Withdrawal of the product from the market |

| | | | | | |
|-------------|-----------|--|---|--|---|
| SR/03062/25 | Norway | Soother (Country of Origin: Unknown) |  | Choking, Suffocation The ventilation holes and the projection of the knob of the pacifier are too small, making it difficult to grab hold of the pacifier if stuck in a child's throat, which could lead to a suffocation risk. Moreover, the plastic parts of the product may easily break, creating small parts. A child may put them into their mouth and choke. The product does not comply with the General Product Safety Regulation nor with the European standard EN 1400. | Recall of the product from end users |
| SR/03068/25 | Lithuania | Plastic doll (Country of Origin: China) |  | Chemical The plastic material of the doll contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 3.6% by weight). DEHP may harm the health of children by causing possible damage to their reproductive system. The product does not comply with the REACH Regulation and the requirements of the Toy Safety Directive. | Withdrawal of the product from the market |
| SR/03072/25 | Lithuania | Plastic toy (Country of Origin: China) |  | Choking Small parts can easily detach from the toy. A small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1. | Withdrawal of the product from the market |
| SR/03077/25 | Norway | Soother holder (Country of Origin: United Kingdom) |  | Choking The beads of the soother holder do not have the required ventilation holes and can be loosened. Furthermore, the garment fastener of the soother holder is protruding. A small child can put those elements in their mouth and choke. The product does not comply with the General Product Safety Regulation nor with the European standards EN 12586 and EN 71-1. | Recall of the product from end users |

| | | | | | |
|-------------|-----------|---|---|--|---|
| SR/03087/25 | Lithuania | Plastic toy (Country of Origin: China) |  | Choking Small parts (the horn) can easily detach from the toy. A small child may put them in their mouth and choke on them. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1. | Withdrawal of the product from the market |
| SR/03088/25 | Germany | Wooden toy truck (Country of Origin: Unknown) |  | Choking Small parts can easily detach from the toy. A small child may put them in their mouth and choke on them. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1. | Stop of sales |
| SR/03089/25 | Sweden | Plastic doll (Country of Origin: China) |  | Chemical The migration of lead and cadmium from the toy is too high (measured value up to 81% and 0.45% by weight, respectively). Lead is harmful to human health, accumulates in the body, can cause developmental neurotoxicity and may affect breast-fed or unborn children. Cadmium is harmful to human health because it accumulates in the body, can damage the kidneys and bones and it may cause cancer. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-3. | Withdrawal of the product from the market |
| SR/03090/25 | France | Hairclips (Country of Origin: China) |  | Chemical The product has an excessive concentration of benzene (measured value up to 0.017% mg/kg). Benzene is mutagenic and causes cancer. The product does not comply with the REACH Regulation. | Withdrawal of the product from the market |

| | | | | | |
|-------------|-----------|--|---|--|---|
| SR/03091/25 | Sweden | Finger painting kit (Country of Origin: China) |  | Chemical The paints contain 2-amino-methylpropanol (3% by weight), methanol (up to 4.6% percent by weight) and ethylene glycol (up to 4.1% by weight). The chemicals may pose a health risk to young children if ingested, inhaled or absorbed through the skin. The product does not comply with the requirements of the Toy Safety Directive. | Withdrawal of the product from the market |
| SR/03097/25 | Lithuania | Yoyo puffer ball (Country of Origin: China) |  | Strangulation The toy can stretch too long. A child could swing the toy around the head and twist it around the neck, causing strangulation. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1. | Withdrawal of the product from the market |
| SR/03100/25 | Ireland | Puzzle set (Country of Origin: Unknown) |  | Choking Small parts (the puzzle pieces) can easily detach. A small child may put them in their mouth and choke on them. The product does not comply with the requirements of the Toy Safety Directive. | Removal of this product listing by the online marketplace |
| SR/03101/25 | Italy | Toy slime (Country of Origin: China) |  | Chemical The migration of boron from the toy slime is too high (measured value up to 340 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-3. | Ban on the marketing of the product and any accompanying measures |
| SR/03110/25 | Sweden | Plastic toy (Country of Origin: Hong Kong) |  | Chemical The plastic material in the product has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 1.14% by weight). This phthalate may harm the health by causing possible damage to the reproductive system. The product does not comply with the REACH Regulation. | Import rejected at border |

| | | | | | |
|-------------|---------|--|---|--|---|
| SR/03112/25 | Ireland | Fidget toy (Country of Origin: China) |  | Choking The product contains small parts. A small child could put these in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive. | Removal of this product listing by the online marketplace |
| SR/03113/25 | Ireland | Plastic toy (Country of Origin: China) |  | Choking The toy figurines are small parts. A small child may put them in their mouth and choke. The product does not comply with the requirements of the Toy Safety Directive. | Removal of this product listing by the online marketplace |

Safety Gate: the EU rapid alert system for dangerous non-food products



“Safety Gate”, the EU rapid alert system (formerly known as “RAPEX”), enables the rapid exchange of information between **31 European countries** and the European Commission on non-food dangerous products found on the market posing a risk to the health and safety of consumers.




A weekly overview of the alerts on those products is published in English for free on <https://ec.europa.eu/safety-gate-alerts/screen/search?resetSearch=true>. The measures taken in the notifying country in order to restrict such products’ marketing or use can be ordered by national authorities (“compulsory measures”) or be taken directly by producers and distributors (“voluntary measures”).


The official contact points of the Member and EFTA-EEA States provide the information published in these weekly overviews. Under the terms of Annex II.10 of the General Product Safety Directive (**2001/95/EC**) responsibility for the information provided lies with the notifying party. The Commission does not take any responsibility for the accuracy of the information provided.


Recall Summary – US Toys / Children’s Products

CPSC Recall List (Aug 2025)

| Recall No. | Notifying Country | Product | Product Photo | Hazard / Risk | Remedy |
|------------|-------------------|---|---|--|---|
| 25-421 | USA | <p>Pet Zone Laser Pointer & LED Ball Pet Toys</p> <p>(Country of Origin: China)</p> |  | <p>Ingestion Hazard</p> <p>Petmate Recalls Pet Zone Pet Toys Due to Risk of Serious Injury or Death from Ingestion Hazard; Violation of Mandatory Standard for Consumer Products with Button Cell Batteries; Sold Exclusively at Menards</p> <p>The recalled pet toys violate the mandatory standard for consumer products containing button cell or coin batteries as required by Reese’s Law because the LED-illuminated plastic sphere can break upon impact, making the button cell batteries easily accessible to children, posing an ingestion hazard. Swallowed batteries can cause serious injuries, internal chemical burns and death.</p> | <p>Consumers should immediately stop using the recalled pet toys and contact Petmate for a full refund.</p> <p>Note: Button cell and coin batteries are hazardous. If disposing of or recycling button cell or coin batteries, do so in a manner that follows local hazardous waste procedures.</p> |
| 25-422 | USA | <p>TEMI Go Basketball Toys</p> <p>(Country of Origin: China)</p> |  | <p>Choking Hazard</p> <p>TEMI Go Basketball Toys Recalled Due to Risk of Serious Injury or Death from Choking; Violates Small Ball Ban; Sold on Amazon by Temitoys</p> <p>The recalled toy contains small balls and is intended for children under three years of age, which violates the small ball ban, posing a deadly choking hazard.</p> | <p>Consumers should immediately take the toy away from children and contact TEMI Toys for a full refund. Consumers will be asked to throw the product away and send a photo of the disposed product to Temitoys@outlook.com.</p> |

| | | | | | |
|--------|-----|--|---|---|---|
| 25-427 | USA | <p>La Ligne Enfant Bonne Nuit Pajamas</p> <p>(Country of Origin: Peru)</p> |  | <p>Risk of Burn Injuries</p> <p>La Ligne Recalls Enfant Bonne Nuit Pajamas Due to Burn Hazard; Violates Mandatory Flammability Standards</p> <p>The recalled children's pajama sets violate mandatory standards for children's sleepwear flammability, posing a risk of burn injuries to children.</p> | <p>Consumers should immediately take the recalled children's pajamas away from children, stop using them and contact La Ligne for a full refund.</p> <p>Consumers will be asked to destroy the garments by cutting them in half and disposing them. Consumers should send a photo of the destroyed garment by email to lou@lalignenyc.com to receive a refund of \$75 or store credit of \$100.</p> |
| 25-425 | USA | <p>LeymanKids Children's Pajama Sets</p> <p>(Country of Origin: China)</p> |  | <p>Risk of Injury or Death</p> <p>AliExpress Recalls LeymanKids Children's Pajama Sets Due to Risk of Injury or Death from Burns; Violates Mandatory Standards for Children's Sleepwear</p> <p>The recalled children's pajama sets violate the mandatory flammability standards for children's sleepwear, posing a risk of burn injuries or death to children.</p> | <p>Consumers should stop using the recalled pajamas immediately and contact AliExpress to receive a full refund. Consumers should destroy the pajamas by cutting them in half, then take a photo and dispose of them.</p> <p>Consumers must send the photo of the destroyed pajamas to us_product_recall@aliexpress.com or by replying to the recall email sent by AliExpress.</p> |
| 25-433 | USA | <p>Children's Spiral Tower Toys</p> <p>(Country of Origin: China)</p> |  | <p>Choking Hazard</p> <p>Children's Toys Recalled Due to Risk of Serious Injury or Death from Choking; Violates the Small Ball Ban; Sold on Shein by STWUQIKONG</p> <p>The recalled toy contains small balls and is intended for children under three years of age, which violates the small ball ban, posing a deadly choking hazard.</p> | <p>Consumers should immediately take the toy away from children and contact STWUQIKONG for a full refund.</p> <p>Consumers will be asked to throw the product away and send a photo of the disposed product to STWUQIKONG_RECALL@hotmail.com.</p> |

| | | | | | |
|--------|-----|--|---|---|--|
| 25-447 | USA | <p>Lulive 12-Drawer Dressers</p> <p>(Country of Origin: China)</p> |  | <p>Over and Entrapment Hazards</p> <p>Lulive Recalls Dressers Due to Risk of Serious Injury or Death from Tip-Over and Entrapment; Violates Mandatory Standard for Clothing Storage Units; Sold on Amazon by Lulive</p> <p>The recalled dressers are unstable if they are not anchored to the wall, posing serious tip-over and entrapment hazards that can result in injuries or death to children. The dressers violate the mandatory standard required by the STURDY Act.</p> | <p>Consumers should stop using the recalled dressers immediately if they are not anchored to the wall and place them in an area that children cannot access.</p> <p>Consumers can contact Lulive for instructions on how to dispose of the dressers to receive a full refund. Consumers must submit a photo to lulive12recall@sina.com of the product demonstrating disposal.</p> |
|--------|-----|--|---|---|--|

| | | | | | |
|--------|-----|---|---|--|--|
| 25-450 | USA | <p>Party Favors Lite-Up Torches and Mini Laser Pointers</p> <p>(Country of Origin: China)</p> |  | <p>Missing of Warnings</p> <p>Party Favors Lite-Up Torches and Laser Pointers Recalled Due to Risk of Serious Injury or Death from Battery Ingestion; Violates Multiple Standards; Imported by MTC Trading</p> <p>The recalled lite-up torches contain button cell batteries in violation of the mandatory standard for toys and the recalled mini laser pointers contain button cell batteries in violation of the mandatory standard for consumer products because the button cell batteries can be accessed easily by children. Additionally, the laser pointers do not have the warnings required under Reese’s Law. When button cell or coin batteries are swallowed, the ingested batteries can cause serious injuries, internal chemical burns, and death.</p> | <p>Consumers should immediately stop using the Lite-Up Torches and Mini Laser Pointers, take them away from children and place them where children cannot access them. Consumers may contact MTC Trading to request a full refund. Consumers will need to email a photograph confirming disposal of the lite-up torches or mini laser pointers to mtcmans@gmail.com to receive the refund.</p> <p>Note: Button cell batteries are hazardous. Batteries should be disposed of or recycled by following local hazardous waste procedures.</p> |
|--------|-----|---|---|--|--|

* Source: www.recalls.gov

CPSC

The United States Consumer Product Safety Commission (CPSC) is an independent agency of the United States Government. To provide better service in alerting the American people to unsafe, hazardous or defective products, a “one stop shop” for U.S. Government recalls, <http://www.recalls.gov>, has been created. Members of the public may report unsafe products to CPSC by using the platform.


The recall list is divided into seven categories: Consumer Products, Motor Vehicles, Boats, Food, Medicine, Cosmetics and Environmental Products. Generally, the recall is conducted voluntarily by the company under CPSC’s Fast Track Recall programme. Fast Track recalls are initiated by firms who are committed to working with CPSC to quickly announce the recall and remedy to protect consumers.

Recall Summary – Australian Toys / Children’s Products

ACCC Recall List (Aug 2025)

| PRA No. | Notifying Country | Product / Description | Product Photo | Hazard / Risk | Remedy |
|------------|-------------------|---|---|---|--|
| 2025/20596 | Australia | <p>Plush alpaca toys handmade in Peru with alpaca fleece</p> <p>(Country of Origin: Peru)</p> |  | <p>Choking Hazard</p> <p>These products do not comply with the mandatory standard for toys for children up to and including 36 months of age.</p> <p>The small plastic eyes may separate from the toy and become a choking hazard.</p> <p>The hazards to consumers</p> <p>There is a risk of serious injury or death from choking if the plastic eyes separate from the toy and small children swallow them.</p> | <p>Stop using these products immediately and keep them out of reach of children.</p> <p>Contact Inkari on support@inkari-alpaca.com to request a refund and for further assistance. Include the following information in your request:</p> <ul style="list-style-type: none"> - Name, contact details and delivery address - Product title and size (e.g. "Large Sandstone", "Mini Limited Edition") - Approx date of purchase and order number(s) if known <p>Contact</p> <p>Inkari Call: 1800 993 363</p> <p>Email: support@inkari-alpaca.com</p> |

| | | | | | |
|-------------------|------------------|--|---|--|---|
| <p>2025/20603</p> | <p>Australia</p> | <p>3D Mini Animal Toy sold at Kmart and Target</p> <p>(Country of Origin: China)</p> |  | <p>Choking Hazard</p> <p>The product contains small parts that may separate from the toy and become a choking hazard.</p> <p>There is a risk of serious injury or death by choking if small parts separate from the toy and a child places them in their mouth.</p> | <p>Stop using these toys immediately and keep out of reach of children.</p> <p>Return to the place of purchase for a full refund.</p> <p>Contact the place of purchase if you are unable to return the product.</p> <p>Contact</p> <p>Kmart Call: 1800 124 125 Monday to Friday, 8am to 6pm (AEST); Saturday 8am to 5pm (AEST)</p> <p>Online: https://www.kmart.com.au/contact-us/</p> <p>Target Call: 1300 753 567 Monday to Friday, 9am to 7pm (AEST); Saturday 9am to 5pm (AEST)</p> <p>Online: https://www.target.com.au/help/contact-us</p> |
|-------------------|------------------|--|---|--|---|

| | | | | | |
|------------|-----------|--|---|--|---|
| 2025/20603 | Australia | <p>3D Mini Animal Toy sold at Kmart and Target</p> <p>(Country of Origin: China)</p> |  | <p>Choking Hazard</p> <p>The product contains small parts that may separate from the toy and become a choking hazard.</p> <p>There is a risk of serious injury or death by choking if small parts separate from the toy and a child places them in their mouth.</p> | <p>Stop using these toys immediately and keep out of reach of children.</p> <p>Return to the place of purchase for a full refund.</p> <p>Contact the place of purchase if you are unable to return the product.</p> <p>Contact</p> <p>Kmart Call: 1800 124 125 Monday to Friday, 8am to 6pm (AEST); Saturday 8am to 5pm (AEST)</p> <p>Online: https://www.kmart.com.au/contact-us/</p> <p>Target Call: 1300 753 567 Monday to Friday, 9am to 7pm (AEST); Saturday 9am to 5pm (AEST)</p> <p>Online: https://www.target.com.au/help/contact-us</p> |
|------------|-----------|--|---|--|---|

Australian Product Safety System

The Australian product safety system is set up to maximise the safety of goods through the cooperation of consumers, businesses and agencies. This policy sets out the principles adopted by the Australian Competition and Consumer Commission (ACCC) for prioritising and addressing product safety risks.

Under the Australian Consumer Law, a responsible Minister can order a compulsory recall when there are hazards on the products. A voluntary recall could be conducted to remove the product from the marketplace when the suppliers become aware of unsafe or defective products.

The ACCC administers a national recalls system for recalls of specific and general consumer products, and publishes all product recalls on <https://www.productsafety.gov.au/recalls>.

STC (Hong Kong Standards and Testing Centre) is a not-for-profit, independent testing, inspection and certification organization. With a global network of ISO/IEC 17025 accredited testing laboratories and over 60 years of experience in consumer product testing, we can meet your conformity assessment needs with highly efficient and reliable service. Our testing scope and capabilities related to toys and children's products include but are not limited to:

EU Requirements

- EN 71
- Phthalates (EC) no. 1907/2006
- Nickel Release (EC) no. 1907/2006
- Total Cadmium (EEC) no. 91/338
- Lead in Jewellery product (EC) no. 836/2012
- Azo-dye (EC) no. 1907/2006
- Bisphenol-A (2014/81/EU)
- DMF (Dimethyl fumarate) (EU) no. 2011/135
- Flame retardants TCEP, TCPP, TDCP (2014/79/EU)
- Package Waste Directive (94/62/EC)

US & Canada Requirements

- ASTM F963
- CPSIA
- California Proposition 65
- 16 CFR 1501
- ASTM F2923 (Children's jewellery)
- ASTM F2999 (Adult's jewellery)
- US Toxic in Packaging Clearinghouse (TPCH)
- CCPSA - Toys Regulations (SOR/2011-17)

Japan Requirements

- Japan Toy Safety Standard (ST)
- Japan Food Sanitation Law (JFSL)

Australia Requirements

- AS/NZS 8124
- Consumer Protection Notice No. 6 of 2010 - DEHP

FOR MORE DETAILS, PLEASE CONTACT US:

Hong Kong: hktcd@stc.group
Changzhou: czstc@stc.group
U.S.A.: usenquiry@stc.group

Guangdong: gdtcd@stc.group
Vietnam: vnstc@stc.group
Germany: grstc@stc.group

Shanghai: shtcd@stc.group
Japan: jpo@stc.group

