

Recall Summary - European Toys / Children's Products

EU Safety Gate Alerts (Oct 2025)

Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
OR/00154/25	France	Soft toys		Choking	Recall of the
		_		The fibrous stuffing material of the toy is easily	product from
		(Country of	CO ANYENT	accessible. A small child could put stuffing	end users
		Origin:	THOUSE THE THE THE THE THE THE THE THE THE TH	material in the mouth and choke. The product	
		China)		does not comply with the requirements of the Toy	
				Safety Directive nor with the European standard	
				EN 71-1.	
OR/00155/25	Slovakia	Plastic slide		Injuries	Withdrawal of
		toy		The slide is not stable. A child may therefore fall	the product
				and suffer injuries. The product does not comply	from the
		(Country of		with the requirements of the Toy Safety Directive	market
		Origin:		nor with the European standard EN 71-8.	
		Hungary)			
SR/03391/25	France	Modelling	The second second	Chemical	Withdrawal of
		paste	TAM AST	The migration of boron from the toy is too high	the product
				(measured value up to 2982.7 mg/kg). Ingestion	from the
		(Country of		or contact with an excessive quantity of boron	market
		Origin:		may harm the health of children by damaging the	
		China)		reproductive system. The product does not	
				comply with the requirements of the Toy Safety	
				Directive, nor with the European standard EN 71-	
				3.	
SR/03395/25	Germany	Balloons		Chemical	Removal of
				The rubber of the balloons releases an excessive	this product
		(Country of		amount of nitrosamines (measured total value:	listing by the
		Origin:	VERSON .	0.082 mg/ kg), and also releases an excessive	online
		China)		amount of nitrosatable substances (measured	marketplace
				value: 8.14 mg/kg) which generate nitrosamines.	
				Nitrosamines may cause cancer through	
				ingestion or dermal exposure. A child could be	
				exposed to them when touching or putting the	
				product in the mouth. The product does not	
				comply with the requirements of the Toy Safety	
				Directive.	





Issue no.: 49/25/TCD

Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
SR/03397/25	Cyprus	Bubble		Choking	Ban on the
		producing	Described out of submitted to his	Small parts (suction cups) can easily detach from	marketing of
		toy	State assignment in the rest of the control of the	the toy. A small child may put them in the mouth	the product
			amenthalism accords and purrous aur user race accommodate	and choke on them. The product does not comply	and any
		(Country of		with the requirements of the Toy Safety Directive	accompanying
		Origin:		nor with the European standard EN 71-1.	measures
		China)			
SR/03402/25	Ireland	Plastic toy		Choking	Removal of
		figure		The toy figure is a small part. The product lacks	this product
				the appropriate age warning, therefore a small	listing by the
		(Country of	7.	child could be given the toy, put it in the mouth	online
		Origin:		and choke on it. The product does not comply	marketplace
		Unknown)		with the requirements of the Toy Safety Directive.	
SR/03409/25	Germany	Balloons		Chemical	Removal of
				The rubber in the balloons releases an excessive	this product
		(Country of		amount of nitrosatable substances (measured	listing by the
		Origin:		value 12.91 mg/kg), from which nitrosamines can	online
		China)	The state of the s	be formed. Nitrosamines can cause cancer if	marketplace
				swallowed or through skin contact. A child could	
				be exposed to them if they touch the product or	
				put it in their mouth. The product does not comply	
				with the requirements of the Toy Safety Directive	
				nor with the European standard EN 71-12.	
SR/03410/25	Germany	Balloons	8	Chemical	Removal of
				The material of the balloons releases an	this product
		(Country of		excessive amount of nitrosatable substances	listing by the
		Origin:		(measured value up to 20.1 mg/kg), which	online
		China)		generates nitrosamines. Nitrosamines may cause	marketplace
				cancer through ingestion or dermal exposure. A	
				child could be exposed to them when touching or	
				putting the product in the mouth. The product	
				does not comply with the requirements of the Toy	
				Safety Directive.	
SR/03414/25	UK	Picture		Choking	Recall of the
		book		The product has small parts that can easily	product from
			TO VICOL	detach. Small children may put them in their	end users
		(Country of	BOOK	mouth and choke. The product does not comply	
		Origin:		with the requirements of the Toy Safety Directive.	
		China)			





Alert No.	Notifying	Product	Product Photo	Hazard/ Risk	Measures
CD/02/44/5/25	Country	Disetic dell		Chaminal	Adopted
SR/03415/25	Cyprus	Plastic doll	Street No. Colons	Chemical The head of the doll has an excessive	Withdrawal of
		(Country of			the product
		(Country of		concentration of bis(2-ethylhexyl) phthalate	from the
		Origin:	Mage	(DEHP) (measured value: 31,2 % by weight). This	market
		China)		phthalate may harm the health by causing	
				possible damage to the reproductive system. The	
				product does not comply with the requirements of	
				the Toy Safety Directive nor with the REACH	
				Regulation.	
SR/03417/25	UK	Children's		Strangulation	Recall of the
		swing		The fabric of the swing can form loops during	product from
			© = \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	use. A small child's head or neck can get trapped,	end users
		(Country of		which increases the risk of strangulation. The	
		Origin:		product does not comply with the requirements of	
		China)		the Toy Safety Directive.	
SR/03418/25	Ireland	Crayon set		Chemical	Recall of the
				The migration of strontium and aluminium from	product from
		(Country of	*4	the toy is too high (measured values: 5200 mg/kg	end users
		Origin:	* * *	and 3370 mg/kg, respectively). Ingestion or	
		China)	CLOW IN THE SLAN COLOURING NAT	contact with an excessive quantity of strontium	
				may harm the health of children by irritating their	
				skin and affecting the normal development of	
				their skeleton. Aluminium is toxic for children if	
				ingested. The product does not comply with the	
				requirements of the Toy Safety directive nor with	
				the European standard EN 71-3.	
SR/03419/25	UK	Chew		Choking, Strangulation	Removal of
0.4.000		necklace		The teethers are too small and could fit in a	this product
				child's mouth, which can cause them to choke.	listing by the
		(Country of		Moreover, the cords have a combined length that	online
		Origin:	A. D. L. A.	exceeds the maximum permitted length which	marketplace
		China)		causes a risk of strangulation. The product does	mantotplace
		Jillia)		not comply with the requirements of the Toy	
				Safety Directive.	
SR/03425/25	Slovenia	Soft toy		Choking	Recall of the
011/00420/20	Sioveilla	JOIL LOY			product from
		(Country of		The product has small parts that can easily	·
		(Country of		detach (leather ears, plastic eyes). A small child	end users
		Origin:		could put them in the mouth and choke. The	
		China)		product does not comply with the requirements of	





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
				the Toy Safety Directive nor with the European	
				standard EN 71-1.	
SR/03427/25	Slovenia	Musical toy		Choking	Recall of the
			The state of the s	The toy contains small parts that can easily	product from
		(Country of	C TO THE STATE OF	detach (pink plastic front lights). Small children	end users
		Origin:	8	may put them in the mouth and choke. The	
		China)		product does not comply with the requirements of	
				the Toy Safety Directive nor with the European	
				standard EN 71-1.	
SR/03429/25	Finland	Soft toy	1	Choking	Import
				The plush toy has small parts which can easily	rejected at
		(Country of		detach (nose). A small child may put them in the	border
		Origin:	25-03055-03	mouth and choke. The product does not comply	
		China)	COMMAND AL CAP	with the requirements of the Toy Safety Directive	
				nor with the European standard EN 71-1.	
SR/03431/25	Europe	Toy slime		Chemical	Ban on the
				The migration of boron from the toy slime is too	marketing of
		(Country of		high (measured value up to 1350 mg/kg).	the product
		Origin:	-76 day	Ingestion or contact with an excessive quantity of	and any
		Unknown)		boron may harm the health of children by	accompanying
				damaging the reproductive system. The product	measures
				does not comply with the requirements of Toy	
				Safety Directive nor with the European standard	
				EN 71-3.	
SR/03433/25	Sweden	Inflatable	S ADELION	Chemical	Withdrawal of
		toy boat	Destroy of the second	The plastic material in the product has an	the product
				excessive concentration of bis(2-ethylhexyl)	from the
		(Country of	BANGE COMMECTED IS NOT THE AFTER A MARKET	phthalate (DEHP) (measured value up to 12.8%	market
		Origin:		by weight). This phthalate may harm the health	
		China)		by causing possible damage to the reproductive	
				system. The product does not comply with the	
				REACH Regulation.	
SR/03441/25	Lithuania	Plastic doll		Chemical	Withdrawal of
				The plastic material of the product has an	the product
		(Country of		excessive concentration of bis(2-ethylhexyl)	from the
		Origin:	BABY	phthalate (DEHP), benzyl butyl phthalate (BBP),	market
		China)	Committee of	diisobutyl phthalate (DIBP) and dibutyl phthalate	
				(DBP) (measured values up to 5,9%, 0.01%,	
				0.01%, and 0.11% by weight, respectively).	
				These phthalates may harm the health by	





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
				causing possible damage to the reproductive	
				system. The product does not comply with the	
				requirements of the Toy Safety Directive nor with	
				the REACH Regulation.	
SR/03442/25	Europe	Toy slime		Chemical	Ban on the
				The migration of boron from the toy slime is too	marketing of
		(Country of	PACS AND MALAN I	high (measured value up to 1160 mg/kg).	the product
		Origin:	MACE IN CHINA	Ingestion or contact with an excessive quantity of	and any
		China)		boron may harm the health of children by	accompanying
				damaging the reproductive system. The product	measures
				does not comply with the requirements of the Toy	
				Safety Directive, nor with the European standard	
				EN 71-3.	
SR/03443/25	Europe	Toy slime		Chemical	Ban on the
				The migration of boron from the toy slime is too	marketing of
		(Country of	/ SLIMB	high (measured value up to 1150 mg/kg).	the product
		Origin:	Control Control	Ingestion or contact with an excessive quantity of	and any
		China)		boron may harm the health of children by	accompanying
				damaging the reproductive system. The product	measures
				does not comply with the requirements of the Toy	
				Safety Directive, nor with the European standard	
				EN 71-3.	
SR/03444/25	UK	Toy slime	200	Chemical	Seizure of
				The migration of boron from the toy slime is too	goods
		(Country of	7	high (measured value up to 639 mg/kg). Ingestion	
		Origin:		or contact with an excessive quantity of boron	
		Unknown)		may harm the health of children by damaging the	
				reproductive system. The product does not	
				comply with the requirements of the Toy Safety	
				Directive, nor with the European standard EN 71-	
				3.	
SR/03447/25	UK	Water	TEUSARIE!	Injuries	Recall of the
		balloons	BALLOOKS	The toy has small parts (magnets) with a high	product from
				magnetic flux, which can be easily detached from	end users
		(Country of		the balloon. A child may put the magnets in the	
		Origin:		mouth and swallow them, which may lead to them	
		China)		attracting one another, causing intestinal	
				blockage or perforation. The product does not	
				comply with the requirements of the Toy Safety	
				Directive.	

warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.





Issue no.: 49/25/TCD

Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
SR/03453/25	Czechia	Toy guitar		Environment	Stop of sales
			100	The solders in the product have an excessive	
		(Country of	Paragonal Control	concentration of lead and cadmium (measured	
		Origin:		values up to 40.1% and 0.21% by weight,	
		China)		respectively). Lead and cadmium pose a risk to	
				the environment. The product does not comply	
				with the requirements of the Directive on the	
				restriction of the use of certain hazardous	
				substances in electrical and electronic equipment	
				(RoHS 2 Directive).	
SR/03454/25	Czechia	Headband	Resist	Environment	Stop of sales
				The solders in the product have an excessive	
		(Country of		concentration of lead (measured value 49.9% by	
		Origin:		weight). Lead poses a risk to the environment.	
		China)		The product does not comply with the	
				requirements of the Directive on the restriction of	
				the use of certain hazardous substances in	
				electrical and electronic equipment (RoHS 2	
				Directive).	
SR/03455/25	Czechia	Toy car with	MAGICAL	Environment	Withdrawal of
		track		The solders in the product have an excessive	the product
			00	concentration of lead (measured value: 55% by	from the
		(Country of	Glower In The Cark :	weight). Lead poses a risk to the environment.	market
		Origin:		The product does not comply with the	
		China)		requirements of the Directive on the restriction of	
				the use of certain hazardous substances in	
				electrical and electronic equipment (RoHS 2	
				Directive).	
SR/03457/25	Czechia	Musical toy		Environment	Stop of sales
			- (23131313 o) ·	The solders in the product have an excessive	
		(Country of		concentration of lead (measured value up to	
		Origin:	9	62.3% by weight). Lead poses a risk to the	
		Unknown)		environment. The product does not comply with	
				the requirements of the Directive on the	
				restriction of the use of certain hazardous	
				substances in electrical and electronic equipment	
				(RoHS 2 Directive).	





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
SR/03460/25	France	(Country of Origin: China)		Chemical The plastic material of the product has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 6,65%). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.	Withdrawal of the product from the market
SR/03463/25	Finland	Toy rattle (Country of Origin: Unknown)	C G SAN C BUILDING THE CONTROL OF	Choking The rattle has protruding parts. A small child may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Recall of the product from end users
SR/03464/25	Ireland	Baby sleeping bag (Country of Origin: Ireland)		Suffocation The material of the neck opening may cover the nose and /or mouth of the child during sleep or while unsupervised. This could lead the child to suffocate. The product does not comply with the General Product Safety Regulation.	Recall of the product from end users
SR/03466/25	France	Musical toy (Country of Origin: China)		Choking The product has small parts (plastic fastening) that can easily detach. Small children may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Withdrawal of the product from the market
SR/03468/25	France	Bath toy (Country of Origin: China)	SLIDEMAY TOTAL AND TOTAL A	Choking The product has small parts (duck figurines in the shape of ducks, spheres and rounded cylinders) that can easily detach. Small children may put them in the mouth and choke. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	Warning consumers of the risks





Issue no.: 49/25/TCD

Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
SR/03470/25	Hungary	Rattle set		Choking	Ban on the
				The rattles' elements can easily break, resulting	marketing of
		(Country of	7117	in small parts. A small child may put them in the	the product
		Origin:		mouth and choke. The product does not comply	and any
		China)		with the requirements of the Toy Safety Directive	accompanying
				nor with the European standard EN 71-1.	measures
SR/03472/25	Slovakia	Toy ball		Environment	Warning
			PLAYLIKE A PRO	The solders in the product have an excessive	consumers of
		(Country of	1	concentration of lead (measured value up to	the risks
		Origin:	STATE AND STATE OF ST	40.6% by weight). Lead poses a risk to the	
		China)		environment. The product does not comply with	
				the requirements of the Directive on the	
				restriction of the use of certain hazardous	
				substances in electrical and electronical	
				equipment (RoHS 2 Directive).	
SR/03476/25	Slovakia	Electronic		Environment	Warning
		game		The solders in the product have an excessive	consumers of
				concentration of lead (measured value up to	the risks
		(Country of		40.6% by weight) and cadmium (measured value	
		Origin:		up to 0.112% by weight). Lead and cadmium	
		China)		pose a risk to the environment. The product does	
				not comply with the requirements of the Directive	
				on the restriction of the use of certain hazardous	
				substances in electrical and electronical	
				equipment (RoHS 2 Directive).	
SR/03477/25	UK	Inflatable		Asphyxiation	Import
		toy		The plastic bag packaging is too thin. If a child	rejected at
			CRIO CRIO	places the plastic bag over their head, they could	border
		(Country of		asphyxiate. The product does not comply with the	
		Origin:		requirements of the Toy Safety Directive.	
		China)			
SR/03484/25	UK	Baby		Suffocation	Withdrawal of
		sleeping		The product has no arm openings. As a result,	the product
		bag	6	the baby may slip down into the sleep bag and	from the
				suffocate. This product does not comply with	market
		(Country of	公 人发	General Product Safety Regulation.	
		Origin:			
		Unknown)			





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
SR/03491/25	UK	Light up toy		Choking	Import
			LIGHT UP STARS	The product is not sufficiently resistant to	rejected at
		(Country of		mechanical impact. It can break into small parts	border
		Origin:		upon impact. A small child may put them in their	
		China)		mouth and choke. This product does not comply	
				with the requirements of the Toy Safety Directive.	
SR/03520/25	Hungary	Rattle set	2 10 10	Choking	Withdrawal of
				The rattle has a protruding part (such as the	the product
		(Country of	661	ladybug, monkey and starfish). A child could put it	from the
		Origin:	350/0	in the mouth, which could block the airways and	market
		China)		cause choking. The product does not comply with	
				the requirements of the Toy Safety Directive nor	
				with the European standard EN 71-1.	
SR/03523/25	Finland	Toy LED		Chemical, Choking	Recall of the
		bracelet	Magne Colors 10 Magnetic 10 Ma	The battery compartment can easily be opened	product from
			Similar and the state of the st	without use of any tools and the button cell	end users
		(Country of	Market Market State Company of the C	batteries inside are easily accessible. A child may	
		Origin:		put them in the mouth and swallow them, which	
		Unknown)		could cause damage to the child's gastrointestinal	
		,		tract and/or choking. The product does not	
				comply with the requirements of the Toy Safety	
				Directive nor with the European standard EN	
				62115.	
SR/03524/25	Lithuania	Toy gun set		Choking	Withdrawal of
		3	PISTOL CHILD	The bubbles which are used as projectiles for the	the product
		(Country of	San Maria	toy gun are swelling materials, expanding 50% in	from the
		Origin:		size when in contact with water. If a child puts	market
		China)	TOTAL COLD IN A COLD IN THE CO	them in the mouth or swallows it, the contact with	a.r.ot
		,		saliva or stomach liquids will cause the projectiles	
				to expand, which can result in occlusion of the	
				respiratory track or intestinal blockage. The	
				product does not comply with the requirements of	
				the Toy Safety Directive nor with the European	
				standard EN 71-1.	
SR/03527/25	Lithuania	Mobile toy		Choking	Withdrawal of
01/100021/20	Littiualila	Mobile toy		The product has several small parts (for example	the product
		(Country of		the ball-shaped detachable components, the	from the
		<u> </u>			
		Origin:	Music	heart shapes of the hanging elements) which can	market
		China)		easily detach. Moreover, the hanging element of	
				the toy can also easily break, releasing small	





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
				parts. Small children may put them in the mouth	
				and choke. The product does not comply with the	
				requirements of the Toy Safety Directive nor with	
				the European standard EN 71-1.	
SR/03532/25	Finland	Toy LED		Chemical, Choking	Recall of the
		wand	Magnes 10 600 via 600	The battery compartment can easily be opened	product from
			The second secon	without use of any tools and the button cell	end users
		(Country of	9	batteries inside are easily accessible. A child may	
		Origin:		put them in the mouth and swallow them, which	
		Unknown)		could cause damage to the child's gastrointestinal	
				tract and/or choking. The product does not	
				comply with the requirements of the Toy Safety	
				Directive nor with the European standard EN	
				62115.	
SR/03533/25	Finland	Toy bricks		Chemical, Choking	Recall of the
		set	Allegen - 100 Al	The battery compartment can easily be opened	product from
				without use of any tools and the button cell	end users
		(Country of	100 (100 m) (1	batteries inside are easily accessible. A child may	
		Origin:		put them in the mouth and swallow them, which	
		Unknown)		could cause damage to the child's gastrointestinal	
				tract and/or choking. The product does not	
				comply with the requirements of the Toy Safety	
				Directive nor with the European standard EN	
				62115.	
SR/03536/25	Lithuania	Toy unicorn	1	Choking	Withdrawal of
				The product has small parts (plastic flakes). Small	the product
		(Country of		children may put them in the mouth and choke.	from the
		Origin:		The product does not comply with the	market
		China)		requirements of the Toy Safety Directive nor with	
				the European standard EN 71-1.	
SR/03537/25	Hungary	Rattle set	Rattle	Choking	Recall of the
				The rattle can easily break, releasing small plastic	product from
		(Country of	Treating Co.	parts. A child may put these small parts in the	end users
		Origin:	300	mouth and choke. The product does not comply	
		China)	N. C.	with the requirements of the Toy Safety Directive	
				nor with the relevant European standard EN 71-1.	





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
SR/03540/25	Finland	Toy flashing slingshot (Country of Origin: Unknown)		Chemical, Choking The battery compartment can easily be opened without use of any tools and the button cell batteries inside are easily accessible. A child may put them in the mouth and swallow them, which could cause damage to the child's gastrointestinal tract and/or choking. The product does not comply with the requirements of the Toy Safety	Removal of this product listing by the online marketplace
SR/03541/25	Finland	Medical kit toy (Country of Origin: China)		Directive nor with the European standard.EN 62115. Chemical The plastic material in the product has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 34.9% by weight). This phthalate may harm the health by causing possible damage to the reproductive system. The product does not comply with the requirements of the Toy Safety Directive nor with	Import rejected at border
SR/03542/25	Finland	Toy LED pen (Country of Origin: Unknown)		the REACH Regulation. Chemical, Choking The battery compartment can easily be opened without use of any tools and the button cell batteries inside are easily accessible. A child may put them in the mouth and swallow them, which could cause damage to the child's gastrointestinal tract and/or choking. This product does not comply with the requirements of the Toy Safety Directive.nor with the European standard EN 62115.	Recall of the product from end users
SR/03543/25	Cyprus	Plastic doll set (Country of Origin: China)		Chemical The plastic material' of the head of the doll has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value: 23.7% by weight). This phthalate may harm the health by causing possible damage to the reproductive system. The product does not comply with the requirements of the Toy Safety Directive nor with the REACH Regulation.	Withdrawal of the product from the market





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
SR/03545/25	Poland	Wooden		Choking	Warning
		stacker toy		The toy has an unprotected protruding part (base	consumers of
				pin), a detachable small part (orange puck) and	the risks
		(Country of		the shape and dimension of the toy's element	
		Origin:	Onethin	(red ball) are inadequate. A child may put them in	
		China)		the mouth and swallow them which could cause	
				choking. The product does not comply with the	
				requirements of the Toy Safety Directive nor with	
				the European standard EN 71-1.	
SR/03553/25	Ireland	Toy car		Choking	Removal of
			THEN	The product has small parts that can easily	this product
		(Country of	ASCYLINDER	detach. A small child may put them in their mouth	listing by the
		Origin:	RI · KO	and choke. Moreover, safety information is	online
		China)		missing. The product does not comply with the	marketplace
				requirements of the Toy Safety Directive.	
SR/03555/25	Hungary	Toy rattle		Choking	Withdrawal of
			akuku	The product contains small parts (the balls) that	the product
		(Country of		can easily detach. A small child may put them in	from the
		Origin:	Port of Early Okuku	the mouth and choke. The product does not	market
		Poland)		comply with the requirements of the Toy Safety	
		ŕ		Directive nor with the relevant European standard	
				EN 71-1.	
SR/03556/25	UK	Soft toys		Choking	Import
			Y 22 1	The product contains small parts (the plastic	rejected at
		(Country of		eyes) that can easily detach. A small child may	border
		Origin:		put them in the mouth and choke. The product	
		China)		does not comply with the requirements of the Toy	
		,		Safety Directive.	
SR/03557/25	Poland	Magnetic		Injuries	Withdrawal of
		toy	BELLEY MAJORITYCENG Same COP	The toy contains small magnets with a high	the product
		_	PRESENTATION OF THE PRESEN	magnetic flux (measured value up to 0.73	from the
	(Country of	CEOSE SUCCESSION OF THE PROPERTY OF THE PROPER	T2mm2). If a child swallows the small magnets,	market	
	Origin:		they could attract one another causing intestinal		
		China)		blockage or perforation. The product does not	
		,		comply with the requirements of the Toy Safety	
				Directive nor with the European standard EN 71-	
				1.	



Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
SR/03566/25	UK	Plush toy	Ω.	Chemical, Choking	Seizure of
			191	The product has a small part that can easily	goods from
		(Country of		detach (the metal ring). A small child could put it	store. Goods
		Origin:		in the mouth and choke. Additionally, the plastic	are due to be
		China)		material of the toy has an excessive	destroyed
				concentration of bis(2-ethylhexyl) phthalate	also.
				(DEHP) and dibutyl phthalate (DBP) (measured	
				values up to 0.02% and 1.64% by weight,	
				respectively). These phthalates may harm the	
				health by causing possible damage to the	
				reproductive system. The product does not	
				comply with the requirements of the Toy Safety	
				Directive.	
SR/03567/25	Iceland	Toy swing		Choking, Strangulation	Recall of the
				Due to the incomplete instructions provided, the	product from
		(Country of		swing can be installed too high, leaving openings	end users
		Origin:		where the child can have its head entangled,	
		China)		leading to strangulation. Moreover, a fragment of	
				excess material is easily accessible and can	
				easily detach. A small child could put it in the	
				mouth and choke. The product does not comply	
				with the requirements of the Toy Safety Directive	
				nor with the European standards EN 71-1 and EN	
				71-8.	
SR/03569/25	Iceland	Climbing		Cuts, Damage to Sight, Injuries	Recall of the
		toy		The toy has a sharp corner; which could cause	product from
				injuries to the child, including eye damage.	end users
		(Country of		Moreover, the toy is not stable enough and can	
		Origin:		cause the child to fall, and suffer injuries. The	
		Latvia)		product does not comply with the requirements of	
				the Toy Safety Directive nor with the European	
				standards EN71-1 and EN 71-8.	
SR/03570/25	Luxembou	Key ring	0	Choking	Recall of the
	rg	with soft		Small parts (legs, arms and keychain) can easily	product from
		toy		detach. As a result, a small child could put them	end users
				in the mouth and choke. Furthermore, the fibrous	
		(Country of		stuffing material of the toy is easily accessible. A	
		Origin:		small child could put stuffing material in their	
		China)		mouth and choke. The product does not comply	





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
				with the requirements of the Toy Safety Directive,	
				nor with the European standard EN 71-1.	
SR/03573/25	Spain	Toy baby bottles		Choking The product is too small. A child can put it in the mouth and choke. The product does not comply	Ban on the marketing of the product
		(Country of Origin: China)		with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.	and any accompanying measures
SR/03579/25	UK	Inflatable		Asphyxiation	Import
		toy (Country of Origin:		The plastic bag packaging is too thin. If a child places the plastic bag over their head, they could asphyxiate. The product does not comply with the requirements of the Toy Safety Directive.	rejected at border
		China)			
SR/03592/25	Poland	Toy		Injuries The product can shoot improvised projectiles, such as a pencil, with excessive kinetic energy,	Withdrawal of the product from the
		(Country of Origin: China)	SPORT THE PRINT PARTY CANAL	which can cause injuries. The product does not comply with the requirements of the Toy Safety Directive, nor with the European standard EN 71-1.	market
SD/03504/35	Finland	Toy horse		Chemical	Making the
SR/03594/25	Finiand	(Country of Origin: China)	E.1	The material of the bridle contains an excessive amount of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 21% by weight). DEHP may harm the health of children by causing possible damage to their reproductive system. This product does not comply with the requirements of the Toy Safety Directive, nor with the REACH Regulation.	Making the marketing of the product subject to prior conditions
SR/03596/25	France	Battery-		Chemical, Choking	Recall of the
		powered		The battery compartment breaks easily, leaving	product from
		toy (Country of		the batteries accessible. A child may put them in the mouth and choke. The button batteries could cause damage to the child's gastrointestinal tract	end users
		Origin:		if they are ingested. The product does not comply	
		China)		with the requirements of the Toy Safety Directive	
				nor with the European standard EN 62115.	





Issue no.: 49/25/TCD

Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
SR/03600/25	Ireland	Children's		Injuries	Withdrawal of
		car seat	The same	The buckle may become deformed,	the product
			A Y FOL	compromising the performance of the buckle in	from the
		(Country of		the event of an accident. This may lead to serious	market
		Origin:		injury. The product does not comply with the	
		China)		regulation on the approval and market	
				surveillance of motor vehicles and their trailers,	
				and of systems, components and separate	
				technical units intended for such vehicles.	
SR/03609/25	UK	Baby		Suffocation	Removal of
		sleeping		The sleeping bag has a hood, which may cover	this product
		bag		the mouth and/or nose area of the baby. This	listing by the
				could lead the child to suffocate. The product	online
		(Country of		does not comply with the requirements of the	marketplace
		Origin:		General Product Safety Directive.	
		Unknown)			
SR/03612/25	Ireland	Plastic toy		Choking	Removal of
				The product lacks the appropriate age warning,	this product
		(Country of		therefore a small child could be given the toy, put	listing by the
		Origin:		it in the mouth and choke. The product does not	online
		China)		comply with the requirements of the Toy Safety	marketplace
				Directive and the relevant European standard EN	
				71-1.	
SR/03613/25	Ireland	Plastic toy	-	Choking	Removal of
				The product lacks the appropriate age warning,	this product
		(Country of		therefore a small child could be given the toy, put	listing by the
		Origin:	TO THE N	it in the mouth and choke. The product does not	online
		China)		comply with the requirements of the Toy Safety	marketplace
				Directive and the relevant European standard EN	
				71-1.	
SR/03614/25	Ireland	Plastic toy	Total Vision	Choking	Removal of
			The state of the s	The product lacks the appropriate age warning,	this product
		(Country of	To Associate the Control of the Cont	therefore a small child could be given the toy, put	listing by the
		Origin:	Constitution of the consti	it in the mouth and choke. The product does not	online
		China)		comply with the requirements of the Toy Safety	marketplace
				Directive and the relevant European standard EN	
				71-1.	





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
SR/03624/25	Germany	Soft toy		Choking	Removal of
			Ki Carlo	The product has small parts that can easily	this product
		(Country of		detach (eyes and nose). A small child could put	listing by the
		Origin:		them in the mouth and choke. The product does	online
		China)		not comply with the requirements of the Toy	marketplace
				Safety Directive nor with the European standard	
				EN 71-1.	
SR/03631/25	Slovakia	Soft toy	* *	Chemical	Withdrawal of
			TO THE STATE OF TH	The battery compartment can easily be opened	the product
		(Country of		without use of any tools and the batteries inside	from the
		Origin:	Sa Ki	are easily accessible. A child may put them in the	market
		China)		mouth and swallow them, which could cause	
				damage to the child's gastrointestinal tract. The	
				product does not comply with the requirements of	
				the Toy Safety Directive, nor with the European	
				standard EN 62115.	
SR/03632/25	UK	Baby	7	Suffocation	Removal of
		sleeping		The sleeping bag has a hood, which may cover	this product
		bag		the mouth and/or nose area of the baby. This	listing by the
				could lead the child to suffocate. The product	online
		(Country of		does not comply with the requirements of the	marketplace
		Origin:		General Product Safety Directive.	
		Unknown)			
SR/03633/25	Lithuania	Toy gun set	Tooks -	Choking	Withdrawal of
				Small parts (the suction tube from the foam	the product
		(Country of	The state of the s	projectiles) can easily detach. A small child may	from the
		Origin:	The state of the s	put them in the mouth and choke. The product	market
		China)		does not comply with the requirements of the Toy	
				Safety Directive, nor with the European standard	
				EN 71-1.	
SR/03635/25	Slovakia	Toy		Chemical	Withdrawal of
		headband		The battery compartment can easily be opened	the product
				without use of any tools and the batteries inside	from the
		(Country of		are easily accessible. A child may put them in the	market
		Origin:	- 1. C. 1/18 S.	mouth and swallow them, which could cause	
		China)		damage to the child's gastrointestinal tract. The	
				product does not comply with the requirements of	
				the Toy Safety Directive, nor with the European	
				standard EN 62115.	

warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
SR/03637/25	Lithuania	Тоу	0	Choking	Withdrawal of
		expandable	Chilleouth	The unicorn figurine expands more than 50% in	the product
		figurines		size when in contact with water. If a child puts it in	from the
				the mouth or swallows it, the contact with saliva	market
		(Country of	POR STATE	or stomach liquids will cause the figurine to	
		Origin:		expand, which can result in occlusion of the	
		China)		respiratory track or intestinal blockage. The	
				product does not comply with the requirements of	
				the Toy Safety Directive, nor with the European	
				standard EN 71.	
SR/03638/25	Poland	Plastic ball		Chemical	Withdrawal of
				The toy contains an excessive amount of dibutyl	the product
		(Country of		phthalate (DBP) (measured value up to 19.7% by	from the
		Origin:		weight). This phthalate may harm the health of	market
		China)		children, possibly by causing damage to the	
				reproductive system. The product does not	
				comply with the REACH Regulation.	
SR/03639/25	Slovakia	Battery-		Chemical	Warning
011/00000/20	Olovania	operated	6. CA	The battery compartment can easily be opened	consumers of
		doll		without the use of any tools and the button cell	the risks
				batteries inside are easily accessible. A child may	and none
		(Country of		put them in the mouth and swallow them, which	
		Origin:		could cause damage to the child's gastrointestinal	
		China)		tract. The product does not comply with the	
		Omna)		requirements of the Toy Safety Directive, nor with	
				the European standard EN 62115.	
SR/03643/25	Lithuania	Toy rattle			Withdrawal of
SR/03043/23	Littiuatila	Toy rattle	ACE SUACO	Choking The product contains small parts (the ball and the	the product
		(Country of		· · · ·	
		(Country of		hooks) that can easily detach from the toy. A	from the
		Origin:		small child may put them in the mouth and choke	market
		China)		on them. The product does not comply with the	
				requirements of the Toy Safety Directive nor with	
OD/00044/05	1.50	0-614		the European standard EN 71-1.	AACO - In.
SR/03644/25	Lithuania	Soft toy		Choking	Withdrawal of
		(0)		The product contains small parts (the eyes) that	the product
		(Country of		can easily detach from the toy. A small child may	from the
		Origin:		put them in the mouth and choke on them. The	market
		China)	THE RESERVE AND ADDRESS OF THE PARTY OF THE	product does not comply with the requirements of	
				the Toy Safety Directive nor with the European	
				standard EN 71-1.	





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
SR/03645/25	UK	Sticker set		Chemical, Choking	Recall of the
				The plastic material of the product has an	product from
		(Country of	68 = Q = 2) = 2)	excessive concentration of diisobutyl phthalate	end users
		Origin:		(DIBP), dibutyl phthalate (DBP) and bis(2-	
		India)		ethylhexyl) phthalate (DEHP) (measured values:	
				0.94 %, 0.06% and 4.8% by weight, respectively).	
				These phthalates may harm the health by	
				causing possible damage to the reproductive	
				system. Moreover, the stickers fit wholly inside	
				the small parts cylinder, presenting a potential	
				choking risk to young children. The product does	
				not comply with the requirements of the Toy	
				Safety Directive.	
SR/03647/25	Ireland	Plastic toy		Choking	Removal of
			DER .	The product lacks the appropriate age warning,	this product
		(Country of		therefore a small child could be given the toy, put	listing by the
		Origin:		it in the mouth and choke. The product does not	online
		Unknown)		comply with the requirements of the Toy Safety	marketplace
				Directive and the relevant European standard EN	
				71-1.	
SR/03648/25	France	Plastic toy		Chemical, Choking	Destruction of
			_	The battery compartment breaks easily, leaving	the product
		(Country of		the batteries accessible. A child may put them in	
		Origin:		the mouth and choke. The button batteries could	
		China)		cause damage to the child's gastrointestinal tract	
				if they are ingested. The product does not comply	
				with the requirements of the Toy Safety Directive	
				nor with European standard EN 62115.	
SR/03695/25	Ireland	Crib mobile		Choking	Removal of
				The product has small parts that can easily	this product
		(Country of		detach. A small child may put them in their mouth	listing by the
		Origin:		and choke. Moreover, there are insufficient and	online
		Unknown)		contradictory warnings about the safety and	marketplace
				placement of the product. The product does not	
				comply with the requirements of the Toy Safety	
				Directive.	





Issue no.: 49/25/TCD

Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
SR/03696/25	UK	Baby		Suffocation	Removal of
		sleeping	H. T. T.	The sleeping bag has a hood, which may cover	this product
		bag		the mouth and/or nose area of the baby. This	listing by the
			THE PARTY OF THE P	could lead the child to suffocate. The product	online
		(Country of	***	does not comply with the requirements of the	marketplace
		Origin:		General Product Safety Directive.	
		China)			
SR/03698/25	Lithuania	Toy puffer	- Althou	Strangulation	Withdrawal of
		ball		The toy can stretch too long. A child could swing	the product
			60	the toy around the head and twist it around the	from the
l		(Country of		neck, causing strangulation. The product does	market
		Origin:		not comply with the requirements of the Toy	
		China)		Safety Directive nor with the European standard	
				EN 71-1.	
SR/03704/25	Lithuania	Anti-stress	P DON'T	Choking	Withdrawal of
		toy	(d) (3.15) (1.9)	The toy has small, removable parts (plastic teddy	the product
				bear, glitter and balls). Small children may put	from the
		(Country of		them in the mouth and choke. The product does	market
		Origin:		not comply with the requirements of the Toy	
		China)		Safety Directive, nor with the European standard	
				EN 71-1.	
SR/03706/25	France	Toy light-up		Chemical, Choking	Destruction of
		wand	1.30	The battery compartment can easily be opened	the product
				without use of any tools and the button batteries	
		(Country of		inside are easily accessible. A child may put them	
		Origin:		in the mouth and swallow them, which could	
		China)		cause damage to the child's gastrointestinal tract	
				and/or choking. The product does not comply with	
				the requirements of the Toy Safety Directive, nor	
				with the European standard EN 62115.	
SR/03708/25	Slovakia	Toy swing		Strangulation	Recall of the
		with horn		Due to the inadequate design of the product and	product from
				the incomplete instructions, the swing can be	end users
		(Country of		assembled incorrectly, leaving open gaps. A	
		Origin:		child's head or neck may become trapped in	
		Hungary)		these gaps, causing the risk of strangulation. The	
				product does not comply with the requirements of	
				the Toy Safety Directive nor with the European	
				standard EN 71-8.	





Issue no.: 49/25/TCD

Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
SR/03709/25	Slovakia	Toy sword		Chemical	Warning
				The battery compartment can easily be opened	consumers of
		(Country of	•=====================================	without use of any tools and the batteries inside	the risks
		Origin:		are easily accessible. A child may put them in the	
		China)		mouth and swallow them, which could cause	
				damage to the child's gastrointestinal tract. The	
				product does not comply with the requirements of	
				the Toy Safety Directive, nor with the European	
				standard EN 62115.	
SR/03711/25	Lithuania	Plastic doll		Chemical	Withdrawal of
				The plastic material of the product has an	the product
		(Country of		excessive concentration of bis(2-ethylhexyl)	from the
		Origin:		phthalate (DEHP), benzyl butyl phthalate (BBP),	market
		China)	(and the state of	diisobutyl phthalate (DIBP) and dibutyl phthalate	
				(DBP) (measured values: 2.0%, 0.01%, 0.01%	
				and 0.78% by weight, respectively). These	
				phthalates may harm the health by causing	
				possible damage to the reproductive system. The	
				product does not comply with the requirements of	
				the Toy Safety Directive.	
SR/03712/25	Lithuania	Plastic doll		Chemical	Withdrawal of
				The plastic material of the product has an	the product
		(Country of		excessive concentration of bis(2-ethylhexyl)	from the
		Origin:	Cran C	phthalate (DEHP), benzyl butyl phthalate (BBP),	market
		China)	S. Suprise.	diisobutyl phthalate (DIBP) and dibutyl phthalate	
				(DBP) (measured values: 0.45%, 0.01%, 0.01%,	
				and 0.013% by weight, respectively). These	
				phthalates may harm the health by causing	
				possible damage to the reproductive system. The	
				product does not comply with the requirements of	
				the Toy Safety Directive.	
SR/03715/25	Slovakia	Activity		Choking	Warning
		play mat	LUDI @	The product contains small parts (the screws of	consumers of
				the steering wheel) that can easily detach. A	the risks
		(Country of	ACTIVITÉ VOITURE / ACTIVITY CAR 0	small child may put them in the mouth and choke.	
		Origin:	THE RESERVE AND DESCRIPTION OF THE PERSON NAMED IN	The product does not comply with the	
		China)		requirements of the Toy Safety Directive nor with	
				the European standard EN 71-1.	



Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
SR/03716/25	Lithuania	Toy rattle		Choking	Withdrawal of
				The toy contains small parts (the ball) that can	the product
		(Country of		easily detach. A small child may put them in the	from the
		Origin:	Love Toys	mouth and choke. The product does not comply	market
		China)		with the requirements of the Toy Safety Directive	
		,		nor with the European standard EN 71-1.	
SR/03717/25	France	Fancy-		Burns	Warning
		dress	dh.	The costume has inflammable material (light blue	consumers of
		costume		fabric). The costume may catch fire if worn close	the risks
				to an ignition source, resulting in burns. The	
		(Country of		product does not comply with the requirements of	
		Origin:		the Toy Safety Directive nor with the European	
		China)		standard EN 71-2.	
SR/03739/25	Spain	Inflatable	Total Care	Choking	Withdrawal of
		swim seat		The product contains small parts (cap of inflation	the product
				valve) that can easily detach. A small child may	from the
		(Country of		put them in the mouth and choke. The product	market
		Origin:		does not comply with the requirements of the Toy	
		China)		Safety Directive nor with the European standard	
				EN 71-1.	
SR/03743/25	Latvia	Modelling		Chemical	Removal of
		clay		The migration of boron from the clay is too high	this product
			The second secon	(measured value up to 2025 mg/kg). Ingestion or	listing by the
		(Country of	The second secon	contact with an excessive quantity of boron may	online
		Origin:	The state of the s	harm the health of children by damaging the	marketplace
		China)		reproductive system. The product does not	
				comply with the requirements of the Toy Safety	
				Directive nor with the European standard EN 71-	
				3.	
SR/03747/25	Slovenia	Magnetic		Injuries, Suffocation	Withdrawal of
		toy	To make the same to the same t	The toy contains small magnets with a high	the product
			()	magnetic flux (measured value up to 210	from the
		(Country of	-	kG ² mm ²). If a child swallows the small magnets,	market
		Origin:		they could attract one another causing intestinal	
		China)		blockage or perforation. Moreover, the plastic bag	
				of the packaging is non-permeable. If a child	
				plays with the packaging, the plastic can cover	
				the mouth and nose, causing the child to	
				suffocate. The product does not comply with the	







Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
				requirements of the Toy Safety Directive nor with	•
				the European standard EN 71-1.	
SR/03751/25	Spain	Inflatable	ZEBRA KIDS	Choking	Recall of the
		swim seat	SHIMRING	The product contains small parts (cap of inflation	product from
			0	valve) that can easily detach. A small child may	end users
		(Country of		put them in the mouth and choke. Moreover, the	
		Origin:	The state of the s	toy is missing warnings for use. The product does	
		China)		not comply with the requirements of the Toy	
				Safety Directive nor with the European standard	
				EN 71-1.	
SR/03752/25	Spain	Inflatable	BABY BOAT	Asphyxiation	Withdrawal of
		swim seat	SIZE 700 Z	The plastic bag packaging is too thin. If a child	the product
				places the plastic bag over their head, they could	from the
		(Country of		asphyxiate. The product does not comply with the	market
		Origin:	CONTROL CONTRO	requirements of the Toy Safety Directive.	
		China)			
SR/03760/25	Germany	Pull-along		Choking	Recall of the
		toy car		The toy contains small parts (the wheel) that can	product from
				easily detach. A small child may put it in the	end users
		(Country of		mouth and choke. The product does not comply	
		Origin:		with the requirements of the Toy Safety Directive	
		Germany)		nor with the European standard EN 71-1.	
SR/03773/25	Slovenia	Wooden toy	SOTTO SIND	Choking	Withdrawal of
			NE STORY	The toy contains small parts (central white pin)	the product
		(Country of	6 5	that can easily detach. A small child may put	from the
		Origin:	The same	them in the mouth and choke. The product does	market
		China)	Penguina hara	not comply with the requirements of the Toy	
				Safety Directive nor with the European standard	
				EN 71-1.	
SR/03797/25	UK	Toy set	Rope Fo	Choking	Recall of the
				The toy contains small parts (the key) that can	product from
		(Country of		easily detach. A small child may put them in the	end users
		Origin:		mouth and choke. The product does not comply	
		China)	Sct.	with the requirements of the Toy Safety Directive.	
SR/03800/25	Spain	Inflatable		Choking	Withdrawal of
		toy		The cap of the inflation valve can easily detach,	the product
			AN THE PROPERTY OF	generating small parts. A small child may put	from the
		(Country of		them in the mouth and choke. The product does	market
		Origin:	0.60	not comply with the requirements of the Toy	
		China)			

warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.





Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
				Safety Directive nor with the European standard	
				EN 71-	
SR/03802/25	UK	Playpen		Asphyxiation	Import
				A child can access the netted hoop and get their	rejected at
		(Country of		head trapped. If the child is unattended when this	border
		Origin:		happens, the restricted air flow could lead to	
		China)		asphyxiation. This product does not meet the	
				requirements of the Toy Safety Directive.	
SR/03805/25	Spain	Inflatable	SAN LITOYS FLOATING ROW	Asphyxiation	Recall of the
		toy		The plastic bag packaging is too thin. If a child	product from
				places the plastic bag over their head, they could	end users
		(Country of	120cm	asphyxiate. The product does not comply with the	
		Origin:	A process on the cold of the c	requirements of the Toy Safety Directive.nor with	
		China)		the European standard EN 71-1.	
SR/03813/25	Lithuania	Antistress	A CONTRACTOR	Choking	Withdrawal of
		toy		The toy has small parts (removable components	the product
				such as the balls and the sprinkles). Small	from the
		(Country of	1	children may put them in the mouth and choke.	market
		Origin:		The product does not comply with the	
		China)		requirements of the Toy Safety Directive nor with	
				the European standard EN 71-1.	
SR/03827/25	Poland	Plastic toy	1.3	Chemical	Warning
		,	FREE BOOTOTS of DEVIACION IS of DEVIACION IS OUNCEZEMAN CONTEZEMAN CONTEZ	The toy has an excessive concentration of bis(2-	consumers of
		(Country of	STREET, Chickenia va su deplant, Chicaga Sarvania, Chicaga Sarvani	ethylhexyl) phthalate (DEHP) (measured value:	the risks
		Origin:	Seatment of the device on the device of the control	up to 12.3% by weight). This phthalate may harm	
		China)	5"904326"459298">	the health of children, causing possible damage	
		ŕ		to the reproductive system. The product does not	
				comply with the REACH Regulation.	
SR/03828/25	Ireland	Toy slime		Chemical	Removal of
				The migration of boron from the toy slime is too	this product
		(Country of	Claw CO A TO	high (measured value up to 798 mg/kg). Ingestion	listing by the
		Origin:	3lim	or contact with an excessive quantity of boron	online
		China)		may harm the health of children by damaging the	marketplace
		,		reproductive system. The product does not	,
				comply with the requirements of the Toy Safety	
				Directive, nor with the European standard EN 71-	
				3.	





Issue no.: 49/25/TCD

Alert No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Measures Adopted
SR/03837/25	Latvia	Toy rattle	6 NG	Choking	Removal of
				The toy contains small parts (the bells) that can	this product
		(Country of		easily detach. A small child may put them in the	listing by the
		Origin:	-	mouth and choke. The product does not comply	online
		China)	\mathbf{U}	with the requirements of the Toy Safety Directive	marketplace
				nor with the European standard EN 71-1.	
SR/03838/25	UK	Playpen	Baby Play Gro Mat	Choking	Withdrawal of
				The product contains small parts (squeaker) that	the product
		(Country of		can easily detach from the toy. A small child may	from the
		Origin:		put them in the mouth and choke on them. The	market
		China)		product does not comply with the requirements of	
				the Toy Safety Directive.	
SR/03841/25	Latvia	Soft toy		Choking, Suffocation	Removal of
				The product contains small parts (the eyes) that	this product
		(Country of		can easily detach from the toy batteries.	listing by the
		Origin:		Moreover, the batteries and fibrous stuffing	online
		China)		material of the toy are easily accessible. A small	marketplace
				child could put them in mouth and choke. The	
				product does not comply with the requirements of	
				the Toy Safety Directive nor with the European	
				standard EN 71-1.	
SR/03846/25	France	Bow toy set		Choking	Recall of the
				The product has small parts (the projectiles'	product from
		(Country of		suction cups) which may easily detach. A small	end users
		Origin:	Z Company	child may put them in the mouth and choke. The	
		France)		product does not comply with the Toy Safety	
				Directive nor with the European standard EN 71-	
				1.	





Safety Gate: the EU rapid alert system for dangerous non-food products

"Safety Gate", the EU rapid alert system (formerly known as "RAPEX"), enables the rapid exchange of information between 31 European countries and the European Commission on non-food dangerous products found on the market posing a risk to the health and safety of consumers.

A weekly overview of the alerts on those products is published in English for free on https://ec.europa.eu/safety-gatealerts/screen/search?resetSearch=true. The measures taken in the notifying country in order to restrict such products' marketing or use can be ordered by national authorities ("compulsory measures") or be taken directly by producers and distributors ("voluntary measures").

The official contact points of the Member and EFTA-EEA States provide the information published in these weekly overviews. Under the terms of Annex II.10 of the General Product Safety Directive (2001/95/EC) responsibility for the information provided lies with the notifying party. The Commission does not take any responsibility for the accuracy of the information provided.





Recall Summary - US Toys / Children's Products

CPSC Recall List (Oct 2025)

	Notifying				
Recall No.	Country	Product	Product Photo	Hazard/ Risk	Remedy
26-001	USA	Evermore		Risk of Serious Injury	Consumers
		Surprise		In Motion Design Recalls Evermore Surprise	should stop
		Eggs		Eggs Due to Risk of Serious Injury; Violates	using the
				Federal Lead Content Ban	Surprise Eggs
		(Country of			immediately
		Origin:		The toy airplane inside the egg contains levels	and contact In
		China)		of lead that exceed the federal lead content ban.	Motion Design
				Lead is toxic if ingested by young children and	for a refund.
				can cause adverse health issues.	Consumers
					should destroy
					the toy
					airplane, send
					a photo of the
					destroyed
					airplane to
					support@in-
					motion-
					design.com,
					and then
					dispose of the
					airplane in
					accordance
					with local and
					state laws.
26-003	USA	Blossom		Serious Risk of Injury or Death	Consumers
		Children's		Blossom Recalls Children's Loungewear Due to	should stop
		Loungewea	章 全	Serious Risk of Injury or Death from Burns;	using the
		r Sets		Violates Mandatory Standard for Children's	recalled
				Sleepwear	loungewear
		(Country of			sets
		Origin:		The recalled children's loungewear sets violate	immediately
		India)		the mandatory flammability standard for	and contact
				children's sleepwear, posing a risk of burn	Blossom for a
				injuries or death to children.	full refund in
					the original
					form of





Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
26-012	USA	Generic Magnetic Balls 1000pcs (Country of Origin: China)		Ingestion Hazard Generic Magnetic Ball Sets Recalled Due to Risk of Serious Injury or Death from Magnet Ingestion; Violates Mandatory Standard for Toys; Sold on Amazon by Ritons The recalled 3 mm magnetic ball sets violate the mandatory standard for toys because the magnet sets contain loose magnets posing an ingestion hazard to children. When high- powered magnets are swallowed, the ingested magnets can attract each other, or other metal objects, and become lodged in the digestive system. This can result in perforations, twisting, and/or blockage of the intestines, blood poisoning and death.	payment or store credit. Consumers should destroy the garments by cutting them in half, then take a photo and dispose of them. Consumers should stop using the recalled magnetic ball sets immediately and take them away from children and contact Ritons for instructions on how to receive a refund. Ritons will provide a prepaid label for consumers
26.012	LICA	Pollabu	_	Purn Hazard	to return the recalled products.
26-013	USA	Bellabu Bear Children's Robes		Burn Hazard Bellabu Bear Recalls Children's Robes Due to Burn Hazard; Violates Mandatory Standards for Children's Sleepwear	Consumers should immediately stop using the recalled
		(Country of Origin: China)		The recalled children's robes violate the mandatory flammability standards for children's sleepwear, posing a risk of burn injuries to children.	children's robes, take them away from children





Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
					and contact
					Bellabu Bear
					for a full refund
					or store credit
					for the original
					purchase
					price.
26-014	USA	Mom	1	Risk of Serious Injury or Death	Consumers
		Genius		Mom Genius Recalls Retractable Safety Gates	should stop
		Retractable	la l	Due to Risk of Serious Injury or Death from	using the
		Safety		Entrapment; Violates Mandatory Standard for	recalled
		Gates		Gates and Enclosures	retractable
					safety gates
		(Country of		The recalled gates violate the mandatory	immediately
		Origin:		standard for expansion gates and expandable	and contact
		China)		enclosures because a child's torso can fit	Mom Genius
				through the opening between the gate and the	for a full
				floor, posing a risk of serious injury or death due	refund.
				to entrapment.	Consumers
				·	must destroy
					the gate by
					cutting through
					the mesh and
					take a photo
					showing the
					destroyed
					gate.
26-015	USA	YGJT Baby	A 11 77 . 17 11	Entrapment Hazard	Consumers
20 010	00/1	Loungers		YGJT Baby Loungers Recalled Due to Risk of	should
		Loungers		Serious Injury or Death from Entrapment and	immediately
		(Country of	100	Fall; Violates Mandatory Standard for Infant	stop using the
		Origin:		Sleep Products; Sold on SHEIN by YGJT Local	recalled baby
		China)	- 10	Warehouse	loungers and
		China)		vvarenouse	
				The recalled haby laungers violete the	contact YGJT
				The recalled baby loungers violate the	Local
				mandatory standard for Infant Sleep Products.	Warehouse for
				The sides are too low to contain an infant. The	a full refund.
				enclosed openings at the foot of the loungers	Consumers
				are wider than allowed, posing a fall and an	should remove
				entrapment hazard to infants. In addition, the	the foam and





Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
				baby loungers do not have a stand, posing a fall	pads from the
				hazard, if used on elevated surfaces. These	baby lounger's
				violations create an unsafe sleeping	cover and cut
				environment for infants and can cause death or	the cover,
				serious injury to infants.	foam and pad
					in half.
26-016	USA	Bmrwtg	CHANGE !	Missing of Warnings	Consumers
		LED Tutu		Children's LED Tutu Skirts Recalled Due to Risk	should
		Skirts		of Serious Injury or Death from Battery	immediately
			SOUTH THE WAY	Ingestion; Violates Mandatory Standard for	stop using the
		(Country of		Consumer Products with Coin Batteries; Sold on	recalled skirt
		Origin:		Amazon by Bmrwtg	and remove
		China)			and properly
				The recalled LED tutu skirts violate the	dispose of the
				mandatory standard for consumer products	batteries.
				containing button cell or coin batteries because	Contact
				the LED lights connected to the skirts contain	Bmrwtg for a
				lithium coin batteries that can be accessed	full refund.
				easily by children. Additionally, the tutu skirts do	Consumers
				not have the warnings required by Reese's Law.	should cut the
				When button cell or coin batteries are	skirt and send
				swallowed, the ingested batteries can cause	a photo of the
				serious injuries, internal chemical burns and	destroyed skirt
				death.	in the trash to
					bmrwtgrecall@
					outlook.com.
26-032	USA	Belivium		Suffocation and Entrapment Hazards	Consumers
		Baby		Belivium Baby Loungers Recalled Due to Risk of	should stop
		Loungers		Serious Injury or Death from Suffocation and	using the baby
				Entrapment Hazards; Violates Mandatory	loungers
		(Country of	(I)	Standard for Infant Sleep Products; Sold on	immediately
		Origin:		Amazon by Belivium	and contact
		China)			Belivium for a
		,		The baby loungers violate the mandatory	full refund.
				standard for Infant Sleep Products because the	Consumers
				sides are shorter than the minimum side height	should remove
				limit to secure the infant; the sleeping pad's	the sleeping
				thickness exceeds the maximum limit, posing a	pad, cut up the
				suffocation hazard; and the enclosed openings	sides of the
				at the foot of the loungers are wider than	baby loungers







Issue no.: 49/25/TCD

Decell No.	Notifying	Droduct	Draduot Photo	Howard/ Diok	Damadu
Recall No.	Country	Product	Product Photo	Hazard/ Risk	Remedy
				allowed, posing fall and entrapment hazards to	and the
				infants. The portable loungers do not have a	sleeping pad
				stand, posing a fall hazard. These violations	and email a
				create an unsafe sleeping environment for	photo of the
				infants, posing a risk of serious injury or death.	destroyed
					lounger
					to BeliviumRec
					all@163.com t
					o obtain a full
					refund.
26-035	USA	Vaast A/1	- ·	Fall Hazard	Consumers
		Bicycles		Super Wheels (Formerly Allite) Recalls Vaast	should
		and Frames	(♦) (♦)	A/1 Bicycles and Frames Due to Fall Hazard	immediately
			0		stop using the
		(Country of		The bicycle frame can develop a hairline fracture	Vaast A/1
		Origin:		near a weld, which can cause the tubes to	bicycles and
		Taiwan)		separate, posing a risk of falling.	frame and
					contact Super
					Wheels Inc. for
					a free
					replacement.
					Once
					consumers
					register their
					bike at Contact
					VAAST
					Bikes,
					(www.vaastbik
					es.com/contact
					-us/), Super
					Wheels Inc.
					will provide the
					consumer with
					a replacement
					frame and pay
					(up to \$200)
					for a bike shop
					technician to
					rebuild the bike
					with the





Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
					replacement
					frame.
26-052	USA	Pack N Play		Risk of Serious Injury or Death	Consumers
		Mattresses		Modera Recalls Modera Pack N Play Mattresses	should
			0	Due to Risk of Serious Injury or Death from	immediately
		(Country of		Entrapment; Violates Mandatory Standard for	stop using the
		Origin:		Crib Mattresses	recalled
		China)			mattresses
				Organic Cotton Pack N Play Mattress Dual-	and contact
				Sided Portable Baby Crib Pad	Modera for a
					full refund.
26-053	USA	Grundens		Strangulation Hazard	Consumers
		Youth		Grundens Recalls Youth Jackets with	should
		Clipper 282		Drawstrings Due to Strangulation Hazard; Risk	immediately
		and Zenith		of Serious Injury or Death	take the
		282 Jackets			recalled
				A drawstring in the hood of the recalled jackets	jackets away
		(Country of		presents a substantial product hazard as it can	from children
		Origin:		get caught on objects and cause death or	and remove
		China)		serious injury to children, due to strangulation.	the drawstrings
		·			to eliminate the
					hazard
26-057	USA	Destination	A 1822	Irritation Hazard	Consumers
		Holiday		H-E-B Recalls 12-Pack Destination Holiday	should not use
		Glow Light		Glow Light Stick Bracelets Due to Skin Irritation	the green
		Stick	######################################	Hazard	bracelet sold
		Bracelets			as part of the
				The green glow stick bracelet within the 12-pack	12-pack of
		(Country of		container can leak, posing a skin irritation	bracelets and
		Origin:		hazard.	return the
		China)			bracelet or
		,			container to H-
					E-B to receive
					a full refund.
26-061	USA	Harppa 5-in-		Fall and Entrapment Hazards	Consumers
_5 00.		1	AL .	5-in-1 Convertible High Chairs Recalled Due to	should
		Convertible		Risk of Serious Injury or Death from Fall and	immediately
		High Chairs	4	Entrapment Hazards; Violates Mandatory	stop using the
		for Babies		Standard for High Chairs; Imported by Harppa	high chairs and
		and		Tamada isi riigii olidiio, iliipolituu by ridippu	contact Harppa







Issue no.: 49/25/TCD

Recall No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
		Toddlers		The high chairs pose a risk of serious injury or	for a
				death to children because they violate the	replacement
		(Country of		mandatory standard for high chairs. The high	high chair. To
		Origin:		chairs were sold without the required attached	destroy the
		China)		restraint system, posing a serious risk of falls to	recalled high
				children. In addition, a child's head can become	chair,
				trapped in the opening created between the seat	consumers
				and the tray, posing a deadly entrapment	should
				hazard.	disassemble
					the high chair,
					cut the
					restraints and
					seat cover,
					and email
					photos of the
					disassembled
					and destroyed
					parts.
26-065	USA	Halloween-		Fire Hazard	Consumers
		themed		The Kroger Co. Recalls Halloween-Themed	should stop
		Skeleton		Skeleton Wax Candles Due to Fire Hazard	using the
		Wax Candle			recalled candle
				The candle contains ornaments that are	and return
		(Country of		flammable, posing fire and burn hazards.	them to any
		Origin:			Kroger store
		China)			for a full refund
					in the original
					form of
					payment.

CPSC

The United States Consumer Product Safety Commission (CPSC) is an independent agency of the United States Government. To provide better service in alerting the American people to unsafe, hazardous or defective products, a "one stop shop" for U.S. Government recalls, http://www.recalls.gov, has been created. Members of the public may report unsafe products to CPSC by using the platform.

The recall list is divided into seven categories: Consumer Products, Motor Vehicles, Boats, Food, Medicine, Cosmetics and Environmental Products. Generally, the recall is conducted voluntarily by the company under CPSC's Fast Track Recall programme. Fast Track recalls are initiated by firms who are committed to working with CPSC to quickly announce the recall and remedy to protect consumers.





Recall Summary - Australian Toys / Children's Products

ACCC Recall List (Oct 2025)

PRA No.	Notifying	Product	Product Photo	Hazard/ Risk	Domody
PRA NO.	Country	Product	Product Photo	nazaru/ Risk	Remedy
2025/20636	Australia	Baby	CEBBE.	Risk of Long-Term Illness	Stop using the
		soothers	131	The soothers may contain BPA, a substance	product
				potentially harmful to health.	immediately and
		(Country of			place out of
		Origin:		Risk of long-term illness if BPA is ingested	reach of children.
		China)		over a period of time, including increased risk	Contact Curaprox
				of certain cancers and hormonal disruption.	to arrange to
					return the
					product for a full
					refund.
2025/20651	Australia	Carnival	6.883	Risk of Choking	Stop using the
		Halloween		The mouth piece doesn't comply with the	product
		Luminous		mandatory standards for products containing	immediately and
		Teeth Cover		button/coin batteries.	keep it out of
					reach of children.
		(Country of		The battery isn't secured, and children could	Do not remove
		Origin:		access the button/coin battery.	the batteries from
		China)			the product and
				The screw isn't secured to the battery	dispose of the
				covering and could be lost when replacing the	product safely.
				battery.	SHIEN will
					contact affected
				The packaging is missing warning information	consumers via
				about the dangers of button/coin batteries to	email with a link
				children what to do when a person suspects	to confirm
				someone has swallowed or placed a	disposal of the
				button/coin battery inside any part of their	product.
				body.	SHEIN will
					process a full
				Children are at risk of choking, severe internal	refund when the
				burn injuries or death if they swallow or place	email is actioned.
				button coin batteries inside their bodies.	Contact SHEIN if
					you have not





PRA No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
				Serious injury can occur in as little as 2 hours	received the
				and the results can be fatal. In Australia,	email or are
				children have suffered serious injuries or died	having difficulties
				from swallowing button/coin batteries.	with the email.
					Contact
				If you suspect a child has swallowed or	
				inserted a button or coin battery:	SHIEN
					Distribution
				Call Triple Zero (000) if a child is having any	Australia Pty Ltd
				difficulty breathing.	Email:
				Call the Poisons Information Centre	aucsteam@shein
				immediately on 13 11 26, available 24 hours a	.com
				day. They can direct you to an appropriate	Live Chat
				medical facility.	(11:00am to
					8:00pm AEST)
				Early action can save lives. Do not wait for	
				symptoms to develop.	
2025/20652	Australia	Mini LED	A some state of	Risk of Choking	Stop using the
		Flashlight		The product doesn't comply with the	product
			MAIN	mandatory standards for products containing	immediately and
		(Country of		button/coin batteries.	keep it out of
		Origin:			reach of children.
		China)	200	The battery isn't secured, and children could	Do not remove
			1	access the button/coin battery.	the batteries from
					the product and
				The screw isn't secured to the battery	dispose of the
				covering and could be lost when replacing the	product safely.
				battery.	SHEIN will
					contact affected
				The product is missing warning information	consumers by
				about the dangers of button/coin batteries to	email with a link
				children. What to do when a person suspects	to confirm
				someone has swallowed or placed a	disposal of the
				button/coin battery inside any part of their	product.
				body.	SHEIN will
					process a full
				Children are at risk of choking, severe internal	refund when the
				burn injuries or death if they swallow or place	email is actioned.
<u></u>				button coin batteries inside their bodies.	Contact SHEIN if

warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.





PRA No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
				Serious injury can occur in as little as 2 hours	you have not received the
				and the results can be fatal. In Australia,	email or are
				children have suffered serious injuries or died	having difficulties
				from swallowing button/coin batteries.	with the email.
				If you suspect a child has swallowed or	Contact
				inserted a button or coin battery:	SHEIN
					Distribution
				Call Triple Zero (000) if a child is having any difficulty breathing.	Australia Pty Ltd
				Call the Poisons Information Centre	Email:
				immediately on 13 11 26, available 24 hours a	aucsteam@shein
				day. They can direct you to an appropriate medical facility.	<u>.com</u>
				medical facility.	Live
					Chat (11:00am to
				Early action can save lives. Do not wait for	8:00pm AEST)
				symptoms to develop.	Link
2025/20658	Australia	Steelcraft		Risk of Serious Injury or Death	Stop using
		One2 V2		The handles may detach from these strollers	affected strollers
		Stroller,		due to missing rivets and the operator may	immediately.
		Britax One2		lose control.	Contact Britax to
		Stroller,			arrange to have
		Safe-n-		Risk of serious injury or death to children if the	the stroller
		Sound Cosy		operator loses control of the stroller while in	inspected and
		Lux Stroller		use.	repaired if
		and Safe-n-			necessary.
		Sound Cosy			
		Lux Duo			Contact:
		Stroller			Britax Childcare
					Pty Ltd
		(Country of			Email:
		Origin:			recall-
		China)			anz@britax.com
					Call: 1800 806
					974, 9:30am to
					5:30pm, Monday
					to Friday





Issue no.: 49/25/TCD

PRA No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
					Visit: www.britax.com.
2025/20661	Australia	Halloween LED Light Up Bouncing Ball (Country of Origin: China)		At Risk of Choking The product doesn't comply with the mandatory standard for products containing button/coin batteries. The packaging is missing warning information about the dangers of button/coin batteries to children what to do when a person suspects someone has swallowed or placed a button/coin battery inside any part of their body. Children are at risk of choking, severe internal burn injuries or death if they swallow or place button or coin batteries inside their bodies. Serious injury can occur in as little as 2 hours and the results can be fatal. In Australia, children have suffered serious injuries or died from swallowing button/coin batteries.	au Stop using the product immediately and place out of reach of children. Contact RMS International to receive the required warning labelling. Contact RMS International Email: enquiries.australi a@rmsint.com Call: 0408 066 395 between 9am to 4pm AEST
2025/20662	Australia	9cm Light up tombstone (Country of Origin: China)		Risk of Choking The product does not comply with the mandatory standards for products containing button/coin batteries. The batteries are not secured, and children can access the button/coin batteries. The screw is not secured to the battery covering and could be lost when replacing the battery.	Stop using the product immediately and keep it out of reach of children. Do not remove the batteries from the product. Contact Oceana International Pty Ltd to arrange to return the







PRA No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
				The packaging is missing warning information	product and
				about the dangers of button/coin batteries to	receive a full
				children what to do when a person suspects	refund.
				someone has swallowed or placed a	
				button/coin battery inside any part of their	
				body.	
					Contact
				Children are at risk of choking, serious injury	Oceana
				or death if they swallow or place button/coin	International Pty
				batteries inside their bodies.	Ltd
					Call 02 9604
					1211, 9:00 am to
					5:00 pm AEDT,
					Monday to Friday
					Email sales@oce
					anainternational.
					com.au
2025/20666	Australia	Aquaman		Risk of Choking	Stop using the
		24oz cup		The products do not comply with the	products
		with LED		mandatory standards for products containing	immediately and
		feature	MILITARIO DE COMPANDO DE COMPA	button/coin batteries.	keep them out of
					reach of children.
		(Country of		The screw in the battery covering can be	Do not remove
		Origin:		removed. This could allow children access to	the batteries from
		China)		the button/coin battery.	the products and
					do not dispose of
				The screw and/or battery covering could also	the products.
				be lost when replacing the battery.	Contact Golden
					Link Australia Pty
				The product is missing warning information	Ltd to arrange to
				about the dangers of button/coin batteries to	return the
				children; and what to do when a person	products and
				suspects someone has swallowed or placed a	receive a full
				button/coin battery inside any part of their	refund.
				body.	If you have
				Children are at risk of choking, serious injury	already disposed
				or death if they swallow or place button/coin	of the products or
				batteries inside their bodies.	given them to
					another person,
					please contact

warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.





PRA No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
					Golden Link Australia Pty Ltd. Contact
2025/20667	Australia	Sonic 3 24oz LED cup (Country of Origin: China)		Risk of Choking The products do not comply with the mandatory standards for products containing button/coin batteries. The screw in the battery covering can be removed. This could allow children access to the button/coin battery. The screw and/or battery covering could also be lost when replacing the battery. The product is missing warning information about the dangers of button/coin batteries to children; and what to do when a person suspect someone has swallowed or placed a button/coin battery inside any part of their body. Children are at risk of choking, serious injury or death if they swallow or place button/coin batteries inside their bodies.	Stop using the products immediately and keep them out of reach of children. Do not remove the batteries from the products and do not dispose of the products. Contact Golden Link Australia Pty Ltd to arrange to return the products and receive a full refund. If you have already disposed of the products or given them to another person, please contact Golden Link Australia Pty Ltd.
2025/20673	Australia	Hooded Towel and Everywhere Zip-up Towel	M	Missing of Warnings The products do not comply with the mandatory standard for children's nightwear. The products do not include the required warning label.	Stop using the towels immediately and keep the product away from heat sources or
		(Country of Origin: China)		There is a risk of serious burn injuries if the product is exposed to a heat or flame source.	flames. Contact Crywolf to arrange for a





Issue no.: 49/25/TCD

PRA No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
				Consumers may not be aware of this risk.	refund or for the affected product to be relabelled.
2025/20676	Australia	LED tealight flameless candle supplied at National Museum of Australia lantern making workshops (Country of Origin: China)		Risk of Choking The LED flameless candle doesn't comply with the mandatory standards for products containing button/coin batteries. The batteries are not secured, and children could access the button/coin batteries. The product is missing warning information about the dangers of button/coin batteries to children what to do when a person suspects someone has swallowed or placed a button/coin battery inside any part of their body. Children are at risk of choking, serious injury or death if they swallow or place button/coin batteries inside their bodies.	Stop using the LED tealight flameless candle immediately and keep out of reach of children. Contact the National Museum of Australia to arrange a refund for the lantern materials, including the LED tealight flameless candle.
2025/20680	Australia	Preowned Xbox and Preowned PlayStation Consoles and Power Cords (Country of Origin: Australia)	To be about the second of the	Risk of Serious Injury Affected Preowned Xbox and Preowned PlayStation consoles may not have completed the required electrical testing before sale. Risk of serious injury, death or property damage from electric shock or fire.	Stop using affected consoles and power cords immediately. Return your affected console, power cord, HDMI cable and controller to an EB Games store for a repair, replacement, refund or exchange. For more information about your repair, replacement, refund or

warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.





Issue no.: 49/25/TCD

PRA No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
2025/20681	Country	Assorted Halloween novelty products with LED lights (Country of Origin: China)	Product Photo	Risk of Choking The products don't comply with the mandatory standards for products containing button/coin batteries. The battery isn't secured, and children could access the button/coin battery. The screw isn't secured to the battery covering and could be lost when replacing the battery. The products are missing warning information about the dangers of button/coin batteries to children what to do when a person suspects someone has swallowed or placed a button/coin battery inside any part of their body. Children are at risk of choking, severe internal burn injuries or death if they swallow or place button coin batteries inside their bodies. Serious injury can occur in as little as 2 hours and the results can be fatal. In Australia, children have suffered serious injuries or died from swallowing button/coin batteries.	exchange options, please visit EB games website: http://www.ebga mes.com.au/pow ersupport Stop using the product immediately and keep it out of reach of children. Do not remove the batteries from the product and dispose of the product safely. SHEIN will contact affected consumers by email with a link to confirm disposal of the product. SHEIN will process a full refund when the email is actioned. Contact SHEIN if you have not received the email or are having difficulties with the email.





Issue no.: 49/25/TCD

PRA No.	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
2025/20641	Australia	Various		Missing of Warnings	1. Stop using the
		toys	de de	These toys don't comply with the mandatory	products
		containing	The The The	standards for products containing button/coin	immediately and
		button		batteries.	keep them out of
		batteries			reach of children.
				The products were not tested prior to sale and	2. Contact
		(Country of		do not include the required warning	mishmashed to
		Origin:		information.	receive the
		China)			warning
				The products are missing warning information	information.
				about the dangers of button/coin batteries to	
				children what to do when a person suspects	Contact
				someone has swallowed or placed a	mishmashed
				button/coin battery inside any part of their	Phone: 03 7006
				body.	5160, 9:00am to
					4:00pm, Monday
				Children are at risk of choking, serious injury	to Friday
				or death if they swallow or place button/coin	Email:
				batteries inside their bodies.	info@mishmashe
					d.com.au
					Visit:
					https://mishmash
					ed.com.au/

Australian Product Safety System

The Australian product safety system is set up to maximise the safety of goods through the cooperation of consumers, businesses and agencies. This policy sets out the principles adopted by the Australian Competition and Consumer Commission (ACCC) for prioritising and addressing product safety risks.

Under the Australian Consumer Law, a responsible Minister can order a compulsory recall when there are hazards on the products. A voluntary recall could be conducted to remove the product from the marketplace when the suppliers become aware of unsafe or defective products.

The ACCC administers a national recalls system for recalls of specific and general consumer products, and publishes all product recalls on https://www.productsafety.gov.au/recalls.



Recall Summary - Japanese Toys / Children's Products

METI Recall List (Oct 2025)

Date	Notifying Country	Product	Product Photo	Hazard/ Risk	Remedy
23 October	Japan	扇風機(充		充電 IC の不具合による動作不良や発熱などの発	「自主回収専
2025		電式・携帯		生率が高いため。	用受付フォー
		型)	The Base		ム」での回
				The high incidence of malfunctions and heat	収・返金(ク
		Fans	-	generation due to charging IC failures.	オカード)
		(Rechargeab			
		le/Portable)			Refund with
					the "Voluntary
					Collection
					Reception
					Form" (Quo
					Card)

Japan's Product Recall System (業産省 リコール情報)

The METI (経済産業省 Ministry of Economy, Trade and Industry) administers a national recalls system for recalls of specific and general consumer products according to the Consumer Product Safety Act, and publishes all product recalls on the website: https://www.meti.go.jp/product_safety/recall/index.html and posting at https://x.com/kochijiko



Issue no.: 49/25/TCD

STC (Hong Kong Standards and Testing Centre) is a not-for-profit, independent testing, inspection and certification organization. With a global network of ISO/IEC 17025 accredited testing laboratories and over 60 years of experience in consumer product testing, we can meet your conformity assessment needs with highly efficient and reliable service. Our testing scope and capabilities related to toys and children's products include but are not limited to:

EU Requirements

- EN 71
- Phthalates (EC) no. 1907/2006
- Nickel Release (EC) no. 1907/2006
- Total Cadmium (EEC) no. 91/338
- Lead in Jewellery product (EC) no. 836/2012
- Azo-dye (EC) no. 1907/2006
- Bisphenol-A (2014/81/EU)
- DMF (Dimethyl fumarate) (EU) no. 2011/135
- Flame retardants TCEP, TCPP, TDCP (2014/79/EU)
- Package Waste Directive (94/62/EC)

US & Canada Requirements

- ASTM F963
- **CPSIA**
- California Proposition 65
- 16 CFR 1501
- ASTM F2923 (Children's jewellery)
- ASTM F2999 (Adult's jewellery)
- US Toxic in Packaging Clearinghouse (TPCH)
- CCPSA Toys Regulations (SOR/2011-17)

Japan Requirements

- Japan Toy Safety Standard (ST)
- Japan Food Sanitation Law (JFSL)

Australia Requirements

- AS/NZS 8124
- Consumer Protection Notice No. 6 of 2010 DEHP

FOR MORE DETAILS, PLEASE CONTACT US:

Hong Kong: hktcd@stc.group Dongguan: dgtcd@stc.group **Shanghai:** shtcd@stc.group Changzhou: czstc@stc.group Vietnam: vnstc@stc.group Japan: ipo@stc.group

U.S.A.: usenquiry@stc.group grstc@stc.group **Germany:**

