### **Recall Summary – European Toys**

**ESTC** NEWSLETTER

| EU Safety Gate Alerts (Oct 2 |           |             |  |  |                   |
|------------------------------|-----------|-------------|--|--|-------------------|
| Alert No.                    | Notifying | Product     | Product  | Hazard/ Risk                                   | Measures          |
|                              | Country   | Troduct     | Photo  |  | Adopted           |
| A11/00116/22                 | Poland    | Soft toy    | and the second s | Choking, Suffocation                           | Withdrawal of the |
|                              |           |             | C. C.  | The fibrous stuffing material of the toy is    | product from the  |
|                              |           | (Country of |  | easily accessible due to the weakness of       | market            |
|                              |           | Origin:     |  | certain seams. A small child may put the       |                   |
|                              |           | China)      |  | stuffing material in the mouth and choke.      |                   |
|                              |           |             |  | Moreover, the plastic of the packaging is      |                   |
|                              |           |             | -inter the   | too thin. If a child plays with the packaging, |                   |
|                              |           |             |  | the plastic can cover the mouth and nose,      |                   |
|                              |           |             |  | causing a child to suffocate. The product      |                   |
|                              |           |             |  | does not comply with the requirements of       |                   |
|                              |           |             |  | the Toy Safety Directive nor with the          |                   |
|                              |           |             |  | European standard EN 71-1.                     |                   |
| A11/00122/22                 | Poland    | Soft toy    |  | Choking  | Withdrawal of the |
|                              |           |             |  | The fibrous stuffing material of the toy is    | product from the  |
|                              |           | (Country of | 1  | easily accessible due to the weakness of       | market            |
|                              |           | Origin:     | AN   | certain seams. A small child may put the       |                   |
|                              |           | China)      |  | stuffing material in the mouth and choke on    |                   |
|                              |           |             |  | it. The product does not comply with the       |                   |
|                              |           |             |  | requirements of the Toy Safety Directive       |                   |
|                              |           |             |  | nor with the European standard EN 71-1.        |                   |
| A12/01364/22                 | Hungary   | Rattle toy  | Outer  | Choking  | Recall of the     |
|                              |           |             |  | The rattle can easily break, generating        | product from end  |
|                              |           | (Country of |  | small parts. A child may put them in the       | users             |
|                              |           | Origin:     |  | mouth and choke. The product does not          |                   |
|                              |           | China)      |  | comply with the requirements of the Toy        |                   |
|                              |           |             |  | Safety Directive nor with the European         |                   |
|                              |           |             |  | standard EN 71-1.                              |                   |
| A12/01365/22                 | Lithuania | Rattle toy  |  | Choking  | Withdrawal of the |
|                              |           |             |  | A small part can easily detach (sticker        | product from the  |
|                              |           | (Country of |  | mirror). Small children may put it in the      | market            |
|                              |           | Origin:     |  | mouth and choke. The product does not          |                   |
|                              |           | China)      |  | comply with the requirements of the Toy        |                   |
|                              |           |             |  | Safety Directive nor with the European         |                   |
|                              |           |             |  | standard EN 71-1.                              |                   |

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

#### EU Safety Gate Alerts (Oct 2022)

www.stc.group

```
Headquarters - The Hong Kong Standards and Testing Centre Ltd. 🛛 🗣 10 Dai Wang Street, Tai Po Industrial Estate, Tai Po, N.T., Hong Kong
```

| A12/01371/22 | Czechia | Plastic doll |              | Chemical   | Withdrawal of |
|--------------|---------|--------------|--------------|--|---------------|
|              |         |              | 011101110110 | The plastic material of the head of the doll     | the product   |
|              |         | (Country of  |              | contains an excessive concentration of           | from the      |
|              |         | Origin:      | CENTS OF     | bis(2-ethylhexyl) phthalate (DEHP) (measured     | market        |
|              |         | China)       | <b>SS</b>    | value up to 13.9 % by weight). This phthalate    |               |
|              |         |              | ATATI ATAL   | may harm the health of children, causing         |               |
|              |         |              |              | possible damage to their reproductive system.    |               |
|              |         |              | e note       | The product does not comply with the REACH       |               |
|              |         |              | EILSISTERS   | Regulation.                                      |               |
| A12/01372/22 | Czechia | Plastic doll |              | Chemical   | Withdrawal of |
|              |         |              |              | The plastic material of the head of the doll     | the product   |
|              |         | (Country of  |              | contains an excessive concentration of           | from the      |
|              |         | Origin:      |              | bis(2-ethylhexyl) phthalate (DEHP) (measured     | market        |
|              |         | China)       |              | value up to 30.2% by weight). This phthalate may |               |
|              |         |              |              | harm the health of children, causing possible    |               |
|              |         |              |              | damage to their reproductive system. The         |               |
|              |         |              |              | product does not comply with the REACH           |               |
|              |         |              |              | Regulation.                                      |               |
| A12/01373/22 | Finland | Plush toy    | 1150-34      | Choking  | Import        |
|              |         |              | 0            | Small parts (nose, zipper puller) can easily     | rejected at   |
|              |         | (Country of  |              | detach from the toy. A small child may put them  | border        |
|              |         | Origin:      |              | in the mouth and choke. The product does not     |               |
|              |         | China)       |              | comply with the requirements of the Toy Safety   |               |
|              |         |              | A CAL        | Directive nor with the European standard EN      |               |
|              |         |              |              | 71-1.  |               |
| A12/01375/22 | Czechia | Plastic toy  |              | Choking  | Withdrawal of |
|              |         |              |              | The plastic pieces of the toy can easily break,  | the product   |
|              |         | (Country of  |              | generating small parts. A child may put them in  | from the      |
|              |         | Origin:      |              | the mouth and choke. The product does not        | market        |
|              |         | China)       |              | comply with the requirements of the Toy Safety   |               |
|              |         |              | Accesso      | Directive nor with the European standard EN      |               |
|              |         |              |              | 71-1.  |               |
|              |         |              |              |  |               |
|              |         |              |              |  |               |
|              |         |              |              |  |               |
|              | 1       | 1            |              |  |               |

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

| A12/01383/22 | Poland   | Expandable     |            | Choking                                       | Warning       |
|--------------|----------|----------------|------------|---|---------------|
|              |          | toy            | AGE GE     | Small part may easily detach from the fish    | consumers of  |
|              |          |                |            | figurine. Further, the toy expands more       | the risks     |
|              |          | (Country of    |            | than 50% in size when in contact with         |               |
|              |          | Origin: China) |            | water. If a child puts it in the mouth or     |               |
|              |          |                | EISH EGG   | swallows it, the contact with saliva or       |               |
|              |          |                | GROWINGTET | stomach liquids will cause the figurine to    |               |
|              |          |                |            | expand, which can result in occlusion of      |               |
|              |          |                |            | the respiratory tract or intestinal blockage. |               |
|              |          |                |            | The product does not comply with the          |               |
|              |          |                |            | requirements of the Toy Safety Directive      |               |
|              |          |                |            | nor with the European standard EN 71-1.       |               |
| A12/01387/22 | Luxembou | Children's     |            | Chemical                                      | Recall of the |
|              | rg       | digital        | • •        | The charging cable, the plug and the plug     | product from  |
|              |          | camera         | e ()       | top of the product contain an excessive       | end users     |
|              |          |                |            | concentration of Dibutyl phthalate (DBP),     |               |
|              |          | (Country of    |            | of bis(2-ethylhexyl) phthalate (DEHP) and     |               |
|              |          | Origin: China) |            | Di-'isodecyl' phthalate (DINP) (up to.2.9%    |               |
|              |          |                |            | by weight). These phthalates may harm the     |               |
|              |          |                |            | health of children by possibly causing        |               |
|              |          |                |            | damage to the reproductive system and         |               |
|              |          |                |            | liver. The product does not comply with the   |               |
|              |          |                |            | requirements of the Toy Safety Directive.     |               |
| A12/01388/22 | Czechia  | Plastic doll   |            | Chemical                                      | Withdrawal of |
|              |          |                |            | The plastic material of the head of the doll  | the product   |
|              |          | (Country of    |            | contains an excessive concentration of        | from the      |
|              |          | Origin: China) |            | di-(2-ethylhexyl) phthalate (DEHP) (up to     | market        |
|              |          |                |            | 11.4 % by weight). This phthalate may         |               |
|              |          |                |            | harm the health of children by possibly       |               |
|              |          |                |            | causing damage to the reproductive            |               |
|              |          |                |            | system. The product does not comply with      |               |
|              |          |                |            | the requirements of the Toy Safety            |               |
|              |          |                |            | Directive.                                    |               |
| A12/01392/22 | Poland   | Puzzle play    |            | Choking                                       | Warning       |
|              |          | mat            |            | Small parts may easily detach from the        | consumers of  |
|              |          |                |            | mat. A small child may put them in the        | the risks     |
|              |          | (Country of    | Fails 1    | mouth and choke. The product does not         |               |
|              |          | Origin: China) |            | comply with the requirements of the Toy       |               |
|              |          |                |            | Safety Directive nor with the European        |               |
|              |          | 1              | 1          | standard EN 71-1.                             |               |

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

Headquarters - The Hong Kong Standards and Testing Centre Ltd. 💡 10 Dai Wang Street, Tai Po Industrial Estate, Tai Po, N.T., Hong Kong

| A12/01393/22 | Hungary | Toy gun set<br>(Country of<br>Origin: China)                                |                | <b>Choking, Injuries</b><br>The suction cups can be easily detached.<br>A child can put them in the mouth and<br>choke. Furthermore, the kinetic energy of<br>the projectiles is too high. This could cause<br>injuries, especially to the eyes. The product<br>does not comply with the requirements of<br>the Toy Safety Directive nor with the<br>European standard EN 71-1.  | Import rejected<br>at border                       |
|--------------|---------|---|----------------|--|--|
| A12/01394/22 | Hungary | Yoyo puffer<br>ball<br>(Country of<br>Origin: China)                        |                | <b>Choking, Strangulation</b><br>Small plastic parts (squeaking elements)<br>may easily detach from the toy. A small<br>child may put them in the mouth and<br>choke. In addition, the flexible cord can<br>stretch too long and poses a risk of<br>strangulation. The product does not comply<br>with the requirements of the Toy Safety<br>Directive nor with the European standard<br>EN 71-1.                                | Import rejected<br>at border                       |
| A12/01396/22 | Hungary | Toy gun set<br>(Country of<br>Origin: China)                                | The FLYING FUN | <b>Choking, Injuries</b><br>The suction cups can be easily detached. If<br>a child puts these in the mouth, it/they can<br>obstruct the airways and the child will<br>choke. Further, the kinetic energy of the<br>projectiles is too high. This could cause<br>injuries, especially to the eyes. The product<br>does not comply with the requirements of<br>the Toy Safety Directive nor with the<br>European standard EN 71-1. | Import rejected<br>at border                       |
| A12/01397/22 | Czechia | Plastic bottle<br>with sweets<br>(Country of<br>Origin: The<br>Netherlands) |                | <b>Chemical</b><br>The teddy bear's head contains an<br>excessive concentration bis(2-ethylhexyl)<br>phthalate (DEHP) (measured value up to<br>18.8% by weight).This phthalate may harm<br>the health of children, possibly causing<br>damage to their reproductive system. The<br>product does not comply with the REACH<br>Regulation.   | Withdrawal of<br>the product<br>from the<br>market |

| A12/01398/22 | Hungary | Toy bow<br>set<br>(Country of<br>Origin:<br>China)       |               | <b>Choking, Injuries</b><br>The suction cups can be easily detached. A child can put them in the mouth and choke.<br>The kinetic energy of the projectiles is too high. This could cause injuries, especially to the eyes. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1.  | Import rejected at<br>border |
|--------------|---------|--|---------------|---|------------------------------|
| A12/01401/22 | Finland | Pranking<br>toy<br>(Country of<br>Origin:<br>India)      | LIQUID<br>FUN | <b>Chemical</b><br>The liquid in the toy (the "disappearing<br>ink"), intended to be spilled on another<br>person, is excessively alkaline (measured<br>pH: 12,5). It may cause chemical burns and<br>injuries if it reaches a person's skin or eyes,<br>or if ingested. The product does not comply<br>with the requirements of the Toy Safety<br>Directive nor with the relevant European<br>standard EN 71-9.            | Import rejected at<br>border |
| A12/01402/22 | Finland | Pranking<br>toys set<br>(Country of<br>Origin:<br>India) |               | <b>Chemical</b><br>One of the liquids in the set (the<br>"disappearing ink"), intended to be spilled<br>on another person, is excessively alkaline<br>(measured pH: 12,5). It may cause<br>chemical burns and injuries if it reaches a<br>person's skin or eyes, or if ingested. The<br>product does not comply with the<br>requirements of the Toy Safety Directive<br>nor with the relevant European standard<br>EN 71-9. | Import rejected at<br>border |

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

| A12/01403/22 | France   | Pull-along     |                | Choking, Strangulation                            | Withdrawal of   |
|--------------|----------|----------------|----------------|---|-----------------|
|              |          | toy            |                | Small parts can easily detach (wooden             | the product     |
|              |          |                |                | splinter and wooden bead). A small child          | from the        |
|              |          | (Country of    |                | may put them in the mouth and choke.The           | market          |
|              |          | Origin:        |                | cord of the toy is too long. It may get           |                 |
|              |          | Türkiye)       |                | wrapped around a child's neck and lead to         |                 |
|              |          |                | Leurn with Fun | strangulation. The product does not comply        |                 |
|              |          |                | Animals        | with the requirements of the Toy Safety           |                 |
|              |          |                |                | Directive nor with the European standard          |                 |
|              |          |                |                | EN 71-1.  |                 |
| A12/01408/22 | Luxembou | Rattle toy     | 3              | Choking, Damage to hearing, Injuries              | Removal of this |
|              | rg       |                |                | Small parts can easily detach (ball and           | product listing |
|              |          | (Country of    | 4              | square). A small child may put them in the        | by the online   |
|              |          | Origin: China) |                | mouth and choke on them. The handle of            | marketplace     |
|              |          |                |                | the rattle toy is too long and if a child puts it |                 |
|              |          |                |                | in the mouth it can block the airways and         |                 |
|              |          |                |                | cause choking. The sound pressure level of        |                 |
|              |          |                |                | the bell is too high (measured value up to        |                 |
|              |          |                |                | 111.3 dB). This could lead to permanent or        |                 |
|              |          |                |                | partial hearing loss when the product is          |                 |
|              |          |                |                | used. The product does not comply with            |                 |
|              |          |                |                | the requirements of the Toy Safety                |                 |
|              |          |                |                | Directive nor with the European standard          |                 |
|              |          |                |                | EN 71-1.  |                 |
| A12/01410/22 | Sweden   | Wooden toy     |                | Choking   | Recall of the   |
|              |          |                |                | Small parts (wheels) can easily detach. A         | product from    |
|              |          | (Country of    | orar           | small child may put them in the mouth and         | end users       |
|              |          | Origin: China) |                | choke on them. The product does not               |                 |
|              |          |                |                | comply with the requirements of the Toy           |                 |
|              |          |                |                | Safety Directive nor with the European            |                 |
|              |          |                |                | standard EN 71-1.                                 |                 |
| A12/01412/22 | Finland  | Soft toy       | -              | Choking   | Recall of the   |
|              |          |                | 1              | Small parts (plastic eyes, suction cup) may       | product from    |
|              |          | (Country of    |                | easily detach. A child may put them in the        | end users       |
|              |          | Origin:        |                | mouth and choke. The product does not             |                 |
|              |          | Unknown)       | 2 2 2 M        | comply with the requirements of the Toy           |                 |
|              |          |                |                | Safety Directive nor with the European            |                 |
|              |          |                |                | standard EN 71-1.                                 |                 |

| A12/01414/22 | Hungary | Toy gun set    |  | Chemical, Choking                              | Import rejected |
|--------------|---------|----------------|--|--|-----------------|
|              |         |                | Contraction of   | The suction cups of the projectiles can be     | at border       |
|              |         | (Country of    | ALS M  | easily detached. A child can put them in the   |                 |
|              |         | Origin: China) |  | mouth and choke. The kinetic energy of the     |                 |
|              |         |                |  | projectiles is too high which could cause      |                 |
|              |         |                |  | injuries, especially to the eyes. In addition, |                 |
|              |         |                |  | the product contains dibutyl phthalate         |                 |
|              |         |                |  | (DBP) (measured value: up 7.9% by              |                 |
|              |         |                |  | weight). This phthalate may harm the           |                 |
|              |         |                |  | health of children, possibly causing           |                 |
|              |         |                |  | damage to the reproductive system. The         |                 |
|              |         |                |  | product does not comply with the               |                 |
|              |         |                |  | requirements of the Toy Safety Directive,      |                 |
|              |         |                |  | nor with the REACH Regulation or with the      |                 |
|              |         |                |  | European standard EN 71-1.                     |                 |
| A12/01415/22 | Finland | Toy gun set    | 140 (H)  | Choking  | Stop of sales   |
|              |         |                |  | The product can easily release small parts     |                 |
|              |         | (Country of    |  | (suction cups on bullets). A child may put     |                 |
|              |         | Origin: China) |  | them in the mouth and choke. The product       |                 |
|              |         |                |  | does not comply with the requirements of       |                 |
|              |         |                |  | the Toy Safety Directive nor with the          |                 |
|              |         |                |  | European standard EN 71-1.                     |                 |
| A12/01416/22 | Finland | Toy gun        |  | Choking  | Recall of the   |
|              |         |                | Sheete   | The product can easily release small parts     | product from    |
|              |         | (Country of    |  | (suction cups on projectiles). A small child   | end users       |
|              |         | Origin: China) |  | may put them in the mouth and choke. The       |                 |
|              |         |                | UTHER TO BE A DESCRIPTION OF THE DESCRIPTION OF   | product does not comply with the               |                 |
|              |         |                |  | requirements of the Toy Safety Directive       |                 |
|              |         |                |  | nor with the European standard EN 71-1.        |                 |
| A12/01418/22 | Iceland | Soother        | All and an and a second s | Strangulation                                  | Recall of the   |
|              |         | holder         |  | The soother holder is too long and may         | product from    |
|              |         |                | lead to strangulation of a child. The  | end users                                      |                 |
|              |         | (Country of    | Sikrier  | product does not comply with the               |                 |
|              |         | Origin: China) | Non-Kitange<br>Statisting<br>Linewing<br>Linewing<br>Linewing  | requirements of the General Product            |                 |
|              |         |                | ACC  | Safety Directive nor with the European         |                 |
|              |         |                |  | standard EN 12586.                             |                 |
|              |         |                |  |  |                 |
|              |         |                |  |  |                 |
|              |         |                |  |  |                 |

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

## ESTC

NEWSLETTER

| A12/01419/22 | Lithuania | Plastic doll<br>set<br>(Country of<br>Origin: China) |  | <b>Chemical</b><br>The plastic material of the doll contains an excessive concentration of dibutyl phthalate (DBP) (measured value: 33% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system. The product does not comply with the REACH Regulation.   | Withdrawal of<br>the product<br>from the<br>market |
|--------------|-----------|--|--|--|--|
| A12/01429/22 | Lithuania | Soft toy<br>(Country of<br>Origin: China)            |  | <b>Choking</b><br>The eyes can easily detach. A small child<br>may put them in the mouth and choke. The<br>product does not comply with the<br>requirements of the Toy Safety Directive<br>nor with the European standard EN 71-1.   | Withdrawal of<br>the product<br>from the<br>market |
| A12/01440/22 | Czechia   | Plastic doll<br>(Country of<br>Origin: China)        |  | Chemical<br>The plastic material of the doll contains an<br>excessive concentration of<br>bis(2-ethylhexyl) phthalate (DEHP)<br>(measured value up to 29.1% by weight).<br>This phthalate may harm the health of<br>children, causing possible damage to their<br>reproductive system. The product does not<br>comply with the REACH Regulation.           | Withdrawal of<br>the product<br>from the<br>market |
| A12/01454/22 | Czechia   | Plastic doll<br>(Country of<br>Origin: China)        |  | <b>Chemical</b><br>The plastic material of the head of the doll<br>contains an excessive amount of<br>bis(2-ethylhexyl) phthalate (DEHP)<br>(measured values: 22.36 % by weight).<br>This phthalate may harm the health of<br>children, causing possible damage to their<br>reproductive system. The product does not<br>comply with the REACH Regulation. | Withdrawal of<br>the product<br>from the<br>market |
| A12/01460/22 | Austria   | Teething toy<br>(Country of<br>Origin:<br>Germany)   | <image/> <section-header></section-header> | <b>Choking</b><br>The toy may break generating separated<br>small parts. A small child may put them in<br>the mouth and choke on them. The product<br>does not comply with the requirements of<br>the Toy Safety Directive nor with the<br>European standard EN 71 -1.   | Stop of sales                                      |

| A12/01466/22 | Cyprus  | Plastic doll<br>(Country of<br>Origin: China) | Chemical<br>The arms and the legs of the doll contain<br>an excessive concentration of bis<br>(2-ethylhexyl) phthalate (DEHP) and Di-<br>(butyl) phthalate (DBP)(measured values<br>2,33% and 0.62% by weight<br>correspondingly).These phthalates may<br>harm the health of children, causing<br>possible damage to the reproductive<br>system or the liver. The product does not<br>comply with the REACH Regulation.   | Removal of this<br>product listing<br>by the online<br>marketplace |
|--------------|---------|---|---|--|
| A12/01467/22 | Hungary | Toy gun set<br>(Country of<br>Origin: China)  | Chemical, Choking, Injuries<br>The suction cups of the projectiles can be<br>easily detached. A child can put them in the<br>mouth and choke. The kinetic energy of the<br>projectiles is too high which could cause<br>injuries, especially to the eyes. In addition,<br>the suction cups contain an excessive<br>concentration of bis(2-ethylhexyl) phthalate<br>(DEHP) and dibutyl phthalate (DBP)<br>(measured value: up to 3.1% and 12.3% by<br>weight, respectively). These phthalates<br>may harm the health of children, possibly<br>causing damage to the reproductive<br>system. The product does not comply with<br>the requirements of the Toy Safety<br>Directive, neither with the REACH<br>Regulation nor with the European standard<br>EN 71-1. | Import rejected<br>at border                                       |

| A12/01468/22 | Czechia | Plastic doll   |  | Chemical                                     | Withdrawal of |
|--------------|---------|----------------|--|--|---------------|
|              |         |                |  | The doll's head contains an excessive        | the product   |
|              |         | (Country of    |  | concentration bis(2-ethylhexyl) phthalate    | from the      |
|              |         | Origin: China) |  | (DEHP) (measured value up to 24.2% by        | market        |
|              |         |                |  | weight). This phthalate may harm the         |               |
|              |         |                |  | health of children, possibly causing         |               |
|              |         |                |  | damage to their reproductive system. The     |               |
|              |         |                |  | product does not comply with the REACH       |               |
|              |         |                |  | Regulation.                                  |               |
| A12/01469/22 | Czechia | Plastic doll   |  | Chemical                                     | Withdrawal of |
|              |         |                | APPY CHILDHOOD WITH ME TOGETHER  | The doll's head contains an excessive        | the product   |
|              |         | (Country of    | X _ ()   | concentration of bis(2-ethylhexyl) phthalate | from the      |
|              |         | Origin: China) | 2 63 🏠   | (DEHP) (measured value up to 44.5% by        | market        |
|              |         |                |  | weight). This phthalate may harm the         |               |
|              |         |                |  | health of children, possibly causing         |               |
|              |         |                | Aaaelails  | damage to their reproductive system. The     |               |
|              |         |                | Bandward and All and A | product does not comply with the REACH       |               |
|              |         |                | MARDS IN CHINA   | Regulation.                                  |               |
| A12/01470/22 | Spain   | Children's     |  | Choking                                      | Withdrawal of |
|              |         | costume        | A second  | A small part (the zipper) can easily detach  | the product   |
|              |         |                | El contra de la co | and a small child may put it in the mouth    | from the      |
|              |         | (Country of    | Contraction of the second seco | and choke. The product does not comply       | market        |
|              |         | Origin: China) |  | with the requirements of the Toy Safety      |               |
|              |         |                |  | Directive nor with the European standard     |               |
|              |         |                |  | EN 71-1.                                     |               |
| A12/01475/22 | Finland | Soft toy       |  | Choking                                      | Recall of the |
|              |         |                |  | The toy's suction cup, plastic eyes and      | product from  |
|              |         | (Country of    | Probal same Shif7729   | muzzle may detach, forming small parts. A    | end users     |
|              |         | Origin:        |  | child may put them in the mouth and          |               |
|              |         | Unknown)       | Ce   | choke. The product does not comply with      |               |
|              |         |                | TANK   | the requirements of the Toy Safety           |               |
|              |         |                |  | Directive nor with the European standard     |               |
|              |         |                |  | EN 71-1.                                     |               |

| A12/01479/22 | Norway   | Electric    |            | Chemical, Environment                         | Withdrawal of |
|--------------|----------|-------------|------------|---|---------------|
|              |          | insect trap |            | The solder has an excessive concentration     | the product   |
|              |          |             |            | of lead (Pb) (measured value up to            | from the      |
|              |          | (Country of | <u> </u>   | 38.08%). Lead poses a risk to the             | market        |
|              |          | Origin:     |            | environment. The plastic wire cape of the     |               |
|              |          | Unknown)    |            | toy contains an excessive amount of           |               |
|              |          |             |            | bis(2-ethylhexyl) phthalate (DEHP), dibutyl   |               |
|              |          |             |            | phthalate (DBP), Diisononyl phthalate         |               |
|              |          |             |            | (DINP) (measured values up to 2.30%,          |               |
|              |          |             |            | 2.18% and 2.44% by weight respectively).      |               |
|              |          |             |            | These phthalates may harm the health of       |               |
|              |          |             |            | children, possibly causing damage to their    |               |
|              |          |             |            | reproductive system. The product also         |               |
|              |          |             |            | contains short chain chlorinated paraffins    |               |
|              |          |             |            | (SCCPs) (measured value 4%). SCCPs            |               |
|              |          |             |            | persist in the environment, are toxic to      |               |
|              |          |             |            | aquatic organisms at low concentrations       |               |
|              |          |             |            | and bioaccumulate in wildlife and humans,     |               |
|              |          |             |            | posing a risk to human health and the         |               |
|              |          |             |            | environment. The product does not comply      |               |
|              |          |             |            | with the REACH Regulation nor with the        |               |
|              |          |             |            | Regulation on persistent organic pollutants   |               |
|              |          |             |            | (POP Regulation).                             |               |
| A12/01481/22 | France   | Soft toy    |            | Choking                                       | Withdrawal of |
|              |          |             |            | Small parts (metal ring and the soft toy's    | the product   |
|              |          | (Country of | AS PL      | eyes) may become detached, and the            | from the      |
|              |          | Origin:     | N/ 1/2     | fibrous stuffing is accessible. A child may   | market        |
|              |          | Unknown)    | LAR        | put any of these in its mouth, and choke.     |               |
|              |          |             |            | The product does not comply with the          |               |
|              |          |             |            | requirements of the Toy Safety Directive      |               |
|              |          |             |            | nor with the European standard EN 71-1.       |               |
| A12/01501/22 | Bulgaria | Soother     | The select | Strangulation                                 | Withdrawal of |
|              |          | holder      |            | The soother holder is too long and may        | the product   |
|              |          |             |            | lead to strangulation of a child. The product | from the      |
|              |          | (Country of |            | does not comply with the requirements of      | market        |
|              |          | Origin:     |            | the General Product Safety Directive nor      |               |
|              |          | Bulgaria)   |            | with the European standard EN 12586           |               |

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

| A12/01503/22 | Poland | Plastic doll          | 95 D256                                  | Chemical                                     | Destruction of |
|--------------|--------|-----------------------|--|--|----------------|
|              |        |                       | 23624                                    | The toy contains an excessive                | the product    |
|              |        | (Country of           |  | concentration of bis(2-ethylhexyl) phthalate |                |
|              |        | Origin: China)        | A Contraction                            | (DEHP) (measured value up to 4.23% by        |                |
|              |        |                       |  | weight). This phthalate may harm the         |                |
|              |        |                       | Ale At                                   | health of children, possibly causing         |                |
|              |        | and the second second | damage to their reproductive system. The |  |                |
|              |        |                       | product does not comply with the REACH   |  |                |
|              |        |                       |  | Regulation.                                  |                |
| A12/01504/22 | Poland | Rattle toy            |  | Choking                                      | Warning        |
|              |        |                       |  | The product can easily break, releasing      | consumers of   |
|              |        | (Country of           | P. RTNER                                 | small parts. A child may put the small parts | the risks      |
|              |        | Origin: China)        |  | in the mouth and choke on them. The          |                |
|              |        |                       |  | product does not comply with the             |                |
|              |        |                       |  | requirements of the Toy Safety Directive     |                |
|              |        |                       |  | nor with the European standard EN 71-1.      |                |

### Safety Gate: the EU rapid alert system for dangerous non-food products

"Safety Gate", the EU rapid alert system (formerly known as 'RAPEX'), enables the rapid exchange of information between **31 European countries** and the European Commission on non- food dangerous products found on the market posing a risk to health and safety of consumers.

A weekly overview of the alerts on those products is published in English for free on https://ec.europa.eu/safety-gate-alerts/screen/webReport#weeklyReports. The measures taken in the notifying country in order to restrict their marketing or use can be ordered by national authorities ("compulsory measures") or be taken directly by producers and distributors ("voluntary measures").

The official contact points of the Member and EFTA-EEA States provide the information published in these weekly overviews. Under the terms of Annex II.10 of the General Product Safety Directive (2001/95/EC) responsibility for the information provided lies with the notifying party. The Commission does not take any responsibility for the accuracy of the information provided.

### **Recall Summary – US Toys / Children's Products**

NEWSLETTER

ESTC

|               |                      |   | CPSC Recall List (Oct 2022) |  |   |  |
|---------------|----------------------|---|-----------------------------|--|---|--|
| Recall<br>No. | Notifying<br>Country | Product   | Product<br>Photo            | Hazard/ Risk   | Remedy  |  |
| 23-008        | USA                  | Children's<br>Rings<br>(Country of<br>Origin: China)  |                             | Lead Toxic Hazard<br>U.P. Fashion Recalls Children's<br>Rings Due to Violation of Federal<br>Lead Content Ban<br>The metal base of the ring contains<br>levels of lead that exceed the federal<br>lead content ban. Lead is toxic if<br>ingested by young children and can   | Consumers should<br>immediately take the recalled<br>rings away from children and<br>contact U.P. Fashion for<br>information on how to properly<br>dispose of the rings and<br>receive a full refund.   |  |
| 23-009        | USA                  | Early<br>Learning<br>Centre Little<br>Senses<br>Lights &<br>Sounds<br>Shape Sorter<br>Toys<br>(Country of<br>Origin: China) |                             | cause adverse health issues.<br><b>Choking Hazard</b><br>Early Learning Centre Little Senses<br>Lights & Sounds Shape Sorter Toys<br>Due to Choking Hazard;<br>Manufactured by Addo Play; Sold<br>Exclusively at Amazon.com<br>The red cube can come apart or<br>detach during use and release the<br>small white ball inside the cube,<br>posing a choking hazard to infants. | Consumers should<br>immediately take the recalled<br>toys away from children, stop<br>using the recalled red cube,<br>discard them, and contact<br>Addo Play for a free<br>replacement red cube. The<br>shape sorter toy can be used<br>without the red cube. |  |
| 23-010        | USA                  | Children's<br>Nightgowns<br>(Country of<br>Origin: China)   | 2                           | Burn Hazard<br>Children's Sleepwear Recalled Due<br>to Violation of Federal Flammability<br>Standards and Burn Hazard;<br>Imported by Jammers Apparel<br>Group; Sold Exclusively at<br>JCPenney<br>The children's nightgowns fail to<br>meet the flammability standards for<br>children's sleepwear, posing a risk<br>of burn injuries to children.                            |   |  |

| 23-011 | USA | Children's           | ۶  | Burn Hazard                   | Consumers should immediately        |
|--------|-----|----------------------|--|-------------------------------|-------------------------------------|
|        |     | Bathrobes            |  | Children's Sleepwear          | take the recalled sleepwear         |
|        |     |                      |  | Recalled Due to Violation     | away from children and contact      |
|        |     | (Country of Origin:  |  | of Federal Flammability       | Ekouaer for a full refund.          |
|        |     | China)               |  | Standards and Burn            | Consumers who purchased the         |
|        |     |                      | 11   | Hazard; Imported by           | bathrobes will be asked to          |
|        |     |                      |  | Ekouaer; Sold Exclusively     | destroy the garments by cutting     |
|        |     |                      |  | at Amazon.com                 | them in half and send the           |
|        |     |                      |  |                               | recalling firm a photo of the       |
|        |     |                      |  | The children's bathrobes      | destroyed garment. Ekouaer and      |
|        |     |                      |  | fail to meet the flammability | Amazon will contact all known       |
|        |     |                      |  | standards for children's      | purchasers.                         |
|        |     |                      |  | sleepwear, posing a risk of   |                                     |
|        |     |                      |  | burn injuries to children.    |                                     |
| 23-018 | USA | Mittal International | C  | Entrapment And                | Consumers should immediately        |
|        |     | Baby Blankets        |  | Strangulation Hazards         | stop using the recalled baby        |
|        |     |                      |  | TJX Recalls Baby Blankets     | blankets and return them to any     |
|        |     | (Country of Origin:  |  | Due to Choking,               | HomeGoods, Marshalls or T.J.        |
|        |     | India)               | Contraction of the                         | Entrapment and                | Maxx store for their choice of a    |
|        |     |                      | 2  | Strangulation Hazards         | full refund or store                |
|        |     |                      |  |                               | credit. Alternately, consumers      |
|        |     |                      | June 199                                   | The threads in the recalled   | can contact TJX for instructions    |
|        |     |                      | videos a construction of the second second | woven baby blankets can       | on how to submit a photo of the     |
|        |     |                      |  | come loose and detach         | recalled blanket, along with their  |
|        |     |                      |  | posing choking,               | contact information and written     |
|        |     |                      |  | entrapment and                | confirmation that they will         |
|        |     |                      |  | strangulation hazards.        | discard the blanket to receive a    |
|        |     |                      |  |                               | full refund or a refund in the form |
|        |     |                      |  |                               | of a store gift card.               |

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

| 23-019 | USA | Gel Blaster |        | Fire Hazard                              | Consumers should     |
|--------|-----|-------------|--------|--|----------------------|
|        |     | SURGE 1.0   |        | Gel Blaster Recalls Gel Blaster SURGE    | immediately stop     |
|        |     | toy guns    |        | Model 1.0 Toy Guns Due to Fire Hazard    | using the recalled   |
|        |     |             | surer. |  | Gel Blaster SURGE    |
|        |     | (Country of |        | The lithium-ion battery pack inside the  | Model 1.0 and        |
|        |     | Origin:     |        | handle can overheat and ignite, posing a | contact Gel Blaster  |
|        |     | China)      |        | fire hazard.                             | to receive a prepaid |
|        |     |             |        |  | mailer to return the |
|        |     |             |        |  | product and receive  |
|        |     |             |        |  | a full refund. Gel   |
|        |     |             |        |  | Blaster is           |
|        |     |             |        |  | contacting known     |
|        |     |             |        |  | purchasers directly. |

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.

| 23-025 | USA | Tesla Cyberquad for  |         | Crash And Injury Hazards      | Consumers should               |
|--------|-----|----------------------|---------|-------------------------------|--------------------------------|
|        |     | Kids by Radio Flyer, | NAT -   | Radio Flyer Recalls           | immediately stop using the     |
|        |     | Model Number 914     | The los | Cyberquad for Kids, Due to    | recalled Cyberquad and         |
|        |     |                      | 640- 8  | Violations of Federal Safety  | contact Radio Flyer for a full |
|        |     | (Country of Origin:  |         | Standard for All-Terrain      | refund. Consumers can          |
|        |     | China)               |         | Vehicles (ATVs) and Risk of   | obtain a full refund by        |
|        |     |                      |         | Injury; Sold Exclusively      | removing the product's moto    |
|        |     |                      |         | Online by Tesla               | controller and sending the     |
|        |     |                      |         |                               | controller back to Radio Flye  |
|        |     |                      |         | The Cyberquad fails to        | via a prepaid envelope.        |
|        |     |                      |         | comply with the federal       | Removing the motor             |
|        |     |                      |         | mandatory safety standard     | controller will permanently    |
|        |     |                      |         | requirements for youth        | disable the                    |
|        |     |                      |         | ATVs, including mechanical    | Cyberquad. Radio Flyer is      |
|        |     |                      |         | suspension and maximum        | contacting all consumers       |
|        |     |                      |         | tire pressure. Additionally,  | directly. Directions on how t  |
|        |     |                      |         | the Cyberquad lacks a         | locate, remove and return      |
|        |     |                      |         | CPSC-approved ATV action      | the motor controller can be    |
|        |     |                      |         | plan, which is required to    | found on the Radio Flyer       |
|        |     |                      |         | manufacture, import, sell, or | recall website.                |
|        |     |                      |         | distribute ATVs. ATV action   |                                |
|        |     |                      |         | plans contain numerous        |                                |
|        |     |                      |         | safety requirements, such as  |                                |
|        |     |                      |         | rider training, dissemination |                                |
|        |     |                      |         | of safety information, age    |                                |
|        |     |                      |         | recommendations, and other    |                                |
|        |     |                      |         | safety measures. These        |                                |
|        |     |                      |         | ATV safety standards are in   |                                |
|        |     |                      |         | place to reduce crash and     |                                |
|        |     |                      |         | injury hazards, preventing    |                                |
|        |     |                      |         | serious injury or death.      |                                |

The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.



| 00.700 |     |               | - |   |                        |
|--------|-----|---------------|---|---|------------------------|
| 23-703 | USA | Butterfly Net |   | Phthalates and Lead Toxic Hazards           | Consumers should       |
|        |     | Sets and      |   | Juvo Plus Recalls Children's Butterfly Net  | immediately take       |
|        |     | Army Action   |   | Sets and Army Action Figure Playsets Due    | the recalled           |
|        |     | Figure        |   | to Violations of Federal Phthalates and     | butterfly net sets     |
|        |     | Playsets      |   | Lead Content Bans (Recall Alert)            | and the action         |
|        |     |               |   |   | figure playsets        |
|        |     | (Country of   |   | Components of the recalled butterfly net    | away from children     |
|        |     | Origin:       |   | sets and the action figure playsets contain | and contact Juvo       |
|        |     | China)        |   | levels of certain phthalates and lead that  | Plus for a full refund |
|        |     |               |   | exceed the federal phthalate and lead       | of the purchase        |
|        |     |               |   | content standards. Phthalates and lead are  | price. Consumers       |
|        |     |               |   | toxic if ingested by young children and can | will be asked to       |
|        |     |               |   | cause adverse health issues.                | register their         |
|        |     |               |   |   | butterfly net sets     |
|        |     |               |   |   | and submit a photo     |
|        |     |               |   |   | of the disposed        |
|        |     |               |   |   | product with the       |
|        |     |               |   |   | nets cut and the       |
|        |     |               |   |   | handles initialed      |
|        |     |               |   |   | and dated.             |

\* Source: www.recalls.gov

### **CPSC**

The United States Consumer Product Safety Commission (CPSC) is an independent agency of the United States government. To provide better service in alerting the American people to unsafe, hazardous or defective products, a "one stop shop" for U.S. Government recalls, <u>http://www.recalls.gov</u>, has been created. Publics can report unsafe products to CPSC by using the platform.

The recall list is divided into seven categories: Consumer Products, Motor Vehicles, Boats, Food, Medicine, Cosmetics and Environmental Products. Generally, the recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall program. Fast Track recalls are initiated by firms who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.

### **Recall Summary – Australia Toys / Children's Products**

ESTC NEWSLETTER

#### Notifying Product PRA No. Product Hazard/ Risk Remedy Country Photo 2022/19598 Australia Various **Choking Hazard** Consumers should Halloween The products do not comply with immediately stop using Masks. the mandatory safety standard for the product and store it Headbands, products containing button/coin in a safe place out of batteries reach of children. Jewellery, **Candles and** Decorations The battery compartment is not adequately secured so one button battery in the products may be easily accessible. If young children gain access to button batteries and ingest them, they are likely to suffer severe internal burn injuries, which can result in serious injury or death. Button batteries also pose a choking hazard to young children. 2022/19601 Various Australia **Choking Hazard** Consumers should **Christmas** The products do not comply with immediately stop using novelty the mandatory safety standard for the product and store it decorations, products containing button/coin in a safe place out of reach of children. jewellery, batteries The battery compartment toys and is not adequately secured so one ornaments or more button batteries in the products may be easily accessible. If young children gain access to button batteries and ingest them, they are likely to suffer severe internal burn injuries, which can result in serious injury or death. Button batteries also pose a choking hazard to young children.

#### ACCC Recall List (Oct 2022)

## ESTC

NEWSLETTER

| 2022/19617 | Australia | LED Flashing      |          | Choking Hazard                     | Consumers should          |
|------------|-----------|-------------------|----------|------------------------------------|---------------------------|
| 2022/10011 | Australia | Starfish Necklace | - Andrew | The product does not comply        | immediately stop using    |
|            |           |                   | S        | with the mandatory standard for    | the product and keep it   |
|            |           |                   |          | products containing button/coin    | out of reach of children. |
|            |           |                   |          | batteries.                         |                           |
|            |           |                   |          | batteries.                         | Consumers can contact     |
|            |           |                   |          | <b>-</b>                           | Everything Glows on the   |
|            |           |                   |          | The battery compartment is not     | contact details below to  |
|            |           |                   |          | adequately secured. The three      | arrange a refund.         |
|            |           |                   |          | button batteries may be easily     |                           |
|            |           |                   |          | accessible.                        |                           |
|            |           |                   |          | If young children gain access to   |                           |
|            |           |                   |          | button batteries and ingest them,  |                           |
|            |           |                   |          | they are likely to suffer severe   |                           |
|            |           |                   |          | internal burn injuries, which can  |                           |
|            |           |                   |          | result in serious injury or death. |                           |
|            |           |                   |          |                                    |                           |
|            |           |                   |          | Button batteries also pose a       |                           |
|            |           |                   |          | choking hazard to young            |                           |
|            |           |                   |          | children.                          |                           |
| 2022/19632 | Australia | Anko Teething     |          | Choking Hazard                     | Consumers should          |
|            |           | Llama             |          | The cap that seals the mold entry  | immediately cease using   |
|            |           | Natural Rubber    | 13/19/19 | point in one foot, may not be      | the teether and return it |
|            |           | Keycode:          | THE REAL | secure and could detach from the   | to the nearest Kmart      |
|            |           | 43144082          | :U:      | teether.                           | store for a full refund.  |
|            |           |                   | n        | If the easy data share from the    |                           |
|            |           | Ages 0+           |          | If the cap detaches from the       |                           |
|            |           |                   |          | teether, it can pose a choking     |                           |
|            |           |                   |          | hazard for young children, which   |                           |
|            |           |                   |          | can lead to severe injury or       |                           |
|            |           |                   |          | death.                             |                           |

NEWSLETTER

### **Australian Product Safety System**

**BESTC** 

The Australian product safety system is to maximize the safety of good by the cooperation of consumers, businesses and agencies. This policy sets out the principles adopted by the Australian Competition and Consumer Commission (ACCC) for prioritizing and addressing product safety risks.

Under the Australian Consumer Law, a responsible Minister can order a compulsory recall when there are hazards on the products. A voluntary recall could be conducted to remove the product from the marketplace when the suppliers become aware of unsafe or defective products.

The ACCC administers a national recalls system for recalls of specific and general consumer products, and publishes all product recalls on the website <u>https://www.productsafety.gov.au/recalls</u>.

STC (Hong Kong Standards and Testing Centre) is a not-for-profit, independent testing, inspection and certification organization. With a global network of ISO/IEC 17025 accredited testing laboratories and nearly 60 years of experience in consumer product testing, we can meet your conformity assessment needs with highly efficient and reliable service. Our testing scope and capabilities related to toys and children's products include but not limited to:

NEWSLETTER

#### **EU Requirements**

- EN 71
- Phthalates (EC) no. 1907/2006

ESTC

- Nickel Release (EC) no. 1907/2006
- Total Cadmium (EEC) no. 91/338
- Lead in Jewellery product (EC) no. 836/2012
- Azo-dye (EC) no. 1907/2006
- Bisphenol-A (2014/81/EU)
- DMF (Dimethyl fumarate) (EU) no. 2011/135
- Flame retardants TCEP, TCPP, TDCP (2014/79/EU)
- Package Waste Directive (94/62/EC)

#### **US & Canada Requirements**

- ASTM F963
- CPSIA
- California Proposition 65
- 16 CFR 1501
- ASTM F2923 (Children's jewellery)
- ASTM F2999 (Adult's jewellery)
- US Toxic in Packaging Clearinghouse (TPCH)
- CCPSA Toys Regulations (SOR/2011-17)

#### **Japan Requirements**

- Japan Toy Safety Standard (ST)
- Japan Food Sanitation Law (JFSL)

### **Australia Requirements**

- AS/NZS 8124
- Consumer Protection Notice No. 6 of 2010 DEHP

#### FOR MORE DETAILS, PLEASE CONTACT US:

| Hong Kong: <u>hktcd@stc.group</u>  | Dongguan: <u>dgtcd@stc.group</u> | Shanghai: <u>shtcd@stc.group</u> |
|------------------------------------|----------------------------------|----------------------------------|
| Changzhou: czstc@stc.group         | Vietnam: vnstc@stc.group         | Japan: jpo@stc.group             |
| U.S.A.: <u>usenquiry@stc.group</u> | Germany: <u>grstc@stc.group</u>  |                                  |



The information contained in this newsletter is obtained from sources believed to be accurate to the best knowledge of STC and its subsidiaries. It is distributed without warranty, representation, inducement or license of any kinds and STC and its subsidiaries do not assume any legal responsibility for use or reliance upon the information.



www.stc.group